



File In Section: Product Recalls
Bulletin No.: 09226B
Date: May 2012

Recall Bulletin



PRODUCT SAFETY RECALL

SUBJECT: Fuel Odor or Spotting on Ground – Replace Fuel Pump Module

MODELS: 2006 Chevrolet Cobalt
2006 Pontiac Pursuit
2006 Saturn ION

Originally Sold or Currently Registered in Arizona, Nevada

2007 Chevrolet Cobalt
2007 Pontiac G5
2007 Saturn ION

**Originally Sold or Currently Registered in Arizona, California, Florida,
Nevada, Texas**

This bulletin is being revised to remind dealers to refer to the General Motors Service Policies and Procedures Manual, Section 6.1.2 - Regional Product Field Actions, for guidelines on handling vehicles that are not involved in this safety recall but may be displaying the same condition. Please discard all copies of bulletin 09226A, issued March 2010.

CONDITION

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2006 model year Chevrolet Cobalt, Pontiac Pursuit, and Saturn ION vehicles originally sold, or currently registered, in Arizona and Nevada; and 2007 Chevrolet Cobalt, Pontiac G5, Saturn ION vehicles originally sold or currently registered in Arizona, California, Florida, Nevada, and Texas. Some of these vehicles have a condition in which the plastic supply or return port on the modular reservoir assembly (MRA) may crack. If either of these ports develop a crack, fuel will leak from the area. The customer may notice a fuel odor while the vehicle is being driven or after it is parked. If the crack becomes large enough, fuel may be observed dripping onto the ground and vehicle performance may be affected. If a sufficient amount of fuel were to leak out and if an ignition source were present, a vehicle fire could occur.

CORRECTION

Dealers are to inspect and, if necessary, replace the fuel pump module.

VEHICLES INVOLVED

Involved are **certain** 2006 model year Chevrolet Cobalt, Pontiac Pursuit, and Saturn ION vehicles originally sold or currently registered in Arizona and Nevada; and 2007 Chevrolet Cobalt, Pontiac G5, Saturn ION vehicles originally sold, or currently registered, in Arizona, California, Florida, Nevada, and Texas, and built within these VIN breakpoints:

Year	Division	Model	From	Through
2006	Chevrolet	Cobalt	67600011	67887442
2007	Chevrolet	Cobalt	77100076	77317715
2007	Pontiac	G5	77100188	77317670
2006	Pontiac	Pursuit	67774864	67774864
2006	Saturn	ION	6Z100063	6Z211248
2007	Saturn	ION	7Z100015	7Z210507

Important: Dealers are to confirm vehicle eligibility prior to beginning repairs by using the Investigate Vehicle History link. Not all vehicles within the above breakpoints may be involved.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to dealers through the GM GlobalConnect Recall Reports. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PARTS INFORMATION

Parts required to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
19168894	Module Kit, F/Tnk F/Pmp (w/o Fuel Lvl Sen) (LE5/L61)	1
19177326	Module Kit, F/Tnk F/Pmp (w/o Fuel Lvl Sen) (LSJ)	1

SERVICE PROCEDURE

1. Inspect the warranty summary in Global Warranty Management (GWM) for a fuel pump module replacement on or after 7/1/07.
 - If the fuel pump module has not been replaced, or was replaced before 7/1/07, the fuel pump module requires replacement. Proceed to Step 2.
 - If the fuel pump module was replaced on or after 7/1/07, what was the part number of the new fuel pump?
 - If the new fuel pump module part number module was 19168892, 19168893, 19168894, or 19177326, no further action is required.
 - If the new fuel pump module part number was **NOT** 19168892, 19168893, 19168894, or 19177326, the fuel pump module requires replacement. Proceed to Step 2.
2. Remove the fuel pump module. Refer to *Fuel Pump Module Replacement* in SI.
3. Install a new fuel pump module. Refer to *Fuel Pump Module Replacement* in SI.

CUSTOMER REIMBURSEMENT

All customer requests for reimbursement of previously paid repairs for the recall condition will be handled by the Customer Assistance Center, not by dealers.

A General Motors Customer Reimbursement Procedure and Claim Form is included with the customer letter.

IMPORTANT: (For GM US Only) Refer to the GM Service Policies and Procedures Manual, section 6.1.12, for specific procedures regarding customer reimbursement and the form.

COURTESY TRANSPORTATION

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a claim using the table below.

Labor Code	Description	Labor Time	Net Item
V2148	Inspect Fuel Pump Module – No Further Action Required – New Module Already Installed	0.2	N/A
V2149	Inspect & Install New Fuel Pump Module <ul style="list-style-type: none"> • Cobalt, G5, Pursuit • ION 	1.5 1.2	N/A
V2150	Customer Reimbursement (not for use by US GM dealers)	0.2	*

* The amount identified in “Net Item” should represent the dollar amount reimbursed to the customer.

CUSTOMER NOTIFICATION

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

DEALER RECALL RESPONSIBILITY

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

All unsold new vehicles in dealers' possession and subject to this recall must be held and inspected/repaired per the service procedure of this recall bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.



February 2010

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect that relates to motor vehicle safety exists in certain 2006 model year Chevrolet Cobalt, Pontiac Pursuit, and Saturn ION vehicles originally sold, or currently registered, in Arizona and Nevada; and 2007 Chevrolet Cobalt, Pontiac G5, Saturn ION vehicles originally sold or currently registered in Arizona, California, Florida, Nevada, and Texas. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

I M P O R T A N T

- Your vehicle is involved in safety recall 09226.
- Schedule an appointment with your GM dealer/retailer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

Your vehicle may have a condition in which the plastic supply or return port on the modular reservoir assembly (MRA) may crack. If either of these ports develop a crack, fuel will leak from the area. You may notice a fuel odor while the vehicle is being driven or after it is parked. If the crack becomes large enough, fuel may be observed dripping onto the ground and vehicle performance may be affected. If a sufficient amount of fuel were to leak out and if an ignition source were present, a vehicle fire could occur.

What will we do?

Your GM dealer/retailer will inspect and, if necessary, replace the fuel pump module. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer/retailer will need your vehicle longer than the actual inspection time of approximately 15 minutes. If the fuel pump module requires replacement, an additional 1½ hours will be needed.

If your vehicle is within the New Vehicle Limited Warranty, your dealer/retailer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the dealership/facility for this repair. Please refer to your Owner's Manual and your dealer/retailer for details on courtesy transportation.

What should you do?

You should contact your GM dealer/retailer to arrange a service appointment as soon as possible.

Did you already pay for this repair? The enclosed form explains what reimbursement is available and how to request reimbursement if you have paid for repairs for the recall condition. Even though you may have already had this condition corrected, you will still need to take your vehicle to your <DIV_DLR> <dlr_rtr> for additional repairs.

Do you have questions? If you have questions or concerns that your dealer/retailer is unable to resolve, please contact the <VINDivisionName> Customer Assistance Center at <DivCACPhone>. More information about your vehicle can be found at the Owner Center at www.gmownercenter.com.

If after contacting your dealer/retailer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Scott Lawson
Director,
Customer and Relationship Services

Enclosure
09226