

*** * ADVANCE TECHNICAL INFORMATION NOTICE * ***

DATE: February 3, 2015

TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, Service Managers, and Parts Managers

RE: Raider Driver Air Bag Inflator Special Service Campaign - Revised

ATIN NO. ATIN-14-SC-005-B

AFFECTED VEHICLES: Certain 2006 – 2007 Raiders built May 18, 2005 to June 29, 2007

PURPOSE

A revision to this special service campaign will be released today for the driver air bag inflator equipped on certain 2006 - 2007 Raider vehicles built May 18, 2005 to June 29, 2007. **The original regional special service campaign was limited to vehicles originally sold in or ever registered in Florida, Hawaii, Puerto Rico, and the US Virgin Islands, however, this campaign is now being expanded nationwide.** The revised Special Service Campaign Bulletin outlining the repair procedure will be available today on MEDIC and MDL.

The replaced inflator must be returned to Takata directly for testing and analysis. Dealers must review the return shipping document attached to the replacement air bag inflator kit PN CBRZP401AA. This document is also attached to SC-14-005REV. To obtain your dealership's CCN, please reference the MDL > Parts > Parts Information > Hazardous Materials > Takata Air Bag Inflator CCN.

Affected new vehicle inventory VINs can be reviewed on the Mitsubishi Dealer Link in the **Most Recent: Open Campaign List** available under the service section of "e-reports". Dealers must review the Warranty Superscreen to confirm if any vehicles in their new or used vehicle inventories are affected, and conduct this campaign prior to delivering them. When checking for applicability of this campaign (C1415R), please check for and complete any other open campaigns. Always get the customer's approval before completing a campaign on a customer owned vehicle.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this service action.