



6555 Katella Avenue • Cypress • California • 90630-5101 • (714) 761-7300 • Fax (714) 761-7303

June 24, 2011

Chief Administrator
National Highway Traffic Safety Administration
Associate Administrator for Safety Assurance (NVS-215)
1200 New Jersey Avenue SE, W46-421
Washington, DC 20590

**Regarding: 2006 ~ 2009 Model Year Yamaha FJR13 (FJR1300A/AC/AE/AEC)
Ground Wire Junction, Factory Modification Campaign**

Dear Sir/Madam:

The purpose of this correspondence is to provide preliminary information required by 49 CFR 573 and the National Traffic and Motor Vehicle Safety Act regarding a defect notification campaign we are initiating. Attached are draft copies of the Owner's notification letter, for Agency review and approval, and the dealer technical bulletin. The envelope format has previously been approved by the Agency for prior campaigns.

1. Manufacturers Name: Yamaha Motor Company, Ltd.
2500 Shingai
Iwata, Japan

Imported Vehicle Distributor: Yamaha Motor Corporation, U.S.A.
6555 Katella Avenue
Cypress, California 90630
2. Vehicles Affected: Make: Yamaha
Model: 2006~2009 Model Year FJR1300 Motorcycles

Nominal Engine Displacement: FJR13 is 1300cc

Production Period: 02/2006 – 03/2009
3. The campaign relates to the motorcycle's Ground Wire Junction terminal.
4. Total number of subject vehicles: Current estimate: 9,850 units. This will be updated in a supplemental report as we finalize the affected VIN range.
5. VIN Range: See tentative range in draft Technical Bulletin attached. Likewise this will be updated in a subsequent report as data is confirmed.

6. The campaign involves the replacement of the ground wire junction terminal. On affected motorcycles, the ground joint connector of the wire harness could overheat and become deformed, possibly causing an intermittent ground wire connection. If the electrical system is not properly grounded, the ignition system and/or other electrical components could malfunction, which could cause the engine to stall. If this happens while the motorcycle is being ridden, there could be a crash resulting in injury or death.

Please refer to the draft Technical Bulletin which will be furnished to the Agency and Yamaha dealers upon completion describing the situation which is the subject of the campaign.

7. On June 17, 2011, Yamaha Motor Corporation, U.S.A. was informed by the manufacturer, Yamaha Motor Company, Ltd., that such a situation exists. This was determined pursuant to a quality control review, testing and a review of foreign models that use a substantially similar part design.

We anticipate commencing dealer/owner notification shortly after the owner's notification letter is approved by NHTSA, the affected VIN range is ascertained and the Technical Bulletin service procedure is confirmed by Yamaha service staff. Assuming the Agency can approve the letter within 5 days of receipt (perhaps July 01) we will have the letter and Technical Bulletin printed. Normal turn-around time is 3 working days for such printing. Hence the materials will be ready for mailing approximately July 08th. Final copies of these notification documents will be forwarded to the Agency as soon as possible.

In the event we can answer any questions or provide supplemental information, please do not hesitate to contact me. My direct telephone number is 714-761-7842. The fax number is 714-229-7944. My email is brad_franklin@yamaha-motor.com.

Sincerely,

Brad Franklin

Brad Franklin
Manager, Government Relations

BRF/lf

cc: By Fed Ex and Facsimile
Defects & Recall Information Analysis Division
Ms. Kelly Schuler (via email)
Mr. Robert Young (via email)