



DAEWOO MOTOR AMERICA, INC.

1056 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5000 Fax: (310) 669-2000

DEF

September 8, 2004

BY OVERNIGHT COURIER

Ms. Kelly Schuler
Recall Management Division
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Kelly,

As requested, I am enclosing copies of actual Safety Recall Notices (Type I and Type II) to Daewoo customers subject to Recall No. 04V-357 involving Camshaft Position Sensor inspection / replacement. R.L. Polk is handling the customer letter production and distribution elements of this recall action for us and have advised that all customer letters have been mailed as of September 7th. If you have any questions or need any additional information, please let me know.

Sincerely,

Ben Rainwater
Vice President

Enclosures

cc: Ms. A. Cha
Mr. B. C. Jung



Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-8709

September, 2004

(1)

Safety Recall Notice Lanos, Nubira, Leganza

Dear Lanos, Nubira, and Leganza Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daewoo has decided that a defect which relates to motor vehicle safety exists in certain Lanos, Nubira and Leganza model vehicles.

The problem is with the Camshaft Position (CMP) Sensor that is installed in your Daewoo vehicle. The CMP sensor sends a signal to the engine control module (ECM). The ECM uses this signal as "sync pulse" to trigger the fuel injectors in the proper sequence. In rare instances, due to a possible crack in the C2 capacitor attached to the Camshaft Position Sensor PC board, the Camshaft Position Sensor may malfunction, which will cause the Check Engine Warning Light in your instrument panel to illuminate. Additionally, the Camshaft Position Sensor and wiring may melt resulting in a burning smell and/or visible smoke and possibly an underhood fire.

The following Lanos, Nubira, and Leganza vehicles are included in this recall:

- Lanos (VIN* numbers 158465 to 715658)
 - Nubira (VIN* numbers 157058 to 778128)
 - Leganza (VIN* numbers 105594 to 332882)
- * VIN=Vehicle Identification Number

Because your safety is very important to Daewoo, we urge you to have your vehicle repaired immediately. Your Daewoo dealer or Authorized Service Center (ASC) will replace the Camshaft Position Sensor and add an in-line fuse to the Camshaft Position Sensor wiring.

This service will be performed for you at no charge and should take about one hour. Thus, to minimize waiting time, you are advised to make an appointment with your Daewoo dealer or Authorized Service Center (ASC), in advance. If, however, you take your vehicle to your Daewoo dealer or Authorized Service Center (ASC) on the scheduled service date and you have a problem with obtaining the corrective service on that date, please contact the Daewoo Customer Assistance Center toll-free at (877) 382-1234, option 6. A Daewoo representative will assist you with arranging prompt service for your vehicle.

The enclosed Owner Reply Card identifies your vehicle. Presenting the card at the time of your service will assist your Daewoo Dealer in completing this procedure in the shortest time possible. If you have sold or traded your vehicle, please let us know by completing the enclosed postage-paid reply card and returning it to us.

If you incurred expenditures to repair the defect identified in this letter within the past twelve months, Daewoo will reimburse you for your reasonable expenses, which include our suggested retail cost for related parts and reasonable labor time / amount for the labor that was performed. To claim your reimbursement, send a copy of your receipt for the work performed on your vehicle. Your receipt must identify the date on which the work was performed, describe the work in enough detail to show that it was done to address the defect identified in this letter, and show the amount of the charges for the work. Send your claim to Daewoo Motor America, 1055 W. Victoria St., Compton, CA 90220, Attention: Daewoo Customer Relations Department. You must include a letter affirming that you were the owner of the vehicle at the time the repair was made, and identifying where the reimbursement check should be sent.

If you are the owner of the subject vehicle, but have leased it to another person, you are required by federal law to forward a copy of this notice to your lessee by first class mail within ten days of your receipt of this letter. See 49 C.F.R. 577.7(a)(2)(iv).

If you believe that Daewoo has failed or is unable to remedy the defect described in this letter without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 800-424-9393 (Washington D.C. area residents may call 202-366-0123).

We apologize for any inconvenience this may cause you. We have taken this initiative in the interest of your safety and continued satisfaction with your Daewoo vehicle.

Sincerely,

Daewoo Customer Relations Department



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS MAIL PERMIT NO. 38 COMPTON, CA

POSTAGE WILL BE PAID BY ADDRESSEE

DAEWOO MOTOR AMERICA, INC.
1055 W. VICTORIA ST.
COMPTON, CA 90220-9709



IF ANY INFORMATION (NAME, ADDRESS OR VIN) HAS CHANGED,
COMPLETE ALL ENTRIES ON THIS CARD AND MAIL IT.

I no longer own this automobile.

It was

- SOLD (Print name and address of new owner at right, if known).
- EXPORTED STOLEN
- DESTROYED I do not own a DAEWOO
- The Vehicle Identification Number on this card is incorrect. The VIN of my DAEWOO is

Name and address has changed (print new information below)

LAST NAME	FIRST NAME	INITIAL

ADDRESS NUMBER	STREET

_____	_____	_____
CITY	STATE	ZIP

VEHICLE
IDENTIFICATION
NUMBER

*****AUTO**3-DIGIT 902
 KLATC5260CB258115 RSB-001-04
 Daewoo Motor America Inc
 1055 W Victoria St
 Compton, CA 90220-5804





DAEWOO

Daewoo Motor America, Inc.

1055 W. Victoria St.

Compton, CA 90220-9709

FIRST CLASS MAIL



IMPORTANT: SAFETY RECALL NOTICE



Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-9709

September, 2004

(II)

**Safety Recall Notice
Lanos, Nubira, Leganza**

Dear Lanos, Nubira, and Leganza Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daewoo has decided that a defect which relates to motor vehicle safety exists in certain Lanos, Nubira and Leganza model vehicles.

The problem is with the Camshaft Position (CMP) Sensor that may be installed in your Daewoo vehicle. The CMP sensor sends a CMP sensor signal to the engine control module (ECM). The ECM uses this signal as "sync pulse" to trigger the fuel injectors in the proper sequence. In rare instances, due to a possible crack in the C2 capacitor attached to the CMP Sensor PC board, CMP Sensor may malfunction, which will cause the check engine warning light in your instrument panel to illuminate. Additionally, the Camshaft Position Sensor and wiring may melt resulting in a burning smell and/or visible smoke and possibly an underhood fire.

If you have taken your Daewoo in for service since October 2001 because the Check Engine Warning Light was illuminated on your instrument panel, contact your Daewoo Dealer or Authorized Service Center (ASC) immediately to arrange for your vehicle to be inspected, because your CMP Sensor may have been replaced with one that is subject to this recall. Your dealer or ASC will inspect your vehicle and, if your CMP Sensor needs to be replaced, will replace the sensor and add an in-line fuse to the CMP Sensor wiring. If you are not the first owner of your Daewoo vehicle and/or are not sure if your vehicle has been serviced because of an illuminated Check Engine Warning Light, you should also immediately contact your Daewoo Dealer or Authorized Service Center (ASC) to arrange for your vehicle to be inspected.

If your vehicle has not been serviced since October of 2001 to address an illuminated Check Engine Light, or your vehicle's VIN* is not within the following VIN range, your vehicle is not subject to this recall campaign, and you need take no further action at this time.

- Lanos (VIN* numbers: 158465 to 715060)
- Nubira (VIN* numbers: 157058 to 778126, 998142 to 998146)
- Leganza (VIN* numbers: 105594 to 331911)

*VIN=Vehicle Identification Number

If it is determined your vehicle is affected by this recall and you incurred out-of-pocket expenses to repair the defect identified in paragraph three above within the past twelve months, Daewoo will reimburse your reasonable expenses, which include our suggested retail cost for related parts and reasonable labor time / amount for the labor that was performed. To claim your reimbursement, send us a copy of your receipt for the work performed on your vehicle. The receipt must identify the date on which the work was performed, describe the work in enough detail to show that it was done to address the defect identified in this letter, and show the amount of the charges for the work. Send your claim to Daewoo Motor America, 1055 West Victoria St., Compton, CA 90220. You must include a letter affirming that you were the owner of the vehicle at the time the repair was made, and identifying where the reimbursement check should be sent.

If you are the owner of the subject vehicle, but have leased it to another person, you are required by federal law to forward a copy of this notice to your lessee by first class mail within ten days of your receipt of this letter. See 49 C.F.R. 577.7(a)(2)(iv).

If you believe that Daewoo has failed or is unable to remedy the defect described in this letter without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at (888) 327-4236.

Because your safety is very important to Daewoo, we urge you to have your vehicle inspected and repaired immediately. Your Daewoo dealer or Authorized Service Center (ASC) inspect your vehicle and determine if it is involved in this recall. If your Daewoo is involved in this recall, your dealer will replace the Camshaft Position Sensor and add an in-line fuse to the Camshaft Position Sensor wiring.

This service will be performed for you at no charge and should take about one hour. Thus, to minimize waiting time, you are advised to make an appointment with your Daewoo dealer or Authorized Service Center (ASC), in advance. If, however you take your vehicle to your Daewoo dealer or Authorized Service Center (ASC) on the scheduled service date and you have a problem with obtaining the corrective service on that date, please contact the Daewoo Customer Assistance Center toll-free at (877) 362-1234, option 6. A Daewoo representative will assist you with arranging prompt service for your vehicle.

The enclosed Owner Reply Card identifies your vehicle. Presenting the card at the time of your service will assist your Daewoo Dealer in completing this procedure in the shortest time possible. If you have sold or traded your vehicle, please let us know by completing the enclosed postage-paid reply card and returning it to us.

We apologize for any inconvenience this may cause you. We have taken this initiative in the interest of your safety and continued satisfaction with your Daewoo vehicle.

Sincerely,

Daewoo Customer Relations Department



DAEWOO

Daewoo Motor America, Inc.

1055 W. Victoria St.

Compton, CA 90220-9709

FIRST CLASS MAIL

**FIRST
FIRST CLASS
U.S. POSTAGE
PAID
Permit No. 328
Long Beach, CA**

IMPORTANT: SAFETY RECALL NOTICE