



DAEWOO MOTOR AMERICA, INC.
1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 225-0700 Fax: (310) 669-2000

SEP 28
OFFICE
DEFECTS INVE

September 28, 2004

BY OVERNIGHT COURIER

Ms. Kelly Schuler
Recall Management Division
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Kelly,

As requested, I am enclosing a copy of the "SECOND NOTICE" that has been distributed to Daewoo customers subject to Recall No. 02V-131 involving Lanos Passenger Air Bag Assembly Modification, which was requested by the NHTSA. R.L. Polk is handling the customer letter production and distribution elements of this recall renotification action for us and have advised that all customer letters were mailed as of September 27th. If you have any questions or need any additional information regarding this matter, please let me know.

Sincerely,

A handwritten signature in black ink, appearing to read "Ben Rainwater", is written over a white background.

Ben Rainwater
Vice President

Enclosure

cc: Ms. A. Cha
Mr. B. C. Jung



Daewoo Motor America, Inc.
1055 W. Victoria St.
Compton, CA 90220-8709

September 27, 2004

Recall Campaign No. 02V-131
Safety Recall: Lanos Passenger Air Bag Assembly Modification

SECOND NOTICE

Dear Lanos Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. We are writing as a follow-up to an earlier communication regarding this important subject. Our records indicate that you have not yet made your Daewoo Lanos available to your Daewoo Dealer or Authorized Service Center (ASC) allowing them to perform this important safety-related repair to the passenger air bag assembly.

Reason for This Recall: Daewoo Motor Company, Ltd. in Korea has decided that all 1998-2001 and specific 2002 Lanos models (VINs KLATC2261WB158465 - KLATA22612B708814) fail to conform to FMVSS 201 (Occupant Protection in Interior Impact). In the event of an accident in which the air bags do not deploy, there is a possibility of increased head injury to the front seat passenger should contact with the passenger side air bag cover occur.

What Will Be Done: To meet the FMVSS 201 requirement, Daewoo will install new energy absorbing air bag mounting brackets. This service will be performed for you at no charge.

How Long Will The Repair Take?: The actual length of time required to perform this air bag assembly modification is approximately one (1) hour. If your dealer has a large number of vehicles awaiting service, however, additional time will be required to process your vehicle. Please ask your Dealer how much time they will need to complete this procedure.

Contacting Your Dealer: Please contact your Daewoo Dealer as soon as possible to schedule a service date. Parts are available, and instructions for making this correction have been sent to your Dealer. Please ask your Dealer if you wish to know how much time will be needed to schedule, process and repair your vehicle. Your Daewoo Dealer is fully prepared and will provide this service as soon as possible. If, however, you take your vehicle to your Dealer on the scheduled service date and you have a problem obtaining the corrective service on that date, please contact the Daewoo Customer Assistance Center toll-free at (877) 362-1234, option 6. A Daewoo representative will assist you with arranging prompt service for your vehicle.

If you are the owner of the subject vehicle, but have leased it to another person, you are required by law to forward a copy of this notice to your lessee by first class mail within ten days of your receipt of this letter. See 49 C.F.R. 577.7(a)(2)(iv).

If after contacting the Dealer and the Daewoo Customer Assistance Center you are still not satisfied that we have done our best to remedy the condition without charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington D.C. 20590 or call (888) 327-4238.

Customer Reply Card: The enclosed Owner Reply Card identifies your vehicle. Presenting the card at the time of your service will assist your Daewoo Dealer in completing this procedure in the shortest time possible. If you have sold or traded your vehicle, please let us know by completing the enclosed postage-paid reply card and returning it to us.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

DAEWOO CUSTOMER RELATIONS DEPARTMENT

PLEASE RETAIN FOR YOUR RECORDS



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS MAIL PERMIT NO. 33 COMPTON, CA

POSTAGE WILL BE PAID BY ADDRESSEE

DAEWOO MOTOR AMERICA, INC.
1055 W VICTORIA ST
COMPTON, CA 90220-9709

