

AUTOCAR SAFETY RECALL A-0603 NHTSA RECALL 06V-167 May 2006

ATTENTION:	SERVICE MANAGERS / PARTS MANAGERS
SUBJECT:	Axilok Spindle Nut Tabs
VEHICLES AFFECTED:	Certain WX, WXR and WXLL 2006 model-year, heavy-duty Class 8 vehicles equipped with Hendrickson Lift Axles, shipped between November 9, 2004 and April 25, 2006 with serial numbers in the range 201463 through 203515.

SAFETY RECALL INFORMATION:

A defect that relating to motor vehicle safety may exist in certain WX, WXR and WXLL, heavy-duty Class 8 vehicles equipped with Hendrickson Lift Axles, shipped between November 9, 2004 and April 25, 2006 with serial numbers in the range 201463 through 203515.

On some of the affected vehicles, the tabs on some of the lift axle spindle nuts may have been broken during assembly. When in place, the tabs on the nuts prevent the nuts from loosening. When the tabs are broken, the possibility exists that the nut might spin off. If this happens, the wheel and wheel end assembly may separate from the axle. This separation could increase the risk of a crash.

NUMBER OF VEHICLES AFFECTED:

There are 250 affected vehicles.

NOTE: To determine whether a particular vehicle is affected by this recall (or any other recall), consult the Service/Warranty screen on www.autocartruck.com. Enter the VIN (Vehicle Identification Number) into the VIN Profile. Any open recalls for the vehicle will be displayed.

If a "Dealer Listing" is enclosed with this Bulletin, it identifies the affected vehicles that were sold or shipped to your dealership. Be sure to check the VIN Profile screen before performing the recall to verify that the recall is still open. If the recall has already been completed, the word "Completed" will be shown behind the recall number. The list of VINs on page 9 identifies the total suspect population of trucks.

REPAIR INSTRUCTIONS:

See detailed REPAIR PROCEDURE below.

TIME ALLOWANCE:

Inspection:	0.5 hours per wheel end
Replacement of Axilok spindle nuts:	1.0 hours per wheel end

RECALL PARTS:

Axilok nuts: AX-12-1500 (“D” Flat)

TOOLS REQUIRED:

- 6-point socket, sized according to the markings stamped on the face of the Axilok. Refer to Figure 1 and Table 1.
- Torque wrench
- Dial Indicator
- Breaker bar (for wheel nuts)
- 1 5/16 socket (wheel nuts)

CLAIMS FOR CREDIT:

The cost of this recall will be reimbursed based on the guidelines identified in this Bulletin. Submit a claim following the published instructions in the “Claim Preparation” section of the Service Operations Manual.

CLAIM CODING INFORMATION:

Authorization Number:	A-0603	
Inspection Labor code:	77318-0-04	1.0 hours
Repair Labor Code (LH hub):	77318-0-05	1.0 hours
Repair Labor Code (RH hub):	77318-0-06	1.0 hours

If associated wheel end components sustained damage due to the deformed tabs on the Axilok nut, standard Autocar repair procedures and repair times must be used to replace or repair the damaged components.

OWNER RECALL RESPONSE CARD:

The Owner Recall Response Card provides the vehicle owner with a convenient way to notify Autocar, LLC of changes in the ownership of the affected vehicles. The owner card is not intended for use by the dealer other than to assist you in the preparation of the repair orders necessary to perform the recall on the affected vehicle. Please do not use the card as a way to inform Autocar, LLC that the vehicle has been inspected or modified. Your claim on-line is sufficient.

DEALER RECALL RESPONSIBILITY:

Dealers must perform this recall on all affected vehicles at no charge to the owner regardless of mileage, age or ownership of such vehicles. If a vehicle affected by this recall is taken into or is in your vehicle inventory or at your dealership for service, you must perform this recall before the vehicle is sold or released to the owner.

NOTE: It is illegal to sell a vehicle from your inventory with any outstanding recalls.

REPAIR PROCEDURE:

WARNING

To prevent eye injury, always wear eye protection when performing vehicle maintenance, service or inspection.

DANGER


Before working on a vehicle, set the parking brake, place the transmission in neutral and block the wheels. Failure to do so can result in unexpected vehicle movement and can cause serious personal injury or death.

1. Turn the battery disconnect switch to the “OFF” position.
2. Follow this link for the Axilok installation instructions or see below
 - a. http://www.mfmvs.com/axilok_inst.html

Axilok

Unitized Wheel Bearing Nut System

Removal and Installation Procedures



Axilok Component View
FIGURE 1.

Removal Procedure


WARNING

Do not use chisel, hammer, or any power tool to remove the Axilok product.

Equipment Required

- 6-point socket, sized according to the markings stamped on the face of the Axilok. Refer to Figure 1 and Table 1.
- Torque wrench
- Dial Indicator

1. Install correct size 6-point socket completely over the hex of the Axilok. Be sure that both the locking clips are completely disengaged from the retainer cage, permitting free rotation. Refer to Figure 2.
2. Turn counterclockwise to remove Axilok. If Axilok does not move freely, stop removal. Check that the socket is completely and fully engaged on the Axilok and that the locking clips are fully retracted from the retainer cage slots. If Axilok still will not turn freely, rotate slightly clockwise, to tighten, and then loosen again. The nut should rotate counterclockwise freely.
3. Continue counterclockwise rotation until Axilok threads disengage from the spindle threads.



Checking Position of Locking Clip Tabs

FIGURE 2.

NOTE

Light burnishing of the retainer cage bearing surface after use is normal.

Pre-Installation Procedure

Before installing Axilok, check the following:

1. Inspect Axilok for two locking clips. Refer to Figure 1.

- Each locking clip should be securely fastened to the nut body and have a rivet that passes through the top of the locking clip body.
- Each locking clip should have a locking clip tab protruding completely through the retainer cage adjustment slot (when properly aligned and not compressed by a socket). Refer to Figures 2, 4 and 5.
- Locking clips should not be bent, cracked or broken.

2. Inspect Axilok retainer cage condition.

- There should be no cracks or other damage to the retainer cage.
- Retainer cage should be secured to the nut body and not fall off when the locking clips are compressed by the socket.
- The retainer cage tab or "D" flat should be free of damage, such as cracks, scarring, gouges, or distortion. Refer to Figure 7.

3. Inspect Axilok threads.

- The threads should show no signs of wear or damage.
- Wipe the threads to remove excess oil or debris.

4. If Axilok fails any of the checks above, the Axilok is unfit for use. DO NOT USE. Replace the unfit Axilok with a new Axilok, and repeat all checks.

5. Free Rotation Inspection. This test will check for nut and socket compatibility.


- With correct size 6-point socket turned upside down, insert Axilok completely into the socket, compressing locking clips.
- Retainer cage should spin freely with no interference between locking clip tabs and retainer cage.
- If locking clip tabs interfere with rotation of the retainer cage, the socket is not fully compressing the locking clips. This indicates that the socket is the incorrect size, worn, or out of specifications and must be replaced. Refer to Figure 2.

WARNING

Axilok may not be compatible with all axles currently in use. Do not use Axilok on an incompatible axle. Review appropriate manufacturer's bulletins for axles not compatible with Axilok. Inappropriate use could produce a "wheel off" condition, which may result in serious bodily injury and/or equipment failure. If Axilok has not been selected as standard equipment by the Original Equipment Manufacturer (OEM), do the following: Review axle manufacturer's bulletins to be sure axle is compatible with Axilok.

OR

Remove hub to fully expose spindle and its slot or "D" flat. Carefully measure the width and depth of the spindle slot or "D" flat at the outboard end of the spindle and at the last full thread of the slot or "D" flat. If the measurements are identical, Axilok may be used. If not, DO NOT use Axilok on this spindle. Use a conventional wheel nut retaining system. Refer to Figure 3.



Measuring Spindle Slot or "D" Flat


Figure 3

SAFETY RECALL BULLETIN




AXILOK	Socket Size 6-Point	Initial Torque (in foot-pounds)	Initial Backoff	Final Torque (in foot-pounds)	Final Backoff	Increments of Adjustment (Per slot)
AX-14-1000	2 1/8"	200	1/2 turn	75	1/8 turn	0.0032"
AX-12-1500D	2 1/8"	200	1/2 turn	75	1/8 turn	0.0038"
AX-18-1500	2 1/8"	200	1/2 turn	75	1/8 turn	0.0025"
AX-18-1500D	2 1/8"	200	1/2 turn	75	1/8 turn	0.0025"
AX-12-1750D	3 1/4"	200	1/2 turn	75	1/8 turn	0.0030"
AX-16-2500	3 1/4"	200	1/2 turn	75	1/8 turn	0.0022"
AX-12-2625	3 1/4"	200	1/2 turn	75	1/8 turn	0.0030"
AX-16-2625	3 1/4"	200	1/2 turn	75	1/8 turn	0.0022"
AX-12-3250	4"	200	1/2 turn	75	1/8 turn	0.0023"
AX-12-3480	4 1/8"	200	1/2 turn	75	1/8 turn	0.0023"
AX-12-3500	4 1/8"	200	1/2 turn	75	1/8 turn	0.0023"


TABLE 1.



Locking clip tabs broken
Figure 4



Improperly positioned locking clip tabs
Figure 5



Recommended End Play Range

Figure 6

Installation Procedure

NOTE

If installing Axilok on vehicles purchased from an OEM, with Axilok as original equipment, follow the OEM's specific installation instructions.

1. Before installation, perform pre-installation checks:

- Be sure the spindle slot is clean and free of burrs and foreign material before installing Axilok.
- Be sure the thread size is the same on both components.
- Put a few drops of oil through one of the retainer cage holes. This will ensure friction-free movement.

2. Put Axilok in the correct size 6-point socket (refer to Table 1) and verify that the locking clips are compressed. Refer to Figure 2. Retainer cage should spin freely.

3. Align Axilok retainer cage tab or "D" flat with spindle slot or "D" flat. Be sure to start and run down the Axilok by hand. Do not use power tools. Rotate the socket clockwise until contacting bearing.

- Do not overtorque. Refer to Table 1 for specific torque values.
- Rotate the socket clockwise until contacting bearing.

4. Using a properly calibrated torque wrench, torque Axilok to the initial torque of 200 ft. lbs. while rotating hub.

- Back off 1/2 turn.
- Tighten to final torque while rotating hub. Refer to Table 1.
- Back off 1/8 turn. This will provide end play. Refer to Figure 6.

5. Remove socket and verify locking clip tabs have engaged the adjustment slots in the retainer cage. Refer to Figures, 2, 4 and 5.

WARNING

If locking clip tabs do not protrude through the adjustment slots, rotate Axilok slightly clockwise. Refer to Figures 2, 4 and 5. If locking clip(s) are broken, replace Axilok and repeat installation procedures.

6. Measure end play using a dial indicator. If correct end play is not achieved, adjust according to Adjustment Increments shown in Table 1.

- Rotate Axilok clockwise to reduce end play. (Example: from .004" to .002" end play.)
- Rotate Axilok counterclockwise to increase end play. (Example: from .001" to .003" end play.)
- This same procedure can be used to achieve a controlled pre-load condition. (Example: from .001" end play to .001" pre-load.)

7. After end play adjustment, make sure that both locking clip tabs are protruding through the slots in the retainer cage. Refer to Figures 2, 4 and 5.

3. After verifying that the locking tabs are in place, check the oil level in the hubs and fill to the required level. The Axilok repair is now complete.

SAFETY RECALL BULLETIN



VIN Numbers:

5VCDC6MF55H201463	5VCDC6MF75H201464	5VCDC6MF95H201465	5VCDC6MF65H201505
5VCDC6MF85H201506	5VCDC6MFX5H201507	5VCDC6MF15H201508	5VCDC6PE95H201596
5VCDC6PE05H201597	5VCDC6PE25H201598	5VCDC6PE45H201599	5VCDC6PE75H201600
5VCDC6PE95H201601	5VCDC6PE05H201602	5VCDC6PE25H201603	5VCDC6PE45H201604
5VCDC6PE65H201605	5VCDC6PE85H201606	5VCDC6PEX5H201607	5VCDC6PE15H201608
5VCDC6PE35H201609	5VCDC6PEX5H201610	5VCDC6PE15H201611	5VCDC6PE35H201612
5VCDC6MF25H201615	5VCDC6MF85H201618	5VCDC6MFX5H201619	5VCDC6RE75H201660
5VCDC6RE95H201661	5VCDC6RE05H201662	5VCHC6MF45H201780	5VCHC6MF65H201781
5VCHC6MF85H201782	5VCDC6FE05H201861	5VCDC6FE25H201862	5VCDC6FE45H201863
5VCDC6MF15H201864	5VCDC6MF35H201865	5VCDC6MF55H201866	5VCDC6MF75H201867
5VCDC6MF95H201868	5VCDC6MF05H201869	5VCDC6MF75H201870	5VCDC6MF95H201871
5VCHC6MF45H201875	5VCHC6MF65H201876	5VCHC6MF95H201967	5VCHC6MF05H201968
5VCHC6MF25H201969	5VCHC6MF05H202019	5VCHC6MF75H202020	5VCHC6MF95H202021
5VCHC6MF05H202022	5VCHC6MF25H202023	5VCHC6MF45H202024	5VCDC6MF45H202071
5VCDC6MF65H202072	5VCDC6MF85H202073	5VCDC6MFX5H202074	5VCDC6MF96H202133
5VCDC6MF06H202134	5VCDC6MF26H202135	5VCDC6MF46H202136	5VCDC6MF66H202137
5VCDC6MF86H202138	5VCDC6MFX6H202139	5VCDC6MF66H202140	5VCDC6MF86H202141
5VCDC6MFX6H202142	5VCDC6MF35H202143	5VCDC6MF55H202144	5VCDC6MF75H202145
5VCDC6MF95H202146	5VCDC6MF05H202147	5VCDC6MF06H202246	5VCDC6MF26H202247
5VCDC6MF46H202248	5VCHC6MF46H202249	5VCDC6MFX6H202254	5VCDC6RE16H202255
5VCDC6MF36H202256	5VCDC6MF56H202257	5VCDC6MF76H202258	5VCDC6MF96H202259
5VCDC6MF56H202260	5VCHC6MF96H202263	5VCHC6MF06H202264	5VCDC6BE16H202265
5VCDC6MF66H202266	5VCHC6BE36H202267	5VCDC6MFX6H202268	5VCDC6MF96H202276
5VCDC6MF06H202277	5VCDC6MF26H202278	5VCDC6MF46H202279	5VCDC6MF06H202280
5VCDC6MF26H202281	5VCDC6MF46H202282	5VCHC6MF46H202283	5VCHC6MF66H202284
5VCHC6MF86H202285	5VCDC6MF76H202289	5VCDC6MF36H202290	5VCDC6MF56H202291
5VCDC6MF76H202292	5VCDC6MF96H202293	5VCDC6BE26H202307	5VCDC6BEX6H202314
5VCHC6MFX6H202322	5VCDC6MF36H202323	5VCDC6MF76H202325	5VCHC6MF76H202326
5VCDC6BE36H202350	5VCDC6BE56H202351	5VCDC6BE76H202352	5VCDC6MF16H202353
5VCHC6RE66H202382	5VCHC6RE86H202383	5VCHC6REX6H202384	5VCHC6RE16H202385
5VCHC6MF96H202425	5VCHC6MF06H202457	5VCDC6FE86H202600	5VCH36MFX6H202630
5VCH36MF96H202635	5VCHC6FE86H202680	5VCDC6MF06H202697	5VCDC6MF76H202731
5VCDC6MF96H202732	5VCDC6MF06H202733	5VCDC6MF26H202734	5VCDC6MF46H202735
5VCDC6MF66H202736	5VCDC6MF86H202737	5VCDC6MFX6H202738	5VCDC6MF16H202739
5VCDC6MF86H202740	5VCDC6MFX6H202741	5VCDC6MF16H202742	5VCDC6MF36H202743
5VCHC6MF96H202750	5VCHC6MF06H202751	5VCHC6MF26H202752	5VCDC6MF86H202785
5VCDC6MF86H202804	5VCDC6MFX6H202805	5VCDC6MF16H202806	5VCDC6MF36H202807
5VCDC6MF56H202808	5VCDC6MF76H202809	5VCDC6MF36H202810	5VCDC6MF56H202811
5VCDC6MF76H202812	5VCDC6MF16H202840	5VCDC6MF36H202841	5VCDC6MF56H202842
5VCDC6MF76H202843	5VCHC6MF76H202844	5VCHC6MF96H202845	5VCHC6MF06H202846
5VCHC6MF26H202847	5VCHC6MF46H202848	5VCHC6MF66H202849	5VCHC6MF26H202850
5VCDC6MF66H202851	5VCDC6MF86H202852	5VCDC6MFX6H202853	5VCDC6MF16H202854
5VCHC6MF66H202902	5VCHC6MF86H202903	5VCHC6MFX6H202904	5VCHC6MF16H202905
5VCHC6MF36H202906	5VCHC6MF56H202907	5VCDC6MF46H202962	5VCDC6MF66H202963
5VCDC6PE56H203007	5VCDC6PE76H203008	5VCDC6PE96H203009	5VCDC6PE56H203010
5VCDC6PE76H203011	5VCDC6PE96H203012	5VCDC6PE06H203013	5VCDC6PE26H203014
5VCDC6PE46H203015	5VCDC6PE66H203016	5VCDC6PE86H203017	5VCDC6PEX6H203018
5VCDC6PE16H203019	5VCDC6PE86H203020	5VCDC6PEX6H203021	5VCDC6PE16H203022
5VCDC6PE36H203023	5VCDC6PE56H203024	5VCDC6PE76H203025	5VCDC6PE96H203026
5VCDC6PE06H203027	5VCDC6PE26H203028	5VCDC6PE46H203029	5VCDC6PE06H203030
5VCDC6PE26H203031	5VCDC6PE46H203032	5VCDC6PE66H203033	5VCDC6PE86H203034
5VCDC6PEX6H203035	5VCDC6PE16H203036	5VCDC6PE36H203037	5VCDC6PE56H203038
5VCDC6MF16H203048	5VCDC6MF56H203151	5VCDC6MF76H203152	5VCDC6MF96H203153
5VCDC6RE86H203208	5VCDC6REX6H203209	5VCDC6RE66H203210	5VCDC6RE86H203211
5VCDC6REX6H203212	5VCDC6RE16H203213	5VCDC6RE36H203214	5VCDC6RE56H203215
5VCDC6RE76H203216	5VCDC6RE96H203217	5VCDC6RE06H203218	5VCDC6MF06H203252
5VCDC6BE76H203274	5VCDC6BE96H203275	5VCDC6BE06H203276	5VCDC6BE26H203277
5VCDC6BE46H203278	5VCDC6MF86H203287	5VCHC6PE36H203380	5VCDC6BEX6H203382
5VCDC6BE16H203383	5VCDC6BE36H203384	5VCDC6BE56H203386	5VCDC6BE76H203386
5VCHC6BFX6H203389	5VCHC6FE66H203391	5VCHC6FE86H203392	5VCHC6FEX6H203393
5VCDC6BEX6H203429	5VCDC6BE66H203430	5VCDC6BE76H203470	5VCDC6BE96H203471
5VCDC6BE06H203472	5VCDC6ME76H203482	5VCDC6BE46H203510	5VCDC6BE66H203511
5VCHC6BEX6H203514	5VCHC6BE16H203515		