



U.S. Department  
of Transportation

400 Seventh Street, SW  
Washington, DC 20590

**National Highway  
Traffic Safety  
Administration**

*December 1, 2006*

DIANE FAUS  
LEGAL AFFAIRS COORDINATOR  
DAMON MOTOR COACH  
52570 PAUL DRIVE  
ELKHART IN 46514

NVS-215paw  
06V-451

Subject: ENGINE FUEL RAIL CLIP FRACTURE/CHEVROLET/WORKHORSE

Dear MS. FAUS:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

DAMON/CHALLENGER/2004-2007  
DAMON/DAYBREAK/2004-2007  
DAMON/INTRUDER/2004-2007  
DAMON/OUTLAW/2004-2007

**NHTSA Campaign Number:** 06V-451

**Mfg's Report Date:** November 17, 2006

**Components:** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected:** 1,517

**Summary:**

ON CERTAIN MOTOR HOMES BUILT ON WORKHORSE CHASSIS AND EQUIPPED WITH GM 8.1L V8 ENGINES, IMPROPER HARDENING DURING THE HEAT TREATMENT PROCESS CAN CAUSE THE FUEL RAIL PULSE DAMPER RETAINER CLIP TO FRACTURE, RESULTING IN INADEQUATE RETENTION OF THE DAMPER. IF THE DAMPER BECOMES LOOSE, FUEL COULD BE PUMPED BY THE FUEL PUMP INTO THE UNDER HOOD AREA.

**Consequence:**

IN THE PRESENCE OF AN IGNITION SOURCE, A FIRE COULD RESULT.

**Remedy:**

CHEVROLET AND WORKHORSE ARE HANDLING THE OWNER NOTIFICATION AND REMEDY FOR THIS CAMPAIGN (PLEASE SEE 06V225 AND 06V289). DEALERS WILL REPLACE THE FUEL RAIL PULSE DAMPER RETAINER CLIPS ON THESE ENGINES FREE OF CHARGE. OWNERS MAY CONTACT CHEVROLET AT 1-800-630-2438, WORKHORSE AT 877-294-6773, OR DAMON AT 1-574-264-5517.

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, Chevrolet/Workhorse will be handling the owner notification, remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.5 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Chevrolet/Workhorse's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at [patricia.wallace@dot.gov](mailto:patricia.wallace@dot.gov) or [delia.lopez@dot.gov](mailto:delia.lopez@dot.gov). We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement