

March 2013
Safety Recall 12V-406
Bulletin SB13-04-S001

PRODUCT SAFETY RECALL

DRIVER DOOR SWITCH SHORT CIRCUIT 12V-406

To: All Isuzu, VP, and Corporate Service Staff

This letter is being sent to you to notify you of a Safety Recall – Driver Door Switch Short Circuit on certain Isuzu Ascender passenger vehicles.

Affected Vehicles:

- 2006-2007MY Isuzu Ascender Vehicles

Condition:

The manufacturer of the vehicle, General Motors, has decided that a defect, which relates to motor vehicle safety, exists in certain 2006-2007 Isuzu Ascender vehicles originally sold or currently registered in: Connecticut, Delaware, District of Columbia, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia and Wisconsin.

If fluid enters the driver's door module, it may cause corrosion that could result in a short in the circuit board. A short may cause the power door lock and power window switches to function intermittently or become inoperative. In rare cases, a short may cause overheating, which could melt components of the door module, producing odor, smoke, or a fire.

Correction:

Service Facilities are to test the driver's window and door lock switch for proper operation. If the switches function properly, Service Facilities are to inspect the module, and as necessary, install a protective coating. If the switches do not function properly, Service Facilities are to install a new door module.

Owner Notification:

OWNER NOTIFICATION WILL BEGIN MARCH 22, 2013