



YAMAHA MOTOR CORPORATION, U.S.A.

6555 KATELLA AVENUE, CYPRESS, CALIFORNIA 90630-5101 800-962-7926

JULY, 23, 2013

IMPORTANT SAFETY RECALL NOTICE

Dear Yamaha Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Yamaha Motor Corporation, U.S.A. has decided that a defect which relates to motor vehicle safety exists in certain 2014 XVS95CE/C ("BOLT") model motorcycles. Our records show that you own the affected motorcycle shown above.

The reason for this recall:

On affected motorcycles, there is a possibility that the wire harness is routed too close to the rear exhaust area where it can contact the rear exhaust header flange. If this happens, heat from the exhaust could damage the wire harness which could result in engine stalling and the possibility of a crash with injury or death.

What Yamaha and your dealer will do:

To correct this defect, your authorized Yamaha dealer will install two retaining bands to hold the wire harness away from the rear exhaust area after first inspecting to be sure the wire harness has not been damaged. Installing the new bands takes about 15 minutes after then engine has cooled. If the wire harness is damaged, it will require replacement, a procedure that takes about 90 minutes once your dealer has the new harness in stock. In either case, your dealer may need to keep your motorcycle longer depending upon their schedule. **There will be no charge to you for this procedure.**

What you should do now:

Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your motorcycle for this service. Remember to take this letter with you when you take in your motorcycle. **You should not ride your motorcycle until this modification is performed.**

If you are unable to return to the Yamaha dealer who sold you the motorcycle, this service will be performed by any authorized Yamaha Motorcycle dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha web site at: www.yamaha-motor.com.

If you have had this repair performed before you received this letter, you may be entitled to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this repair. For more information, contact Yamaha Customer Relations at 1-800-962-7926.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need help:

If, after contacting your dealership, you have questions or concerns which the dealership is unable to answer, please write to:

Yamaha Motor Corporation, U.S.A.
Customer Relations Department
P.O. Box 6555
Cypress CA 90630
or call 1-800-962-7926.

If, after contacting Yamaha Customer Relations, you are still not satisfied that we have done our best to remedy the situation without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this Yamaha:

If you have sold your motorcycle to another party, please call us toll-free at 1-800-962-7926 with the name and address of the new owner, along with the serial number shown to the right of your name and address above.

We're sorry to cause you any inconvenience, but we are sincerely concerned about your safety and continued satisfaction with our products. Thank you for giving your attention to this important matter.

Sincerely,

Customer Support Group
Yamaha Motor Corporation, U.S.A.