

TOYOTA

Updated 02/03/2015: 2005 Corolla and Corolla Matrix Part Number Added
Updated 02/03/2015: UIO Updated
Updated 01/07/2015: 2005 Sequoia & Tundra Part Number Added
Updated 11/19/2014: Hang Tag Part Number Added
Updated 11/13/2014: ASM Reference Guide Added and UIO Updated
Updated 10/27/2014: Op. Codes Added
Updated 10/22/2014: Part Ordering Section update to clarify correct part for corresponding location

Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

To: All Toyota Dealer Principals, Service Managers, and Parts Managers

Subject: **Safety Recall E04 – For Areas of High Absolute Humidity**
Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles
Certain 2002 – 2005 Model Year Sequoia Vehicles
Front Passenger Air Bag Inflator Module

This Safety Recall applies to owners of vehicles originally sold in or currently registered in areas of High Absolute Humidity, encompassing the following: Coastal Areas around the Gulf of Mexico for Texas, Alabama, Mississippi, Georgia, and Louisiana. In addition it will include Florida, Puerto Rico, Guam, Saipan, American Samoa, Virgin Islands and Hawaii.

On October 20, 2014 Toyota filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) informing the agency of our intent to conduct a voluntary Safety Recall on certain 2003-2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles and certain 2002 - 2005 Model Year Sequoia Vehicles.

Condition

The subject vehicles are equipped with front passenger air bag assemblies. When located in areas with consistently high absolute humidity, the front passenger air bag inflator could be susceptible to rupture and the front passenger air bag could deploy abnormally in a crash, increasing the risk of injury to the occupant. The cause of the potential ruptured inflators and influence of high absolute humidity are under investigation.

Remedy

Toyota has a limited amount of parts to support vehicle repairs at this time; therefore Toyota will be undertaking the following actions until parts become available in greater quantities.

Dealers are requested to replace the front passenger air bag inflator module at no charge to the vehicle owner. If the inflator module is not available dealership are requested to temporarily disable the front passenger air bag and install a glove box reminder hang tag.

The following information is provided to inform you of the owner notification timing and your degree of involvement.

1. Owner Letter Mailing

Toyota will be mailing all customers whose vehicles are covered by this Safety Recall in late October, 2014.

Toyota tries very hard to obtain current customer name and address information when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Safety Recall announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.

If a dealer is contacted by an owner who has not yet received the notification, please **verify coverage by confirming through TIS**. Dealers should perform the procedure as outlined in the Technical Instructions located on TIS.

2. Pre-Owned Vehicles in Dealer Stock

All vehicles in dealership stock that are covered by this Safety Recall must have the passenger air bag inflator replaced before customer delivery. If the passenger air bag assembly is not available, the vehicle must be held until the vehicle can be remedied.

3. Number and Identification of Covered Vehicles


There are approximately 325,650 Toyota vehicles covered by this Safety Recall. The majority of vehicles covered by this superseding Safety Recall were previously part of Safety Recall DSF or Limited Regional Safety Recall E0V.

If a dealer is contacted by an owner who has not yet received the notification, please **verify coverage by confirming through TIS**. Dealers should perform the procedure as outlined in the Technical Instructions located on TIS.

4. Campaign Special Service Tools

Dealerships will need to utilize the Special Service Tools provided for Safety Recall D0F. The special service tools were previously sent to your dealership on July 31, 2013.

These tools are needed when performing the front passenger air bag inflator module campaign. These tools **ARE NOT** available through normal parts or tools channels. There is a very limited supply of tools, but if additional tools are needed, contact your regional representative.

Name	Sample Image	Qty
Air Bag Mounting Bracket & hardware		1
Barcode Scanner		1

5. Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership associates involved in the recall process are required to successfully complete E-Learning course **SC13A**. To ensure that all vehicles have the repair performed correctly, technicians performing this repair must also complete **SC13B** and be certified to one or more of the following levels:

- **Toyota Expert - Electrical**
- **Master**
- **Master Diagnostic Technician (MDT)**

It is the dealership’s responsibility to select technicians with the above certification level or greater to perform this Safety Recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

6. Campaign Specific Part Associate E- Learning Training Requirement

The Air Bag Inflator Assembly being replaced during this campaign is a Class 9 Hazmat part. Therefore Parts Associates involved in this recall are required to complete E-Learning Module (**E2140** “Safety Recall D0F – Front Passenger Airbag Inflator” found on www.utodealer.com) This E-Learning module will explain the proper procedure for documenting and returning the Air Bag Inflator Assembly to TK Holdings Incorporated.

7. Shipping Information for Removed Inflator Assemblies

IMPORTANT: Do not deploy the removed inflator. The removed used inflator must be returned, within 1-2 business days after replacement directly to the manufacturer, TK Holdings Incorporated.

As the shipper, you are responsible for proper packing and document completion. The person packaging the inflator must have received hazardous material training per 49 CFR 172.702 (**EHM001** “HazmatU General Awareness Hazardous Materials Training” found on www.utodealer.com), and the training records must be on file at your dealership. The U.S. Department of Transportation will impose substantial fines and/or penalties on the shipper if the packaging, labeling, or documentation is not properly prepared and Customer Copy of OP 900PRP form is not kept on file for a minimum of 2 years.

Each dealer will need to document a unique dealer specific CCN number on the return shipment form. You can locate your dealer unique CCN number by logging into the following website.

<http://toyota-d0f.imagespm.info/>

Default Password “XXXXX”

In addition to the E-Learning module, a laminated “Campaign D0F – 48 State FEDEX Ground Shipment Preparation” aid was previously sent to your dealership when the D0F Remedy launched. Additional copies of the aid can be found on TIS and inside of each new parts box.

8. Glove Box Reminder Hang Tags

Your dealership will be sent a package of Glove Box Reminder Hang Tags; a sample is shown below for your reference.



Please ensure these are applied to any vehicle where the passenger air bag is temporarily disabled. Additional glove box reminder hang tags can be ordered from the Material Distribution Center.

MDC #	Description	Package Qty.
00411-INFTAG-ENG	Safety Recall E04 Glove Box Hang Tag - English	1 Package Includes 25 Tags
00411-INFTAG-SPN	Safety Recall E04 Glove Box Hang Tag - Spanish	1 Package Includes 25 Tags

(Parts Ordering Process Continued...)



Non SET and GST MAC Parts Ordering Process

To ensure parts availability these kits have been placed on Manual Allocation Control (MAC). The majority of repairs for this activity will be limited to SET and GST dealers; if you have a vehicle at your dealer applicable to E04 which requires repairs, please send an email to PQSS_MAC@Toyota.com with the following information:

- **Subject Line: E04 MAC Release Request (Dealer Code)**
- **Dealer Code**
- **VIN Number**
- **Part Number**
- **Order Reference Number**
- **Order Date**
- **Contact Person**

Once a representative confirms the information provided, the part will be released. If there is a concern regarding the information provided, a representative will contact your dealership.

Important Notes:

- ***Once you have placed your order DO NOT upgrade or change your order status.***
- ***Failure to provide the above information within 48 hours will result in an order cancellation.***

IMPORTANT PARTS ORDERING UPDATE


All Safety Recall, Service Campaign (SSC/LSC) and Customer Support Program (CSP) parts are eligible for the Monthly Parts Return Program. Please refer to PANT Bulletin 2011-087 for campaign parts that are currently returnable under the Monthly Parts Return Program and additional details.

10. Remedy Procedures

Please refer to TIS for Technical Instructions on inspection and repair.

Conduct all applicable, non-completed Safety Recall and Service Campaigns on the vehicle during the time of appointment.

11. Warranty Reimbursement Procedure



Model	Op. Code	Description	Flat Rate Hour
Tundra & Sequoia	AGGC7B	Replace Air Bag Inflator Module	1.2 hr/vehicle
Corolla & Matrix	AGGC7G	Replace Air Bag Inflator Module	0.9 hr/vehicle
Tundra & Sequoia Corolla & Matrix	AGGC9A	Disable Passenger Air Bag Assembly and Install Glove Box Reminder Hang Tag	0.3 hr/vehicle


- The flat rate times include 0.1 hours for administrative cost per unit for the dealership.
- The cost of Electrical Tape and Zip Ties can be claimed as sublet type “ZZ” at maximum of \$0.25 per vehicle under Op Code AGGC9A.
- A customer rental vehicle through the Toyota Rent-A-Car (TRAC) can be claimed under Op. Code AGGC7B and AGGC7G for a maximum of 120 days as sublet type “RT” if a customer refused passenger air bag disablement and requests repair only. Follow the Toyota Transportation Assistance Program (TTAP) guidelines.
- Towing can be claimed under Op. Code AGGC7B, AGGC7G, AGGC9A, and AGGC7W for a maximum of \$250 as sublet type “TW” in the event the customer requested vehicle pickup.

(Warranty Reimbursement Procedure Continued. . .)

In limited instances, a Sequoia vehicle may have an inflator utilizing a large retaining hex nut on the right side. These vehicles are not involved in this Safety Recall. **Refer to the Sequoia Technical Instructions Section VIII-2 for additional details.**

Model	Op. Code	Description	Flat Rate Hour
Sequoia (ONLY)	AGGC7W	Large Retaining Hex Nut Found Vehicle not Involved Under this Safety Recall (Refer to the Sequoia Technical Instructions Section VIII-2)	0.3 hr/vehicle

12. Campaign Designation Decoder



13. Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

14. Media Contacts

If you are a dealership associate and have any questions, please contact your District Service/Parts Manager. **In the event you are contacted by the News media**, it is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Cindy Knight (310) 468-2170 in Toyota Corporate Communications. (Please do not provide this number to customers.)

15. Customer Contacts

A FAQ is attached to help respond to any customer concerns. If the customer has any further questions, they are requested to contact the Toyota Customer Experience Center. The Toyota Customer Experience Center can be reached at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am to 4:00 pm Pacific Time.

Please note the attached FAQ is published on the www.Toyota.com website for customer viewing.

Please review this entire package with your Service and Parts staff to familiarize them with the proper step-by-step procedures required to implement this Safety Recall.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.



Safety Recall E04 – For Areas of High Absolute Humidity

Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles

Certain 2002 – 2005 Model Year Sequoia Vehicles

Front Passenger Air Bag Inflator Module

Customer Frequently Asked Questions

Published late October, 2014

This Safety Recall applies to owners of vehicles originally sold or currently registered in areas of High Absolute Humidity, encompassing the following: Coastal Areas around the Gulf of Mexico for Texas, Alabama, Mississippi, Georgia, and Louisiana. In addition it will include Florida, Puerto Rico, Guam, Saipan, American Samoa, Virgin Islands and Hawaii.

We at Toyota care greatly about your safety. We are providing the following information to keep you informed of the details specific to this recall. Please check back frequently as this document will be updated.

Q1: What is the condition?

A1: The subject vehicles are equipped with front passenger air bag assemblies. When located in areas with consistently high absolute humidity, the front passenger air bag inflator could be susceptible to rupture and the front passenger air bag could deploy abnormally in a crash, increasing the risk of injury to the occupant. The cause of the potential ruptured inflators and influence of high absolute humidity are under investigation.

Q1a: What is the Inflator?

A1a: The inflator is a device contained within the air bag assembly. It contains a solid propellant wafer which is ignited in the event air bag deployment is necessary. When ignited, the wafer expands into an inert gas, inflating the air bag.

Q1b: What is the cause of this condition?

A1b: The cause of the potential ruptured inflators and influence of high absolute humidity are under investigation.

Q1c: What is absolute humidity?

A1c: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity.

Q1d: How is humidity related to the condition?

A1d: The specific relationship of humidity to the operation of the inflator and the cause of improper air bag inflator performance and rupture is still under investigation.

Q2: What is Toyota going to do?

A2: Owners of vehicles covered by this Safety Recall will begin receiving notification by first class mail in late October, 2014.

Toyota Dealers are requested to replace the front passenger air bag inflator module at **no charge** to the vehicle owner. If the inflator module is not available, dealerships are requested to temporarily disable the front passenger air bag and install a glove box reminder hang tag.

Q3: Are there any warnings that this condition exists?

A3: No. There are no warnings that this condition exists. However, the condition does not cause the air bag to activate when it should not. Also, the front passenger air bag is designed to inflate only in certain moderate to severe crashes.

Q4: What should you do?

A4: Toyota strongly recommends that you have this Safety Recall remedy performed immediately. Please contact any authorized Toyota dealer to schedule an appointment. When taking your vehicle to the dealership for your service appointment, it is recommended that only the driver occupy the vehicle. If you are uncomfortable driving the vehicle to the dealership, please contact your local authorized Toyota dealer who will arrange for vehicle pick up. Until the remedy is performed, the front passenger seat should NOT be occupied.

If you do not follow the instructions in the owner letter, you should not drive your vehicle.

Q5: If the Front Passenger Air Bag is disabled, will other Supplemental Restraints Systems be functional?

A5: If the vehicle does not have any concerns with supplemental restraint systems at the time of front passenger Air Bag disablement, all other supplemental restraint systems will remain fully functional. An onboard diagnostic system check will be performed to confirm Supplemental Restraint System (SRS) health at the time the dealer performs that temporary disablement of the passenger air bag assembly. After the dealer has disabled the front passenger air bag assembly, the SRS warning lamp will remain illuminated at all times until the recall campaign is completed.

Q6: Are there concerns with other Air Bags in the vehicle.

A6: No, this condition only applies to the front passenger air bag inflator module. Other air bags in the vehicle are not affected by this condition.

Q7: How is this Safety Recall related to other actions Toyota has taken regarding Takata Front Passenger Air Bag Inflator modules?

A7: In April 2013 Toyota announced a nationwide Safety Recall to inspect and, as necessary, replace front passenger air bag inflator modules. In June 2014, the recall remedy was revised to replace all inflators regardless of inspection results. In cooperation with NHTSA, Toyota also launched a Limited Regional Recall for an expanded model year range for certain areas with high levels of humidity to study the correlation to high humidity. As part of these actions, Toyota recovered air bag inflators for further investigations by Takata. These investigations have found that some inflators from South Florida performed improperly during testing. The geographic concentration of inflators with abnormal performance in areas with consistently high absolute humidity warrants priority replacement in these areas. Therefore, Toyota has launched this superseding recall for these areas.

Q8: Are all vehicle involved in the previous Takata Front Passenger Inflator Module Recall Actions covered by this Safety Recall?

A8: No, this Safety Recall applies to owners of vehicles originally sold in or currently registered in areas of High Absolute Humidity, encompassing the following: Coastal Areas around the Gulf of Mexico for Texas, Alabama, Mississippi, Georgia, and Louisiana. In addition it will include Florida, Puerto Rico, Guam, Saipan, American Samoa, Virgin Islands and Hawaii.

Q9: Which and how many vehicles are covered by this Safety Recall?

A9: There are approximately 325,650 Toyota vehicles covered by this Safety Recall. The majority of vehicles covered by this superseding Safety Recall were previously part of Safety Recall DSF or Limited Regional Safety Recall E0V.

Model	Model Year	Appx. UIO	Production Range
Corolla	2003 – 2005	198,450	Late December, 2001 through Late December, 2004
Corolla Matrix	2003 – 2005	37,700	Early January, 2002 through Late December, 2004
Tundra	2003 – 2005	52,250	Late July, 2002 through Late December, 2004
Sequoia	2002 – 2005	37,250	Early April, 2002 through Late December, 2004

Q9a: Are there any other Lexus/Toyota/Scion vehicles covered by this Safety Recall in the U.S.?

A9a: Yes. There are approximately 14,700 SC430 vehicles (certain 2002-2005 MY) covered by this Safety Recall in the US.

Q10: How does Toyota obtain my mailing information?

A10: Toyota uses an industry provider who works with each state's Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q11: Do I need my owner letter to have the remedy performed?

A11: You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

Q12: What if I previously paid for repairs to my vehicle for this condition?

A12: Reimbursement consideration instruction will be provided in the remedy owner letter.

Q13: What if I have additional questions or concerns?

A13: If you have additional questions or concerns, please contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am to 4:00 pm Pacific Time.



Safety Recall D0F/DSF(D3F)/E0V(E1V)/E04 - Supplemental ASM Reference
2003 - Certain 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles
2002 - Early 2005 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module



The following information is being provided to help dealership associates understand the differences between the multiple Takata actions Toyota has announced.

Safety Recall Overview:

In April 2013, Toyota announced a nationwide Safety Recall (D0F) to inspect and, as necessary, replace front passenger air bag inflator modules manufactured for Toyota by Takata Corporation. In June 2014, the recall remedy was revised to replace all inflators regardless of inspection results. The revision of the remedy was announced as a new Safety Recall DSF (D3F). All vehicles that did not receive a replacement inflator under D0F were included in DSF (D3F).

Safety Recall
DSF (D3F)
Nationwide

In cooperation with NHTSA, Toyota also launched in June 2014, a Limited Regional Recall E0V (E1V) covering an expanded model year range for certain areas with high levels of absolute humidity to study the possible correlation of abnormal inflator deployment to environmental factors. As part of these actions, Toyota recovered air bag inflators for further investigations by Takata. Testing found some inflators from South Florida to perform abnormally during deployment.

~~Safety Recall
E0V (E1V)
Regional~~

Not Active – Superseded by E04

The geographic concentration of inflators with abnormal performance in areas with consistently high absolute humidity warranted priority replacement in these areas. Therefore, Toyota has launched superseding Safety Recall (E04) which involves vehicles originally sold in or currently registered in areas that are exposed to consistent High Absolute Humidity encompassing the Gulf Coastal and island areas. These vehicles were previously included in Safety Recalls D0F/DSF and E0V.

Safety Recall
E04
Regional


The map below provides a visual representation of the areas which have been included in Superseding Safety Recall E04 (Red Area). The yellow portion of the map represents an approximate geographic representation of vehicles covered by Safety Recall DSF (D3F).

Safety Recall DSF:

- 2003-2004 Corolla
- 2003-2004 Corolla Matrix
- 2003-2004 Tundra
- 2002-2003 Sequoia

Safety Recall E04:

- 2003-2005 Corolla
- 2003-2005 Corolla Matrix
- 2003-2005 Tundra
- 2002-2005 Sequoia



Legend

 = DSF (D3F)

 = E04

Note: This map is provided for reference purposes only. The inclusion of vehicles in Safety Recall E04 and DSF (D3F) may differ from the visual representation shown on the map. Always verify vehicle campaign applicability using the Technical Information System (TIS).

Q1: Is the remedy different between DSF and E04?

A1: No, all vehicles involved in DSF and E04 will receive a replacement passenger Air Bag Inflator as parts become available. At this time Toyota has a limited number of inflators; therefore, we are first focusing on the E04 area, because testing of some recovered inflators from South Florida experienced abnormal performance. In the event parts are not available, Toyota is also offering passenger airbag disablement for the areas covered in E04 only.

Q2: Why is Toyota offering Passenger Air Bag Disablement only for vehicles in Superseding Safety Recall E04?

A2: At this time, Toyota has a very limited supply of replacement air bag inflators which are being sent to the E04 areas to assist customers there. We are offering customers in these areas a temporary option to have their passenger air bag inflator disabled.

Airbag disablement is an extraordinary measure and only is being offered in the E04 areas as a “short term” solution when parts are not available. The National Highway Traffic Safety Administration (NHTSA) has granted Toyota permission to temporarily disable airbags only in these areas, but no others.

Q3: Which vehicles from Safety Recall DSF (D3F) are now covered by Superseding Safety Recall E04?

A3: Approximately 145,150 vehicles originally involved in DSF (D3F) are now involved in Superseding Safety Recall E04. Vehicle transferred to E04 were originally sold in or currently registered in areas of High Absolute Humidity, encompassing the following: Coastal Areas around the Gulf of Mexico for Texas, Alabama, Mississippi, Georgia, and Louisiana. In addition it will include Florida, Puerto Rico, Guam, Saipan, American Samoa, Virgin Islands and Hawaii.

Q4: When does Toyota anticipate the remedy will be available?

A4: Toyota is currently working on obtaining the remedy parts for this Safety Recall. The expected parts availability date for locations beyond the E04 areas is early next year.

Q5: What is absolute humidity?

A5: The measure of the water vapor content in the air is known as absolute humidity, and it is displayed in grams of water vapor per cubic meter of air. Higher temperature, southern coastal-type climates consistently experience the greatest concentrations of water vapor in the air, as warmer ambient air can hold more water.

Note: relative humidity is simply a percentage value and is related to current or measured temperature; therefore, areas with high relative humidity do not necessarily have high absolute humidity.

Certain 2003-2005 Model Year Corolla, Corolla Matrix, and Tundra and
Certain 2002 - 2005 Model Year Sequoia Vehicles
Front Passenger Airbag Inflator Module

SAFETY RECALL NOTICE

This notice applies to your vehicle [VIN]

URGENT SAFETY RECALL

This is an important Safety Recall.
The remedy will be performed at
NO CHARGE to you.

[VIN]

Dear Toyota Owner:

Toyota strongly recommends that you have this Safety Recall remedy performed immediately. If you do not follow the instructions in this letter, you should not drive your vehicle.

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2003 - 2005 Model Year Corolla, Corolla Matrix, Tundra, and certain 2002 – 2005 Model Year Sequoia vehicles.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

What is the Condition?

The subject vehicles are equipped with front passenger air bag assemblies. When operated in areas with consistently high absolute humidity, the front passenger air bag inflator could be susceptible to rupture and the front passenger air bag could deploy abnormally in a crash, increasing the risk of injury to the occupant.

What will Toyota do?

Any authorized Toyota dealer will replace the front passenger inflator assembly at **no charge** to you.

In the event a front passenger inflator assembly is not available, at the time of vehicle service, the dealer will follow procedures to temporarily disable the front passenger air bag assembly. In addition the dealer will install a glove box hang tag informing occupants that the front passenger seat should not be occupied until the front passenger inflator assembly is replaced and the airbag is fully functional.

What should you do?

This is an important Safety Recall

Toyota strongly recommends that you have this remedy performed immediately. Please contact any authorized Toyota dealer to schedule an appointment. When taking your vehicle to the dealership for your service appointment it is recommended that only the driver occupy the vehicle. If you are uncomfortable driving the vehicle to the dealership, please contact your local authorized Toyota dealer who will arrange for vehicle pick up. Until the remedy is performed, the front passenger seat should NOT be occupied.

The repair will take approximately 2 hours. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

If you would like to update your vehicle ownership or contact information, you may do so by registering at www.toyota.com/ownersupdate. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

What if you have other questions?

- ***Your local Toyota dealer will be more than happy to answer any of your questions and set up an appointment to perform the repair.***
- You can find additional information and locate a Toyota dealer in your area by going online and visiting www.toyota.com/recall.
- If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, Saturday 7:00 am through 4:00 pm Pacific Time.

If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

What if you have previously paid for repairs to your vehicle for this specific condition?

If you have previously paid for repair to your vehicle for this specific condition prior to receiving this letter, please mail a copy of your repair order, proof-of-payment and proof-of-ownership to the following address for reimbursement consideration:

Toyota Motor Sales, U.S.A., Inc
Toyota Customer Experience, WC 10
19001 South Western Avenue
Torrance, CA 90509

Please note that the dealer must complete the Safety Recall remedy before reimbursement consideration requests can be processed.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,
TOYOTA MOTOR SALES, U.S.A., INC.

SAMPLE