



«Owner\_name»  
«Street»  
«City», «State» «Zip»  
«Country»

This notice applies to your vehicle: «VIN»

Dear «Owner\_name»:

You recently received the attached Safety Recall Notice and it has been determined that this recall does not apply to the following models: Coleman 2015 CM295QBSWE and Aspen Trail 2015-2016 AT2720RKSWE, AT2780RLSWE, AT2810BHSWE, because it is equipped with 10" 6 bolt hubs and the recall only applies to 10" 5 bolt hubs. The recall for your vehicle has been closed in our system and no further action is needed on your part.

We apologize for any inconvenience this action may have caused you and your safety and continued satisfaction are of the utmost importance to us.

Sincerely,

**KEYSTONE RV COMPANY**

Rick Deisler  
Sales & Service Manager



**Keystone RV  
Company**

**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

Safety Recall: 15V-207  
Safety Advisory: 15-230  
June 29, 2015

**IMPORTANT SAFETY RECALL**

«Owner\_name»  
«Street»  
«City», «State» «Zip»

This notice applies to your vehicle: «VIN»

Dear «Owner\_name»:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model «Yr\_Model\_Type». As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided the vehicles identified in this recall population equipped with axles manufactured by Lippert Components Inc. (LCI) and Tru Ryde or Axle Tek 10" or 12" wheel hubs may have been manufactured with wheel studs which could break. If more than one wheel stud breaks and the vehicle is in motion, it could result in the separation of the wheel from the vehicle leading to an increased risk of property damage and/or vehicle crash.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect the wheel hubs and replace if necessary. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 3 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

Rick Deisler  
Sales & Service Manager  
cc: National Highway Traffic Safety Administration (NHTSA)

