



Service Bulletin

SB-10057653-4981



SERVICE UPDATE

SUBJECT: Service Update for Inventory and Customer Vehicles
Accessory Drive Idler Pulley Failure
Expires with Base Warranty

MODELS: 2015 Chevrolet Camaro
Equipped with V8 Engine (L99/LS3/LSA/LS7)
2015 Chevrolet Silverado
2015 GMC Sierra
Equipped with V6 Engine (LV3)

This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

PURPOSE

This bulletin provides a service procedure to replace the accessory drive idler pulley on certain 2015 model year Chevrolet Camaro vehicles equipped with a V8 engine (L99/LS3/LSA/LS7) and certain 2015 model year Chevrolet Silverado and GMC Sierra vehicles equipped with a V6 engine (LV3). A supplier manufacturing defect may exist in the idler pulley on these vehicles. If the defect exists, the customer may experience noise from the bearing. If the vehicle is not repaired and the vehicle continues to be driven, the pulley bearing may fail and the alternator and water pump may stop working, resulting in a malfunction indicator lamp (MIL) light for loss of charging and a possible MIL light for overheating.

This service procedure should be completed as soon as possible on involved vehicles currently in dealer inventory and customer vehicles that return to the dealer for any type of service during the New Vehicle Limited Warranty coverage period.

VEHICLES INVOLVED

All involved vehicles are identified by VIN in the Global Warranty Management System – Investigate Vehicle History Application. Dealership technicians should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.


Additionally, a list of involved vehicles currently in dealer inventory is available on the “Service Update Bulletin Information” link under the “Service” tab in GM GlobalConnect (US) or attached to the GlobalConnect message (Canada) used to release this bulletin. Customer vehicles that return for service, for any reason, and are still covered under the vehicle's base warranty should also be checked for vehicle eligibility.

PART INFORMATION

Parts required to complete this service update are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your “involved vehicles listing” before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
12629519	Pulley Assembly-Belt Idler	LSA, LS7, LV3, QTY: 1 LS3, L99 QTY: 2

SERVICE PROCEDURE



4063612

Note: Remove and replace both drive belt idler pulleys on engines with RPOs LS3 and L99. Refer to the photograph above to determine the location of the drive belt idler pulley(s).

1. Remove the drive belt idler pulley. Refer to *Drive Belt Idler Pulley Replacement* in SI.
2. Install a new drive belt idler pulley. Refer to *Drive Belt Idler Pulley Replacement* in SI.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9101236	Drive Belt Idler Pulley Replacement	0.8
	Add: LS3, L99	0.2

DEALER PROGRAM RESPONSIBILITY

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

