

## SB-10056462-9689

**FORD:**

2014 Explorer, Flex, Taurus

**LINCOLN:**

2014 MKS, MKT

**ISSUE**

Some 2014 Explorer, Flex, MKT, MKS, and Taurus vehicles equipped with a 3.5L Gasoline Turbocharged Direct Injection (GTDI) engine and built on or before 2/20/2014 may exhibit a raw fuel-type odor that is most noticeable near the intake manifold.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

1. Remove the intake manifold. Refer to Workshop Manual (WSM), Section 303-01.
2. Replace the high-pressure fuel tube. Refer to WSM, Section 303-04.
  - a. It is not necessary to remove the fuel injection pump to perform this procedure.
3. Install the intake manifold. Refer to WSM, Section 303-01.

PART NUMBER	PART NAME
AA5Z-9J323-E	High-Pressure Fuel Tube Assembly
AA5Z-9439-A	Intake Gasket Set (Includes 6)
7T4Z-9439-D	Gasket - Intake Manifold
AA5Z-9439-BA	Gasket - Intake Manifold
VC-3-B	Motorcraft® Orange Antifreeze/Coolant Concentrated

OPERATION	DESCRIPTION	TIME
140091A	2014 MKS And Taurus 3.5L GTDI: Replace The High-Pressure Fuel Tube (Do Not Use With Any Other Labor Operations)	2.5 Hrs.
140091A	2014 Explorer 3.5L GTDI: Replace The High-Pressure Fuel Tube (Do Not Use With Any Other Labor Operations)	2.6 Hrs.
140091A	2014 Flex And MKT 3.5L GTDI: Replace The High-Pressure Fuel Tube (Do Not Use With Any Other Labor Operations)	2.7 Hrs.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage  
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
9J323	D8

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.