

1.6L TI-VCT - MIL ILLUMINATED - DIAGNOSTIC TROUBLE CODE (DTC)
P0627 - NO DRIVABILITY SYMPTOMS - BUILT ON 4/1/2014 AND
THROUGH 7/31/2014

TSB 14-0170

FORD:

2014-2015 Fiesta

SB-10056712-7631

ISSUE

Some 2014-2015 Fiesta vehicles equipped with a 1.6L Twin independent-Variable Cam Timing (Ti-VCT) engine and built on 4/1/2014 and through 7/31/2014 may exhibit a malfunction indicator lamp (MIL) illuminated with DTC P0627 present and no drivability symptoms.

ACTION

Follow the Service Procedure to correct the condition.

SERVICE PROCEDURE

Replace the fuel pump driver module (FPDM). Refer to Workshop Manual (WSM), Section 303-04B.

PART NUMBER	PART NAME
AU5Z-9D370-P	Fuel Pump Driver Module
W700883-S424	Screw (4 Required)

OPERATION	DESCRIPTION	TIME
140170A	2014-2015 Fiesta 1.6L Ti-VCT: Retrieve DTCs And Replace The FPDM (Do Not Use With Any Other Labor Operations)	1.0 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are
determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
9D370	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.