



# RECALL CAMPAIGN BULLETIN

Reference:

NTB16-011a

Date:

March 23, 2016

## VOLUNTARY SAFETY RECALL CAMPAIGN 2013 - 2015 ALTIMA; HOOD LOCK ASSEMBLY REPLACEMENT

This bulletin has been amended. Additional images have been added to page 2.  
Please discard previous versions of this bulletin.

**CAMPAIGN ID #:** PC426

**APPLIED VEHICLES:** 2013 – 2015 Altima Sedan (L33)

**Check Service COMM to confirm campaign eligibility.**

### INTRODUCTION

Nissan is conducting a Voluntary Safety Recall Campaign on certain specific Model Year 2013 - 2015 Altima vehicles to replace the hood lock assembly. This service will be performed at no charge for parts or labor.

### IDENTIFICATION NUMBER

Nissan has assigned identification number PC426 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

### DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service Comm for the campaign status on each vehicle falling within the range of this voluntary safety recall campaign which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## SERVICE PROCEDURE

1. Replace the hood lock assembly.

- Refer to the Electronic Service Manual (ESM), section **DLK-DOOR & LOCK**, for replacement information.




Figure 1

**IMPORTANT:** When disconnecting the plastic cable stop from the hood lock assembly, gently pry it from beneath with a flat blade screw driver (see Figure 2).




Figure 2

2. After the new hood lock assembly is installed, completely close and latch the hood.

3. Open the hood using the hood lock release handle.



Figure 3

4. Gently pull the hood up to confirm that the secondary hood latch holds the hood from opening.

5. Again, completely close and latch the hood.



Figure 4

**PARTS INFORMATION**

DESCRIPTION	PART #	QUANTITY
Hood Lock Assembly <b>With</b> Remote Engine Start (RES)	65601-9HP0D	1
Hood Lock Assembly <b>Without</b> Remote Engine Start (RES)	65601-9HP1D	

**CLAIMS INFORMATION**

Submit a “CM” line claim using the following claims coding:

CAMPAIGN (“CM”) I.D.	DESCRIPTION	OP CODE	FRT
PC426	Replace Hood Lock Assembly	PC4260	0.3 hrs.

