Leonard M. Dainski@US_GM_DET_RN101, Jack W. Diesing@GMAC, Booker Wright@GM, Christine M. Witz/US/GM/GMC@GM, Marilyn Parker@US_GRM_TRSC, ella.pfeiffer@eds.com, Tom Geve@US_GM_DET_RN101, Robert E. Drozz/US/GM/GMC@GM, THOMAS W HASKINS@US_GM_SATURN, Vernon J. Stolte@GMAC, FCN Team/US/GM/GMC@GM, Jim Colyer@US_GM_PON_POC01, Karen D. Raab@US_GM_PON_POC01, Karen A. Grimaldi/US/GM/GMC@GM

99V-193

GM SERVICE OPERATIONS
DC8535
URGENT - DISTRIBUTE IMMEDIATELY

DATE: May 24,2000

SUBJECT: 99041 - PRODUCT SAFETY CAMPAIGN
INCORRECT FRONT AXLE STATUS SIGNAL TO
EBC4 ABS (PHASE 1)

MODELS: 1991-1996 CHEVROLET AND GMC 4WD T UTILITIES
1994-1996 CHEVROLET AND GMC 4WD T PICKUP TRUCKS

TO: ALL CHEVROLET AND GMC DEALERS

ATTN: PARTS MANAGER, SERVICE MANAGER AND WARRANTY ADMINISTRATOR

****
DUE TO THE AVAILABILITY OF PARTS, THIS CAMPAIGN WILL BE ADMINISTERED IN PHASES. YOU WILL RECEIVE A DEALER LISTING AS PHASES ARE RELEASED.
****

CONDITION

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 1991-1996 Chevrolet and GMC 4WD T utilities and 1994-1996 Chevrolet and GMC 4WD T pickup trucks. Some of these vehicles exhibit a condition in which a switch that signals the antilock brake system (ABS) module when the vehicle is in four-wheel drive (4WD) may malfunction. The ABS module is designed with two different operating algorithms: one for two-wheel drive (2WD) operation and another for 4WD drive operation. This allows the ABS system to compensate for the braking torque applied to the rear wheels through the drivetrain when the vehicle is in 4WD drive. When the vehicle is in 2WD, a malfunctioning switch may send an incorrect signal to the ABS module. If this occurs during an ABS stop, a somewhat longer stopping distance could result. If this occurred when minimum stopping distance was required, it could result in a vehicle crash.

CORRECTION

Dealers are to install a new transfer case selector switch, wiring harness, and an additional switch to ensure that the ABS receives the 4WD signal only when the drivetrain is in 4WD.

VEHICLES INVOLVED

Involved are certain 1991-1996 Chevrolet and GMC 4WD T utilities and 1994-1996 Chevrolet and GMC 4WD T pickup trucks built within these VIN breakpoints:

YEAR	DIVISION	MODEL	PLANT	FROM	THROUGH
1991	GMC	T Utility	Moraine	M2500005	M2561399
1992	GMC	T Utility	Moraine	N2500001	N2539169
1992	GMC	T Utility	Shreveport	N8500002	N8500002
1992	GMC	T Utility	Pontiac West	N0500002	N0519368
1993	GMC	T Utility	Moraine	P2500002	P2543249
1993	GMC	T Utility	Pontiac West	P0500007	P0528015
1994	GMC	T Utility	Moraine	R2500002	R2527917
1994	GMC	T Utility	Pontiac West	R0500001	R0535325
1995	GMC	T Utility	Moraine	S2500001	S2559899
1995	GMC	T Utility	Linden	SK500001	SK545839
1996	GMC	T Utility	Moraine	T2500001	T2580013
1996	GMC	T Utility	Linden	TK500001	TK532448
1994	GMC	T Pickup	Shreveport	R8500040	R8533971
1994	GMC	T Pickup	Linden	RK500006	RK525917
1995	GMC	T Pickup	Shreveport	S8500003	S8541052
1995	GMC	T Pickup	Linden	SK500022	SK545837
1996	GMC	T Pickup	Shreveport	T8500001	T8536619
1996	GMC	T Pickup	Linden	TK500013	TK531877
1991	Chevrolet	T Utility	Moraine	M2100006	M2325893
1992	Chevrolet	T Utility	Moraine	N2100002	N2326379
1992	Chevrolet	T Utility	Shreveport	N8100004	N8100010
1992	Chevrolet	T Utility	Pontiac West	N0100004	N0161853
1993	Chevrolet	T Utility	Moraine	P2100001	P2218436
1993	Chevrolet	T Utility	Pontiac West	P0100002	P0196997
1994	Chevrolet	T Utility	Moraine	R2100004	R2179415
1994	Chevrolet	T Utility	Pontiac West	R0100001	R0184857
1995	Chevrolet	T Utility	Moraine	S2100001	S2266694
1995	Chevrolet	T Utility	Linden	SK100004	SK263006
1996	Chevrolet	T Utility	Moraine	T2100004	T2318776
1996	Chevrolet	T Utility	Linden	TK100006	TK240985
1994	Chevrolet	T Pickup	Shreveport	R8100011	R8243089
1994	Chevrolet	T Pickup	Linden	RK100001	RK183770
1995	Chevrolet	T Pickup	Shreveport	S8100002	S8266172
1995	Chevrolet	T Pickup	Linden	SK100038	SK262978
1996	Chevrolet	T Pickup	Shreveport	T8100002	T8232042
1996	Chevrolet	T Pickup	Linden	TK100019	TK239494

IMPORTANT: Dealers should confirm vehicle eligibility through GMVIS (GM Vehicle Inquiry System) or GM Access Screen (Canada only) or DCS Screen 445 (IPC only) before beginning campaign repairs. [Not all vehicles within the above breakpoints may be involved.]

MAILING INFORMATION

The mailing of the dealer bulletin will begin on May 24, 2000. Owner letters for phase 1 will be mailed on May 31, 2000.

GM VIS INFORMATION

GM VIS information will be available May 25, 2000.

End Of Message

GM Service Operations

GM SERVICE OPERATIONS
DCS895
URGENT - DISTRIBUTE IMMEDIATELY

99V-193

DATE: JANUARY 24, 2002

SUBJECT: 99041 - PRODUCT CAMPAIGN OWNER RENOTIFICATION

TO: ALL CHEVROLET AND GMC DEALERS

ATTN: SERVICE MANAGERS, PARTS MANAGERS, AND WARRANTY ADMINISTRATORS

General Motors Recall Information System (GMRIS) will be sending out an additional owner notification on the following campaign:

99041 - PRODUCT SAFETY CAMPAIGN
INCORRECT FRONT AXLE STATUS SIGNAL TO EBC4 ABS
1991-1996 CHEVROLET AND GMC 4WD T UTILITIES
1994-1996 CHEVROLET AND GMC 4WD T PICKUP TRUCKS

Original Release Date - May 25, 2000
Scheduled Starting Remail Date - January 24, 2002

For a copy of these owner letters please refer to the campaign bulletin.

The intent of this remailing is to increase the completion rate of this recall.

End Of Message

GM Service Operations