BLIS/CTA SYSTEM FAULT WARNING - DTCS U049A:86 OR U0501:86 - BUILT ON OR BEFORE 12/3/2012	TSB 14-0009

SB-10054921-6053

FORD:

2013 Fusion

LINCOLN:

2013 MKZ

ISSUE

Some 2013 Fusion and MKZ vehicles equipped blind spot information system (BLIS) or cross-traffic alert (CTA) system and built on or before 12/3/2012 may exhibit a fault warning message displayed in the instrument cluster with diagnostic trouble codes (DTCs) U049A-86 or U0501-86 stored.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Determine vehicle build date.
   a. Vehicles built before 11/1/2012, proceed to Step 2.
   b. Vehicles built on or after 11/1/2012, proceed to Step 3.
2. Replace both rear door modules. Refer to Workshop Manual (WSM), Section 419–10.
3. Reprogram driver door module (DDM) and passenger door module (PDM) to the latest calibration using IDS release 87.01 and higher. Calibration files may also be obtained at www.motorcraft.com.

PART NUMBER	PART NAME
DG9Z- 9923394-D	Rear Door Module

OPERATION	DESCRIPTION	TIME
140009A	2013 Fusion And MKZ: Reprogram The DDM And PDM Includes Time To Perform Power Door Window Initialization (Do Not Use With Any Other Labor Operations)	0.4 Hr.
140009B	2013 Fusion And MKZ: Replace Both Rear Door Modules, Reprogram The DDM And PDM Includes Time To Perform Power Door Window Initialization (Do Not Use With Any Other Labor Operations)	1.1 Hrs.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
14B291	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service.The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article.The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates.The most recent information is available through Ford Motor Company's on-line technical resources.

Copyright © 2014, Ford Motor Company