



MAZDA DEALER EMAIL

zoom-zoom

zoom-zoom

zoom-zoom

Attention: Mazda Parts & Service Managers

Subject: Safety Recall 6812G Parts Installation

To prevent possible subsequent vehicle damage, dealers must install only the engine cover rear stud with spacer assembly intended for the model year vehicle under repair. Any damage caused by installing the incorrect part will not be covered by warranty.

Install p/n 1F01-10-218 ONLY on affected 2001-2005 and early 2006 model year Tributes.

Part number 1F02-10-218 SHOULD NOT be used. Revised parts for 2006.5 – 2008 model years will be available mid-November. Until these parts are available, for these model years only, please continue to perform only the interim repair of disconnecting the speed control cable away from the throttle linkage, until further notice.

You will receive a separate notification shortly with details on the disposition of the 1F02-10-218 parts you have in stock now. Until then, please quarantine these parts in your inventory and do not use them for any repair.

To determine the required part for 2006 model year vehicles, inspect the engine cover (see inspection step in the 6812G repair procedure). If part number 1F02-10-218 is required, do not install the part. Perform only the interim repair.

Notices for affected 2006 and 2008 model year owners will be mailed when the new parts are available. Please do not send recall reminders to these customers until further notice.

Please make certain that the appropriate personnel in your dealership are familiar with the details of this recall. Adherence to all recall repair instructions is mandatory. Your continued support in carrying out this recall campaign is greatly appreciated.

Mazda Technical Services