



Ricon Corporation
A Wabtec Company
7900 Nelson Road
Panorama City, CA 91402

Phone: 818.267.3000
Fax: 818.267.3001
www.Riconcorp.com

REVISED SAFETY RECALL NOTICE

April 29, 2013

OEM

FOREST RIVER, INC.
Attn: Larry Hall
2367 Century Dr.
Goshen, IN 46528 USA

RE: Safety Standard Recall Notification 13E-001 (formerly 12E-038)

Dear Larry Hall:

After sending the original notification letters, anomalies were discovered in Ricon's data set upon which the mailing was based. Though the total number of affected units does not change, the number of units sold to your company may have been affected. Please see the attached revised summary of affected units.

As outlined in the original notification letter, Ricon has determined that a defect which relates to motor vehicle safety exists in a Ricon wheelchair lift installed in (a) vehicle(s) manufactured by your company. This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

! I M P O R T A N T !

- Ricon Wheelchair Lift is being recalled
- If you haven't already done so, please contact Ricon Corporation

WHAT IS BEING RECALLED:

This recall applies to approximately 4,075 Ricon DOT Public Use, S and K Series wheelchair lifts manufactured between August 1, 2006, and September 29, 2012, equipped with an optional armored cord on the hand held control pendant. A revised list of affected serial numbers, corresponding order numbers and ship dates of affected units sold to your company is attached.

WHY IS IT BEING RECALLED:

The affected lifts are equipped with a hand held pendant control where upon the cord is protected by a flexible, steel conduit (an armored pendant cable) and an external power lug at the base of the hydraulic pump. In the event the lift is installed such that the armored pendant cable is not managed to be kept clear of the wheelchair lift and the protective, elastomeric cover is either omitted or



Ricon Corporation
A Wabtec Company
7900 Nelson Road
Panorama City, CA 91402

Phone: 818.267.3000
Fax: 818.267.3001
www.Riconcorp.com

improperly installed, the armored pendant cable may contact the power lug resulting in a high current short circuit and the possibility of fire.

WHAT YOU AS THE [OEM][DEALER] SHOULD DO:

As the vehicle manufacturer, you Must Notify NHTSA & Conduct a Safety Recall: According to our records, affected units were purchased by your company. If those units were installed as original equipment on vehicles manufactured by your company, your company must notify the National Highway Traffic Safety Administration (NHTSA) within 5 business days and conduct a safety recall of those vehicles. It is critical that the NHTSA guidelines are followed in a timely manner and that your customers are notified of the potential hazard. You may contact the NHTSA with questions by sending an email to rmd.odi@dot.gov.

In the event your company must file with NHTSA, to help you comply with your obligation, we have attached a sample letter that might be placed on your company's letterhead and sent to owners of potentially affected vehicles. We have also included a sample customer notification letter, which should facilitate your notification of dealers and owners of the recall and the required repair and service procedures. Although we have provided these samples for your convenience, if you are required to file with NHTSA, you must submit drafts of your version, on your company's letterhead of these notices to NHTSA for approval at least 5 days prior to mailing such notification to dealers and owners of potentially affected Ricon lifts.

Important: Proper diligence in the notification of dealers and/or end users of affected units is required by Federal law for all safety recalls. Notification letters to dealers are to be sent by certified mail, verifiable electronic means such as emails with return receipts, or other means providing for more expeditious and verifiable transmission. Notifications to owners of potentially affected vehicles are by first class mail. Please be advised that the outside of each envelope containing an owner notification letter must be marked "SAFETY RECALL NOTICE" all in capital letters, either in boldface or underlined, and in type that is larger than that used in the address section. A sample of the envelope must be submitted to NHTSA for approval at least 5 business days before mailing to owners.

IMPORTANT: Some of the vehicles affected may still be in your inventory. Federal law requires you to complete the recall service on these vehicles before delivery. Ricon will provide replacement or repair for these units prior to delivery to your customers.

In addition to providing the materials required for this recall, Ricon is prepared to assist you with the notification mailings and NHTSA reporting requirements. Please contact the undersigned at (800)322-2884 x3016, or by email, at admin12E038@wabtec.com

WHAT RICON CORPORATION WILL DO:

With specific regard to customer notification, Ricon is prepared to execute your company's customer notification mailing. To do so, we respectfully request that you provide a file in Excel format



Ricon Corporation
A Wabtec Company
7900 Nelson Road
Panorama City, CA 91402

Phone: 818.267.3000
Fax: 818.267.3001
www.Riconcorp.com

containing your customers' contact information and a notification letter on your company's letterhead in MS Word format (the attached sample customer notification is available in MSWord format upon request).

Additionally, Ricon will provide instructions for managing the pendant cord and will supply a supplemental cover kit at no charge. It will be the responsibility of the lift owners to install the cover kit.

If you feel Ricon has not fully answered your questions, please contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Thank you for your prompt attention to this matter. If you have any questions concerning these procedures please contact the undersigned at (800)322-2884 x3016 or by email at admin12E038@wabtec.com.

We apologize for the inconvenience associated with this this safety recall.

Sincerely,

A handwritten signature in black ink, appearing to read "S. Saucier", written over a light blue horizontal line.

Stanton D. Saucier, PE
Vice President – Marketing and Product Planning
Ricon Corp.

Enclosures:

1. Sample End User Letter
2. Sample Inspection Repair Log

SAFETY RECALL NOTICE

[Date]

END USER - DRAFT

[End User]

RE: Defect Recall Notification (recall number)

Dear [End User]:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Ricon has determined that a defect which relates to motor vehicle safety exists in the Ricon wheelchair lift installed in your vehicle.

! I M P O R T A N T !

- Your Ricon Wheelchair Lift is being recalled
- Contact Ricon Corporation immediately

WHAT IS BEING RECALLED:

This recall applies to approximately 4,075 Ricon DOT Public Use, S and K Series wheelchair lifts manufactured after August 1, 2006, equipped with an optional armored cord on the hand held control pendant.

All affected model numbers end either with a "B" or "3". These characters in these positions of the Model number indicate that the unit is equipped with an optional, armored pendant cord:

S20XX-XXXXXXXXB S20XX-XXXXXXXX3 S55XX-XXXXXXXXB S55XX-XXXXXXXX3	K20XX-XXXXXXXXB K20XX-XXXXXXXX3 K55XX-XXXXXXXXB K55XX-XXXXXXXX3
--	--

WHY IS IT BEING RECALLED:

The affected lifts are equipped with a hand held pendant control where upon the cord is protected by a flexible, steel conduit (an armored pendant cable) and an external power lug at the base of the hydraulic pump. In the event the lift is installed such that the armored pendant cable is not managed to be kept clear of the wheelchair lift and the protective, elastomeric cover is either omitted or

improperly installed, the armored pendant cable may contact the power lug resulting in a high current short circuit and the possibility of fire.

WHAT YOU AS THE OWNER/OPERATOR SHOULD DO:

Immediately locate and inspect the affected unit(s) in your fleet. If the pendant has been replaced such that the lift is no longer equipped with an armored pendant cord, no further action is necessary.

Make sure the cord is managed so that the cord does not contact the lift, make sure that the protective, elastomeric cover shipped with the lift is properly installed and contact Ricon for supplemental cover kit and instructions.

Materials are available by calling Ricon Customer Service at (800)322-2884, or by emailing Ricon's Recall Coordinator, at admin12E038@wabtec.com or by locating the nearest Ricon servicing dealer using the locator on the Ricon website – www.riconcorp.com

WHAT RICON CORPORATION WILL DO:

Ricon will provide materials as outlined above. If after attempting to have your vehicle repaired you believe you have not been able to have your vehicle remedied within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Thank you for your prompt attention to this matter. If you have any questions concerning these procedures please contact Ricon Customer Service at (800)322-2884.

We apologize for the inconvenience this safety recall will cause.

Sincerely,

[OEM Recall Administrator / Title]

Armored Cord – Recall 13E-001 (Formerly 12E038)

04/29/13

264637	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264638	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264641	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264642	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264643	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264644	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264646	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264647	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264649	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264654	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264656	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
264658	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	10/11/2010 *
258974	K5510-F1020000B	K55(48trv)34x54" PFRM,FMVSS,LH	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
258975	K5510-F1020000B	K55(48trv)34x54" PFRM,FMVSS,LH	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
258976	K5510-F1020000B	K55(48trv)34x54" PFRM,FMVSS,LH	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
264897	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265181	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265182	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265185	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265186	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265367	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265368	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265369	S5510-F1020100B	S55(51trv)34x54 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265401	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265402	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
265403	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	494093	FOREST RIVER, INC.-0014609	11/2/2010 *
267998	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	497284	FOREST RIVER, INC.-0014609	1/25/2011 *
264214	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	498157	FOREST RIVER, INC.-0014609	2/10/2011 *
264215	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	498157	FOREST RIVER, INC.-0014609	2/10/2011 *
264216	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	498157	FOREST RIVER, INC.-0014609	2/10/2011 *
264217	S5505-F1020100B	S55(51trv)32x51 PFRM,FMVSS,RH P	498157	FOREST RIVER, INC.-0014609	2/10/2011 *
273701	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH S55(51trv)32x51 PFRM,FMVSS,RH PUMP,12V	909317	FOREST RIVER, INC.-0014609	9/12/2011 *
L278616	RIS5505-F1020100B	STEEL JACKET PENDANT S55(51trv)32x51 PFRM,FMVSS,LH PUMP,12V	500447	FOREST RIVER, INC	5/9/2012 *
501311	RIS5505-F1020000B	STEEL JACKET PENDANT S55(51trv)32x51 PFRM,FMVSS,LH PUMP,12V	500621	FOREST RIVER, INC	6/14/2012 *
L501309	RIS5505-F1020000B	STEEL JACKET PENDANT S55(51trv)32x51 PFRM,FMVSS,LH PUMP,12V	500621	FOREST RIVER, INC	6/14/2012 *
L501310	RIS5505-F1020000B	STEEL JACKET PENDANT K55(48trv)34x54" PFRM,FMVSS,RH PUMP,12V	500621	FOREST RIVER, INC	6/14/2012 *
502867	RIK5510-F1020100B	STL JACKET PENDANT	500706	FOREST RIVER, INC	7/23/2012 *

37

TOTAL 169

Armored Cord – Recall 13E-001 (Formerly 12E038)

04/29/13

234770	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	455228	FOREST RIVER, INC.-0014609	9/18/2008 *
237426	K2010-F1020100B	K2010(37trv)34x54"PLTFRM,FMVSS	456836	FOREST RIVER, INC.-0014609	10/23/2008 *
237964	K2010-F1020100B	K2010(37trv)34x54"PLTFRM,FMVSS	456836	FOREST RIVER, INC.-0014609	10/23/2008 *
241298	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	457929	FOREST RIVER, INC.-0014609	12/10/2008 *
241342	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	457929	FOREST RIVER, INC.-0014609	12/10/2008 *
243320	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	461348	FOREST RIVER, INC.-0014609	2/6/2009 *
243326	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	461348	FOREST RIVER, INC.-0014609	2/6/2009 *
239059	S5510-F1020000B	S55(51trv)34x54PFRM,FMVSS,LH P	461588	FOREST RIVER, INC.-0014609	2/13/2009 *
239060	S5510-F1020000B	S55(51trv)34x54PFRM,FMVSS,LH P	461588	FOREST RIVER, INC.-0014609	2/13/2009 *
239085	S5510-F1020000B	S55(51trv)34x54PFRM,FMVSS,LH P	461588	FOREST RIVER, INC.-0014609	2/13/2009 *
239086	S5510-F1020000B	S55(51trv)34x54PFRM,FMVSS,LH P	461588	FOREST RIVER, INC.-0014609	2/13/2009 *
239861	S5510-F1020000B	S55(51trv)34x54PFRM,FMVSS,LH P	461588	FOREST RIVER, INC.-0014609	2/13/2009 *
245080	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	464346	FOREST RIVER, INC.-0014609	4/2/2009 *
245081	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	464346	FOREST RIVER, INC.-0014609	4/2/2009 *
255394	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	478400	FOREST RIVER, INC.-0014609	1/5/2010 *
255905	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	482209	FOREST RIVER, INC.-0014609	3/23/2010 *
255906	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	482209	FOREST RIVER, INC.-0014609	3/23/2010 *
260411	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260412	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260413	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260414	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260415	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260416	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260417	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260418	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260419	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260420	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260421	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260422	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260423	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260424	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260425	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260426	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260427	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260428	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
260429	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	483672	FOREST RIVER, INC.-0014609	6/4/2010 *
259526	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	489974	FOREST RIVER, INC.-0014609	8/5/2010 *
259527	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	489974	FOREST RIVER, INC.-0014609	8/5/2010 *
263456	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	492053	FOREST RIVER, INC.-0014609	9/21/2010 *
263459	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	492053	FOREST RIVER, INC.-0014609	9/21/2010 *
263461	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	492053	FOREST RIVER, INC.-0014609	9/21/2010 *
263464	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	492053	FOREST RIVER, INC.-0014609	9/21/2010 *
264610	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	9/27/2010 *
264611	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	9/27/2010 *
264618	S2005-F1020000B	S20(42trv)32x51 PFRM,FMVSS,LH	491857	FOREST RIVER, INC.-0014609	9/27/2010 *

45

Armored Cord – Recall 13E-001 (Formerly 12E038)

04/29/13

SerialNo	EqItemCode	EqItemDesc	OrderNo	CustName	ShipDate
207750	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	418684	FOREST RIVER, INC.-0014609	11/1/2006
208213	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	421312	FOREST RIVER, INC.-0014609	1/2/2007
210368	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	422673	FOREST RIVER, INC.-0014609	1/2/2007
211011	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	422948	FOREST RIVER, INC.-0014609	1/26/2007
212048	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	424335	FOREST RIVER, INC.-0014609	2/9/2007
210786	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	423464	FOREST RIVER, INC.-0014609	2/16/2007
210787	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	423464	FOREST RIVER, INC.-0014609	2/16/2007
212365	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	424941	FOREST RIVER, INC.-0014609	2/16/2007
211004	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	423684	FOREST RIVER, INC.-0014609	2/22/2007
211007	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	423684	FOREST RIVER, INC.-0014609	2/22/2007
211010	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	423684	FOREST RIVER, INC.-0014609	2/22/2007
213542	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	425788	FOREST RIVER, INC.-0014609	3/28/2007
212388	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	429013	FOREST RIVER, INC.-0014609	5/8/2007
207734-D	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	432121	FOREST RIVER, INC.-0014609	7/23/2007
220378	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	433955	FOREST RIVER, INC.-0014609	8/15/2007
220380	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	433955	FOREST RIVER, INC.-0014609	8/15/2007
221644	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	435423	FOREST RIVER, INC.-0014609	9/21/2007
221752	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	436842	FOREST RIVER, INC.-0014609	9/24/2007
221647	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	435423	FOREST RIVER, INC.-0014609	9/28/2007
221643	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	435423	FOREST RIVER, INC.-0014609	10/3/2007
222429	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	438196	FOREST RIVER, INC.-0014609	11/6/2007
223145	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	438345	FOREST RIVER, INC.-0014609	11/7/2007
223947	S2010-F1020100B	S20(42trv)34x54 PFRM,FMVSS,RH	438345	FOREST RIVER, INC.-0014609	11/13/2007
224870	K5505-F1020000B	K55(48trv)32x51pfrm,FMVSS,LH P	441254	FOREST RIVER, INC.-0014609	1/11/2008
226464	K5505-F1020000B	K55(48trv)32x51pfrm,FMVSS,LH P	441254	FOREST RIVER, INC.-0014609	1/17/2008
228165	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	444380	FOREST RIVER, INC.-0014609	3/7/2008
228167	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	444380	FOREST RIVER, INC.-0014609	3/7/2008
228169	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	444380	FOREST RIVER, INC.-0014609	3/7/2008
228271	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	444380	FOREST RIVER, INC.-0014609	3/7/2008
228272	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	444380	FOREST RIVER, INC.-0014609	3/7/2008
229901	S5510-F1020100B	S55(51trv)34x54PFRM,FMVSS,RH P	446151	FOREST RIVER, INC.-0014609	4/9/2008
227647	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	446461	FOREST RIVER, INC.-0014609	4/17/2008
231998	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	446677	FOREST RIVER, INC.-0014609	5/16/2008
232768	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	451206	FOREST RIVER, INC.-0014609	7/17/2008
232770	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	451206	FOREST RIVER, INC.-0014609	7/17/2008
233559	S5505-F1020100B	S55(51trv)32x51PFRM,FMVSS,RH P	451419	FOREST RIVER, INC.-0014609	7/24/2008
236389	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	454643	FOREST RIVER, INC.-0014609	9/5/2008
236390	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	453677	FOREST RIVER, INC.-0014609	9/5/2008
236394	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	453677	FOREST RIVER, INC.-0014609	9/5/2008
236395	K5510-F1020100B	K55(48trv)34x54" PFRM,FMVSS,RH	453677	FOREST RIVER, INC.-0014609	9/5/2008
233921	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	455228	FOREST RIVER, INC.-0014609	9/18/2008
234769	K5505-F1020100B	K55(48trv)32x51pfrm,FMVSS,RH P	455228	FOREST RIVER, INC.-0014609	9/18/2008