



Mitsubishi Motors North America, Inc.

PARTS BULLETIN

SUBJECT:

**2011 OUTLANDER SPORT PANORAMIC GLASS ROOF
-SAFETY RECALL SERVICE PARTS BULLETIN-**

No: 42-US-01-13

Date: JULY 2013

Model:
2011 Outlander Sport

Purpose:

Due to a manufacturing error, a necessary primer may not have been applied to certain 2011 Outlander Sport vehicles during the installation of the panoramic glass roof. Continued use of those vehicles without the primer could result in reduced glass roof adhesion, and in the worst case, detachment of the panoramic glass roof. Detachment of the panoramic glass roof while the vehicle is in motion can create a road hazard to other vehicles.

Safety Recall Bulletin (SR-13-007) has been created to instruct dealers to inspect the panoramic glass roof to determine if the primer was applied during production, and if necessary, remove and properly reinstall the glass roof.

AFFECTED VEHICLE:

Certain 2011 Outlander Sport with panoramic glass built from August 26, 2010 to March 29, 2011.

PARTS INFORMATION

PART NUMBER	QUANTITY	PNC	DESCRIPTION
6190A035	1	71119	MOULDING,ROOF DRIP,FR
6190A036	1	71126	MOULDING,ROOF DRIP,RR
6190A041	1	78635	PIN,ROOF
6190A045	1	78283B	STOPPER,ROOF BLIND
6190A046	1	78283C	STOPPER,ROOF BLIND
MB851058	4	61793B	SPACER,WINDSHIELD
MB851060	2	78969C	SPACER,ROOF WINDOW

Parts are only necessary when it is discovered that the primer is missing from the panoramic glass roof.

Do not order parts until it has been confirmed with Tech Line that the glass roof requires removal and re-installation.

- There will be no forced allocation or parts.
- There will be no need to stock the parts.
- Parts are available for repairs only, not for stocking.

Contact your local Zone Representative, District Parts and Service manager, or Facing PDC for questions.

