

GM CUSTOMER CARE AND AFTERSALES
DCS3266
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 24, 2014

Subject: 14115B – Safety Recall
Electric Power Steering Assist
Revised Service Procedure

Models: 2009-2010 Chevrolet HHR (non-turbo), 2010 Chevrolet Cobalt,
2004-2007 Saturn ION Equipped with Electric Power Steering
and
2005-2010 Chevrolet Cobalt, 2005 Pontiac Pursuit, 2005-2006
Pontiac G4, 2006 Pontiac G5 Pursuit, and 2007-2010 Pontiac G5
Vehicles that were Serviced under Safety Recall 10023 Prior to
May 31, 2010

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Caution statement in the service procedure has been revised. Please discard all
copies of bulletin 14115A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES