

GM CUSTOMER CARE AND AFTERSALES  
DCS3263  
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 22, 2014

Subject: 14115A – Safety Recall  
Electric Power Steering Assist  
Revised Service Procedure

Models: 2009-2010 Chevrolet HHR (non-turbo), 2010 Chevrolet Cobalt,  
2004-2007 Saturn ION Equipped with Electric Power Steering  
**and**  
2005-2010 Chevrolet Cobalt, 2005 Pontiac Pursuit, 2005-2006  
Pontiac G4, 2006 Pontiac G5 Pursuit, and 2007-2010 Pontiac G5  
Vehicles that were Serviced under Safety Recall 10023 Prior to  
May 31, 2010

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

A Note statement has been added to the service procedure informing dealers that there is no power steering assist motor housing inspection for the Chevrolet HHR. For HHR vehicles go directly to the power steering assist motor replacement procedure. Please discard all copies of bulletin 14115.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES