



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 31, 2014

Mr. Jim Olson
Product and Safety Engineer
Terex South Dakota, Inc.
500 Oakwood Road
Watertown, SD 57201

NVS-215SM
14V-371

Subject: PTO Pressure Switch Oil Leak may Result in Fire

Dear Mr. Olson:

This letter serves to acknowledge Terex South Dakota, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TEREX/HR40/2009-2013
TEREX/L13I/2009-2013
TEREX/LT38/2009-2013
TEREX/LT40/2009-2013
TEREX/LTM40/2009-2013
TEREX/NT29/2009-2013
TEREX/TL37/2009-2013
TEREX/TPL40/2009-2013

Mfr's Report Date: June 25, 2014

NHTSA Campaign Number: 14V-371

Components:

EQUIPMENT

Potential Number of Units Affected: 74

Problem Description:

Terex South Dakota, Inc. (Terex) is recalling certain model year 2009-2013 LT38, LT40, LTM40, NT29, TL37, HR40, L13i, and TPL40 aerial devices manufactured on 2009-2013 Ford F-350, F-450, or F-550 Super Duty chassis with a 6.8L engine, and equipped with certain Muncie Power Products PTO Assemblies. In the affected vehicles, oil may leak from the PTO pressure switch onto a thermal blanket covering the exhaust.

Consequence:

The leaking oil may soak into the thermal blanket covering the exhaust, which when combined with heat from exhaust, may result in an increased risk of fire.

Remedy:

Terex will notify owners, and dealers will install a new pressure switch kit that moves the switch away from the exhaust system, free

of charge. The recall is expected to begin in August 2014. Owners may contact Terex customer service at 1-605-882-4000. Terex's number for this recall is SN611.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Terex's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah McShane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement