

GM CUSTOMER CARE AND AFTERSALES
DCS3336
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 3, 2014

Subject: 14359A – Safety Bulletin
Roof Carrier Retaining Nut Interaction with Roof Rail Airbag
Customer Letter Added

Models: 2015 Chevrolet Suburban, Tahoe
2015 GMC Yukon, Yukon XL

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Bulletin 14359A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 14359.

Customer Letter Mailing

The customer letter mailing will begin on September 15, 2014.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES