

[Next Unread Message](#)

**View Message**

---

**Sent on** 08 28 2014 **Expires on** 11 25 2014  
**From** American Honda Parts, Service & Technical Division, Campaign Administration  
**Subject** 2001-11 Multi-Model Airbag Inflator Recalls UPDATE

DATE: August 28, 2014

TO: All Honda Service Managers and Personnel  
FROM: American Honda Parts, Service & Technical Division, Campaign Administration  
RE: 2001-11 Multi-Model Airbag Inflator Recalls **UPDATE**

On Monday, June 23, 2014, American Honda announced three recalls for various 2001-11 Honda models. As of August 4, 2014, affected VINs have been identified, and VIN status inquiry has been updated. Refer to service bulletins 14-040, *Safety Recall: Accord, Civic, and Others – Front Passenger’s Airbag Inflator Can Be Over-Pressurized*, 14-045, *Recall: Front Driver’s Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity Recall*, and 14-046, *Recall: Front Passenger’s Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity* for further instructions on addressing affected units.

Please note that the procedures outlined in the service bulletins listed above only apply to vehicles that show VIN inquiry links to bulletins 14-040, 14-045 and/or 14-046. Please **do not** include any recall disclosure messages on repair orders for vehicles not affected by these recalls. Needlessly including these messages may cause customers undue concern about their vehicles; instead, make sure to verify that a particular vehicle is affected by one or more of the recalls by checking VIN status inquiry, and confirming that one or more of the bulletins listed above is present. If so, include the disclosure; if not, omit it.

Parts to support this issue remain unavailable at this time. American Honda expects to provide an update on this situation in the next several weeks.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.