

GM CUSTOMER CARE AND AFTERSALES
DCS3342
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 5, 2014

Subject: 14234A – Safety Recall
Transmission Turbine Shaft Fracture
Revised Part Information Section

Models: 2012 Chevrolet Sonic
With 6 Speed Automatic Transmission (Model 6T30 - RPO MH9)
And 1.8L Engine (RPO LUW)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

The parts information section in this bulletin has been revised due to recent Service Information procedure updates. As a result, part number 92139090 and 11516382 were removed from the part list since it is not necessary to remove the control arms from the frame. The quantities for part numbers 11517996, 13208672, and 11611963 were adjusted from quantity 1 to quantity 2 to account for disassembly on both sides of the vehicle. Part number 24231666 was adjusted from quantity 1 to quantity 3. Part number 13231667 (quantity 2) was also added for the steering gear bolts. Please discard all copies of bulletin 14234.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES