



*MAZDA DEALER EMAIL*

*zoom-zoom*

*zoom-zoom*

*zoom-zoom*

November 10, 2014

Attention: Mazda Service Managers

Subject: Repair Procedure Update for Safety Recall 7914J - Front Air Bag Inflator

The repair procedure for Safety Recall 7914J has been updated to add Caution instructions when removing the air bag module, to prevent damage to the air bag connector.

Please be sure to always observe all Caution instructions when performing air bag module repairs.

Thank you for your continued support in carrying out this campaign.

Mazda Technical Services