

[Next Unread Message](#)**View Message**

**Sent on** 12 11 2014 **Expires on** 03 11 2015  
**From** Acura Parts, Service & Technical Division, Campaign Administration  
**Subject** Safety Improvement Campaign: 2002-06 Multi-Model Driver's Airbag Inflator

DATE: December 11, 2014

TO: All Acura Sales, Service & Parts Managers and Personnel  
FROM: Acura Parts, Service & Technical Division, Campaign Administration

RE: Safety Improvement Campaign: 2002-06 Multi-Model Driver's Airbag Inflator

On December 8, 2014, Acura announced a voluntary expansion of the existing 2002-06 multi-model driver's airbag inflator safety improvement campaign. The original range covered vehicles sold or ever registered in Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, or US Virgin Islands. The range has now been expanded to include all suspect VINs nationwide. Any used vehicles in dealer stock must be repaired per S/B 14-029, *Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity* prior to sale. **Refer to VIN Inquiry status to determine which vehicles in your inventory are affected.**

As of December 11, 2014, all affected VINs have been identified and are in the process of being loaded into the system. This process will take several days. Acura expects to have the VIN loading process completed by Monday, December 15, 2014.

Note that as with the original safety improvement campaign range, large numbers of VINs previously repaired under bulletins 09-033 and/or 10-026 now require additional repair under bulletin 14-045.

Parts to support this recall are available through the controlled parts order system.

Client notification will begin in early 2015. Notices will be issued according to parts availability.

As always, please check VIN Inquiry status to determine if a particular VIN is covered by this (or any other) open recall.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.