



Michael A. Berardi
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

May 28, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Advance Notice - Safety Recall 15S21
Certain 2005-2006 Ford GT and 2005-2014 Mustang Vehicles
Driver Airbag Inflator Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Ford GT	2005-2006	Wixom	February 20, 2004 through September 22, 2006
Mustang	2005-2014	Flatrock	April 6, 2004 through June 21, 2014

Affected vehicles are identified in OASIS. In addition, for a list of vehicles assigned to your dealership, visit <https://web.fsavinlists.dealerconnection.com>.

REASON FOR THIS SAFETY RECALL

Takata has determined that the air bag inflator propellant wafers in some inflators may experience an alteration over time, which could potentially lead to an over-aggressive combustion in the event of an airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which could result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.

SERVICE ACTION

A complete Dealer Bulletin will be provided to dealers when parts ordering information and repair instructions will be available to support this safety recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information are provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery

QUESTIONS

Special Service Support Center (Dealer Assistance Only)1-800-325-5621

Sincerely,

Michael A. Berardi