

GM CUSTOMER CARE AND AFTERSALES  
DCS3746  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 13, 2015

Subject: 13142C – Safety Recall  
Loss of Battery Charge – Replace Generator Control Module  
Revised Part Information and Service Procedure Sections

Models: 2012-13 Buick LaCrosse, Regal; 2013 Chevrolet Malibu Eco  
Equipped with eAssist

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

The service procedure and part information sections have been revised to remove the requirement to inspect the new module prior to vehicle installation. The associated modules have also been removed from the part information section. Please discard all copies of bulletin 13142B.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES