

**\*\* ADVANCE TECHNICAL INFORMATION NOTICE \*\***

**DATE:** June 23, 2008  
**TO:** Mitsubishi Motors Service Managers  
**RE:** Safety Recall SR-08-003  
**ATIN NO.** ATIN-08-SR-003

\*\*\*\*\*

**AFFECTED VEHICLES:** 2004-08 Endeavor built prior to March 14, 2008.

Safety Recall Bulletin **SR-08-003** is being mailed to all dealers today for two-day air delivery. It will also be available on MEDIC and the Mitsubishi Dealer Link for download today. Under certain circumstances, it is possible to remove the key from the ignition while the transmission is in a position other than P (park). A new cam lever and return spring must be installed as described in the recall bulletin.

The dealer bulletin mailing will include a list of affected VINs shown as being in their new vehicle inventory as of June 17, 2008. Dealers must review the Warranty Superscreen to confirm if any vehicles included in new shipments are affected. **Included in the bulletin mailing is a quantity of 4 special lock pins.** There are two different lengths and either can be used during this repair.

Owners of affected vehicles will be notified by mail, asking them to bring their vehicle to a Mitsubishi dealer for this repair.

Dealers will automatically receive an initial quantity of parts to complete the recall. Additional parts must be ordered according to each dealer's requirements. Please refer to Parts Bulletin **AI-ED-01-08** for additional details.

***IMPORTANT***

***ALL affected VINS in dealer inventory and en route to dealers must be repaired BEFORE THE VEHICLE IS SOLD. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is an affected VIN for this safety recall.***