

HONDA

American Honda Motor Co., Inc.
1919 Torrance Boulevard
Torrance, CA 90501-2746
Phone (310) 793-2000

03V-3510

November 2003

Dear Honda Dealer:

RE: 2002-2003 GL1800/A Safety Recall – Frame Weld

**DEALER RESPONSIBILITY REPORT – Current as of 11-17-03
(Service Bulletin GL1800/A #14)**

The enclosed Campaign Responsibility Report for the 2002-2003 GL1800/A shows the affected VINs that were either sold by your dealership or are still in your inventory. All sold units that have been registered with American Honda show the customer's most current name and address.

Please review the report to ensure that any GL1800/A listed is in your inventory, or contact the customer so an appointment can be made to have the repair completed. For your information, the report codes in the "UNIT STAT" column mean:

02 – In your inventory; perform the Safety Recall as necessary.

FX – Safety Recall has been performed.

BB – Repair coordinated by AHM; no action necessary

PA – Repair was performed in the warehouse.

blank – Customer already notified; no action necessary.

- For each unit shown in your inventory (code 02), but already sold, notify the owner and arrange to perform the repair.
- Reminder: If you have not yet registered a sold unit with American Honda, please do so now.

If you have completed any repairs for which you have not yet submitted warranty claims, please do so as quickly as possible. This is necessary for our tracking purposes. If you have any questions, please contact your District Service Manager.

Regards,

American Honda Motor Co., Inc.



Silvio Carrara
Vice President – Service
Motorcycle Division

Bulletin Number	Page	File Behind Dealer Guide Bulletin Tab
03-0608	1 of 1	Service