



ADMINISTRATIVE MESSAGE

Message Author: Theresa Toccace@US/GM/GMC
Template Type: Standard
Author's VESM
Division/Department:
Status: Forwarded
Message Date: 02/04/2004
Message Number: VSU20040026

Message Criteria/Information

Dealer Recipient Criteria:	Chevy Oldsmobile
Exclude SAC(s):	
Originating Dept:	SPO - Recalls, Joan Stone
Subject:	GMP04-014 - 03043 Turn Signals/Hazard Warning Flashers Inoperative
Actionable Item:	Information Only
Actionable Item Details:	
Contact Person: (for Wholesale)	Name: Joan M. Stone Phone: 810-606-4422 Email: Joan.M.Stone@US/GM/GMC @ GM Fax:
Contact Person: (for Wholesale)	Name: Phone: Email: Fax:
Contact Person: (for Dealership)	Name: Joan M. Stone Phone: 810-606-4422 Email: Joan.M.Stone@US/GM/GMC @ GM Fax:
Contact Person: (for Dealership)	Name: Phone: Email: Fax:
Function(s) Role(s): (Recommended Distribution):	Parts Manager, Service Manager

Message Categorization Information

Message Type:	GM Parts Bulletin & Information
Revision Reference:	

Message Retention

Release Date:	02/05/2004
Archive Date:	02/19/2004

Dealer Salutation: TO ALL CHEVROLET AND OLDSMOBILE DEALERS

Product Safety Recall #03043 Dated February 2004

- General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2000 and 2001 model year Chevrolet Malibu and Oldsmobile Alero vehicles. Some of these vehicles have a condition in which solder joints in the hazard warning flasher switch may crack. If cracking occurs, it may cause the audible flasher indicator, visual flasher indicator in the instrument cluster, turn signals, and the hazard warning flashers to work intermittently or not at all. If the turn signals or hazard warning flashers are not working, others may react more slowly to a turning or stopped vehicle and a crash could occur.
- Dealers are to replace the hazard warning flasher switch.
- Refer to the Product Safety Recall Bulletin #03043 for further information.

EFFECTIVE DATE:

Owner mailing is scheduled to begin February 16, 2004.

GENERAL INFORMATION:

Part Number	Description	Quantity/Vehicle
22584146	Switch, Hazard Wrmg (w/flasher) (Malibu)	1
22642608	Switch, Hazard Wrmg (w/flasher) (Alero)	1

Important: An initial supply of Hazard Warning Switches required to complete this program will be pre-shipped to involved Dealers of record. This pre-shipment will take place the week of January 26, 2004, and equates to approximately 20% of each Dealer's involved vehicles. Pre-shipped parts will be charged to Dealer's open parts account.

VSSM Library Fields

Do Not Send Message to VSSM Library

Does This Document Require Action from a Field Rep? Information

Intended Audience(s): Area Parts Manager, Field Zone Manager, Region-NC, Region-NE, Region-SC, Region-SE, Region-W, Regional Field Operations Manager, Regional Parts Manager

Involved Brand(s): Chevrolet-Malibu, Oldsmobile-Alero

Document Type(s): Parts

Expiration Date: 03/15/2004

Topic: GM Parts - Product Safety Recall #03043/Turn Signals/Hazard Warning Flashers Inoperative
GMP04-014

**GM SERVICE AND PARTS OPERATIONS
DCS1145
URGENT - DISTRIBUTE IMMEDIATELY**

DATE: March 8, 2004
SUBJECT: 03043A – Product Safety Recall
Turn Signals/Hazard Warning Flashers Inoperative
MODELS: 2000-2001 Pontiac Grand Am
2000-2001 Chevrolet Malibu
2000-2001 Oldsmobile Alero
TO: All Chevrolet, Oldsmobile and Pontiac Dealers
ATTENTION: Service Manager, Parts Manager and Warranty
Administrator

**THIS BULLETIN IS BEING REVISED TO INCLUDE 2000 AND 2001 MODEL
YEAR PONTIAC GRAND AM VEHICLES.**

DISCARD ALL COPIES OF BULLETIN 03043, ISSUED FEBRUARY 2004.

PRODUCT FIELD ACTION ANNOUNCEMENT

General Motors is announcing Product Safety Recall 03043A today. This addendum adds 2000 and 2001 model year Pontiac Grand Am vehicles to the recall. The total number of Pontiac vehicles involved is 296,835. Please see the attached bulletin for details.

Mailing Information

Pontiac customer letter mailing will begin on March 15, 2004.

GM Vehicle Inquiry System (GMVIS)

GMVIS information will be available for involved Pontiac vehicles on March 9, 2004.

Service Information System (SI)

Bulletin 03043A is scheduled to be available in SI on March 19, 2004.

Campaign Initiation Detail Report (CIDR)

The CIDR for involved Pontiac vehicles will be available in DealerWorld on March 8, 2004.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS