

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 2 OF 6**

**BOOK 12 OF 43**

TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.  
RIGHT SEATBELT WONT LATCH REPLACED RIGHT SEATBELT BUCKLE  
INOP REPLACED PASSENGER AND DRIVERS SIDE SEAT BELT BUCKLES  
INOP REPL FR SEATBELT ASY SEATBELT ASSEMBLY FRONT REPLACE

INOP REPLACED DRIVERS SIDE SEAT BELT BUCKLE  
01S21 E BOTH BUCKLES FAILED RPL BOTH BELT BUCKLES  
LOOSE SEATBELT ASSEMBLY FRONT REPLACE  
INOP SEATBELT ASSEMBLY FRONT REPLACED  
11987 81202,42 DOES ONT OPERATE PROPERLY R R PASS FRONT SEAT REPLACED SEAT BELT BUCKLE  
DIAG AND RR SEAT BELT BUCKLE  
14022 ORIGINALLY TESTED FRONT BELT BUCKLES AND FOUND DRIVERS FAILED AND PASSENGERS PASSED LATER FOUN D OUT SERVICE  
R&R DRIVER FRONT SEAT TO GAIN ACCESS TO REPLACED SEAT BELT LATCH  
INOP REPLACE RIGHT SEAT BELT  
REPLACED SEAT BELT BUCKLE PER RECALL 01S21  
1 REPL BOTH FRONT SEAT BELT BUCKLES  
RIGHT SEATBELT WONT BUCKLE REPLACED RIGHT SEATBELT BUCKLE  
INOP REPLACED BOTH FRONT SEAT BELT BUCKLES  
01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE  
RECALL RECALL 01S21,REPLACED DRIVERS SEAT BELT BUCKLE  
CRITICAL ORDERED DRIVERS SEATBELT BUCKLE 7 2 01 REPLACED DRIVERS SEATBELT BUCKLE INOP AT TIMES  
BUCKLE WOULDNT LATCH,REPLACED AND TESTED OK  
REPLACED INOP SEAT BELTS  
3391 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLA  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE  
PERFORM RECALL 01S21D REPLACE PASSENGER SEAT BELT BUCKLE  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
WARR 944247 TEST AND REPLACE BOTH FRONT SEATBELT BUCKLES

14364 INSPECT AND VERIFY CONCERN DRIVERS EAT BELT BUCKLE UNBUCKLES WHILE DRIVING. REPLACE B7UCKLE AND VERIFY REPAIR..(  
SEATBELT WONT BUCKLE REPLACED SEATBELT ASSY.  
REPLACE BUCKLE, RECK OK  
CUST STATE THE DRIVER SIDE SEAT BELT BUCKLE IS INOP CAUSE: SEAT BELT CORE: REPLACE SE.  
CC 42 A85 7881203 REMOVED DRIVERS SIDE SEAT AND REMOVED BUCKLE AND INSTALLED NEW AND RETESTED OK  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
SEATBELT INOP

BUCKLE HAD A BROKEN & JAMMED PUSH BUTTON REPLACE THE DRIVER SIDE SEAT BUCKLE ASSY,TESTED ALL FUNCTIONS AFTER THE RE  
R AND R SEAT T60 REPLACE DRIVERS SEAT BELT  
REMOVED SEAT BUCKLE DRIVERS SIDE REPLACED WITH NEW REMOVED SEAT TO REACH BOTTOM OF SEAT REPLACED BUCKLE ON P.  
REPLACE BUCKLE.

01S21 E BOTH BELT BUCKLE FAILED RPL BOTH BELT BUCKLES

01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE

14584 DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH AND UNLATCH REPLACED BUCKLE AND RETESTED OK.

REPLACED LEFT FRONT SEAT BELT 61203

38 01S21D 0.8 INSP AND REPL L FRONT SEAT BELT

BINDING REPLACED LEFT SIDE SEAT BELT BUCKLE

1 REPLACED SEAT BELT ASSEMBLY. RETEST. O.K.

2508 INOP 42 NEEDED TO REMOVE LT FT SEAT ASSY TO REPLACE SEAT BELT BUCKLE

INSPECTED AND REPLACE BOTH FRONT SEATBELTS

R'R PASSENGER SIDE SEAT BELT

REPLACE RIGHT SEAT BELT BUCKLE

REPLACE RT HAND SEATBELT.

RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL

CKED OUT AND REPLACE SEAT BELT BUCKLE INOP WILL NOT LATCH

REPLACE DRIVERS FRONT BUCKLE.

RECALL REPLACED SEAT BELT PER RECALL

10788 LEFT FRT SEAT BELT POPS LOOSE WHILE DRIVING. REMOVE SEAT AND REPLACE BUCKLE AND REINSTALL ALL PARTS AND VERIFY I

REPLACE BOTH SEAT BELTS

REPLACED DRIVERS SIDE FRONT SEAT BELT BUCKLE ASSEMBLY

802 DOES NOT OPERATE PROPERLY 01S21D 0.4 ADMIN 0.1 0.5HRS LG R R DRIVERS SEAT BELT BUCKLE, TESTED, OK. REMOVED DRIVERS :

SEAT BELT INOP. WILL NOT SECURE REPLACE LEFT FRONT SEAT BELT

RECHECK SEAT BELT AND TEST CUSTOMER STATES INTERMITTANT PROBLEM WITH UNSNAPPING REPLACE DRIVERS SIDE SEAT BELT BUK

REPLACED SEAT BELT BUCKLE

REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLY 61203 CAUS 42

CONFIRMED CUSTOMERS COMPLAINT. REPLACED DRIVERS SEAT BELT BUCKLE FOR NOT LATCHING.

10 RECALL 01S21D 0.8 PERFORM RECALL, INSPECT SEAT BELT BUCKLES AND REPLACE LEFT BUCKLE.

M TIME TIME TO REPLACE SEAT BELT

17088 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCESS SEAT BELT BUCKLE ASSY REPLACED LF DR SEAT BELT BUCKLE /

885 LEFT FRONT SEAT BELT WILL NOT LATCH. ACCESS LEFT FRONT SEAT AND REPLACED BUCKLE AND HARNESS ASSEMBLY. 1.0 CC 42 Q

VERIFIED, NEED NEW BUCKLE,

BUCKLE FAILED REPLACE DRIVERS FRONT SEAT BELT BUCKLE

REPLACE SEAT BELT BUCKLE

INOPERATIVE SEAT BUCKLE.

SEAT BELT BUCKLE BROKEN. PASS SIDE SEAT BELT BUCKLE INOP. REMOVED SEAT FOR ACCESS. R R BUCKLE, REINSTALLED SEAT AND VI  
GM REPLACE 2 BELTS  
20506 INOP W 42 REMOVE DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE ASY. INOP  
SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELT BUCKLES  
BUCKLE SEATBELT ASSEMBLY FRONT REPLACE  
REMOVE FRONT SEAT AND REPLACE BUCKLE  
REPLACE SEAT BELT  
REPLACE SEAT BELT BUCKLE.  
SEATBELT BINDING  
REPLACED SEATBELT INOP  
30 01S21D 0.8 INSP AND REPL SEAT BELT  
31 INSTALL SEAT BELT LEFT SIDE 01S21D 0.8 INSTALL SEAT BELT  
PARTS ARE HERE INSTALL SEAT BELT FOR BUCKLE NOT LATCHING, BOUND UP  
CC42 DOES NOT OPERATE PROPERLY MILES IN 2852 MILES OUT 2854 TESTED DRIVERS SEATBELT BUCKLE WITH RECALL TESTED FOUND T  
INSPECTED AND REPLACED BOTH FRONT SEAT BELT BUCKLES.  
REPLACED SEATBELT  
14894 OK BUCKLES REPLACE DR BUCKLE ORDERED MIDDLE SEAT BUCKLES  
FAIL TO LOCK SEAT CLIP R R SEAT BUCKLE ASSY  
10000 CP 81384 CC 38 PART REF. 892 81384A 0.4 0.4 REPLACE LH SEAT BELT BUCKLE WRONG COLOR  
REPLACE SEATBELTS WILL NOT LATCH PROPERLY  
CCG26 CHECKED OUT REPLACED DRIVERS SEAT BELT BUCKLE.  
1 INSPECT AND REPLACE R FRT SEAT BELT BUCKLE  
5657 LOOSE REPLACE LOOSE RF SEAT BELT BUCKEL \*\*\*\*\*QUALITY CONTROL BY JAMES PENNOCK\*\*\*\*\*  
CC348 PERFORMED 01S21 SEATBELT RECALL  
INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.  
41 REPLACED BOTH FRONT SEATBELT BUCKLES  
REPLACED SEAT BELT BUCKLE  
TEST AND REPLACE SEATBELT BUCKLE  
REPLACE SEATBELT BUCKLE ASSEMBLY  
REPLACED DRIVERS SIDE SEAT BELT BUCKLE(BUCKET SEATS) PER RECAL L,TECH 636  
REPL RT FRT SEAT BELT BUCKLE.REMOVE SEAT REPL BUCKLE.  
CC,01 BROKEN BASIC61203 REPLACE L F SEAT BELT  
CC348 PERFORMED 01S21 SEATBELT RECALL  
01S21 REPLACE BOTH BUCKLES  
SEATBELT BUCKLE INOP REPLACED SEATBELT BUCKLE  
21004 7861203 CC 42 VERIFY CONCERN.R& R DRIVERS SEAT TO GAIN ACCESS AND REPLACED DRIVERS SEAT BELT BUCKLE,VERIFY REPAI  
13544 W INSP AND FOUND PASS SEAT BELT TO BE STICKING WHEN RELEASED CHECKED SEAT BELT W SEAT TOOL BUT PASSED REPLACE

VERIFIED CUSTOMERS CONCERN, REMOVED & REPLACED SEAT BELT BUCKLE, RETESTED, PASSED...  
5 TESTED SEAT BELTS AND INSTALLED BOTH LEFT AND RIGHT SIDE SEAT BELT LATCHES R.L.B  
REPLACED SEATBELT BUCKLE  
REPLACED SEAT BELT ASSEMBLY  
21000 OPEN ELECTRICAL DIAG, FOUND DRIVERS SEAT BELT BUCKLE TO HAVE AN OPEN REPLACED, AND TESTED OK \*\*\*QUALITY CONTROL E  
SEAT BELT HARD TO UN SNAP REPLACE BOTH SEAT BELT BUCKLES  
FAILED BUCKLE REPLACED BUCKLE  
CCF12 REPLACE SEATBELT BUCKLES  
REPLACED LEFT AND RIGHT SEATBELTS.  
R&R RT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY...  
6884 REPLACE FRNT BUCKLES AS PER RECALL  
01821 SPECIAL PART ORDERED  
6208 INOP 61203 42 WARR REPLACE LEFT SEAT BELT BUCKLE 61202A  
CC107 REPLACED RIGHT FRONT SEAT BELT BUCKLE  
BINDING (41) HAD TO ACCESS REAR MIDDLE SEAT & REPLACE CENTER SEATBELT BUCKLE, TK8562  
SEAT BELTS WONT LATCH REPLACE BUCKLES  
REPLACE SEATBELTS WILL NOT LATCH  
6897 SEAT BELT LATCH INOP 61172A 4 REPLACED SEAT BELT LATCH  
14 INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED SEAT BELT  
REPLACE BELTS  
REPLACE SEATBELT WILL NOT LATCH PROPERLY  
SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE  
INOP, WOULD NOT LOCK IN PLACE REPLACED SEATBELT BUCKLE.  
SOP M TIME TO REPLACE LEFT BUCKLE  
61290 M TIME TO REPLACE LEFT SEAT BELT BUCKLE  
REPLACE BOTH SEAT BELT BUCKLES  
42 REMOVED RITE FRONT SEAT FOR ACCESS TO BELT BUCKLE REPLACED BUCKLE AND REINSTALLED SEAT  
PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED PASSENGER FRONT SEAT TO ACCESS SEATBELT BUCKLE, REPLACED SEATBELT I  
FOUND BOTH SEATBELTS MALFUNCTIONING REPLACED BOTH ASSEMBLIES AS NEEDED TO REGAIN PROPER SEATBELT OPERATION  
SEATBELT ASSEMBLY FRONT REPLACE (611A72 611A73) DRIVERS FRONT SEAT  
REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH  
TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE  
15038 WARR REPLACE BROKEN DRIVER SEAT BELT BUCKLE CC 01 TECH 5772  
SEATBELT ASSY REPLACED FRONT SEATBELT ASSY  
REPLACED THE LEFT FRONT SEAT BELT ASSEMBLY. CHECKED OPERATION, OKAY NOW.  
REPLACED SEAT BUCKLES  
BUCKLE & SWITCH BAD SEATBELT ASSEMBLY FRONT REPLACE

REPLACED BUCKLE  
OK OASIS, FOUND RECALL WAS PERFORMED AT ANOTHER DEALER. TEST SEAT BELT WITH TOOL AND IT DID NOT HOLD. REPLACE RF SEAT B  
REPLACE DRIVERS FRONT SEAT BELT  
INSTALLED NEW LEFT FRONT SEAT BELT  
18589 BELT RELEASE INT 1.3 OK BELTS, REPLACE BOTH BUCKLES AND DRIVERS BELT AND RETEST OK  
INSTALL SOP SEATBELT ASSEMBLY FRONT REPLACE  
LEFT FRONT SEAT BELT BUCKLE NOT LATCHING CC 42 BP#7861203 BUCKLE SEATS CHECKED OPERATION OF LEFT FRONT SEAT BELT BUC  
REPLACED DR SIDE SEAT BELT  
NECC TO REPLACE RIGHT SIDE SEAT BELT  
S40 42 VERIFY CONCERN REPLACED SEAT BELT BUCKLE WITH NEW RECHECK OK  
INSPECTED FOUND SEAT BELT BUCKLE BROKEN, REPLACED BUCKLE AND RETESTED OK.  
REPLACE SEAT BELT BUCKLE  
LEFT SEAT BELT BUCKLE INOP REPLACED BUCKLE  
R / SEAT AND REPLACE DRIVERS SEAT BELT BUCKLE CHECK OP, OK.  
REPLACE SEAT BELT ASSEMBLY  
REPLACED LEFT FRONT SEAT BELT  
INSTALLED SEAT BELT BUCKLE ASSY  
DEFECTIVE CHECK BELT OPERATION, ORDER PART REMOVE D S SEAT REPLACE LATCH REASSEMBLE CHECK OPERATION OK  
REPLACE DRIVERS SIDE SEAT BELT BUCKLE PER RECALL.  
580 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MT81203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON  
TESTED SEAT BELTS AND FOUND BOTH NOT LATCHING REPLACED BELTS AND RETESTED ALL OK  
REPLACE RIGHT FRONT SEAT BELT BUCKLE  
SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.  
REPLACE LT FRN SEATBELT ASSY  
WILL NOT LATCH. REPLACED RIGHT FRONT SEAT BELT.  
DR SEAT BELT BUCKLE TESTED & REPLACED BUCKLE  
COMPLETED RECALL  
CHECK SEAT BELT OPERATION PERFORM DIAG FOUND LATCH NOT LATCHING REPLACE SEAT BELT LATCH RETEST OPERATION OK  
6861 INSTALLED NEW DRIVERS SEAT BELT BUCKLE CANT PERFORM 01821 RECALL W OUT TOOL D S BUCKLE WOULDNT LATCH  
REPLACE DR SIDE SEAT BELT FOR RECALL  
REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES  
CHECKED AND CONFIRMED CONCERN. REPLACED SEAT BELT TO FIX REPAIR.  
18665 INOP WAR REPLACED HE DR SIDE SEAT BELT BUCKLE, RETESTS O  
REPLACED LEFT DRIVERS SEAT BELT  
HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.  
REPLACE RIGHT FRONT SEAT BELT BUCKLE TEST ALL OK AT THIS TIME  
REPLACE DRIVERS SEAT BELT

11 SEAT BELT NOT LATCHING A DR SEAT BELT BUCKLE NOT LATCHING. ORDERED NEW BUCKLE. INSTALLED PROBLEM FIXED  
14602 BUCKLE WILL NOT LATCH VERIFIED CONCERN REPLACED PASS FRONT SEAT BELT ASS QUALITY INSPECTED BY 8686 . . . .  
5577 BROKEN 01 REPLACED LT FT SEAT BELT BUCKLE  
8606 REPLACED SEAT BELT BUCKLE TESTED ALL WORKS PROPERLY  
09 7861203 LEFT FRONT SEAT ACCESS TO REPLACE DRIVERS SEAT BELT BUCKLE THAT  
LEFT FRT SEAT BELT BUCKLE SWITCH FAILED. VERIFIED CONCERN, TEST AND REPLACED LEFT FRONT SEAT BELT BUCKLE CLOSED BY WI  
REPLACED DRIVERS SIDE SEAT BELT BUCKLE  
REMOVE DRIVE SEAT BELT BUCKLE TO REPLACE (POPPE D LOOSE WHILE DRIVING  
OK AND REPL DFCVTE BUCKLE ASSY, REASSMBLE AND RECK, OK  
11849 SOP PART 0.8MT REMOVED AND REPLACED FEMALE SEAT BELT BUCKLE AFTER DUPLICATING CONCERN RETESTED QUALITY OK  
R&R SEAT BELT BUCKLE  
REPLACED SEAT BELT LATCH.  
FOUND SEAT BELT BUCKLE NOT LATCHING REPLACE SEAT BELT BUCKLE  
372 RECALL B2 TESTED AND REPLACED BOTH FRONT SEATBELTS  
SEAT BELT BUCKLE INOP R&R PASS FRONT SEAT TO REPLACE SEAT BELT BUCKLE  
REPLACED BROKEN BUCKLE  
DIAG AND REPLACED BUCKLE  
TEST & REPLACE DRIVERS SEAT BELT BUCKLE FOR SEAT BELT UN BUCKLES BY ITSELF CONCERN  
OK AND REPLACED SEAT BELT  
BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE  
NA REMOVE AND REINSTALL SEAT, REMOVE AND REPLACE BUCKLE.  
REPLACED BELT DUE TO BEING BROKEN  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
3388 INOP LATCH W VERIFY CONCERN, INSTALL DRIVERS SICE SEATBELT LATCH ASSEMBLY OK M TIME TO REPLACE PART, NO LABOR OP  
42 TECH 14507 MO 1253 REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE  
INSPECTED AND FOUND PASS FRONT SEAT BELT BUCKLE FIT LOOSE REPLACE SEAT BELT VERIFY REPAIR  
VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK  
REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE  
10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 ( 18880 ACCESS STEERING COLUMN & REPAIRED LOCK ACTUATOR BINDING  
IN SOME OF THE EFFECTED VEHICLES ITS POSSIBLE THAT THE DRIVERS AND OR THE PASSENGERS FRONT OUTBOARD SEAT BELT REPL  
IT WOULD WORK SOMETIMES THEN GET HUNG UP REPLACED SEAT BELT BUCKLE WITH NEW  
REPLACE SEAT BELT  
REMOVED AND INSTALL DRIVER SEAT BELT BUCKLE(SOP OPERATE THE SEAT BELT AND BUCKLE TO VERIFY OPERATION.  
18339 R&R L F SEAT, TEST & REPLACE SEAT BELT BUCKEL R&R R F SEAT, TEST & REPLACE SEAT BELT BUCKEL  
5050 L F SEATBELT BUCKLE INOP 0.9 M ITME REMOVE SEAT TO REPLACE BUCKLE 0.9 M TIME  
REPLACED 2 FRONT SEAT BELT BUCKLES. RECALL HAD PREVIOUSLY BEEN DONE, CALLED RECALL HOTLINE AND TOLD TO SUBMIT AS A RE

A SEAT BELT BUCKLE  
CC 42 BVASIC 7881203 M O 22082 REMOVED AND REPLACED BOTH FRONT SEAT BELT RECIEVERS,RETESTED OK.  
NA REPLACED DRIVERS SIDE SEATBELT BUCKLEMILEAGE IS CORRECT ENTERED INCORRECTLY AT SPALDING FORD ON 07  
REPLACED SEAT BELT  
LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH. REPLACED SEAT BELT BUCKLE NOW OKAY. 04 03 08.21 08.48.  
REPL DRIVERS SEAT BELT BUCKLE WPI ADD ON AUTHO BY AS  
REPLACED BUCKLE  
REPLACE RIGHT SEAT BELT.  
REPLACE LEFT SEAT BELT BUCKLE NO TIME LISTED  
FAULTY SEATBELT (61203) DIAGNOSIS AND REPLACED LF SET BELT BUCKLE  
REPLACED DRIVERS SEATBELT ASSY  
REPLACE SEAT BELT  
SEATBELT BUCKLE ASSY. M TIME R R SEAT AND REPLACED IMPROPERLY LATCHING SEAT BUCKLE ASSY.  
INOP REPLACE DRIVERS SIDE SEAT BELT BUCKLE  
NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE  
REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY  
REPLACE INOP BUCKLE  
FAULTY BELT ASSY .. ACCESSED ASSY AND REPLACED.  
INSTALL S.O.P SEAT BELT BUCKLE  
3801 ROAD TEST PERFORMED SYSTEM TESTS FOUND SEATBELT LATCH STICKING REPLACED LF SEAT BELT LATCH RETEST  
ERPL BELT AND BUCKLE ASSY  
REPLACED DRIVERS SEAT BET  
VERIFIED CONCERN,INSPECTED AND FOUND FAULTY SEAT BELT BUCKLE..... REMOVED AND REPLACED SEAT BELT BUCKLE TO CORRECT  
VERIFY CONCERN REPLACED SEAT BELT TECH 300  
REPL LF SEATBELT BUCKLET ASSEMBLY  
12486 FP 61203 CC 42 MT81203 .4 \* AUTH 3131 REPLACED THE DRIVERS SEAT BUCKLE  
SEAT BELT BUCKEL REPLACED SETA BELT BUCKLE  
REPLACE LEFT FRT SEAT BELT BUCKLE.  
COMPLETED.  
REPL SEAT BELT LATCH REPL SEAT BELT LATCH ASSY  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
01821 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE  
3848 SEATBELTS PASSED 01821 TEST, CUSTOMER STATES DRIVERS SEATBELT BUCKLE WILL COME LOOSE AFTER DRIVING AWHILE, REPL  
8121 RECALL WARR VERIFY PERFORM RECALL RR PASSENGER BELT RECHECK OK  
REPLACE LEFT FRT SEATBELT BUCKLE  
BAD SEAT BELT TONGUE AND ASSEMBLYSEATBELT ASSEMBLY FRONT REPLACE

VERIFY SEAT BELT INOP REPLACE DRIVERS SEAT BELT  
2413 ERRATIC W 42 REMOVE RT AND LEFT FRONT SEATS AND REPLACE SEAT BELT BUCKLES ON BOTH SEATS,ERRATIC  
REPLACE DRIVERS SEAT BELT BUCKLE  
CUST STATE THE ELFT FRONT SEAT BELT BUCKLE WONT LATCH CAUSE: SEAT BELT CORRE: REPLA  
REMOVED DRIVERS SIDE SEAT. R&R SEATBELT LATCH ANDVERIFIED REPAIR.  
REPLACED DR FRT SEAT BELT ASSY  
8400 REPLACED DRIVERS SEAT BELT LATCH. \*\*\* QUALITY CONTROL BY JOHN MEDROW \*\*\*  
REPLACE RECEIVER RECHECK OPERATION AND NOW OK.  
12831 SEAT BELT BUCKLE 42 WR VERIFIED CUSTOMERS CONCERN AND FOUND SEAT BELT WOULD COME LOOSE WHEN BRAKING HARD. /  
INSPECT LF BELT BUCKLE BINDING DOES NOT LATCH REPLACE, INSPECT LEFT REAR 2ND ROW SEAT BELT OPERATION FOUND BINDING, FI  
19248 LOOSE REPLACE LOOSE RF SEAT BELT BUCKEL  
16368 LOOSE REPLACE BOTH FRONT SEAT BELT BUCKELS LOOSE  
SREPLACE LEFT FRONT SEAT BELT BUCKLE  
INSPECTED DR SEAT BELT REPLACED REMOVED LF FR D OOR FOUND BAD REGULATOR REPLACED MOTOR AND REGU LATOR ASM WORK  
44768 REMOVE AND INSTALL SEATBELT ON PASSENGER SIDE  
REPLACE SEAT BELT  
R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT LATCH.  
RIGHT FRONT SEAT BELT BUCKLE INOPSEATBELT ASSEMBLY FRONT REPLACE  
1 REPLACE BELT BUCKLE  
REPLACE SEAT BELT  
CCK31 INTALLED NEW BUCKLE  
INSPECT ACCESS SEAT ADN REPLACE SEAT BELT  
CK SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE  
REPLACED SEAT BELT  
REPLACE LEFT FRT SEATBELT  
  
REPLACED SEAT BELT BUCKLE  
BUCKLE ASSEMBLY MALFUNCTION SEATBELT ASSEMBLY FRONT REPLACE  
SEAT BELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE  
ERRACTIC OPERATION (33) ACCESS LF SEAT & REPLACE SEATBELT BUCKLE, TK8582  
BROKEN VERIFY CUSTOMER CONCERN. REMOVE AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE.  
250 TIME TO REPLACE DRIVERS SIDE FRONT FEMALE END OF SEAT BELT ASSEMBLY TIME TO R AND I SEAT ASSEMBLY TO GAIN ACCESS  
1 REPLACED L F SEAT BELT BUCKLE  
98 01S21D 0.8 REPL D SIDE SEAT BELT  
15411 SERVICE REPLACE THE SEAT BELT BUCKLE CAR HAS DAMAGE TO THE LEFT FRONT FENDER BWO  
DEFECTIVE BUCKLE REPLACED SEATBELT BUCKLE CC42  
REPLACE INOP SEATBELT INSTALLED SEAT BELT BUCKLE

7108 R&R SEAT AND SEAT BUCKLE  
7881202 CODE 89 7448 M O R I BOTH FRONT BUCKET SEATS. REPLACED BOTH FRONT SEATBELTS. RETEST PASS.  
TEST AND REPLACED SEAT BELT  
REPLACED DRIVERS SIDE SEATBELT  
REPLACED SEATBELT BUCKLE AND NOW OK.  
RT FT SEATBELT WONT LATCH SEATBELT PROBLEM REP L BELT AND CK AFTER REPAIRS  
R&R PASSANGER SEAT REPLACE BUCKLE  
CK AND REPLACED LEFT FRT SEAT BELT BUCKLE ASSY.  
RECALL REPLACE RT FT BUCKLE  
INSPECT PASS SIDE SEAT BELT REPLACE DEFECTIVE SEAT BELT  
4889 RECALL 01S21E 0.9 7282 REPLACED LH AND RH SEAT BELT BUCKLES PER RECALL 01S21  
REPLACE BOTH FRONT SEAT BELT BUCKLES  
1008 W 302 VERIFIED CONCERN. REPLACE DRIVER SEAT BELT RECIEVER DUE TO INOP. RETEST, OK AT THIS TIME. QUALITY INSPECTED BY S  
SEAT BELT LATCHES DEFECTIVE REPLACE SEAT BELTS FRT.  
SEAT BELT BUCKLE REMOVED PASS SEAT AND REPLACED SEAT BELT BUCKLE.  
3438 BROKEN 01 REPLACED LT FT SEAT BELT ASSY  
REPLACE DRIVERS SEAT BELT BUCKLE  
REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL THE DRIVER SIDE SEAT BLET BUCKLE WAS DEFECTIVE.  
1 TECH REMOVED AND REPLACED DRIVER SIDE SEAT BELT ASY ALL OK AT THIS TIME  
REPLACED SEAT BELT BUCKLE WITH NEW ONE  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
  
REPLACED LEFT SEAT BELT  
INSP AND VERIFY FRONT CENTER SEAT BELT BUCKLE INOP, REPLACED CENTER SEAT BELT BUCKLE, CHECK OPERATION OK. COND CODE  
REPLACED RIGHT FRONT SEAT BELT  
REPLACE DRIVERS SEAT BELT BUCKLE NOT CATCHING AND R. REAR MIDDLE SEAT BUCKLE INOP NOT CATCHING. REPLACED.  
INSPECT LEFT FRONT TEAT BELT WITH TESTER, REPLACE LEFT FRONT SEAL BELT BUCKLE  
REMOVED AND INSTALLED FRONT SEAT BELT  
REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY  
REPLACE RT SIDE BELT.  
WILL NOT BUCKLE UP LABOR OP. 01S21D 0.8 PERFORM RECALL #01S21 REPLACE PASS. SEAT BELL BUCKLE PER RECALL  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
INSTALLED DRIVERS SEAT BELT LATCH  
LEFT FRT SEAT BELT INOP WILL NOT BUCKLE REPLACE  
DOESNT OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE  
CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION  
CP 7881203 CC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT

REPLACED BUCKLE

10539 SEAT BUCKLES 30 WR INSPECTED AND FOUND BOTH SEAT BUCKLES INOP. R R BOTH FRONT SEAT BUCKLES AND RETESTED.PASS.  
REPLACE DRIVERS SEAT BELT BUCKLE.

33072 MT 7881203 .8 & REPLACED DRIVER SEAT BELT BUCKLE.

REPLACED BELT BUCKLE

CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.

SEATBELT ASSEMBLY FRONT REPLACE

SOP. INSTALLED RF SEAT BELT BUCKLE, VERIFIED REPAIRS

REPLACE PASS SIDE SEAT BELT BUCKLE

NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

SEAT BELT WONT HOLD REPLACED DRIVERS SEAT BELT

1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE

INOP REPLACED RIGHT SIDE SEAT BELT BUCKLE

REPLACED LEFT BUCKLE

M0782 REPLACED DR SIDE BELT BUCKEL AS PER RECALL.

175 RECALL 01821. WR. 01821D. PERFORM RECALL 01821. PERFORM INSPECTION AND REPLACE PASSENGERS SIDE SEAT BELT BUCKLE. I

REPL SEAT BELT BUCKLE PERFORM

DEFECTIVE REPLACED RH BUCKLE

1 DIAG UPON INSP REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMBLY & CKD F  
E VERIFIED COMPLAINT REPLACED FRONT BUCKLE ASSEMBLYS

823 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES

INSPECT AND REPLACE DRIVER SIDE SEAT BELT

REPLACED ALL FRONT SEAT BELT BUCKLES

REPLACE SEAT BELT BUCKLE ADDITIONAL MISC. REPAIRS

DIAG AND RR SEATBELT

CHECK SEAT BELT PASS FRONT COME OUT AT WILL COULD NOT CONFIRM RECAA WAS PERFORM AND PASSED REMOVE AND REPLACE SE

8841 REPLACE DR FT SEAT BELT

SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE

TRACK ASSEMBLY FRONT SEAT REPLACE

REPLACE LEFT FRONT SEATBELT END

VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY , OK AT THIS TIME

SEAT BELT BROKE SEATBELT ASSEMBLY FRONT REPLACE

REPLD SEAT BELT BUCKLE

3052 FOUND DRVS SEAT BELT BUCKLE NOT LATCHING REMOVED AND REPLACED BUCKLE

REPLACED DRIVER SIDE SEAT BELT CP 81203 CC 42

31170 BUCKEL R,LT FT SEAT TO REPLACE SEAT BELT BUCKLE

RECALL 01821  
 REPLACED SEAT BELT BUCKLE  
 INSPECT 7 TEST SEAT BELT BUCKLE & VERIFIED NOT WORKING PROPERLY. R&R SEAT ASSY TO GAIN ACCESS. REPLACE DRIVERS SEAT BELT  
 RT FT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE  
 VERIFIED CONCERN, REPLACED BAD SEAT BELT BUCKLE.  
 RENEW DRIVER SEAT BELT ASSY  
 RUN BCE DIAG. W NGS. RUN PINPOINT TEST. REPLACE LF FT SEAT BELT BUCKLE.  
 SEATBELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE  
 DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....  
 3259 42 DOES NOT OPERATE PROPERLY REPLACED L FRONT BUCKLE  
 INSPECT. REPLACED L F SEAT BELT BUCKLE  
 SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE  
 DEFECTIVE REPLACED DEFECTIVE DRIVERS SEAT BELT BUCKLE MILEAGE ERROR ON PRIC  
 REPALCED DRIVER SIDE SEATBELT BUCKLE  
 25184 REPLACE RIGHT AND LEFT SEAT BELT FEMALE ENDS. (BUCKET SEATS WITH CONSOLE)  
 3159 42 REPLACED DRIVER SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES  
 VERIFY SEAT BELT BUCKLE INOP, R&R PASSENGER SEAT ASSEMBLY, REPLACED SEAT BELT BUCKLE, CHECK OPERATION  
 1 REPLACED SOP DRIVERS SEAT BELT BUCKLE ASSEMBLY  
 PERFORMED RECALL 01821, REPLACED DRIVERS SIDE SEAT BELT. 01821D...0.8...  
 NA INSPECTED BUCKLE AND REPLACE RIGHT FRONT BUCKLE.  
 REPLACE DRIVER SIDE SEAT BELT RETEST SEAT BELT PASS TEST DONE  
 BROKEN, CRACKED SEATBELT ASSEMBLY FRONT REPLACE  
 VERIFY CONCERN REPLACE SEAT BELT BUCKLE CORRECTED  
 1 R&R DRIVERS SEAT BELT BUCKLE ASSEMBLY. R&R SEAT TO ACCESS. RETEST. CC42  
 4626 FAULTY RT SIDE BUCKLE NEC TO REPLACE RT SIDE BUCKLE  
 RECALL PERFORMED RECALL. REPLACED SEAT BELT BUCKLE AT RIGHT FRONT  
 REPLACED SEAT BELT 01821 RECALL  
 REPLACE BOTH FRONT SEAT BELTS.  
 REPLACED SEAT BELT PER ED KARAZIN  
 RPL DEFECTIVE SEAT BELT FOUND BY SEATBELT ASSEMBLY FRONT REPLACE  
 PERFORMED RECALL  
 1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST  
 RECALL REPLACE BOTH ISDES BUCKLES PER 01821  
 RECALL 01821 TECH 14507 MO 11714 REMOVED AND REPLACED DRIVERS SIDE SEAT BELT LATCH BUCKET POWER SEAT  
 PASS FRONT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE  
 REPLACE PASSENGER SIDE SEAT BELT BUCKLE  
 SEAT BUCKLE IN OP AT THIS, RELEASES BELT 811 INSPECT AND TEST DRIVER SEAT BUCKLE ASSY, REMOVE DRIVER SEAT AND REPLACE

10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE  
SEAT BELT BUCKLES INOP REPL INOP FRONT SEAT BELT BUCKLES  
1 REPLACED DRIVERS SIDE SEAT BELT BUCKLE  
DOES NOT WORK PROPERLY. REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY.  
14007 RECALL 01S210 0.4 REPLACE PASSENGER SIDE SEATBELT BUCKLE PER RECALL  
REPL BUCKLE ASSY  
15265 MT 81202 0.8 INSPECTED AND REPLACED RT. FRONT SEATBELT BUCKLE , R AND R RT.SEAT FOR ACCESS  
1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE  
DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE  
RECALL PERFORMED RECALL. REPLACED 2 SEAT BELTS  
RECALL INSTALLED RECALL SEATBELT BUCKLE A98

RECALL INSPECT PER RECALL, R+R RT. FT. SEAT REPLACE BUCKLE  
E COMPLETED ABOVE

INSPECTED.REPLACED BOTH FRONT SEATBELT ASSEMBLY.TEST & RETEST.

SEAT BELT BUCKLE REPALCE LEFT SIDE SEAT BUCKLE

BROKEN SEATBELT ASSEMBLY FRONT REPLACE

INOP SEATBELT ASSEMBLY FRONT REPLACE

REPLACED SEAT BELT

REPLACED DRIVERS SEAT BELT

REPLACED SEAT BELT LATCH

7124 W INSP AND REPLACED PASS SIDE SEAT BELT RETESTED ALL OK

25588 SEATBELT ON DRIVERS SIDE FOUND FAULTY WARR VERIFIED CONCERN, FOUND SEATBELT BUCKLE FAULTY, REMOVED SEATBELT

REPLACE DRIVERS SIDE SEAT BELT BUCKLE

REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD

ACCESS BOTH SEATS, REPL BUCKLES TRACK ASSEMBLY FRONT SEAT REPLACE

BUCKEL SEATBELT ASSEMBLY FRONT REPLACE

5190 42 W R&R DRIVERS SEAT FOR ACCESS, INSTALL DRIVERS BELT BUCKLE

BROKEN SEATBELT ASSEMBLY FRONT REPLACE

REPALCED DRIVERS SIDE SEAT BELT BUCKLE

REPLACED SEAT BELT 01S21

REPLACE SEAT BELT ASSY

R&R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT AS SEMBLY, LOOSE.

DRV SEAT BELT BUCKLE INOP CHECK AND NECESS TO REPL INOP DRV SEAT BELT BUCKLE

FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE

4680 81202 33 RIGHT FRONT SEAT BELT BUCKLE WAS LOOSE R I RIGHT FRONT SEAT TRACK TO REPLACE SEAT BELT BUCKLE. 81172A .4 6'

8573 REPLACED LEFT FRONT SEAT BELT LATCH. \*\*\* QUALITY CONTROL BY JOHN MEDROW \*\*\*

A                    REPLACE LEFT SEAT BELT BUCKLE  
REPL SEAT BELT BUCKLES  
LEFT SEAT BELT BUCKLE BINDING    DG, RPLD SEAT BELT BUCKLE  
CC487 REPLACED BOTH SEAT BELT BUCKLES  
RF SEAT BELT WONT STAY LATCHED    SEATBELT ASSEMBLY FRONT    REPLACE  
REPLACE RF SEATBELT BUCKLE  
NO OPERATING PROPERLY    REPLACE DRIVER SEAT BELT BUCKLE ASSY  
INSPECT AND REPLACE DRIVERS SEAT BELT  
16225 01S21D 0.8 9267 REPLACED DRIVERS SEATBELT BUCKLE PER RECALL  
2058 INSTALL L F SEATBELT BUCKLE PER RECALL 01S21.  
SEAT BELT                    INSP AND REPLACE SEATBELT BUCKLE  
REPLACED LF SEATBELT.  
01S21                    INSPECT AND REPLACE ONE BUCKLE PER RECALL  
1    INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE  
REPL SEAT BELT BUCKLE            PERFORM  
REPLACE RIGHT SIDE BELT  
SEATBELT RECEIVER INOP            CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER  
CC487 REPLACED SEAT BELT BUCKLE  
REPLACED LEFT FRONT SEAT BELT BUCKLE  
REPLACED LEFT FRONT SEAT BELT BUCKLE ASSY. 03 18 13.32 14.31.

TECH\_TXT2

CONNECTOR, REINSTALLED NEW ONE. NOT AN EASY TASK.  
AT THIS TIME

RC04-011 02894

IME

.E ASSY RETEST OK

RQ04-011 02895

ELT BUCKLES RETEST OK

REPLACED RIGHT FRONT BELT BUCKLE AS PER BULLETIN QC BF

ELECTRICAL DIAGNOSIS \*NGS PIN POINT TEST FOUND

REPLACED RIGHT SEAT BELT BUCKEL FAILED UNDER SEAT BELT BUCKEL TEST QC BF

EAT BELT BUCKLE

CC 42

\* LATCHED INPUT CONNECTOR WORKING PROPERLY

RD04-01 1 02697

PLACED PASSENGER BUCKLE PER RECALL 01921 SEE RO 301713 FOR DRIVERS BUCKLE REPLACEMENT.

MILEAGE ON RO 224538 SHOULD HAVE BEEN 2420 NOT 24206.

CCD4.M;14364.

APROX TIME: 0.4 HRS JOB STARTEDV 7.68.7 ON 01 23 02

REPAIR ALL TO SPEC AT THIS TIME

PASSENGER SIDE

REPAIR CCD4..M:10789

SEAT

WHEEL AS SERVICE PART REPLACEMENT OF LAST RO

ASSY RETEST OK  
QUALITY CHECKED BY MJM

ERIFY REPAIR..

T DID NOT PASS REPLACED DRIVERS SEATBELT BUCKLE AND RETEST

IR TECH 4441  
ED BAD PASS SIDE SEAT BELT

R004-011 02700

BY TIM HUDSON\*\*\*

BUCKLE, NO LABOR OPS, USE M TIME

R004-011 02701

BELT BUCKLE

FRONT SEAT BELT BUCKEL OK

ONE

P1

CASUAL PART 1L7Z 7861203 BAA  
ACED BOTH LEFT AND RIGHT BUCKLE ASSEMBLIES PER RECALL.

REGULAR WARRANTY

71901

\* CONCERN...

AGED DRIVERS SEATBELT BUCKLE FOR RECALL 01S21

RC04-011 02704

APPROX TIME: 0.4 HRS JOB STARTED 10.716.8 ON 05 15 02

T COMING LOOSE.  
EPLACE SEAT BELT AND RETEST OK

CS OK

302,1008.

42

RQ04-011 02708

RETEST PASS OK.

FOR PROP

EAT BELT BUCKLE CHECK GOOD MT FOR NO LABOR OFFP

RQ04-011 0Z707

.T BUCKLE ASSE.

DR TICKET CAR HAS 6707

BUCKLE ASSY, TEST OP

RC04-01 1 02708

BUCKLE,REPLACED SEATBELT BUCKL E, VERIFIED REPAIR

1704AC .8

RQ04-011 02709

CUST\_TXT

CUST SAYS PASS SEAT BELT WONT HOLD

INSTALL S.O. PART FOR SEAT BELT BUCKLE (POSS RECALL)

DRIVERS SEAT BELT BUCKLE INOP

SEAT BELT LIGHT ON PARTS IN

FRONT LEFT SEAT BELT WILL COME UNATTACHED WHILE DRIVING DOWN THE ROAD

INSTALL SOP SEAT BELT L F

SO PART SEAT BELT INSTALL

DRIVERS SEAT BELT COMES UNBUCKLED.

INSTALL SOP SEAT BELT

S40 STATES THAT THE PASS SIDE SEATBELT IS NOT LATCHING PROPE

CUST STS DRIVERS SEAT BELT BUCKLE DOESNT STAY LATCHED SOMETIMES

CHECK SEAT BELT SOP

REPLACE SEAT BELT ( SOP) STICKS

C S SEAT BELT ON D S

DRIVER SEAT BELT BUCKLE INOP

CUST STATES THE DRIVERS SEAT BELT UNLATCHES WHILE DRIVING. CONCERN OCCURS INTERMITTENTLY...CK & ADVI

SEATBELT INOP SOP IS IN

INSTALL SPECIAL ORDER PARTS RELATED TO SEAT BELT RECALL ON PREVIOUS RO.

DRIVERS SEAT BELT WONT LATCH

THE DRIVERS SEATBELT WILL UNLATCH ON ITS OWN WHEN DRIVING

CUST STATES DSIDE SEATBELT BUCKLE COMES LOOSE

CUSTOMER SAYS DRIVERS SEAT BELT IS INOP PARTS ARE IN

SEATBELT NOT STAYING ENGAGED

DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING..S40

INSTALL SOP SEATBELT BUCKLES BOTH FRONT, WONT STAY LATCHED, RO 138815 TECH 7619

RECALL SEAT BELT BUCKLES PARTS IN

CK.CAN NOT SECURE DRIVER FRONT SEATBELT

NEEDSR FRONT BELT

CUSTOMER STATES DRIVERS SIDE SEAT BELT INOP

CUSTOMER STATES SEATBELT RECALL INSTALL SOP

LT FRONT SEAT BELT WONT LATCH AT TIMES S O

FRONT SEAT BELT BUCKLES DO NOT FULLY LATCH

R R S O SEATBELT

LEFT FRONT SEAT BELT INTERMIT STICKS

CUSTOMER STATES FRT PASS. SEAT BELT LATCH WOULD NOT LET YOU LATCH IT IN.

FRONT SEAT BELT IS INOP

RECALL 01S21 SEAT BELT INSPECTION NOT ON RECALL BUT LEFT BUCKLE WONT LATCH

LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING  
CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNONCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECA  
S28 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD  
REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES S.O.PARTS  
SEAT BELT INOP  
CHECK SEAT BELT ON DRIVER SIDE WONT LATCH EASILY  
PASS SIDE SEAT BELT INOP

OWNER STATES LT FRT SEATBELT COMES OUT OF BUCKLE WHILE DRIVING  
CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF  
SEATBELTS DO NOT LATCH PROPERLY WITH TOOL  
CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERENT TIMES  
CUST STATES TO PERFORM SEAT BELT RECALL 01S21

REPLACE SEAT BELT BUCKLE  
DRIVERS SEATBELT BUCKLE INOP  
FRONT SEAT BELT WONT LATCH  
SEAT BELT COME UN BUCKLED WHILE DRIVING  
THE RIGHT FRONT SEAT BELT BUCKLE WILL NOT ENGAGE.  
SEAT BELT WILL NOT LATCH DRIVERS FRONT  
SOP SEAT BELT  
PARTS REPLACE SEAT BELT ON THE DRIVERS SEAT  
CUSTOMER STATES DRIVERS SEAT BELT DOES NOT LATCH  
CUST STATES DRIVERS SEATBELT UNLATCHES ITSELF  
CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH  
LEFT FRONT SEAT BELT WILL NOT BUCKLE AND CHIME STAYS ON  
RIGHT FRONT SEAT BELT BUCKLE INOP

DRIVERS SIDE SEAT BELT LATCH NOT WORKING AT TIMES  
VEH SEATBELT LATCH INOP  
L F SEAT BELT W N LATCH  
C S THAT LEFT FRONT SEAT BELT RECEIVER WILL NOT LOCK CHECK AND ADVISE

CK RIGHT FORNT SEATBELT BUCKLE INTERMITTANTLY WILL NOT LATCH  
CUSTOMER STATES SEAT BELT BUCKLE ON DRIVER SIDE IT JAMMED  
SEAT BELT NOT WORKING PROPERLY  
INSTALL SOP SEAT BELT BUCKLE.  
CHECK DRIVERS SEAT BELT COMES UNLATCHED S40

D S SEAT BELT DOES NOT STAY BUCKLED  
RECALL 01S21 REPLACE SEATBELT  
PASSENGER SIDE SEATBELT BUTTON STICKS SOP IN  
CK DRIVERS SIDE SEAT BELT BUCKLE INOP  
RIGHT FRONT SEATBELT BUCKLE JAMS  
REPLACE RIGHT FRONT SEAT BELT BUCKLE WITH NEW WILL NOT LATCH PARTS IN STOCK TO REPLACE  
CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED

PASSENGER FRONT SEAT BELT HARD TO CLASP IN  
SEAT BELT BUCKLE NOT WORKING PROPERLY  
CHECK PASS SIDE COMES UNLATCHED  
01S21 SEAT BELT BUCKLE  
CUST STATES THAT DRIVER SEAT BELT SOMETIMES DOES NOT LOCK IN AND COMES LOOSE WHEN DRIVING  
DRIVER SIDE SEAT BELT INOP  
C S THE DRIVERS SEAT BELT WILL NOT STAY LATCHED  
SEAT BELTS NO WORKING CORRECTLY  
DRIVER SIDE SEAT BELT INOP  
DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE  
CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SOP IN  
CUSTOMER STATES DRIVERS SEAT BELT WILL COME UNLATCHED BY ITSELF WHILE DRIVING. CC S28

SEAT BELT BUCKLES DID NOT PASS NEED TO REPLACE SOP BELTS ARE HERE  
CUSTOMER STATES THE RIGHT FRONT SEAT BELT DOES NOT LATCH  
CUST STATES DRIVER SEAT BELT WONT STAY LATCHED  
SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41062, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND RI  
CUSTOMER STATES DRIVERS SEAT BELT INDICATOR INOP  
CK SEAT BELT WILL NOT BUKLE  
CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH  
S25 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE  
RECALL 01S21 SEAT BELT BUCKLE SOP HERE PASSENGER SIDE

SPO HERE FOR RECALL # 02821 INSPECTED ON 12 19 01 RO# 10564 LEFT FRONT FAILED  
C S DRIVER SEAT BELT WONT LATCH  
SEAT BELTS INOP  
SEAT BELT BUCKLE INOPERATIVE  
CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.

BOTH FRONT SEAT BELT DONT SNAP TOGETHER GOOD  
REPLACE DRIVERS SEAT BELT BUCKLE INOP  
C S THE DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING

PASSENGER SIDE SEAT BELT DOESNT HOLD PER OASIS NO OPEN CAMPAIGN BUT FAILED TEST  
S40 C S DRIVERS SEATBELT WILL NOT STAY LATCHED SOP IN  
CUST STATES PERFORM RECALL ON SEATBELT ASSY  
LEFT & RIGHT FRONT SEAT BELT BUCKLES DEFECTIVE  
CK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40  
PERFORM RECALL #01821

DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED  
CUST REQRS RECALL 01821 PASS BELT  
CHECK SEAT BELTS BINDS  
PASS FRT SEAT BELT INSPECTION  
CK PASSENGER FRONT SEAT BELT WONT LATCH  
CUST STATES CK PASS FT SEAT BELT BUCKLE INOP  
S26 CUST STATES DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED AT TIMES, PARTS ORDERED AND HERE.  
CUST STS DRIVERS SEATBELT WONT LATCH  
S25 DRIVERS SEAT BELT WILL COME UNLATCHED  
CK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN  
DRIVERS BELT WILL NOT CLOSE  
INSTALL TESTER FAILED INSTALLED 2 BUCKLE ASSYS  
CHECK FOR LEFT FRONT SEATBELT INOP  
LEFT FRONT DRIVER SEAT BELT INOP  
CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT CLICK IN BUCKLE  
SEAT BELT BUCKLE

WPG40..S40..CUSTOMER SAYS DRIVERS SEAT BELT BUCKLE DOES NOT LOCK..

LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIMES

LEFT SEAT BLET NOT LATCHING AT TIMES

CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNONCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECALL FOR LABOR OPE  
CK DRIVERS SEAT BELT FEMALE END WONT LATCH

CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES NOT STAY LATCHED REPLACE BUCLE PART HERE SEE KAY

LEFT FRONT SEAT BELT COMES UNDONE WHEN BRAKING

DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FAILING ALSO

SEAT BELT HERE FOR VEHICLE SEE RECALL

LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES

CUST STATES L F SEAT BELT KEEPS COMING UNBUCKELED

INSTALL SOP SEAT BELT FOR REECALL 01S21

SEAT BELT INOP

CUST STATES DRIVERS SEATBELT LOCKS,SOP HERE

CUST STATES DR. SIDE SEAT BELT WONT BUCKLE

SOP SEAT BELT IN

RF SEAT BELT WONT BUCKLE

SEAT BELT BUCKLES WILL NOT STAY LATCHED

USE SPO 01275014

CHECK SEAT BELT P O

DRIVERS SEAT BELT WILL NOT UNBUCKLE, SOMETIMES

CHECK AND ADVISE CUST STATES DRIVER SIDE SEAT BELT DOES NOT LOCK IN TO BUCKLE. S40

LEFT FRONT SEAT BELT WONT BUCKLE

THE RIGHT FRONT SEAT BELT BUCKLE IS INOPERATIVE.

CUST STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK

CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.

PERFORM RECALL #01S21

CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.

PERFORM RECALL #01S21

INSTALL SPECIAL ORDERED PART,RIGHT FRONT SEAT BELT BUCKLE PART WAS SPECIAL ORDERED,NOT LATCHING

PERFORM RECALL #01S21

CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING

S25 LT FT SEAT BELT WONT STAY LATCHED

INSTALL SOP PASS FRIT SEAT BUCKLE

S40 CK DRIVER SEAT BELT WONT STAY BUCKLED REPORT

CUSTOMER SAYS THAT DRIVERS SEATBELT WILL UNLATCH WHILE DRIVING

SEAT BELT BUCKLE RETENTION

INSTALL S,O,P BUCKLE DRIVERS SEAT AS PER RECALL 01S21

CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PFC PARTS HERE.

RIGHT SEAT BELT BUCKLE WONT LATCH

PASSENGER AND DRIVERS SIDE SEAT BELTS INOP

(FAILED)

RIGHT FRONT SEAT BELT WILL NOT CONNECT

S40\*CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING

DRIVERS SIDE SEAT BELT INOP

(FAILED)

PERFORM RECALL #01S21

O R L F SEATBELT BUCKLE COME LOOSE

CUST STATES PASSENGER SEAT BELT DOES NOT WORK PROPERLY

S40 RIGHT FRONT SEAT BELT WAS ORDERED FOR RECALL BUT NEVER REPLACED IN STOCK

CUST STATES DRIVERS SEAT BELT WONT CATCH BUCKLE AND STAY FASTENED

RECALL SEAT BELT BUCKLE,REFER TO RO 981718

REPLACE DRIVERSIDE SEAT BELT LATCH(SOP IN)

PASS SIDE SEAT BELT DOESN T WORK

CUSTOMER STATES R F SEAT BELT NOT HOLDING ADVISE

OK FRONT SEAT BELT BUCKLES RELEASE WHILE DRIVING.

RIGHT SEAT BELT BUCKLE WONT LATCH

BOTH FRONT SEAT BELT BUCKLES INOP

PERFORM RECALL #01S21

CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED RECALL WAS CHECKED NO PROBLEM 8 3 01 BY TECH

DRIVERS SEAT BELT UNLATCHES BY ITSELF WHILE DRIVING

PASSENGER SEATBELT COMES UNBUCKLED SOMETIMES

REPLACE SEAT BELTS

S40 OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED AT TIMES, RED CAP DOESNT COME BACK UP PROPERL

CUST STATES DRIVERS SEATBELT BUCKLE WONT LATCH AT TIMES

PERFORM RECALL #01S21

PERFORM RECALL 01S21,SEAT BELT BUCKLE RECALL.

REPLACE DR. FT. SEATBELT SOP

USE SPO 02128003

CUST STATES CHECK FRONT SEATBELT BUCKLES

S38\*CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT UNLATCHES WHILE DRIVING

S40 INSTALL SOP PARTS, DR FRONT SEAT BELT UNBUCKLES WHILE DRIVING

DR SEAT BELT WILL COME UN LATCHED

CUST STATES THE DRIVER SIDE SEAT BELT BUCKLE IS INOP

DRIVERS SEAT BELT WONT BUCKLE PART IS HERE

VERIFY THE SEAT BELT RECALL WAS PERFORMED CORRECTLY CUST THOUGHT A PART HAD TO BE ORDERED LAST VISIT BUT NO SOP IS II

C S DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING CHECK AND ADVISE

WARRANTY REPAIR DRIVER SIDE SEAT BELT BUCKLE WILL NOT HOLD  
DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING  
C S DRIVERS AND PASS SD BUCKLES COME UNLOCKED INTERM. SOP  
C S THAT THE DRIVER S SEAT BELT IS INOP  
PERFORM RECALL #01S21

PERFORM RECALL #01S21

DRIVERS FRONT SEAT BELT BUCKLE DOES NOT LATCH INTERM. WHEN IT DOES IT IS HARD TO GET BELT UN LACTCHED  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE WILL NOT CLOSE

01S21 SEAT BELT CAMPAIGN

SEAT BELT WILL NOT LATCH

LEFT FRONT SEAT BELT DOES NOT STAY LATCHED. CHIME FOR SEAT BELT GOES OFF EVEN AFTER SEAT BELT IS BUCKLED  
SEAT BELT PART HAS COME IN, PLEASE INSTALL.

OK SEATBELT WILL NOT BUCKLE

PASSENGER SIDE FRONT SEAT INOP, 1H TRIM CODE

CK OUT SEAT BELT ON PASSENGER SEAT DONT WORK

CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.

PERFORM 01S21 RECALL SEATBELT

DRIVER SIDE SEAT BELT WILL NOT LATCH

DR FRT SEAT BELT COMES UNLATCHED WONT LATCH AT TIMES 838

SEAT BELT ORDERED ON RECALL RO #13422

S40, CUSTOMER STATES DRIVER SIDE SEAT BELT WILL NOT STAY FASTEN, IT KEEPS POPPING LOOSE.

SEAT BELT WILL NOT LATCH YOU HAVE TO PRESS THE RED BUTTON TO LATCH

CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES LOCK

CUSTOMER STATES LEFT FRONT SEAT WILL UNLATCH

CUSTOMER STATES THAT DRIVERS SIDE SEATBELT IS INOP FINAL ATTEMPT REPAIR SERVICE PART WARRANTY

S40 CUSTOMER STATES THAT DRIVER SEAT BELT WONT LATCH

CS DR SEAT BELT WONT LATCH 836

CUSTOMER REPORTS DRIVER S SEAT BELT BUCKLE WILL NOT LATCH... WILL NOT HOLD BELT.

A98 PERFORM 00S21 SEAT BELT BUCKLE

CHECK FOR SEAT BELT INOP

S28 CUST STS LEFT FRONT SEATBELT UNLATCHES BY ITSELF SOP RO#329063 MI 13720 1 2 02

S40 DRIVERS SEAT BELT WILL NOT LATCH

CUSTOMER STATES THE DRIVERS SEAT BELT DOES NOT ALWAYS LOCK IN 3

CK FOR DRIVER SIDE SEATBELT INOP FEMALE PART

SEAT BELT COVER CAME IN A FEW MONTHS AGO

S25 DRIVERS SIDE SEAT BELT WILL NOT GO INTO CLAMP AT TIMES

PASS FRONT SEAT BELT INOP  
CUSTOMER STATES BOTH FRT SEAT BELT BUCKLES WONT WORK  
S26 CUST STS LEFT FRONT SEATBELT WILL NOT LATCH SOP RO#328734 MI 18980 1 14 02  
SEAT BELTS WILL NOT LATCH PROPERLY  
BELT SEAT ASSY

USE SPO 01282018

DR. SEAT BELT BUCKLE HAS COME LOOSE TWICE SINCE RECALL PERFORMED.  
PART IN SEAT BELT  
DRIVERS SEAT BELT

LF. SEAT BELT BUCKLE WONT LATCH SOP IN  
INSTALL SOP PASS FRONT SEAT BELT INOP  
01S21 RECALL SEAT BELT

ASS PERFORM 00S21 SEAT BELT BUCKLE  
PASSENGER FRONT SEAT BELT BUCKLE WONT LOCK SEAT BELT IN  
CUSTOMER STATES:DRIVERS SEAT BELT COMES UNBUCKLED WHILE DRIVING.  
CHECK SEATBELTS

LEFT FRONT SEATBELT BUCKEL INOP  
S40 CK MID SEAT AND DRIVERS SEAT BELTS WILL COME UNBUCKLED. RELATED TO 01S21 IF SO REFERENCE BACK.  
C S LF SEAT BELT WONT LOCK CK AND ADVISE  
T80 SEE DUANE DRIVERS FRONT SEAT BELT WONT LATCH INT TRIM TAN 1H

CUST STATES DRIVERS SEAT BELT WILL NOT LOCK  
RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 1H  
SEAT BELT BUCKLE NOT ENGAGING SOMETIMES ON P SIDE FRONT  
PERFORM 01S21 RECALL SEATBELT  
CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED  
DRIVERS SEAT BELT INOP PART HERE REF.RO#84032, TECH 117 BY NOON  
S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE..  
CK DR SEATBELT COMES UNDONE WHILE DRIVING  
PARTS HERE INSTALL SEAT BELT RECEIVER  
SEAT BELT BUCKLE INSTALL SOP  
CUSTOMER STATES RIGHT SEATBELT DOES NOT ALWAYS LATCH  
QUALITY CHECK INITIALS SEAT BELT ON DRIVERS SIDE DOES NOT BUCKLE S40  
PERFORM 01S21 RECALL SEATBELT  
DRIVER POWER SEAT, PASS MANUAL SEAT, BOTH FAILED  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE INOP  
S26 DRIVERS SIDE FRONT SEAT BELT UNBUCKLES BY ITSELF  
CUST STATES PASS FRT SEAT BELT WILL NOT LATCH

RO04-011 02718

S40 CUSTOMER STATES PASSENGER SIDE SEAT BELT BUCKLE STICKING, STATES NOT LATCHING...

S25 SEATBELT WONT STAY LOCKED

SEATBELT BUCKLE UNLATCHES

C 8 DRIVERS SIDE SEAT BELT NOT WORKING

DRIVER SIDE SEAT BELT BUCKLE INOP INTERIOR CODE IH

CK BOTH DRIVER AND PASSENGER SEAT BELT HARD TO UNSNAP

CUST STATES PASS FRT BELT WONT LATCH CHECK AND ADVISE

SEAT BELTS WILL NOT LATCH PROPERLY

CHECK SEATBELTS INOP

CUST SAYS RIGHT FRONT SEAT BELT DOES NOT HOLD AND COMES UNLATCHED

REPAIR RIGHT AND LEFT FRT SEAT BELT BUCKLES DO NOT CATCH AT TIMES. \*\* PARTS ORDERED & HERE \*\* TECH# 8370 \*\*

RECALL 01821 SEAT BELT BUCKLE

CUST STATES LEFT SEAT BELT GET LOOSE WHEN DRIVING

INSTALL SPECIAL ORDERED PART. SPOT ID 133827 SEAT BELTS

CUST STATES MIDDLE SEAT CENTER SEAT BELT WONT LATCH

SEAT BELTS WILL NOT LATCH PROPERLY

S40 SEATBELT CUST STATES THE DRIVERS SEATBELT WILL NOT HOLD LATCH

INSPECT PER 01821 RECALL INSTRUCTIONS

SEAT BELT CHIMES, SEAT BELT DOESNT CLICK IN ALL THE WAY

SEAT BELT BUCKLE INOP. SERVICE INSTALL PART

INSTALL SOP SEAT BELT BUCKLE

DRIVERS SEAT BELT WILL NOT BUCKLE

FRONT SEAT BELT BUCKLES ERRATIC WONT LATCH.

CUST STATES THAT PASS SIDE FRT SEAT BELT WILL NOT LOCK S28

CUSTOMER STATES SEATBELT BUCKLE WILL NOT HOLD

CUSTOMER STATES BOTH SEATBELTS WILL NOT BUCKLE UP PROPERLY AT ALL TIMES

CUST ST THE DRIVERS SIDE BUCKLE IS COMING LOOSE SEATBELT POPS OPEN BY ITSELF

DRIVER SIDE SEATBELT DOESNT HOLD

CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE

DRIVERS SIDE SEATBELT BUCKLE SOP

SOP RIGHT SIDE SEATBELT

CUSTOMER STATES THE DRIVERS SEAT BELT WILL POP OUT (UNLATCH) WHILE DRIVING.

INSTALL SOP SEAT BUCKLE REFER TO LAST RO 320839 BOTH FRONT

CK. DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING

CUSTOMER STATES DRIVERS SEATBELT DOESNT LOCK CLICK SHUT  
RF SEAT BELT DOES NOT ALWAYS LATCH  
DRIVERS SEAT BELT WONT STAY LATCHED

CUSTOMER STATES: DRIVER SEAT BELT IS INOPERATIVE; PER S.O.P INSTALL SEAT BELT PART. INSPECT AND ADVISE  
INSTALL SOP DRIVERS SIDE SEAT BELT  
CUSTOMER STATES DRIVERS SIDE SEAT BELT RECEPICLE DOES NOT ALWAYS LATCH. BUCKLE WAS INSPECTED LAST MONTH PER RECAL  
REPLACING DR SIDE SEAT BELT PARTS ORDERED  
CUST STATES SEAT BELT INOP  
CUSTOMER STATES P S FRONT SEAT BELT WILL NOT LATCH REPORT  
PLEASE INSTALL SOP ( SEAT BELT BUCKLES )  
SEAT BELT INOPP  
O S DRIVERS SIDE SEAT BELT BUCKLE INOP. INSTALL SPEC ORDERED PART

DS SEAT BELT SOP HERE  
LEFT FRONT SEAT BELT WILL NOT STAY LATCHED

DS SEATBELT INOP  
DRIVERS SEAT BELT DOES NOT ALWAYS LATCH SOP HERE  
S40 CUS STS THAT THE LF SEAT BELT WONT LATCH, S O PART  
BOTH FRONT SEAT BELTS DO NOT STAY LATCHED  
CK R FRIT SEAT BELT BUCKEL WONT LATCH  
CUST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED  
LEFT FRONT SEAT BELT WONT LATCH  
C S RIGHT FRONT SEAT BELT WILL NOT LOCK INTO RECEIVER  
DRIVER SEAT BELT STICKS OR DOENT MAKE A CLICKING NOISE TO LOCK IN  
PERFORM RECALL 01621 SEAT BELT BUCKLE  
CUSTOMER STATES INSTALL SPO SEAT BELT PART LEFT FRONT SEAT BELT WILLNOT LATCH  
CUST STATES D S FRONT SEATBELT DOES NOT LATCH IN SPO PART CHECK ALSO FOR 01S21 RECALL SEATBELT BUCKLE  
S O PART SEAT BUCKLE DRIVERS FT USE SPO 01267005  
REPAIR FOR DRIVER SEAT BELT COMES UNDONE AT TIMES. INSTALL SOP.  
DRIVER SEAT POSITION THE MALE END OF SAFETY BELT KEEPS POPPING OUT.  
ADD ON WARRANTYDRIVER SEATBELT DOEW NOT ALWAYS STAY SECURE  
CUSTOMER STATES, DRIVERS SIDE SEAT BELT FAILED INSTALLED SOP SEAT BELT (DRIVERS)  
CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART  
CUSTOMER STATES THE PASS FRONT SEAT BELT IS INOP SOP  
THE DRIVERS SEATBELT IS NOT WORKING PROPERLY SOP HERE

C.S LEFT FRONT SEAT BELT INOP. CH ADVISE  
S28 CUSTOMER STATES RF SEAT BELT WONT LATCH  
S40 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES  
CUSTOMER STATES DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY  
CUST STATES DR FRT SEAT BELT WILL POP OUT OF RECEPTACLE WHILE DRIVING INTERM AND TAKES ABOUT 3 4 TIMES BEFORE WILL LOC

CHECK AND ADVISE IN SEATBELT  
DRIVERS SEAT BELT WONT STAY LATCHED  
CUSTOMER REPORTS SECOND SEAT RT.SIDE SEAT BELT WILL NOT BUCKLE  
CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING  
C S DRIVE SIDE SEAT BELT COME UNBUCKELED  
FRT DRIVERS SEAT BELT COMES UNLATCHES  
CUSTOMER SAYS THE PASSENGER SEAT BELT WONT LOCK  
CUST STATES WHILE DRIVING DRIVERS SEAT BELT CAME UNLATCHED BY ITSELF  
CUSTOMER STATES THAT RT FT SEATBELT WILL NOT LOCK IN BUCKLE  
CK DRIVERS SEAT BELT WONT LATCH. BUCKLE INOP  
PASS SEAT BELT WILL NOT HOLD  
DRIVER SIDE FRONT SEAT BELT BUCKLE, UN BUCKLES ON ITS OWN WHILE DRIVING, DIAGNOSE AND REPORT.  
DRIVER SIDE SEAT BELT  
CUSTOMER STATES THAT THE PASS SEAT BELT WILL NOT LOCK INTO PLACE  
INSTALL SPO # 01281014 CUSTOMER STATES PASSENGER SIDE SEAT BELT IS NOT WORKING . TECH # 110 PART #7881202 AAA  
CUST STATES FRONT SEAT RIGHT OUTER BELT DOESNT LATCH  
DRIVERS SEAT BELT UNBUCKLES  
CUSTOMER STATES THAT THE DRIVERS FRT SEAT BELT COMES LOOSE CONTINUOSLY WHILE DRIVING  
S40 CUST STATES SEAT BELT POPS OPEN DRIVERS SIDE SOP PART IS IN UNDER NEIL HARVEY  
PASSENGER FRONT SEAT BELT COMES UNLATCHED WHEN DRIVING 3 38  
RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK  
S40 PER CUST, THE DRIVERS SEAT BELT COMES UNLATCHED. SEE HISTORY  
T90 C S DRIVERS SEAT BELT WONT STAY LATCHED SOP  
DRIVERS SEATBELT KEEPS COMMING UNLATCHED.  
VEHICLE EFFECTED BY SEAT BELT BUCKLE RETENSION SAFETY RECALL 01S21 CERTIAN MODEL YEAR CROWN VICTOR  
DRIVER SIDE SEAT BELT WON T LOCK  
CUST STATES D S SEATBELT BUCKLE WONT LATCH  
REPLACE DRIVERS SEAT BELT (FINISH LINE A  
CHECK SEAT BELT OPERATION  
CUST STATES LEFT FRONT SEAT BELT KEEPS COMING LOOSE ADVISE SOP  
RECALL 01S21 SEAT BELT BUCKLE RETENTION BOTH SIDES FAILED

01S21 SEAT BELT BUCKLE SOP  
CUSTOMER STATES DRIVERS SEATBELT INOPERATIVE S O PART IN ? SEE HISTORY  
SEAT BELT ON DRIVERS SIDE WILL NOT STAY LOCKED  
SEAT BELT NOT WORKING  
CHECK LEFT FRONT SEAT BELT WONT LATCH TO BUCKLE  
SEATBELT WILL NOT LATCH AND STAY HOOKED ALL THE WAY IT POPS BACK OUT.  
DRIVERS SEAT BELT BUCKLE WILL NOT HOLD T FH  
CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.  
LEFT SEAT BELT WILL NOT STAY LATCHED  
S40 PER CUSTOMER THE DRIVERS SEAT BELT BUCKLE WON T RECIEVE THE MALE END INSTALL SOP PARTS TECH #605  
DRIVER SEAT BELT WILL NOT FASTEN  
SEAT BELT NOT WORKING  
INSTALL S.O.P.#02117011 CUSTOMER STATES RIGHT FRONT SEAT BELT INOP  
CUST STATES DRIVER SIDE SEATBELT KEEPS COMING UNBUCKLED SOP PART IN STOCK  
DRIVERS SEATBELT UNBUCKLES WHILE DRIVING  
RIGHT FRONT SEAT BELT INOP  
LEFT SEAT BELT BUCKLE IS NOT WORKING  
REPLACE LEFT FRONT SEAT BELT ASSY ..

Y WHILE DRIVING FOR NO APPARENT REASON.

INSTALL SOP FOR SEAT BELT RECALL DRIVERS BELT  
C S DRIVER SEAT BELT INOP.....  
CUST STATES DRIVER SEAT BELT CAME APART WHILE DRIVING  
SEAT BELT WILL NOT BUCKLE SOP HERE  
S40 C S THE DRIVERS SEAT BELT POPS LOOSE WHEN DRIVING  
CUG STATES D SIDE SEAT BELT COMES UNDONE RO 96954 RECHECK TECH 160  
L F SEAT BELT BUCKLE WONT RELEASE  
CUSTOMER STATES: SEAT BELTS ARE HERE. DRIVERS SIDE SEAT BELT NEEDS REPLACED.  
SEAT BELT ON DRIVERS SIDE WILL NOT BUCKLE  
CUSTOMER STATES THAT AFTER THE SEAT BELT RECALL WAS DONE THE PASS FRONT SEAT BELT POPS OFF  
PASS SIDE SEAT BELT BUCKLE TECH 125  
PERFORM RECALL #01S21  
S25 DRIVERS SEAT BELT WILL NOT STAY BUCKLED (01S21?)  
A99 SOP SEAT BELT IN PASSENGERS SIDE BUCKLE FOR RECALL  
OWNER STATES DRIVERS SEATBELT COMES UNLATCHED WHEN PULLED ON  
DRIVERS SEAT BELT DOESNT LATCH, INSTALL SOP PARTS USE SOP 01188002

C S DRIVER SIDE SEAT BELT KEEPS COMING OUT OF CLIP SOP IS IN  
S40 DRIVERS SIDE SEAT BELT UNCLICKED OVER BUMP TWICE  
INSTALL SOP FOR DRIVERS SEAT BELT  
CUSTOMER STATES THE LEFT FRONT SEAT BELT BUCKLE WONT LATCH (GRAY)  
DRIVER SEATBELT INOP  
LEFT SEAT BELT INOP PART IN  
CHECK DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING CHECK OTHER SEAT BELTS FOR PROPER OPERATION  
DRIVERS SIDE SEAT BELT RECEIVER WONT HOLD ALL THE TIME  
(S25)CK. DRIVERS SIDE SEAT BELT COMES LOOSE.  
C S DRIVER SEAT BELT BUCKLE INOP ALSO LEFT REAR SEAT BELT KEEPTS TIGHTING UP  
PASSENGERS SIDE SEAT BELT BUCKLE WILL NOT LATCH AT TIMES  
BOTH FRONT SEAT BELTS NOT BUCKLING INTERMITTENT PROBLEM  
CHECK AND ADVISE ON DRIVERS SEAT BELT WILL COME UNLOCKED WHEN DRIVING SOP HERE  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE POPS IN AND OUT  
RT FT SEATBELT WONT HOLD IN BUCKLE ASY  
CUSTOMER STATES RIGHT FRONT SEAT BELT IN OP REPORT  
DRIVERS SEATBELT IS INOP  
CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT WILL NOT LATCH CHECK AND ADVISE  
INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION  
SEAT BELT DEFECTIVE  
CUST STATES LT FRONT SEAT BELT COMES UN DONE WHILE DRIVING  
CUST STATES RT FRT SEAT BELT DOESNT BUCKLE INTERMITTANTLY  
CUST STATES DRIVERS SIDE SEAT BELT INOP WAITER  
CUST STATES FRONT SIDE PASSENGER SEAT BELT WILL NOT LATCH  
CUST STATES SEAT BELT DRIVERS SIDE WILL COME LOOSE  
S40\* CUST STATES FRONT PASS BUCKLE WILL NOT LATCH...(SOP HERE)  
C S DRIVERS SIDE SEAT BELT COMES UN FASTENED AT TIMES  
LEFT FT SEAT BELT COMES UN CLASP SOP PARTS  
LEFT FT SEAT BELT SEAT BELT COMES UNBUCKLED FOR NO REASON  
CHK FOR D SEATBELT COMING UNLATCHED WHILE DRIVING.  
S40 CUST STATE CK LEFT FT SEAT BELT WILL NOT LATCH  
DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES, ALSO COMES LOOSE AT TIMES WHILE DRIVING, ADVIS  
S40 CUST STATES LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIME POPS OUT WHILE DRIVING  
CK SEATBELT WONT LATCH  
INSTALL SOP SEAT BELTS.

INSTALL SOP HERE FOR SEATBELT

S40 CUST STATES PASS SEAT BELT DOES NOT LATCH EVERY TIME  
CUSTOMER STATES:DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL

INSTALL SEATBELTS  
DRIVER SIDE SEATBUCKLE WONT LATCH SOP  
R F SEAT BELT BUCKLE WONT LATCH SOP HERE

DRIVERS SEATBELT WILL NOT LATCH  
CUSTOMER STATES FRONT PASSENGER SEAT BELT DOES NOT LATCH PROPERLY  
PASS SIDE SEAT BELT BUCKLE WONT LATCH  
CUST STATES SEATBELTS WONT LATCH  
CUST STATES SEAT BELTS NOT STAY LOCKED AT TIMES.  
S40 CUST CONCERN DRIVER SIDE SEAT BELT NOT WORKING CORRECTLY  
CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES LOOSE FOR NO REASON  
SEAT BELT INOP (PARTS HERE )  
S06 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES  
DRIVERS SEAT BELT BUCKLE WILL NOT STAY FASTENED  
S40 D S F RESTRAINT UNLOCKS WHILE DRIVING  
CUST STATES INTT THE DRIVER SEAT BELT WILL POP OUT FROM THE BUCKLE CHECK AND ADVISE  
DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN  
CUST STATES DRIVERS SEAT BELT DOES NOT CONNECT ALL THE TIME  
DRIVER SIDE SEAT BELT WILL NOT LATCH  
INSTALL S.O.P. SEAT BELT RECALL PART  
CUST STATES FRONT SEAT CENTER SEAT BELT INOP, PLEASE INSTALL SOP SEAT BELT, SEE PHIL IN PARTS  
C S R. FT. SEAT BELT WON T BUCKLE UP AT TIMES, S O PART HERE ADVISE  
INSTALL SOP SEAT BELTS

INSTALL SPECIAL ORDERED BELT BRAKES FRONT SEATBELT BROKEN REFER BACK TO RO 142840  
CUST STATES PASS FRONT SEAT BELT BUCKLE WILL NOT ACCEPT BELT INTO RECEPTACLE WITHOUT DEPRESSING BUTTON AND FORCIB  
CUSTOMER STATES THAT RT SIDE BELT INOP  
PERFORM RECALL #01S21  
DRIVER SEATBELT WILL NOT BUCKLE AT TIMES  
DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP  
DR SEATBELT WONT FASTEN  
CK THE SEAT BELT DRIVER SIDE NOT LATCHING PROPERLEY  
S28 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED  
C S THE SEAT BELT WILL COME UNLATCHED

USE SPO 02058001

CUST HAS RETURNED TO HAVE SOP INSTALLED. (REFER TO HISTORY ROW# 88917)  
S40 CUSTOMER STATES DRIVER SEAT BELT COMES UNBUCKLED  
C S TYHAT THE DRIVER SEAT BELT ENTERPRISE DW278835  
THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT, CHECK AND ADVISE

CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...  
C S PASSENGER SEAT BELT COMES UNLATCHED WHILE DRIVING , INSTALL SOP BELT ASSY HAS OPEN 01S21 RECALL  
MISSING FEMALE SEAT BELT ENDS FOR RT FRONT AND CENTER PASSENGERS

CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES.  
CUSTOMER STATES DRIVERS SEAT BELT INOP SOP  
RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12  
PASSENGER SIDE SEAT BELT FAILED INSPECTION NOT ON RECALL (FAILED)  
CRIVER'S SEAT BELT BUCKLE WILL NOT HOLD.  
CUST STATES DRIVER SEAT BELT RELEASES WHILE DRIVING  
RECALL 01S21  
REPL SEAT BELT BUCKLE  
R F SEAT BELT COMES LOOSE DRIVING  
DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH  
CUST STATES SEAT BELST WONT LATCH INSTALL S.O.P.  
DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED AT TIMES  
CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING

INSTALL SPO PART HERE DRIVER SEAT BELT BUCKLE NOT LOCKING INTERMIT  
S40\*\*DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED  
CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE  
PASS SEAT BELT WILL NOT LOCK .... CK ALL SEAT BELTS  
S25 DRIVERS SIDE SEAT BELT WONT STAY LATCHED  
PASSENGER FRONT SEATBELT DOESNT LATCH  
C S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING  
CUSTOMER STATES DRIVERS SEATBELT WILL NOT LATCH SOMETIME  
A98 DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE  
LEFT SEAT BELT WILL NOT LATCH  
CUSTOMER STAETS SEAT BELT HARD TO OPERATE  
C S DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT  
PARTS REPLACEMENT SEAT BELT  
INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES

SPO# 01159009

DRIVERSIDE AND PASSENGER SIDE SEAT BELT BUCKLES INOP  
SEAT BELT BUCKLE INOP  
DRIVERS SIDE FRONT SEAT BELT KEEPS COMING LOOSE...INSTALL SOP  
CUSTOMER STATES RIGHT FRONT SEAT BELT INOP SOP  
CK REASON WHY DRIVERS SEAT BELT BUCKLE WONT LOCK BELT AT TIMES.INSTALL S.O.P.  
CUST STATES DRIVERS SEAT BELT COMES UNHOOKED  
CUST STATES SOP IS IN FROM FRI SEAT BELT  
SEAT BELT DRIVERS SIDE COMES LOOSE WHILE DRIVING SOP PART HERE  
CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN  
DRIVER SHOULDER HARNESS POPS LOOSE AT TIMES WHILE DRIVING  
CUSTOMER STATES DRIVERS SEATBELT BUCKLE DOES NOT HOLD BELT AT TIMES. CHECK AND ADVISE.  
SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED  
REPLACE DEFECTIVE SEATBELT BUCKLE SPW  
CHECK SEAT BLET&SOP PART FOR DRIVERS SEAT  
INSTALL SOP 2 SEAT BELTS DONT WORK PROPERLY  
DRIVERS SEAT BELT COMES LOOSE, UNBUCKLES AT TIMES, S.O.P. AT PARTS  
CUSTOMER STATES PASSENGER FRONT SEAT BELT WASNT BUCKLEY CORRECTLY  
CLIENT STATES DRIVERS SEAT BELT WONT LATCH SOP HERE TO REPAIR.  
PERFORM 01S21 SEATBELT BUCKLE  
INSTALL SPECIAL ORDERED PART, SEAT BELT. USE SPO 02061006  
CUST STATES INSTALL SOP SEAT BELT BUCKLE  
PASS SEAT BELT WILL NOT LATCH PART HERE  
PASS. SIDE SEAT BELT INOP WILL NOT LATCH AT TIMES  
CUSTOMER STATES DRIVER SEATBELT LATCH INOP.SOP ORDERED BY CS.SEE DENNIS IN PARTS.  
RT FT SEATBELT WILL NOT LATCH  
RECALL 01S21 SAFTEY RECALL SEAT BELT BUCKLES  
SEAT BELT BUCKLES DONT LATCH  
BOTH FRONT SEAT BELTS WONT LATCH  
CUST STATES SEATBELT FAILED  
REPLACE DEFECTIVE SEAT BELT FOUND BY SEAT BELT RECALL INSPECTION  
SEAT BELT RECALL..01S21..SPECIAL ORDERED PARTS HERE  
CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO  
RECALL 01S21 BOTH FAILED CUS  
T90 RT FRT DRIVERS SEAT BELT BUCKLE FAILES RECALL TEST 01S21 ON RO 85231 INSTALL SOP DRIVERS SEAT BELT BUCKLE  
PASS FRONT SEAT BELT INOP PARTS IN 315  
FAULTY SEAT BELT BUCKLES  
C STATES DRIVERS SEAT BELT SNAPS OFF

OK DRIVERS SEAT BELT WONT STAY ATTACHED  
REPLACE SEAT BELT BUCKLES THAT FAILED UNDER RECALL 01821 SEAT BELT BUCKLE S.O.P. ARE HERE  
DRIVERSIDE SEAT BELT WILL NOT OPERATE INSTALL SPECIAL ORDER PART  
CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE DOES NOT WORK PROPERLY  
01821 REPLACE PASSENGER SIDE SEAT BELT BUCKLE SOP IN  
SOP HERE FOR SEAT RECALL 01821 REF RO 200456  
CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE INOP.  
RECALL 01821 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 77  
PASSENGER SIDE SEAT BELT INOP  
RECALL 01821 SEAT BELT BUCKLE

S40 PASS SIDE MIDDLE SEAT BELT LATCH COMING APART  
CUST STATES PASS FRONT SEAT BELT WILL NOT STAY LATCHED UNBUCKLES WHEN DRIVING DOWN THE ROAD AND LEFT  
CUSTOMER STATES THAT THE FRONT SEAT BELT ARE NOT LOCKUNG IN NEEDS LEFT AND RIGHT SIDE BELT TRIM CODE 12  
SEATBELT SOP

CUST STATES DR SIDE SEAT BELT INOP SOP IN  
CUST STATES DRIVER SEAT BELT SNAPS LOOSE BY ITSELF POPS OUT BY ITSELF  
CUSTOMER STATES DRIVERS SEAT BELT KEEP COMING UNBUCKLED  
SEAT BELT ON DRIVERS SIDE INOP  
CS THAT THE DRIVERS SEAT BELT WILL NOT FASTEN AT TIMES  
DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED  
SOP IN CUST STATES VEH HAS SEAT BUCKLE WILL NOT LATCH.  
CUST STATES THAT THE DRIVERS SIDE SEAT BELT COMES UNBUCKLED WHILE DRIVING  
REPLACE SOP SEAT BELT

S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING  
DIAG DRIVER AND PASS SEAT BELTS UNLOCK WHILE DRIVING DOWN THE FREEWAY  
CUST REPORTS CHECK PASSENGER FRONT SEAT BELT WONT BUCKEL  
S40 DRIVER SEAT BELT NOT CLICKING TO LOCK

CUSTOMER STATES RIGHT FRT SEATBELT\*\*\*\*\* FEMALE SIDE WONT LATCH  
DIAG DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES CUST HAS TO FIRST PUSH RELEASE AND THEN IT WILL BUCKLE CHECK ALL O'  
RECALL 01821 DRIVER FRONT SEAT BELT USE SPO 01309037

CHECK SEAT BELT  
THE DRIVERS SEAT BELT RELEASES WHILE DRIVING  
SOP SEAT BELT  
INSTALL SOP DRIVER SEAT BELT TECH#307  
PASSENGER SIDE FRONT SEAT BELT BUCKLE CLICKS.  
INSTALL SO SEAT BELT ORDERED WHEN IT FAILED SEAT BELT RETENTION RECALL

S26\* DRIVERS SEAT BELT KEEPS COMING LOOSE  
LEFT SEAT BELT BUCKLE COMES LOOSE BY SELF  
REPLACE CENTER ROW RIGHT SEAT BELT BUCKLE.PER TOM PEELER FQE  
CUST STATES DRIVER SEAT BELT NOT LATCHING  
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 138534/ 138533  
CUSTOMER STATES SEAT BELT KEEPS UN LOCKING

STATES SEAT BELT WILL NOT LATCH S40

CUST STATES SEAT BELT IS INOP (SOP IN STOCK)  
INSTALL SOP SEAT BELT FOR RECALL 01S21  
SEAT BELT WILL NOT CONNECT PROPERLY  
DRIVER SEAT BELT LATCH HANGS AT TIMES  
RECALL 01S21

USE SPO 01212002

RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12  
RECALL 01S21 IS NOT ELIG FORD REP GAVE APPROVAL NUMBER  
CUSTOMER STATES THAT RIGHT SIDE BELT WILL NOT HOLD REPLACE RIGHT SIDE BELT  
CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN  
S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE  
S40CUST STATES SEAT BELTS COME APRT WHILE DRIVING  
CHECK LEFT FRONT SEAT BELT BUCKLE IN OP AT TIMES WONT POP UP

AREA_CD	COUNTRY_CD	SLS_DLFL_CD	TXN_CD	ONTRY_SOLD	QRT_CD	VFG_CD	AWS_VL_CD	VRT_CD	TIS_FLAG
254	USA	367326		1 USA	Q21	V05	B4	S08	
608	USA	315040		1 USA	Q21	V05	B4	S08	
	USA	342574	E84	USA	Q21	V05	B4	S08	0
319	USA	325727	E84	USA	Q21	V05	B4	S08	0
912	USA	328234		2 USA	Q21	V05	B4	S08	
718	USA	314437		1 USA	Q21	V05	B4	S08	
952	USA	343008		2 USA	Q21	V05	B4	S08	
783	USA	343319	E84	USA	Q21	V05	B4	S08	0
218	USA	318539		1 USA	Q21	V05	B4	S08	
423	USA	348235		1 USA	Q21	V05	B4	S08	
618	USA	354301		1 USA	Q21	V05	B4	S08	
609	USA	315040		1 USA	Q21	V05	B4	S08	
201	USA	314340		1 USA	Q21	V05	B4	S08	
516	USA	314014		1 USA	Q21	V05	B4	S08	
	USA	355836		2 USA	Q21	V05	B4	S08	
909	USA	354172	E84	USA	Q21	V05	B4	S08	0
313	USA	345345		1 USA	Q21	V05	B4	S08	
757	USA	328278	E84	USA	Q21	V05	B4	S08	
714	USA	354265	E84	USA	Q21	V05	B4	S08	
616	USA	345160	E84	USA	Q21	V05	B4	S08	
913	USA	363556	E84	USA	Q21	V05	B4	S08	
732	USA	314376	E84	USA	Q21	V05	B4	S08	0
614	USA	346382		2 USA	Q21	V05	B4	S08	
206	USA	351077		2 USA	Q21	V05	B4	S08	
970	USA	355491		2 USA	Q21	V05	B4	S08	
414	USA	342527		1 USA	Q21	V05	B4	S08	
851	USA	343319		1 USA	Q21	V05	B4	S08	
781	USA	312398	E84	USA	Q21	V05	B4	S08	
908	USA	314031		1 USA	Q21	V05	B4	S08	
910	USA	325308		1 USA	Q21	V05	B4	S08	
508	USA	312190		1 USA	Q21	V05	B4	S08	
925	USA	351078	E84	USA	Q21	V05	B4	S08	
847	USA	342412		1 USA	Q21	V05	B4	S08	
217	USA	354135		2 USA	Q21	V05	B4	S08	
989	USA	345237		2 USA	Q21	V05	B4	S08	
505	USA	355522	E84	USA	Q21	V05	B4	S08	

913 USA	363556	1 USA	Q21	V05	B4	S08	•
USA	315146	1 USA	Q21	V05	B4	S08	
215 USA	315306	1 USA	Q21	V05	B4	S08	
616 USA	314361	1 USA	Q21	V05	B4	S08	
610 USA	345275	2 USA	Q21	V05	B4	S08	
757 USA	328637	1 USA	Q21	V05	B4	S08	
616 USA	363559 EB4	USA	Q21	V05	B4	S08	
724 USA	316309	1 USA	Q21	V05	B4	S08	
847 USA	342535	2 USA	Q21	V05	B4	S08	
615 USA	322320	1 USA	Q21	V05	B4	S08	
480 USA	354547	1 USA	Q21	V05	B4	S08	
516 USA	314361	2 USA	Q21	V17	B4	S09	
608 USA	351484 EB4	USA	Q21	V05	B4	S08	•
303 USA	355115	1 USA	Q21	V05	B4	S08	
314 USA	363197	1 USA	Q21	V05	B4	S08	
659 USA	351046	1 USA	Q21	V03	B4	S08	
914 USA	314541	1 USA	Q21	V05	B4	S08	•
USA	38404J	2 USA	Q21	V05	B4	S08	
310 USA	354222	1 USA	Q21	V05	B4	S08	
USA	355836 EB4	USA	Q21	V05	B4	S08	
620 USA	363174	1 USA	Q21	V05	B4	S08	•
973 USA	314474 EB4	USA	Q21	V05	B4	S08	•
617 USA	312386	2 USA	Q21	V05	B4	S08	
USA	342402	2 USA	Q21	V05	B4	S08	
952 USA	343662	1 USA	Q21	V05	B4	S08	
270 USA	346686 EB3	USA	Q21	V05	B4	S08	
541 USA	38404J EB4	USA	Q21	V05	B4	S08	•
904 USA	325062 EB4	USA	Q21	V05	B4	S08	
303 USA	355120	1 USA	Q21	V05	B4	S08	
281 USA	367032 EB4	USA	Q21	V03	B4	S08	
603 USA	312483	1 USA	Q21	V05	B4	S08	
301 USA	328486	2 USA	Q21	V05	B4	S08	•
USA	38403J	2 USA	Q21	V05	B4	S08	
410 USA	328057 EB4	USA	Q21	V05	B4	S08	•
USA	355836 EB4	USA	Q21	V05	B4	S08	
USA	355836 EB0	USA	Q21	V05	B4	S08	
480 USA	354269	1 USA	Q21	V05	B4	S08	

516 USA	314381	1 USA	Q21	V17	B4	S08
647 USA	342635 E84	USA	Q21	V05	B4	S08
981 USA	367048	2 USA	Q21	V05	B4	S08
908 USA	354800	1 USA	Q21	V05	B4	S08
610 USA	316304	2 USA	Q21	V05	B4	S08
713 USA	387298	1 USA	Q21	V05	B4	S08
USA	38409J E83	USA	Q21	V05	B4	S08
609 USA	315040	1 USA	Q21	V05	B4	S08
423 USA	328105 E84	USA	Q21	V05	B4	S08
757 USA	328278 E84	USA	Q21	V05	B4	S08
414 USA	342984 E84	USA	Q21	V05	B4	S08
703 USA	328008 E84	USA	Q21	V05	B4	S08
610 USA	345358 E84	USA	Q21	V05	B4	S08
515 USA	363588	2 USA	Q21	V05	B4	S08
781 USA	312288	1 USA	Q21	V05	B4	S08
913 USA	363407 E84	USA	Q21	V05	B4	S08
713 USA	387020	1 USA	Q21	V05	B4	S08
843 USA	328223	1 USA	Q21	V05	B4	S08
672 USA	367008	1 USA	Q21	V05	B4	S08
310 USA	354280	2 USA	Q21	V05	B4	S08
770 USA	328140	2 USA	Q21	V05	B4	S08
770 USA	328233 E84	USA	Q21	V05	B4	S08
281 USA	367023	1 USA	Q21	V05	B4	S08
714 USA	354016	1 USA	Q21	V05	B4	S08
407 USA	325188	1 USA	Q21	V05	B4	S08
901 USA	322664	1 USA	Q21	V06	B4	S08
407 USA	325218 E84	USA	Q21	V05	B4	S08
310 USA	354280	2 USA	Q21	V05	B4	S08
618 USA	354800	1 USA	Q21	V05	B4	S08
714 USA	354015 E84	USA	Q21	V05	B4	S08
806 USA	354138	2 USA	Q21	V05	B4	S08
925 USA	351024 E84	USA	Q21	V05	B4	S08
714 USA	354015	2 USA	Q21	V05	B4	S08
770 USA	328233 E84	USA	Q21	V05	B4	S08
407 USA	325132 E84	USA	Q21	V05	B4	S08
613 USA	325168 E84	USA	Q21	V05	B4	S08
619 USA	354800	1 USA	Q21	V05	B4	S08

407 USA	325184 EB4	USA	Q21	V05	B4	S08
407 USA	325032 EB4	USA	Q21	V05	B4	S08
281 USA	367023	1 USA	Q21	V05	B4	S08
713 USA	367021	1 USA	Q21	V05	B4	S08
214 USA	367510	1 USA	Q21	V05	B4	S08
805 USA	354290	2 USA	Q21	V05	B4	S08
813 USA	325007 EB4	USA	Q21	V05	B4	S08
334 USA	326552	1 USA	Q21	V05	B4	S08
770 USA	326057	2 USA	Q21	V05	B4	S08
805 USA	354290	1 USA	Q21	V05	B4	S08
714 USA	354015	1 USA	Q21	V05	B4	S08
872 USA	367324	1 USA	Q21	V05	B4	S08
205 USA	326378 EB4	USA	Q21	V05	B4	S08
318 USA	322842	1 USA	Q21	V05	B4	S08
770 USA	326057	1 USA	Q21	V05	B4	S08
818 USA	354251	1 USA	Q21	V05	B4	S08
805 USA	354290	1 USA	Q21	V05	B4	S08
850 USA	325123	1 USA	Q21	V05	B4	S08
805 USA	354133	2 USA	Q21	V05	B4	S08
281 USA	367298	1 USA	Q21	V05	B4	S08
334 USA	326135 EB4	USA	Q21	V05	B4	S08
702 USA	354137 EB4	USA	Q21	V05	B4	S08
281 USA	367023	1 USA	Q21	V05	B4	S08
205 USA	326074 EB4	USA	Q21	V05	B4	S08
818 USA	354301	1 USA	Q21	V05	B4	S08
817 USA	367013	1 USA	Q21	V05	B4	S08
881 USA	354041 EB4	USA	Q21	V05	B4	S08
757 USA	326278 EB3	USA	Q21	V05	B4	S08
757 USA	326278	1 USA	Q21	V05	B4	S08
850 USA	325191	2 USA	Q21	V05	B4	S08
205 USA	326076	2 USA	Q21	V05	B4	S08
770 USA	326057	2 USA	Q21	V05	B4	S08
908 USA	354283	2 USA	Q21	V05	B4	S08
305 USA	325036	1 USA	Q21	V05	B4	S08
407 USA	325143	1 USA	Q21	V05	B4	S08
512 USA	367036 EB4	USA	Q21	V05	B4	S08
682 USA	322423	1 USA	Q21	V05	B4	S08

405 USA	387235 E84	USA	Q21	V05	B4	S08
767 USA	328837	2 USA	Q21	V05	B4	S08
882 USA	322584 E84	USA	Q21	V05	B4	S08
904 USA	354283	2 USA	Q21	V05	B4	S08
828 USA	354283	2 USA	Q21	V05	B4	S08
941 USA	325044	2 USA	Q21	V03	B4	S08
678 USA	328233	2 USA	Q21	V05	B4	S08
818 USA	354301	2 USA	Q21	V05	B4	S08
912 USA	328218 E84	USA	Q21	V05	B4	S08
604 USA	322800 E84	USA	Q21	V05	B4	S08
909 USA	354015	2 USA	Q21	V05	B4	S08
305 USA	325201	1 USA	Q21	V05	B4	S08
281 USA	387023	1 USA	Q21	V05	B4	S08
805 USA	354290	1 USA	Q21	V05	B4	S08
306 USA	325044 E84	USA	Q21	V05	B4	S08
713 USA	387023 E84	USA	Q21	V06	B4	S08
281 USA	387082	2 USA	Q21	V05	B4	S08
310 USA	354100 E84	USA	Q21	V05	B4	S08
912 USA	329182 E84	USA	Q21	V05	B4	S08
858 USA	354585	1 USA	Q21	V05	B4	S08
582 USA	354081 E84	USA	Q21	V05	B4	S08
803 USA	328218 E84	USA	Q21	V05	B4	S08
404 USA	328135 E84	USA	Q21	V05	B4	S08
281 USA	387023 E84	USA	Q21	V74	B4	S08
714 USA	354015 E84	USA	Q21	V05	B4	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
817 USA	152525	1 USA	Q21	V05	B3	S08
582 USA	171007	1 USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
203 USA	124009	2 USA	Q21	V05	B3	S08
713 USA	158031	1 USA	Q21	V05	B3	S08
210 USA	158058	1 USA	Q21	V05	B3	S08
281 USA	158055	1 USA	Q21	V05	B3	S08
713 USA	158026	1 USA	Q21	V05	B3	S08
972 USA	152525 E84	USA	Q21	V05	B3	S08
708 USA	121214	1 USA	Q21	V05	B3	S08

850 USA	172013	2 USA	Q21	V05	B3	808
760 USA	171102	1 USA	Q21	V05	B3	808
727 USA	124454	1 USA	Q21	V05	B3	808
819 USA	121019 EB4	USA	Q21	V05	B3	808
214 USA	152003	1 USA	Q21	V05	B3	808
727 USA	124408	1 USA	Q21	V05	B3	808
562 USA	171055	1 USA	Q21	V05	B3	808
407 USA	124224	1 USA	Q21	V74	B3	808
770 USA	121018 EB4	USA	Q21	V05	B3	808
713 USA	152031	1 USA	Q21	V05	B3	808
770 USA	121405	2 USA	Q21	V05	B3	808
281 USA	152054 EB4	USA	Q21	V05	B3	808
854 USA	124008	2 USA	Q21	V07	B3	808
770 USA	121025 EB4	USA	Q21	V74	B3	808
813 USA	124449	1 USA	Q21	V05	B3	808
281 USA	152731 EB4	USA	Q21	V05	B3	808
760 USA	171102	1 USA	Q21	V05	B3	808
727 USA	124454	1 USA	Q21	V05	B3	808
562 USA	171055	1 USA	Q21	V05	B3	808
770 USA	121022	1 USA	Q21	V05	B3	808
817 USA	152008	1 USA	Q21	V05	B3	808
408 USA	152052 EB4	USA	Q21	V05	B3	808
310 USA	171025 EB4	USA	Q21	V05	B3	808
281 USA	152020	2 USA	Q21	V05	B3	808
337 USA	123271	1 USA	Q21	V05	B3	808
562 USA	171055	1 USA	Q21	V05	B3	808
562 USA	171055	1 USA	Q21	V05	B3	808
210 USA	152058 EB4	USA	Q21	V74	B3	808
770 USA	121024	2 USA	Q21	V05	B3	808
214 USA	152003	1 USA	Q21	V05	B3	808
713 USA	152241 EB4	USA	Q21	V05	B3	808
210 USA	152143 EB4	USA	Q21	V05	B3	808
415 USA	172013 EB4	USA	Q21	V05	B3	808
562 USA	171056	1 USA	Q21	V05	B3	808
734 USA	148019	2 USA	Q21	V17	B3	808
841 USA	124402	1 USA	Q21	V05	B3	808
512 USA	152303	1 USA	Q21	V74	B3	808

954 USA	124009 E84	USA	Q21	V05	B3	S08
281 USA	152052	1 USA	Q21	V05	B3	S08
512 USA	152302 E84	USA	Q21	V05	B3	S08
972 USA	152017 E84	USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
281 USA	152054 E84	USA	Q21	V05	B3	S08
770 USA	121024	2 USA	Q21	V05	B3	S08
936 USA	152188	1 USA	Q21	V05	B3	S08
214 USA	152484	1 USA	Q21	V05	B3	S08
979 USA	152734	2 USA	Q21	V05	B3	S08
801 USA	123307	1 USA	Q21	V05	B3	S08
225 USA	123203	1 USA	Q21	V05	B3	S08
258 USA	121588 E84	USA	Q21	V05	B3	S08
214 USA	152480	2 USA	Q21	V05	B3	S08
817 USA	152525	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
817 USA	152020	2 USA	Q21	V05	B3	S08
972 USA	152017 E84	USA	Q21	V05	B3	S08
940 USA	152414	1 USA	Q21	V05	B3	S08
713 USA	152241	1 USA	Q21	V05	B3	S08
813 USA	124481	1 USA	Q21	V05	B3	S08
870 USA	123551 E84	USA	Q21	V05	B3	S08
306 USA	124901	1 USA	Q21	V44	B3	S11
954 USA	124009	1 USA	Q21	V05	B3	S08
954 USA	124009 E83	USA	Q21	V05	B3	S08
972 USA	152013	2 USA	Q21	V05	B3	S08
318 USA	123039	1 USA	Q21	V05	B3	S08
817 USA	152020 E84	USA	Q21	V05	B3	S08
936 USA	152188	1 USA	Q21	V05	B3	S08
803 USA	152442	1 USA	Q21	V05	B3	S08
407 USA	124227 E84	USA	Q21	V05	B3	S08
713 USA	152049	2 USA	Q21	V05	B3	S08
949 USA	171034 E84	USA	Q21	V05	B3	S08
770 USA	121480 E84	USA	Q21	V05	B3	S08
972 USA	152017	2 USA	Q21	V05	B3	S08
305 USA	124008	2 USA	Q21	V05	B3	S08

305 USA	124012 EB4	USA	Q21	V05	B3	S08
361 USA	152132	1 USA	Q21	V05	B3	S08
407 USA	124227 EB4	USA	Q21	V05	B3	S08
618 USA	171040	1 USA	Q21	V05	B3	S08
918 USA	121019	1 USA	Q21	V03	B3	S08
972 USA	152017	1 USA	Q21	V05	B3	S08
972 USA	152017	1 USA	Q21	V05	B3	S08
972 USA	152017	1 USA	Q21	V05	B3	S08
612 USA	152303 EB4	USA	Q21	V05	B3	S08
407 USA	124228	2 USA	Q21	V05	B3	S08
938 USA	152166	1 USA	Q21	V05	B3	S08
938 USA	152166 EB3	USA	Q21	V05	B3	S08
817 USA	152011 EB4	USA	Q21	V05	B3	S08
281 USA	152046	1 USA	Q21	V05	B3	S08
828 USA	171069	1 USA	Q21	V05	B3	S08
801 USA	123440 EB4	USA	Q21	V05	B3	S08
913 USA	153009 EB4	USA	Q21	V05	B3	S08
956 USA	152104 EB4	USA	Q21	V05	B3	S08
949 USA	171074	1 USA	Q21	V05	B3	S08
816 USA	171040	1 USA	Q21	V05	B3	S08
816 USA	171040	1 USA	Q21	V05	B3	S08
941 USA	124426	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
580 USA	152568 EB4	USA	Q21	V05	B3	S08
770 USA	148200	2 USA	Q21	V05	B3	S08
972 USA	152500	1 USA	Q21	V05	B3	S08
884 USA	121792	1 USA	Q21	V05	B3	S08
252 USA	121630	1 USA	Q21	V05	B3	S08
954 USA	124009	1 USA	Q21	V05	B3	S08
915 USA	152540 EB4	USA	Q21	V05	B3	S08
210 USA	152056	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
910 USA	121224	2 USA	Q21	V05	B3	S08
210 USA	152057	1 USA	Q21	V05	B3	S08
817 USA	152016 EB4	USA	Q21	V05	B3	S08
817 USA	152020 EB4	USA	Q21	V05	B3	S08

626 USA	171073 EB4	USA	Q21	V05	B3	S08
406 USA	152209	2 USA	Q21	V05	B3	S08
210 USA	152083	2 USA	Q21	V05	B3	S08
727 USA	124205	2 USA	Q21	V03	B3	S08
817 USA	152016 EB4	USA	Q21	V05	B3	S08
229 USA	18980J EB4	USA	Q21	V05	B3	S08
714 USA	171057 EB4	USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
843 USA	121248	2 USA	Q21	V05	B3	S08
972 USA	152013	1 USA	Q21	V05	B3	S08
406 USA	152684	2 USA	Q21	V05	B3	S08
904 USA	124223	1 USA	Q21	V74	B3	S08
305 USA	124007	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
817 USA	152018 EB4	USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
972 USA	152001	1 USA	Q21	V05	B3	S08
225 USA	123203	1 USA	Q21	V05	B3	S08
843 USA	124010 EB4	USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
979 USA	152134 EB4	USA	Q21	V05	B3	S08
979 USA	152134	1 USA	Q21	V05	B3	S08
714 USA	171082	2 USA	Q21	V05	B3	S08
803 USA	121274 EB4	USA	Q21	V05	B3	S08
818 USA	124208	2 USA	Q21	V05	B3	S08
704 USA	121212 EB4	USA	Q21	V05	B3	S08
757 USA	127080	1 USA	Q21	V05	B3	S08
973 USA	113044	1 USA	Q21	V05	B3	S08
808 USA	118445	1 USA	Q21	V05	B3	S08
805 USA	171486	1 USA	Q21	V05	B3	S08
412 USA	144017	1 USA	Q21	V05	B3	S08
502 USA	147017 EB4	USA	Q21	V05	B3	S08
215 USA	116045	1 USA	Q21	V05	B3	S08
201 USA	113147	1 USA	Q21	V05	B3	S08
918 USA	172209 EB4	USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08

516 USA		113089	2 USA	Q21	V05	B3	S08
570 USA		118574 EB4	USA	Q21	V05	B3	S08
282 USA		141304	2 USA	Q21	V05	B3	S08
USA	18904J	EB4	USA	Q21	V05	B3	S08
760 USA		171079 EB4	USA	Q21	V05	B3	S08
410 USA		127037	2 USA	Q21	V05	B3	S08
810 USA		148048	1 USA	Q21	V05	B3	S08
508 USA		111463	1 USA	Q21	V05	B3	S08
201 USA		113154 EB4	USA	Q21	V05	B3	S08
201 USA		113450	1 USA	Q21	V05	B3	S08
USA		171165	1 USA	Q21	V05	B3	S08
412 USA		144007 EB4	USA	Q21	V05	B3	S08
732 USA		113588 EB4	USA	Q21	V05	B3	S08
206 USA		174024	1 USA	Q21	V05	B3	S08
734 USA		148434	2 USA	Q21	V05	B3	S08
708 USA	18958R		2 USA	Q21	V05	B3	S08
516 USA		113088	1 USA	Q21	V05	B3	S08
302 USA		127588 EB4	USA	Q21	V05	B3	S08
248 USA		148439	2 USA	Q21	V05	B3	S08
812 USA		147527	1 USA	Q21	V05	B3	S08
603 USA		111586 EB4	USA	Q21	V05	B3	S08
973 USA		113048	2 USA	Q21	V05	B3	S08
810 USA		148048	2 USA	Q21	V05	B3	S08
703 USA		127049	1 USA	Q21	V05	B3	S08
201 USA		113147	1 USA	Q21	V05	B3	S08
310 USA		171206	2 USA	Q21	V05	B3	S08
818 USA		171251 EB4	USA	Q21	V05	B3	S08
973 USA		113452 EB4	USA	Q21	V05	B3	S08
732 USA		113055	1 USA	Q21	V05	B3	S08
301 USA		127047	1 USA	Q21	V05	B3	S08
916 USA		172202	1 USA	Q21	V05	B3	S08
703 USA		127081 EB4	USA	Q21	V05	B3	S08
248 USA		148028 EB4	USA	Q21	V05	B3	S08
603 USA		111582 EB4	USA	Q21	V05	B3	S08
317 USA		147027	1 USA	Q21	V05	B3	S08
303 USA		156001	1 USA	Q21	V03	B3	S08
816 USA		153015	2 USA	Q21	V05	B3	S08

407 USA	124900	1 USA	Q21	V05	B3	S08
561 USA	124015 EB4	USA	Q21	V05	B3	S08
972 USA	152002	1 USA	Q21	V05	B3	S08
225 USA	123203	1 USA	Q21	V05	B3	S08
818 USA	171043	1 USA	Q21	V05	B3	S08
405 USA	152205 EB4	USA	Q21	V05	B3	S08
619 USA	171102	2 USA	Q21	V05	B3	S08
908 USA	171106	1 USA	Q21	V05	B3	S08
408 USA	172402	2 USA	Q21	V05	B3	S08
780 USA	171078	2 USA	Q21	V05	B3	S08
780 USA	171423	1 USA	Q21	V05	B3	S08
337 USA	123275	1 USA	Q21	V05	B3	S08
961 USA	152098 EB4	USA	Q21	V05	B3	S08
225 USA	123203	1 USA	Q21	V74	B3	S08
770 USA	121022 EB4	USA	Q21	V05	B3	S08
310 USA	171015	1 USA	Q21	V05	B3	S08
910 USA	121224	1 USA	Q21	V05	B3	S08
780 USA	171430 EB4	USA	Q21	V05	B3	S08
854 USA	124015	1 USA	Q21	V07	B3	S08
407 USA	124476	2 USA	Q21	V03	B3	S08
714 USA	171052	1 USA	Q21	V05	B3	S08
626 USA	171097	2 USA	Q21	V05	B3	S08
281 USA	152047 EB4	USA	Q21	V05	B3	S08
757 USA	127060	1 USA	Q21	V05	B3	S08
727 USA	124202	1 USA	Q21	V05	B3	S08
619 USA	171060	1 USA	Q21	V05	B3	S08
208 USA	172514	1 USA	Q21	V05	B3	S08
512 USA	152302 EB1	USA	Q21	V05	B3	S08
504 USA	123009	1 USA	Q21	V74	B3	S08
713 USA	152024 EB4	USA	Q21	V05	B3	S08
819 USA	124449	1 USA	Q21	V05	B3	S08
770 USA	121025	2 USA	Q21	V74	B3	S08
305 USA	124003	1 USA	Q21	V05	B3	S08
650 USA	172024 EB4	USA	Q21	V05	B3	S08
504 USA	123008 EB4	USA	Q21	V05	B3	S08
908 USA	171151	2 USA	Q21	V05	B3	S08
480 USA	171175 EB4	USA	Q21	V05	B3	S08

708 USA	121205	1 USA	Q21	V05	B3	S08
841 USA	124480 EB4	USA	Q21	V05	B3	S08
770 USA	121488	2 USA	Q21	V05	B3	S08
727 USA	124454	1 USA	Q21	V05	B3	S08
828 USA	171083	1 USA	Q21	V05	B3	S08
708 USA	141063 EB4	USA	Q21	V05	B3	S08
910 USA	121224	1 USA	Q21	V05	B3	S08
817 USA	152009	1 USA	Q21	V05	B3	S08
388 USA	124444	1 USA	Q21	V05	B3	S08
512 USA	152302 EB4	USA	Q21	V05	B3	S08
972 USA	152007	2 USA	Q21	V05	B3	S08
727 USA	124454	1 USA	Q21	V05	B3	S08
582 USA	171104 EB4	USA	Q21	V05	B3	S08
954 USA	124010	1 USA	Q21	V05	B3	S08
210 USA	152007	2 USA	Q21	V05	B3	S08
780 USA	171430	1 USA	Q21	V05	B3	S08
818 USA	171058 EB4	USA	Q21	V05	B3	S08
818 USA	171031	1 USA	Q21	V05	B3	S08
805 USA	171452	1 USA	Q21	V05	B3	S08
938 USA	152788	1 USA	Q21	V05	B3	S08
310 USA	171051	2 USA	Q21	V05	B3	S08
843 USA	121338	1 USA	Q21	V05	B3	S08
830 USA	152719	1 USA	Q21	V05	B3	S08
727 USA	124202	1 USA	Q21	V05	B3	S08
706 USA	121215	1 USA	Q21	V05	B3	S08
501 USA	123205 EB4	USA	Q21	V05	B3	S08
210 USA	152057 EB4	USA	Q21	V83	B3	S08
551 USA	124218 EB4	USA	Q21	V05	B3	S08
912 USA	124229 EB4	USA	Q21	V05	B3	S08
404 USA	121007 EB4	USA	Q21	V05	B3	S08
407 USA	124213 EB4	USA	Q21	V74	B3	S08
404 USA	121008	1 USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
713 USA	152049	1 USA	Q21	V05	B3	S08
954 USA	124015	1 USA	Q21	V05	B3	S08
281 USA	152037	1 USA	Q21	V05	B3	S08
702 USA	171187	1 USA	Q21	V05	B3	S08

727 USA	124205	1 USA	Q21	V05	B3	S08
407 USA	124227	1 USA	Q21	V05	B3	S08
619 USA	171076	1 USA	Q21	V05	B3	S08
582 USA	171058 E84	USA	Q21	V05	B3	S08
252 USA	121848	1 USA	Q21	V05	B3	S08
801 USA	123347	2 USA	Q21	V05	B3	S08
817 USA	182016	1 USA	Q21	V05	B3	S08
805 USA	171472	1 USA	Q21	V05	B3	S08
956 USA	152772 E84	USA	Q21	V05	B3	S08
828 USA	171176	2 USA	Q21	V05	B3	S08
817 USA	182001 E84	USA	Q21	V05	B3	S08
817 USA	182001 E84	USA	Q21	V05	B3	S08
909 USA	171106	1 USA	Q21	V05	B3	S08
630 USA	172208	2 USA	Q21	V05	B3	S08
308 USA	141078 E81	USA	Q21	V05	B3	S08
610 USA	172013 E84	USA	Q21	V05	B3	S08
902 USA	171176 E84	USA	Q21	V05	B3	S08
806 USA	171451	1 USA	Q21	V05	B3	S08
520 USA	171204	1 USA	Q21	V05	B3	S08
919 USA	121028	1 USA	Q21	V05	B3	S08
818 USA	171072 E84	USA	Q21	V05	B3	S08
757 USA	127051 E84	USA	Q21	V05	B3	S08
310 USA	171069 E84	USA	Q21	V05	B3	S08
931 USA	123079 E84	USA	Q21	V05	B3	S08
409 USA	152754	2 USA	Q21	V05	B3	S08
214 USA	152003	1 USA	Q21	V05	B3	S08
727 USA	124205 E84	USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08
704 USA	121213 E84	USA	Q21	V05	B3	S08
817 USA	182013 E84	USA	Q21	V05	B3	S08
210 USA	152204	2 USA	Q21	V05	B3	S08
972 USA	152002	1 USA	Q21	V05	B3	S08
817 USA	182009 E84	USA	Q21	V05	B3	S08
938 USA	152166	1 USA	Q21	V05	B3	S08
510 USA	171097 E84	USA	Q21	V05	B3	S08
909 USA	171097	1 USA	Q21	V05	B3	S08
310 USA	171015	2 USA	Q21	V05	B3	S08


561 USA	124224	2 USA	Q21	V05	B3	S08
941 USA	124480	1 USA	Q21	V05	B3	S08
770 USA	121490 EB4	USA	Q21	V05	B3	S08
252 USA	121019 EB4	USA	Q21	V05	B3	S08
805 USA	171251 EB4	USA	Q21	V05	B3	S08
714 USA	171068 EB4	USA	Q21	V03	B3	S08
915 USA	152564 EB4	USA	Q21	V05	B3	S08
864 USA	121226	1 USA	Q21	V05	B3	S08
805 USA	171447 EB4	USA	Q21	V05	B3	S08
949 USA	171006	1 USA	Q21	V05	B3	S08
909 USA	171425	2 USA	Q21	V05	B3	S08
501 USA	123204 EB4	USA	Q21	V05	B3	S08
954 USA	124015	1 USA	Q21	V05	B3	S08
229 USA	121573	1 USA	Q21	V05	B3	S08
910 USA	121225 EB4	USA	Q21	V05	B3	S08
972 USA	152002	1 USA	Q21	V05	B3	S08
915 USA	152573	1 USA	Q21	V05	B3	S08
305 USA	124001	1 USA	Q21	V05	B3	S08
408 USA	172039 EB4	USA	Q21	V05	B3	S08
938 USA	152158	2 USA	Q21	V05	B3	S08
407 USA	124214	2 USA	Q21	V05	B3	S08
409 USA	152771	1 USA	Q21	V05	B3	S08
918 USA	172205	2 USA	Q21	V05	B3	S08
719 USA	159461 EB4	USA	Q21	V05	B3	S08
915 USA	152211 EB4	USA	Q21	V05	B3	S08
915 USA	152211 EB4	USA	Q21	V05	B3	S08
818 USA	171019	1 USA	Q21	V05	B3	S08
910 USA	121225 EB4	USA	Q21	V05	B3	S08
760 USA	171430	1 USA	Q21	V05	B3	S08
817 USA	152009	1 USA	Q21	V05	B3	S08
582 USA	171055	1 USA	Q21	V05	B3	S08
910 USA	121026 EB4	USA	Q21	V74	B3	S08
708 USA	141052	2 USA	Q21	V05	B3	S08
954 USA	124015 EB4	USA	Q21	V05	B3	S08
337 USA	123271 EB4	USA	Q21	V03	B3	S08
601 USA	123309 EB4	USA	Q21	V05	B3	S08
318 USA	123223	2 USA	Q21	V05	B3	S08

323 USA	171022	1 USA	Q21	V74	B3	S08
955 USA	152772	1 USA	Q21	V05	B3	S08
972 USA	152012 E84	USA	Q21	V05	B3	S08
936 USA	152166 E84	USA	Q21	V05	B3	S08
910 USA	171029	1 USA	Q21	V05	B3	S08
915 USA	152016	2 USA	Q21	V06	B3	S08
813 USA	124208 E84	USA	Q21	V05	B3	S08
916 USA	172207	1 USA	Q21	V05	B3	S08
805 USA	171452 E84	USA	Q21	V05	B3	S08
714 USA	171009	2 USA	Q21	V05	B3	S08
561 USA	124404	1 USA	Q21	V05	B3	S08
841 USA	124428	1 USA	Q21	V05	B3	S08
727 USA	124544	1 USA	Q21	V05	B3	S08
910 USA	121224	1 USA	Q21	V05	B3	S08
727 USA	124302	1 USA	Q21	V05	B3	S08
956 USA	152772	1 USA	Q21	V05	B3	S08
404 USA	121024	1 USA	Q21	V05	B3	S08
512 USA	152302 E84	USA	Q21	V05	B3	S08
261 USA	152024 E84	USA	Q21	V05	B3	S08
310 USA	171015	1 USA	Q21	V05	B3	S08
972 USA	152462	2 USA	Q21	V05	B3	S08
851 USA	171491	1 USA	Q21	V05	B3	S08
818 USA	171019 E84	USA	Q21	V05	B3	S08
626 USA	171072	1 USA	Q21	V05	B3	S08
214 USA	152008	1 USA	Q21	V05	B3	S08
770 USA	121405 E84	USA	Q21	V05	B3	S08
281 USA	152044 E84	USA	Q21	V05	B3	S08
601 USA	123306	1 USA	Q21	V05	B3	S08
702 USA	171167 E84	USA	Q21	V05	B3	S08
813 USA	124208 E84	USA	Q21	V05	B3	S08
915 USA	152573 E84	USA	Q21	V05	B3	S08
281 USA	152032 E84	USA	Q21	V05	B3	S08
826 USA	171072	2 USA	Q21	V05	B3	S08
809 USA	171097	2 USA	Q21	V05	B3	S08
205 USA	121011	1 USA	Q21	V05	B3	S08
305 USA	124003 E83	USA	Q21	V05	B3	S08
817 USA	152020 E84	USA	Q21	V05	B3	S08


702 USA	171187	1 USA	Q21	V05	B3	S08
727 USA	124213	1 USA	Q21	V05	B3	S08
703 USA	127044	2 USA	Q21	V05	B3	S08
661 USA	171481	1 USA	Q21	V05	B3	S08
323 USA	171007	1 USA	Q21	V05	B3	S08
813 USA	124445 E84	USA	Q21	V05	B3	S08
228 USA	124017	2 USA	Q21	V05	B3	S08
210 USA	152057	1 USA	Q21	V05	B3	S08
251 USA	124017 E84	USA	Q21	V05	B3	S08
915 USA	152210	1 USA	Q21	V05	B3	S08
916 USA	172201 E84	USA	Q21	V05	B3	S08
985 USA	123050	1 USA	Q21	V05	B3	S08
843 USA	121281	1 USA	Q21	V03	B3	S08
919 USA	121026	1 USA	Q21	V05	B3	S08
405 USA	152688 E84	USA	Q21	V05	B3	S08
972 USA	152002	1 USA	Q21	V05	B3	S08
727 USA	124202	1 USA	Q21	V05	B3	S08
408 USA	172039	1 USA	Q21	V05	B3	S08
817 USA	152019 E84	USA	Q21	V05	B3	S08
714 USA	171052 E84	USA	Q21	V05	B3	S08
941 USA	124480	1 USA	Q21	V05	B3	S08
808 USA	152578	2 USA	Q21	V05	B3	S08
972 USA	152525	2 USA	Q21	V05	B3	S08
254 USA	152504 E81	USA	Q21	V05	B3	S08
281 USA	152054	1 USA	Q21	V05	B3	S08
310 USA	171018	1 USA	Q21	V07	B3	S06
727 USA	124454	1 USA	Q21	V05	B3	S08
760 USA	171102	1 USA	Q21	V05	B3	S08
919 USA	121026	1 USA	Q21	V05	B3	S08
252 USA	121644	1 USA	Q21	V05	B3	S08
885 USA	121869	1 USA	Q21	V77	B3	S09
251 USA	124017 E84	USA	Q21	V05	B3	S08
727 USA	124454	1 USA	Q21	V05	B3	S08
727 USA	124802	1 USA	Q21	V74	B3	S06
258 USA	121108	1 USA	Q21	V05	B3	S08
840 USA	152529	2 USA	Q21	V05	B3	S08
954 USA	124003	2 USA	Q21	V05	B3	S08

872 USA	152014	1 USA	Q21	V74	B3	S08
808 USA	171150 E84	USA	Q21	V05	B3	S08
813 USA	124486 E84	USA	Q21	V05	B3	S08
912 USA	124452	1 USA	Q21	V05	B3	S08
949 USA	171082 E84	USA	Q21	V05	B3	S08
872 USA	152012 E84	USA	Q21	V05	B3	S08
826 USA	171040 E84	USA	Q21	V05	B3	S08
941 USA	124428	1 USA	Q21	V05	B3	S08
USA	121026 E84	USA	Q21	V05	B3	S08
310 USA	171018	1 USA	Q21	V07	B3	S06
909 USA	171067	1 USA	Q21	V05	B3	S08
214 USA	152003	1 USA	Q21	V05	B3	S08
256 USA	121717	1 USA	Q21	V05	B3	S08
252 USA	121847	1 USA	Q21	V05	B3	S08
884 USA	121784 E84	USA	Q21	V05	B3	S08
714 USA	171057	1 USA	Q21	V05	B3	S08
770 USA	121025	2 USA	Q21	V05	B3	S08
770 USA	121059	1 USA	Q21	V05	B3	S08
828 USA	121810	1 USA	Q21	V06	B3	S08
582 USA	171051	1 USA	Q21	V05	B3	S08
229 USA	121408	1 USA	Q21	V05	B3	S08
817 USA	152020	1 USA	Q21	V05	B3	S08
757 USA	127060 E84	USA	Q21	V05	B3	S08
703 USA	127009	1 USA	Q21	V05	B3	S08
210 USA	152083 E84	USA	Q21	V05	B3	S08
828 USA	171072	1 USA	Q21	V05	B3	S08
770 USA	124227 E84	USA	Q21	V05	B3	S08
407 USA	124227	1 USA	Q21	V05	B3	S08
949 USA	171065 E84	USA	Q21	V05	B3	S08
405 USA	152503 E84	USA	Q21	V05	B3	S08
770 USA	121060 E84	USA	Q21	V74	B3	S08
614 USA	147030	1 USA	Q21	V05	B3	S08
281 USA	152052	1 USA	Q21	V05	B3	S08
909 USA	171150	1 USA	Q21	V05	B3	S08
662 USA	171047	1 USA	Q21	V74	B3	S08
819 USA	171060	2 USA	Q21	V74	B3	S08
817 USA	152016 E84	USA	Q21	V05	B3	S08

214 USA	152003	2 USA	Q21	V05	B3	S08
706 USA	121205	2 USA	Q21	V05	B3	S08
404 USA	121001	1 USA	Q21	V05	B3	S08
805 USA	171439	1 USA	Q21	V05	B3	S08
818 USA	171040	2 USA	Q21	V05	B3	S08
386 USA	124200 E84	USA	Q21	V05	B3	S08
618 USA	171043 E84	USA	Q21	V05	B3	S08
912 USA	121209	1 USA	Q21	V05	B3	S08
618 USA	171019	1 USA	Q21	V05	B3	S08
909 USA	171152 E84	USA	Q21	V05	B3	S08
606 USA	141100	1 USA	Q21	V05	B3	S08
918 USA	121019	2 USA	Q21	V05	B3	S08
602 USA	171173	2 USA	Q21	V05	B3	S08
770 USA	121007	1 USA	Q21	V05	B3	S08
941 USA	124429	1 USA	Q21	V05	B3	S08
404 USA	121001	1 USA	Q21	V05	B3	S08
817 USA	152009	1 USA	Q21	V05	B3	S08
919 USA	121026	2 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
281 USA	152055	1 USA	Q21	V05	B3	S08
626 USA	171031 E84	USA	Q21	V05	B3	S08




RCR04-011 02747



Years 01 Exped-Nav first inspect\_PROD\_N\_DT

2001 TRW Buckles Post 01S21



	2000				2001					
	Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May
■ CV/GM	2		1	2	2	8	1	8	11	4
■ Excursion				1	2	9	5	8	9	3
□ Exped/Nav	1	1	4	2		9	8	18	52	8
□ F150			2	3		2	5	7	8	
■ F250-F550			8	13	8	5	13	23	133	20
■ Ranger		2	4	12	2	1		8	40	2
■ Town Car		2	8	4		14	38	22	16	10
□ Windstar	3	2	2	3	9	21	5	3	4	3

Month of Production

Count of 01 Exped-Nav first inspect_VIN_CD		VL Date
Years	01 Exped-Nav first inspect_PROD DT	CV/GM
2000	Aug	2
	Sep	
	Oct	1
	Nov	2
	Dec	2
2001	Jan	8
	Feb	1
	Mar	6
	Apr	11
	May	4
<b>Grand Total</b>		<b>35</b>

Ratings							
Excursion	Exped/Nav	F150	F250-F550	Ranger	Town Car	Windstar	Grand Total
		1				3	6
		1		2	2	2	7
		4	2	8	4	8	29
1	2	3	13	12	4	3	40
2			8	2		9	21
3	9	2	5	1	14	21	61
5	8	5	13		39	5	74
8	18	7	23	8	22	3	95
9	52	8	133	40	16	4	273
3	8		20	2	10	3	50
31	101	27	221	71	115	55	658

2001	1FMNU425	30.75	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	60.55	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	24.81	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	37.56	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	24	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	58.38	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	14.84	T/L1	*	T/W/D	T/C/A
2001	1FMNU421	44.12	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	47.27	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	46.76	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	24.09	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	47.41	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	51.98	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	15.56	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	95.25	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU425	55.47	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	12.28	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	22.4	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	21.6	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	57.07	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	15	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	35.01	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	0	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	25.8	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	30.17	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	19.6	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	62.84	T/L1	*	T/W/D	T/C/A
2001	1FMNU415	54.74	T/L1	*	T/W/D	T/C/A
2001	1FMNU405	22.92	T/L1	*	T/W/D	T/C/A

2001	1FMNU408	14.76	T/L1	*	T/WD	T/CA
2001	1FMNU408	61.14	T/L1	*	T/WD	T/CA
2001	1FMNU408	49.82	T/L1	*	T/WD	T/CA
2001	1FMNU408	51.25	T/L1	*	T/WD	T/CA
2001	1FMNU408	27.3	T/L1	*	T/WD	T/CA
2001	1FMNU408	0	T/L1	*	T/WD	T/CA
2001	1FMNU408	25.21	T/L1	*	T/WD	T/CA
2001	1FMNU408	37.61	T/L1	*	T/WD	T/CA
2001	1FMNU408	15.78	T/L1	*	T/WD	T/CA
2001	1FMNU408	47.17	T/L1	*	T/WD	T/CA
2001	1FMNU408	43	T/L1	*	T/WD	T/CA
2001	1FMNU408	28.8	T/L1	*	T/WD	T/CA
2001	1FMNU408	188.55	T/L1	*	T/WD	T/CA
2001	1FMNU408	10.77	T/L1	*	T/WD	T/CA
2001	1FMNU408	22.82	T/L1	*	T/WD	T/CA
2001	1FMNU408	27.88	T/L1	*	T/WD	T/CA
2001	1FMNU408	24	T/L1	*	T/WD	T/CA
2001	1FMNU408	35.11	T/L1	*	T/WD	T/CA
2001	1FMNU408	49.29	T/L1	*	T/WD	T/CA
2001	1FMNU408	85.6	T/L1	*	T/WD	T/CA
2001	1FMNU408	11.85	T/L1	*	T/WD	T/CA

T/B	T/WA	T/DE	A1	29-Jan-01	24-Mar-01	FIVERTO	871152	6537420
T/B	T/WA	T/DE	A1	4-Jun-01	30-Oct-01	CERRITO	25468401	8655554
T/B	T/WA	T/DE	A1	30-Jan-01	17-May-01	LAKELAN	5808051	8821102
T/B	T/WA	T/DE	A1	18-Jan-01	30-Jun-01	WALNUT	338570A	9322900
T/B	T/WA	T/DE	A1	1-Nov-00	7-Nov-01	ED MOSE	4088701	8373581
T/B	T/WA	T/DE	A1	22-May-01	1-Dec-01	FORD OF	177266A	9485555
T/B	T/WA	T/DE	A1	1-Feb-01	9-Mar-01	WORTHIN	14088201	4203333
T/B	T/WA	T/DE	A1	11-Jan-01	30-Jun-01	RAY ANDR	8728702	3386291
T/B	T/VZ	T/DE	A1	18-Jun-01	5-Nov-01	BLUEBON	18450001	8088011
T/B	T/VZ	T/DE	A1	10-Jun-01	18-Aug-01	MARCOON	383313A	8727200
T/B	T/VZ	T/DE	A1	10-Jun-01	18-Aug-01	MARCOON	383313B	9727200
T/B	T/VZ	T/DE	A1	27-Feb-01	27-Jul-01	PRESTIGE	022538A	3575522
T/B	T/VZ	T/DE	A1	27-Feb-01	9-Jul-01	APPEL FO	4848110	8383869
T/B	T/DS	T/DS	A1	10-Jun-01	30-Jul-01	RANDALL	20870801	4488171
T/B	T/DS	T/DS	A1	4-Apr-01	31-May-01	PRESTON	017568B	8737171
T/B	T/DS	T/DS	A1	7-Mar-01	13-Apr-01	ARMSTR	1014504	2475112
T/B	T/DS	T/DS	A1	6-Feb-01	13-Aug-01	DUB HER	5497355	7988882
T/B	T/DS	T/DS	A1	3-Apr-01	9-Jan-02	BAY FORD	2347552	8889545
T/B	T/DS	T/DS	A1	4-Jun-01	7-Jul-01	PARK CIT	12982001	3588800
T/B	T/DS	T/DS	A1	11-Jun-01	11-Oct-01	RANDALL	20671501	4489171
T/B	T/DS	T/DS	A1	11-Jun-01	17-Oct-01	BELL FOR	7715401	8881778
T/E	T/WA	T/DE	A1	1-Feb-01	11-Nov-01	LANCE CL	20452301	8872100
T/E	T/WA	T/DE	A1	22-Mar-01	10-Apr-01	EDDIE YA	087734D	5922861
T/E	T/WA	T/DE	A1	26-Jan-01	11-Feb-01	HERTZ RA	98788901	*
T/E	T/WA	T/DE	A1	1-Apr-01	7-May-01	WALDORF	4820151	8432400
T/E	T/WA	T/DE	A1	21-Jun-01	4-Sep-01	FREEHOL	2832351	-358
T/E	T/WA	T/DE	A1	27-Feb-01	15-Mar-01	HERTZ RA	40883901	*
T/E	T/WA	T/DE	A1	7-Feb-01	19-Feb-01	MEL CLAY	3837551	2841611
T/E	T/WA	T/DE	A1	26-Jan-01	7-Aug-01	YORK FOR	285452A	2311845
T/E	T/WA	T/DE	A1	18-May-01	3-Jun-01	HERTZ RA	43309901	*
T/E	T/WA	T/DE	A1	25-Apr-01	20-May-01	SALINAS V	10458301	7584444
T/E	T/WA	T/DE	A1	4-Mar-01	21-Mar-01	HERTZ RA	37871401	*
T/E	T/VZ	T/DE	A1	25-May-01	3-Nov-01	COUNTRY	078713A	5753873
T/E	T/VZ	T/DE	A1	8-Jan-01		TOWN & C	403501	2885211
T/B	T/WA	T/DE	A1	27-Feb-01	31-Mar-01	JAMES HC	278923B	6821345

T/B	T/WA	T/DE	A1	14-Mar-01	26-Apr-01	SESSLER	088761A	3824550
T/B	T/WA	T/DE	A1	3-Jun-01	15-Aug-01	GALPIN F	59881051	7873800
T/B	T/WA	T/DE	A1	11-Dec-00	8-Jan-01	NEW CEN	075447A	2852221
T/B	T/WA	T/DE	A1	25-Jan-01	19-Nov-01	TIDELAND	105170A	2373873
T/B	T/NZ	T/DE	A1	27-Feb-01	29-Mar-01	WEBB FO	8605951	7211984
T/B	T/NZ	T/DE	A1	23-Dec-00	12-Feb-01	MAC HAIK	142880A	8308873
T/B	T/NZ	T/DE	A1	18-Oct-00	4-Nov-00	METRO F	2063901	8227181
T/B	T/NZ	T/DE	A1	3-Apr-01	18-May-01	PLAZA FO	101723F	8772900
T/B	T/NZ	T/DE	A1	30-Oct-00	26-Apr-01	QUALITY I	2072301	8324063
T/B	T/NZ	T/DE	A1	13-Jan-01	31-Jan-01	SCOTTSE	8309751	8353701
T/B	T/NZ	T/DE	A1	27-Apr-01	5-Jul-01	BIG VALLE	43508801	8704400
T/B	T/NZ	T/DE	A1	13-Mar-01	3-Sep-01	COUNTY L	10491802	2958121
T/B	T/NZ	T/DE	A1	28-Jan-01	14-Nov-01	DOWNEY	3384851	8818771
T/B	T/NZ	T/DE	A1	12-Oct-00	10-Nov-00	GOLDING	7828851	3725707
T/B	T/NZ	T/DE	A1	25-Jan-01	10-Feb-01	MY LINCO	10729001	4444000
T/B	T/NZ	T/DE	A1	20-Apr-01	25-Jun-01	CHAPMAN	18844702	9990261
T/B	T/NZ	T/DE	A1	29-Mar-01	11-Jun-01	VILLAGE F	1504751	8882298
T/B	T/DS	T/DS	A1	22-Oct-00	22-Mar-02	FEDLAND	8112452	7833211
T/B	T/DS	T/DS	A1	19-Apr-01	24-Jun-01	SUNRISE	520585A	8224401
T/B	T/DS	T/DS	A1	18-Feb-01	19-Jan-02	BAYVIEW	088982B	8287777
T/B	T/DS	T/DS	A1	17-Feb-01	12-Mar-01	PRESTON	018277A	8737171

6R02	1L7Z	7	AAA	G09	42	8/21/2001	3252867
6R02	1L7Z	7	AAA	S40	42	7/27/2001	3490894
6R02	1C3Z	2	CAA	G29	42	12/20/2001	5919805
6R02	1C3Z	2	CAA	S40	42	11/16/2001	5136958
6R02	1C3Z	2	CAA	S40	42	8/14/2002	8165858
6R02	1L7Z	7	AAA	S25	41	7/19/2001	2725914
6R02	1C3Z	2	CAA	S25	42	11/1/2001	4893030
6R02	1L7Z	7	AAA	B54	33	11/5/2001	5045541
6R02	1L7Z	7	AAA	T90	42	7/24/2001	3288298
6R02	1L7Z	7	AAA	S40	42	7/17/2001	2616036
6R02	1L7Z	7	AAA	S40	42	7/17/2001	2897109
6R02	1L7Z	7	AAA	S25	69	8/28/2001	6201307
6R02	*	2	*	S40	42	9/11/2001	4453831
6R02	1L7Z	7	AAA	S40	42	7/26/2001	2965890
6R02	1C3Z	2	BAA	S25	42	2/13/2002	7889734
6R02	F81Z	2	MMM	S40	43	8/28/2001	4176782
6R02	1C3Z	2	CAA	B09	33	10/18/2001	6717835
6R02	1C3Z	2	CAA	S40	42	2/28/2002	7291376
6R02	F81Z	2	CCD	H19	42	6/22/2001	2263531
6R02	1L7Z	7	AAA	S40	42	7/26/2001	3024579
6R02	YC3Z	7	AAA	S25	42	4/17/2002	8238651
6R02	*	7	*	S40	7	4/24/2002	8671846
6R02	1C3Z	2	BAC	S25	42	5/2/2002	8580663
6R02	F81Z	2	MMM	G29	28	8/26/2001	2311617
6R02	1L7Z	7	AAB	S25	1	10/19/2001	4573407
6R02	1C3Z	2	CAA	S25	41	8/4/2001	3536590
6R02	1C3Z	2	CAC	S40	33	7/19/2001	4964899
6R02	1L7Z	7	AAB	S40	42	1/25/2002	6586349
6R02	1C3Z	2	CAC	S25	1	7/25/2001	4861084
6R02	F81Z	2	MMM	S40	42	11/8/2001	5852593
6R02	1L7Z	7	AAB	S25	42	1/29/2002	6848370
6R02	1L7Z	7	AAB	S40	42	8/30/2001	4227726
6R02	1L7Z	7	AAB	S40	41	7/20/2001	4492425
6R02	1C3Z	2	CAC	S25	42	1/14/2002	6819320
6R02	1C3Z	2	CAC	G29	42	5/31/2002	8910977

6R02	1C3Z	2	[REDACTED]	CAC	S40	41	9/26/2001		3986165
6R02	1L7Z	7	[REDACTED]	AAB	S40	42	6/14/2001		3525091
6R02	1L7Z	7	[REDACTED]	AAB	S40	42	3/11/2002		7336207
6R02	1C3Z	2	[REDACTED]	CAA	G29	46	1/18/2002		6335940
6R02	1L7Z	7	[REDACTED]	AAB	S40	41	4/17/2002		8085048
6R02	F81Z	2	[REDACTED]	JJJ	S40	42	1/2/2002		6071990
6R02	1L7Z	7	[REDACTED]	AAB	S25	42	2/28/2002		7115875
6R02	1C3Z	2	[REDACTED]	CAA	S25	42	5/8/2002		8608207
6R02	1C3Z	2	[REDACTED]	CAA	S40	41	1/8/2002		6124457
6R02	1L7Z	7	[REDACTED]	AAB	S25	42	1/30/2002		6692366
6R02	1L7Z	7	[REDACTED]	AAB	S25	41	6/4/2002		9073648
6R02	F81Z	2	[REDACTED]	MMM	S40	42	11/9/2001		5284315
6R02	1C3Z	2	[REDACTED]	CAC	C19	12	11/30/2001		5457677
6R02	*	7	[REDACTED]	*	S25	33	7/3/2001		2224239
6R02	1L7Z	7	[REDACTED]	AAB	S40	42	11/16/2001		5234716
6R02	1L7Z	7	[REDACTED]	AAB	S25	42	3/19/2002		7482802
6R02	1L7Z	7	[REDACTED]	AAA	S40	42	10/29/2001		4881373
6R02	1L7Z	7	[REDACTED]	AAB	S25	42	3/25/2002		7623651
6R02	1L7Z	7	[REDACTED]	AAB	S25	41	11/27/2001		5468528
6R02	1C3Z	2	[REDACTED]	BAA	S40	1	2/7/2002		6697323
6R02	1C3Z	2	[REDACTED]	CAC	S40	42	7-Nov-01		5121937

9588	39.32	70.1	0.5	4110*	NA	GA	
6	20.27	80.82	0.8	5401*	NA	CA	
11215	19.05	43.86	0.4	1741*	NA	FL	
8737	23.86	61.22	0.4	7820*	NA	CA	
17366	19.05	43.05	0.4	2843*	NA	TX	
12	39.32	97.88	0.8	5555*	NA	CA	
13678	0	0	0	7839*	NA	CA	
8091	20.27	35.11	0.2	7858*	NA	CA	
11	20.27	64.38	0.7	4570*	NA	TX	
26	0	0	0	4820*	NA	FL	
26	20.27	67.54	0.7	4820*	NA	FL	
15	39.32	88.1	0.8	4932*	NA	FL	
6282	0	24.09	0.4	4500*	NA	TX	
6	0	0	0	4482*	NA	TX	
27418	23.16	70.57	0.8	25*	NA	MD	
11811	0	51.88	0.8	4332*	NA	FL	
4424	19.05	34.61	0.3	6538*	NA	MS	
2439	19.05	114.3	1.5	5374*	NA	FL	
20	0	0	0	2405*	NA	TX	
16	0	0	0	4482*	NA	TX	
10602	18.16	71.83	0.8	20980*	NA	AZ	
7980	0	12.28	0.2	6613*	NA	TN	
9459	23.16	45.56	0.4	4181*	NA	TX	
9833	16.33	37.93	0.4	45282*	NA	TX	
9905	20.27	77.34	0.8	149*	NA	MD	
8	0	0	0	20554*	NA	NJ	
10089	16.33	31.33	0.3	45250*	NA	FL	
21427	20.27	65.28	0.5	20303*	NA	AZ	
10	0	0	0	8888*	NA	MA	
10791	16.86	42.86	0.5	45255*	NA	FL	
13884	20.27	50.44	0.4	7725*	NA	CA	
9897	17.38	36.98	0.4	45279*	NA	TX	
6	20.27	83.11	0.9	7780*	NA	CA	
18	19.05	73.79	0.7	5179*	NA	OR	
8272	19.05	41.97	0.4	2496*	NA	OK	

4978	23.07	37.83	0.2	1711	*	NA	IL	
10	39.32	100.48	0.8	5536	*	NA	CA	
16686	20.27	69.89	0.7	1733	*	NA	CA	
1791	19.05	70.3	1	1231	*	NA	SC	
17733	20.27	47.57	0.4	1892	*	NA	IN	
28026	0	0	0	7870	*	NA	TX	
38816	20.27	45.48	0.4	7618	*	NA	MA	
11081	19.05	58.86	0.8	17	*	NA	MD	
10822	19.05	34.83	0.3	6509	*	NA	LA	
13898	20.27	67.44	0.9	7388	*	NA	NE	
22333	20.27	83.27	0.5	7742	*	NA	CA	
2238	19.87	46.27	0.4	6802	*	NA	TX	
854	0	188.55	2.1	2282	*	NA	CA	
25141	0	10.77	0.2	2588	*	NA	TX	
28585	20.27	43.09	0.3	12751	*	NA	CA	
14169	20.27	48.13	0.4	1402	*	NA	DE	
9576	20.27	44.27	0.4	3080	*	NA	TX	
424	20.27	55.88	0.5	1895	*	NA	CA	
6508	20.27	69.58	0.7	5539	*	NA	CA	
1137	23.18	108.76	1.4	6420	*	NA	AL	
31001	19.05	30.9	0.2	25	*	NA	MD	

X	RMVD		RSTRIPPI	708	USA	121208	1	USA
X	BELT		BELT	562	USA	171055	1	USA
X	SEATBEL		STATES	863	USA	124203	2	USA
X	WARR		ER	925	USA	172022	1	USA
X				909	USA	152100	E84	USA
X	111		01S21	909	USA	171106	1	USA
X	DEFECTI		THE	562	USA	171089	E84	USA
X	D		SOP	828	USA	171084	1	USA
X				890	USA	162752	1	USA
X	VERIFIED		SEAT	954	USA	124015	1	USA
X	CUST		BELT	954	USA	124015	1	USA
X	BOTH		STATES	352	USA	124446	1	USA
X	REINSTA		ROW	979	USA	152734	1	USA
X	D SEAT		BLET	281	USA	152046	1	USA
X	SEAT		ER	410	USA	127547	E84	USA
X	BELT		SEAT	305	USA	124228	2	USA
X	DOOR		STATES	601	USA	123659	2	USA
X	WIRE AT		SIDE	727	USA	124644	1	USA
X	ELECT		BAG	214	USA	152005	1	USA
X	D		BELT	281	USA	152046	1	USA
X	BHR		ER	602	USA	171177	1	USA
X	BELT		FOR	605	USA	121216	1	USA
X	D FRONT		BELT ON	361	USA	183000	E84	USA
X	D LEFT		BELT	*	USA	152815	2	USA
X	M		SO	301	USA	183000	2	USA
X	REPLACE		SEATBEL	732	USA	113470	1	USA
X	D DRIVER		BELT	*	USA	124804	2	USA
X	AND		FRONT	602	USA	18906R	E84	USA
X	ONE		BELT	781	USA	111502	1	USA
X	DRIVERS		SEAT	*	USA	124804	2	USA
X	RIGHT			408	USA	172412	E84	USA
X	D THE RF		FRONT	*	USA	152815	2	USA
X	D PASS.		SIDE	209	USA	172819	1	USA
X	REPLACE		SEAT	503	USA	174015	E84	USA
X	OUT AND		BELT	918	USA	152535	E84	USA

X	TO		SEATBEL	847	USA	141082		1	USA
X	SEAT			818	USA	171040		1	USA
X	MED		CHECK	626	USA	171900	E84		USA
X	DAND		STATES	843	USA	121299	E93		USA
X	SEAT		SAFTEY	312	USA	141075	E84		USA
X	RECALL		RECALL	512	USA	152782	E84		USA
X	CONCER		PASS	508	USA	124125	E81		USA
X	DRIVERS		T HARD	410	USA	127419		2	USA
X	BUCKLE.		DRIVER	318	USA	123217		2	USA
X				308	USA	156433	E84		USA
X	SEAT		ER	209	USA	172402	E84		USA
X	IN		BELT	817	USA	152188		2	USA
X	DUCT,		SIDE	582	USA	171049		1	USA
X	CONCER		SEAT	915	USA	124125	E84		USA
X	SEAT		SOP	831	USA	124125	E84		USA
X	REPLACE		SEATBEL	302	USA	127037	E84		USA
X	BELT		SEAT	940	USA	152414		1	USA
X	BUCKLE		PASSEN	909	USA	171153		2	USA
X	01S21C		RIGHT	809	USA	171152		1	USA
X	CONCER		STATES	251	USA	124552		1	USA
X	REPLACE		T 01S21	410	USA	127647	E84		USA

Q21	V09	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V83	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V71	L1	S08		#REF!	#REF!	#REF!
Q21	V74	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V06	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V31	L1	S01		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V21	L1	S10		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V83	L1	S09		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V05	L1	S08		#REF!	#REF!	#REF!
Q21	V83	L1	S09		#REF!	#REF!	#REF!



01 Exped-N	01 Exped-N	01 Exped-N	01 Exped-Nav first Inspe	01 Exped-N	01 Exped-N	VL Desc	01 Exped-N
14	2001	14	5LMFU28RB1L	21.48	T/B4	Exped/Nav*	
144	2001	144	1FMRU17W61L	19.19	T/B3	Exped/Nav*	
148	2001	148	1FMRU17W51L	52.42	T/B3	Exped/Nav*	
153	2001	153	1FMRU17W31LB35710	19.28	T/B3	Exped/Nav*	

172	2001	172	FMRU17L71L		18.17	T/B3	Exped/Nav*
252	2001	252	FMRU15WX1LB23217		22.26	T/B3	Exped/Nav*

273	2001	273	1FMRU15W91	[REDACTED]	18.52	T/B3 Exped/Nav*
387	2001	387	1FMRU15W21L	[REDACTED]	50.12	T/B3 Exped/Nav*
53	2001	53	2FTPF18L31C	[REDACTED]	17.17	T/F5 F150 *

30	2001	30	1FTZR15EX1T		17.59	T/R3	Ranger	*
122	2001	122	1FTWW33FX1E		44.94	T/F7	F250-F550*	
110	2001	110	1FTWX33F41		24.16	T/F7	F250-F550*	
54	2001	54	3FTNW21FX1M		52.96	T/F7	F250-F550*	
450	2001	450	1FTNX21F81ED		72.19	T/F7	F250-F550*	
145	2001	145	1FTWW33F51E		19.87	T/F7	F250-F550*	

348	2001	348	1FTNX21S31E [REDACTED]	37.25	T/F7	F250-F550*
399	2001	399	1FTNX21L41E [REDACTED]	18.75	T/F7	F250-F550*
481	2001	481	1FTNX21F51E [REDACTED]	17.7	T/F7	F250-F550*
33	2001	33	3FTNX21L71M [REDACTED]	17.99	T/F7	F250-F550*
445	2001	445	1FTNX21F91E [REDACTED]	18	T/F7	F250-F550*
212	2001	212	1FTSX31S21E [REDACTED]	18.77	T/F7	F250-F550*
436	2001	438	1FTNX21F91E [REDACTED]	73.36	T/F7	F250-F550*
460	2001	480	1FTNX21F81E [REDACTED]	33.94	T/F7	F250-F550*

385	2001	385	1FTNX21L71E	[REDACTED]	14.9	T/F7	F250-F550*
257	2001	257	1FTSW31FX1E	[REDACTED]	18.1	T/F7	F250-F550*
351	2001	351	1FTNX21S11E	[REDACTED]	13.18	T/F7	F250-F550*
420	2001	420	1FTNX21L11E	[REDACTED]	19.92	T/F7	F250-F550*
249	2001	249	1FTSW31S51E	[REDACTED]	20.4	T/F7	F250-F550*
387	2001	387	1FTNX21L71E	[REDACTED]	20.82	T/F7	F250-F550*

515	2001	515	1FTNX21F01E [REDACTED]	18.08	T/F7	F250-F550*
28	2001	28	3FTSW31F01M [REDACTED]	14.07	T/F7	F250-F550*
484	2001	484	1FTNX21F41E [REDACTED]	83.37	T/F7	F250-F550*
446	2001	446	1FTNX21F91E [REDACTED]	20.48	T/F7	F250-F550*
500	2001	500	1FTNX21F31E [REDACTED]	18.16	T/F7	F250-F550*

403	2001	403	1FTNX21L31E [REDACTED]	42.99	T/F7	F250-F550*
52	2001	52	3FTNW21L11M [REDACTED]	48.27	T/F7	F250-F550*
180	2001	180	1FTWW33F11E [REDACTED]	27.02	T/F7	F280-F560*
374	2001	374	1FTNX21LB1E [REDACTED]	14.7	T/F7	F250-F550*

74	2001	74	3FTNW21F31M		70.35	T/F7	F250-F550*
16	2001	16	3FTSW31F61		17.03	T/F7	F250-F550*
258	2001	258	1FTSW31FX1E		19.44	T/F7	F250-F550*
288	2001	288	1FTSW31F31E		18.28	T/F7	F250-F550*
479	2001	479	1FTNX21F51		15.44	T/F7	F250-F550*
65	2001	65	3FTNW21F61M		19.17	T/F7	F250-F550*
28	2001	28	3FTSW31F01M		14.07	T/F7	F250-F550*

291	2001	231	1FTSX31F51E [REDACTED]	18.41	T/F7	F250-F550*
229	2001	229	1FTSX31F71E [REDACTED]	21.01	T/F7	F250-F550*
289	2001	289	1FTSW31F31E [REDACTED]	16.59	T/F7	F250-F550*
51	2001	51	3FTNW21L41N [REDACTED]	20.4	T/F7	F250-F550*
97	2001	97	3FTNW20F11M [REDACTED]	36.98	T/F7	F250-F550*
332	2001	332	1FTNX21S81E [REDACTED]	17.13	T/F7	F250-F550*

335	2001	335	1FTNX21S71E		15.59	T/F7	F250-F550*
507	2001	507	1FTNX21F21E		16.07	T/F7	F250-F550*
119	2001	119	1FTWW33851E		14.44	T/F7	F250-F550*
394	2001	394	1FTNX21L61E		38.81	T/F7	F250-F550*
101	2001	101	3FTNF21F71M		16.79	T/F7	F250-F550*
Town Car 25	2001	291	1LNHM81W81Y		107.1	CVC	Town Car C/M
334	2001	334	1LNHM81W21Y		44	CVC	Town Car C/M

63	2001	23	1LNHM83W81Y	130.01	CVC	Town Car	C/M
235	2001	235	1LNHM81WX1Y	83.88	CVC	Town Car	C/M
288	2001	288	1LNHM81W61Y	121.59	CVC	Town Car	C/M
90	2001	50	1LNHM83W21Y	97.52	CVC	Town Car	C/M
188	2001	148	1LNHM82W41Y	135.49	CVC	Town Car	C/M

308	2001	308	1LNHM81W41Y		133.22	CVC	Town Car C/M
319	2001	319	1LNHM81W31Y		122.18	CVC	Town Car C/M
249	2001	249	1LNHM81W91Y		26.38	CVC	Town Car C/M
43	2001	3	1LNHM85W51Y		25.1	CVC	Town Car C/M
300	2001	300	1LNHM81W51Y		14.85	CVC	Town Car C/M

57	2001	17	1LNHM83W01Y [REDACTED]	18.1	CVC	Town Car	C/M
333	2001	333	1LNHM81W21Y [REDACTED]	23.81	CVC	Town Car	C/M
101	2001	61	1LNHM83W01Y [REDACTED]	21.98	CVC	Town Car	C/M
294	2001	294	1LNHM81W61Y [REDACTED]	18.34	CVC	Town Car	C/M

182	2001	152	1LNHM82W41Y [REDACTED]	23.34	CVC	Town Car	C/M
308	2001	308	1LNHM81W41Y [REDACTED]	14.83	CVC	Town Car	C/M
273	2001	273	1LNHM81W71Y [REDACTED]	18.71	CVC	Town Car	C/M
155	2001	115	1LNHM82W71Y [REDACTED]	15.81	CVC	Town Car	C/M

167	2001	127	1LNHM82W61Y	17.17	CVC	Town Car	C/M
264	2001	264	1LNHM81W81Y	19.5	CVC	Town Car	C/M
337	2001	337	1LNHM81W21Y	15.83	CVC	Town Car	C/M
29	2001	210	1LNHM82W11Y	20.69	CVC	Town Car	C/M
238	2001	238	1LNHM81WX1Y	17.5	CVC	Town Car	C/M

40	2001	221	1LNHM82W01Y	14.66	CVC	Town Car	C/M
58	2001	18	1LNHM83W91Y	23.65	CVC	Town Car	C/M
274	2001	274	1LNHM81W71Y	15.48	CVC	Town Car	C/M
175	2001	135	1LNHM82W51Y	14.61	CVC	Town Car	C/M
181	2001	141	1LNHM82W51Y	16.71	CVC	Town Car	C/M

182	2001	122	1LNHM82W71Y [REDACTED]	17.51	CVC	Town Car	C/M
140	2001	100	1LNHM82W81Y [REDACTED]	12.83	CVC	Town Car	C/M
55	2001	15	1LNHM83WX1Y [REDACTED]	20.08	CVC	Town Car	C/M

316	2001	318	1LNHM81W41Y		17.82	CVC	Town Car	C/M
218	2001	178	1LNHM82W21Y		18	CVC	Town Car	C/M
329	2001	329	1LNHM81W31Y		20.27	CVC	Town Car	C/M
250	2001	250	1LNHM81W91Y		16.5	CVC	Town Car	C/M
250	2001	250	1LNHM82W01Y		20.06	CVC	Town Car	C/M
252	2001	252	1LNHM81W91Y		17.96	CVC	Town Car	C/M

280	2001	280	1LNHM81W71Y		18.69	CVC	Town Car	C/M
285	2001	285	1LNHM81W81Y		15.48	CVC	Town Car	C/M
292	2001	292	1LNHM81W81Y		100.8	CVC	Town Car	C/M
327	2001	327	1LNHM81W31Y		33.83	CVC	Town Car	C/M
83	2001	43	1LNHM83W41Y		17.45	CVC	Town Car	C/M
313	2001	313	1LNHM81W41Y		16.84	CVC	Town Car	C/M
287	2001	287	1LNHM81W71Y		23.34	CVC	Town Car	C/M

353	2001	353	1LNHM81W11Y [REDACTED]	22.04	CVC	Town Car	C/M
209	2001	189	1LNHM82W31Y [REDACTED]	23.24	CVC	Town Car	C/M
334	2001	334	1LNHM81W21Y [REDACTED]	44	CVC	Town Car	C/M
322	2001	322	2FAFP71W41X [REDACTED]	52.62	C/FB	CV/GM	C/F
287	2001	287	2FAFP71W81X [REDACTED]	48.05	C/FB	CV/GM	C/F

342	2001	342	2FAFP71W31X	19.58	C/FB	CV/GM	C/F
233	2001	233	2FAFP71W81X	19.72	C/FB	CV/GM	C/F

352	2001	352	2FAFP71W31X [REDACTED]	20.04	C/FB	CV/GM	C/F
77	2001	77	2FAFP74W31X [REDACTED]	19.54	C/FB	CV/GM	C/F
328	2001	328	2FAFP71W41X [REDACTED]	17.85	C/FB	CV/GM	C/F
72	2001	72	2FAFP74W31X [REDACTED]	15.12	C/FB	CV/GM	C/F