

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 2 OF 6
BOOKS 34 OF 43

S25	42	1-Nov-01	6	4893030	13678		7933
B64	33	5-Nov-01	5	5045541	6091		7858
T90	42	24-Jul-01	0	3288298	11		4570
S40	42	17-Jul-01	0	2818036	28		4820
S40	42	17-Jul-01	0	2997109	28		4820
S25	69	28-Sep-01	3	6201307	15		4932
S40	42	11-Sep-01	3	4453631	6282		4500
S40	42	26-Jul-01	0	2966830	8		4462
S25	42	13-Feb-02	9	7883734	27418		25
S40	43	28-Sep-01	6	4176782	11611		4332
B09	33	18-Oct-01	3	6717835	4424		8536
S40	42	26-Feb-02	2	7291376	2439		6374
H19	42	22-Jun-01	0	2283531	20		2405
S40	42	26-Jul-01	0	3024679	16		4462
S25	42	17-Apr-02	7	8238661	10502		20360
S40	7	24-Apr-02	6	8671848	7980		5613
S25	42	2-May-02	13	8590883	9458		4181
G29	28	26-Jun-01	6	2311817	9833		45282

S25	1	19-Oct-01	8	4573407	9905		149
S25	41	4-Sep-01	0	3536590	8		20554
S40	33	19-Jul-01	6	4964889	10089		45250
S40	42	25-Jan-02	12	6589349	21427		20303
S25	1	25-Jul-01	0	4661094	10		8888
S40	42	6-Nov-01	6	5652593	10791		45255
S25	42	29-Jan-02	9	6649370	13884		7725
S40	42	30-Aug-01	6	4227726	9897		45279
S40	41	20-Jul-01	0	4492425	6		7780
S25	42	14-Jan-02	-1	6819320	18		5179
G29	42	31-May-02	15	8910977	8272		2496
S40	41	26-Sep-01	6	3988165	4978		1711
S40	42	14-Aug-01	0	3525091	10		5538
S40	42	11-Mar-02	15	7336207	16566		1733
G29	46	18-Jan-02	3	6335940	1791		1231
S40	41	17-Apr-02	13	8065048	17733		1892
S40	42	2-Jan-02	11	6071990	28026		7870
S25	42	26-Feb-02	16	7116675	36815		7816
S26	42	8-May-02	12	8609207	11081		17

S40	41	8-Jan-02	9	6124467	10822	[REDACTED]	6509
S25	42	30-Jan-02	13	6692366	13836	[REDACTED]	7366
S26	41	4-Jun-02	12	9073648	22333	[REDACTED]	7742
S40	42	9-Nov-01	3	6284315	2236	[REDACTED]	6902
C19	12	30-Nov-01	1	5457677	954	[REDACTED]	2262
S25	33	3-Jul-01	8	2224239	25141	[REDACTED]	2588
S40	42	16-Nov-01	10	5234716	28595	[REDACTED]	12751
S25	42	19-Mar-02	9	7492802	14159	[REDACTED]	1402
S40	42	29-Oct-01	5	4821373	9576	[REDACTED]	3080
S25	42	25-Mar-02	1	7623651	424	[REDACTED]	1695
S25	41	27-Nov-01	6	5469529	6508	[REDACTED]	5539
S40	1	7-Feb-02	1	6897323	1137	[REDACTED]	6420
S40	42	7-Nov-01	9	5121937	31001	[REDACTED]	25

DLR_SUB_CD	REGION_CD	ST_PROV_CD	CPSC_CD_6	TECH_TXT1
*	NA	CO	11001	BUCKLE WOULD NOT LATCH INSTALLED NEW BUCKLE
*	NA	OH	11001	INSTALLED NEW PASS SIDE FRT SEATBELT LATCH ASSY S28 01
*	NA	FL	11001	VERIFY CONCERN, TEST AND REPLACE R F SEAT BELT BUCKLE, RETEST.
*	NA	FL	11001	FAULTY OPERATING MECHANISM REPLACE SEATBELT LATCH.
*	NA	CA	11001	BUCKLE WON T LATCH SOP SEATBELT INSTALLED
*	NA	SC	11001	REPLACE PASS SEAT BELT ASSY
*	NA	TX	12001	REPALCED RIGHT FRONT SEAT BELT BUCKLE
*	NA	TX	12001	INTERNAL BUCKLE FAILURE M.O.1271 REPLACED RIGHT FRONT SEAT BELT BUCKLE TEST WORKS PROPERLY
*	NA	CA	12001	01S21 RECALL INSPECTED AND REPLACED RT SIDE SEAT BELT BUCKLE AS PER RECALL 01S2
*	NA	SC	12001	WONT LOCK REPLACED PASS SEAT BELT BUCKLE
*	NA	VA	12001	61202 FOUND THAT SEAT BELT WAS BROKEMN INTERNALLY AND WOULD NOT LATCH. REMOVED SEAT AND REPLACED SEATBLET. REINSTALLED SEAT
*	NA	NY	12001	BUCKLE INOPERABLE REPLACED RIGHT FRONT OUTBOARD SEATBELT BUCKLE NO LTG FOUND
*	NA	TX	12001	REPLACED SEAT BELT BUCKLE.
*	NA	SK	11001	CHECK SEAT BELT OPERATION//REPLACE LEFT FRONT SEATBELT (42)
*	NA	NJ	12001	VERIFY CONCERN SEATBELT BUCKLE WONT LATCH NECC TO REPLACE VERIFY OK
*	NA	FL	11001	VERIFY BUCKLE INOP, INSPECT FIND RECEPTABLE BROKE.R AND I DRIVERS SEAT BUCKLE AND VERIFY REPAIR
*	NA	MI	11001	1 VERIFIED LT FRT SEAT BELT WONT LATCH,NEC TO REPLACE LT FRT TULIP ASSEMBLY.CC 89
*	NA	CA	11001	. VERIFIED CONCERN SEAT BELT WILL NOT BUCKLE REPLACED DRIVERS SEAT BELT/ BUCKLE

*	NA	FL	11001	R AN DI LF SEAT REPLACED SEAT BUCKLE
*	NA	FL	11001	BROKEN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	TX	11001	VERIFY CONCERN REPLACED BINDING SEAT BELT BUCKLE RETEST OK
*	NA	FL	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	11001	VERIFIED CONCERN; LOCKING PLATE JAMMED, REMOVE & REPLACE DRIVERS SIDSEAT BELT BUCKLE ASSEMBLY. BUCKETS W O SIR
*	NA	TX	11001	3554 VERIFIED CONCERN,ACCESS DRIVERS SEAT AND REPLAC D SEAT BELT BUCKLE.
*	NA	SC	11001	61203 SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NJ	11001	R&R SEAT BELT BUCKLE L S FRONT SEAT,
*	NA	TX	11001	MO.1299 CC42 VERIFIED CUSTOMERS CONCERN. REPLACED DRIVER SEAT BELT BUCKLE.
*	NA	CA	11001	DRIVERS SEAT BELT WONT LATCH REPLACE SEATBELT
*	NA	AZ	11001	REPLACED LH SEAT BELT BUCKLE USED MTIME TO REMOVE CROSS THREADED NUT
*	NA	CA	11001	R&R DRIVESIDE SEATBELT
*	NA	TN	11001	SEATBELT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TN	11001	REPLACE LEFT SEATBELT BUCKLE
*	NA	NM	11001	REPLACED PASS. FRONT SEATBELT BUCKLE
*	NA	MO	12001	PART ON ORDER 04 25 02 REPLACE LEFT FRONT SEAT BELT BUCKLE .
*	NA	NV	11001	DOES NOT OPERATE PROPERLY INSPECT R&R PASS FRONT SEAT BELT RECEPTACLE
*	NA	TX	12001	FOUND RIGHT SIDE FRONT SEAT BELT WOULD NOT STAY BUCKLED R R RETEST OK
*	NA	FL	12001	REPLACED PASSENGER SIDE SEAT BELT BUCKLE.

*	NA	FL	12001	7861202 CC 42 3479 M O VERIFIED CUSTOMER CONCERN. REMOVED PASS SEAT, R I NEW SEATBELT BUCKLE. INSTALLED PASS SEAT. RETEST PASS.
*	NA	TX	12001	RT FRT BELT WILL NOT STAY FASTENED. 1 INSTALLED NEW PASS SIDE SEAT BELT BUCKLE
*	NA	NY	11001	1 REPLACED DRIVERS SEAT BELT BUCKLE
*	NA	TX	11001	SEAT BELT BUCKLE WILL NOT STAY CLASPED . VERIFIED CONCERN. INSPECTED SEAT BELT AND FOUND
*	NA	CA	11001	BUCKLE NOT HOLDING. REPLACED BUCKLE ASSY AND RETESTED. OK AT THIS TIME.
*	NA	NC	11001	3848 DRIVER SIDE SEAT BELT BUCKLE WOULD NOT LATCH. REPLACED DRIVER SIDE SEAT BELT BUCKLE.
*	NA	TX	11001	VERIFIED CONCERN. PERFORMED SAFETY BELT INSPECTION NECC. TO REPLACE DRIVERS BELT BUCKLES. TO CORRECT
*	NA	CA	11001	3887 R&R DRIVERS SEAT & REPLACE SEAT BELT BUCKLE ASSEM.
*	NA	TX	11001	PERFORMED SEAT BELT TEST DRIVER BELT FAILED R&R SEAT AND R&R SEAT BELT RETEST OK
*	NA	AZ	11001	3801 VERIFIED DRIVERS SEAT BELT LATCH FAILURE, REMOVED AND REPLACED SEAT BELT RECEIVER AND RETESTED,ALL FUNCTIONS NORMAL(BUCKETS)
*	NA	GA	11001	BUCKLE R&I SEAT BELT ASSY REPLACED BELT BUCKLE
*	NA	NC	11001	VERIFIED CONCERN AND REPLACED DRIVER FRONT SEAT BELT BUCKLE
*	NA	FL	12001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	12001	CK OUT REPLACED FT PASS SIDE SEAT BELT LATCH END
*	NA	CA	12001	REPLACE RIGHT SEAT BELT BUCKLEINTERMITANTLY WOULD UNLATCH NO LABOR OPS FOR SEAT BELT BUCKLES USED TIME FOR EXCISTING

*	NA	TX	12001	13500 RIGHT FRT SEAT BELT RECEIVER DOES NOT HOLD INSPECT FOUND CAN WIGGLE SEAT BELT AND WILL COME UNLATCHED. REPLACE SEAT BELT RECEIVER OK AFTER REPAIR. CC 42
*	NA	CA	12001	INSPECTED AND REMOVED RIGHT SEAT TO REPLACE SEAT BELT BUCKEL AND RETESTED OK
*	NA	AZ	12001	REPLACE RIGHT FRONT SEAT BELT BUCKLE
*	NA	TX	12001	REMOVED SEAT FOR ACCESS AND REPLACED RIGHT FRONT SEAT DELT
*	NA	CA	12001	PASS SIDE SEAT BELT INOP CHECK ALL BELT OPERATIONS, PASS BUCKLE INOP. REPLACED BELT BUCKLE
*	NA	FL	11001	REPLACE LEFT SEATBELT BUCKLE
*	NA	AL	11001	2044 42 CHECKED OPERATION OF LEFT FRONT SEATBELT BUCKLE, WILL NOT LATCH. REMOVED SEAT TO ACCESS. REPLACED SEATBELT BUCKLE, ASSEMBLED. RECHECKED, PASSED.
*	NA	AZ	11001	REPLACE DRIVER SEAT BELT BUCKLE
*	NA	CA	11001	DRIVER SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AZ	11001	LF SEAT BELT COMES ONLATCHED TEST REPLACED BELT ASS
*	NA	NY	11001	REPLACED DRIVERS SIDE SEATBELT
*	NA	HI	11001	724 PULLED B.O. PART.(LEFT FRONT SEAT BELT BUCKEL FRONT SEAT BELT BUCKLE. TESTED OPERATION, OKAY.
*	NA	AZ	11001	REPLACED SEATBELT.
*	NA	AR	11001	LATCH INOP AT TIMES, NOT HOLDING. REPLACED SEAT BELT LATCH.
*	NA	AZ	11001	REPLACED DEFECTIVE LEFT FRONT SEATBELT BUCKLE THAT WOULD S OM ETIMES UNLATCH ON ITS OWN
*	NA	GA	11001	700 DRIVER INBOARD SEAT BELT BUCKLE RECEIVER WONT STAY LATCHED AT TIMES. FAILED TEST. INSTALLED NEW BUCKLE. TECH 4 COND CODE X2 BASIC 7861203

*	NA	TX	11001	BINDING TEST AND REPLACE BOTH LEFT AND RIGHT SEATBELT BUCKLE ASSY
*	NA	CA	11001	REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. 03 29 08.02 08.31.
*	NA	TX	11001	LEFT SEATBELT WILL NOT STAY BUCKLED REPLACE BUCKLE END TO RESOLVE CONCERN
*	NA	VA	11001	3161 DRIVERS BUCKLE NOT HOLDING FOUND DRIVERS BUCKLE NOT HOLDING BELT. REMOVED AND REPLACED SEAT BUCKLE (FEMALE END) CHECKS OK
*	NA	TX	11001	SEAT BELT INOP REPLACED SEAT BELT
*	NA	CA	11001	SEATBELT POPS OUT REPL LH BUCKLE , NOT LATCHING
*	NA	CA	11001	BELT INOP M TIME TO TEST BUCKLE OPE REPLACE BUCKLE
*	NA	TX	11001	REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE ASSEMBLY
*	NA	TX	11001	REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	FL	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	11001	INSPECTED AND REPLACED TWO SEATBELT BUCKLES
*	NA	CA	12001	REMOVED SEAT AND REPLACED THE SEATBELT FOR THE PASSENGER FRONT SEAT
*	NA	CA	12001	SEAT BELT REPLACED SEAT BELT BUCKLE
*	NA	TX	12001	RR RIGHT FRONT SEAT RR SEAT BELT BUCKLE
*	NA	SC	12001	REMOVED FRONT SEAT REPLACED SEATBELT LATCH ON PASS SIDE
*	NA	TX	12001	5508 REPLACED PASSENGER SEAT BELT RECEIVER AS PER MANAGMENT. CC33? TECH 307

*	NA	GA	12001	SEAT BELT INOP BUCKLE	REPLACED PASSENGER SEAT BELT
*	NA	FL	12001	REP BELT BUCKLE RATTLING	
*	NA	CA	12001	.	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	GA	12001	SEAT BELT INOP	REPLACED PASSENGER SIDE SEAT BELT
*	NA	AR	12001	REPLACED SEAT BELT BUCKLE, NOISEY	
*	NA	OH	12001	REPLACE SEAT BELT RT FRONT	
*	NA	CA	12001	1 VERIFIED CONCERN. R AND R SEAT TO GAIN ACCESS. REPLACED BUCKLE. VERIFIED REPAIRS	
*	NA	IL	11001	RR DRIVERS SIDE BUCKET ASSY PROBLEM WPI	
*	NA	IL	11001	ENTERED AT WPI	
*	NA	IL	11001	REPLACED THE BUCKLE	
*	NA	MI	11001	REPLACED DRIVER SIDE SEAT BELT	
*	NA	FL	11001	R AND R LF SEAT AND REPLACED SEAT BUCKLE	
*	NA	CA	11001	INSTALL MISSING DRIVERS SEAT BELT BUCKLE. Q. C. B. M.	
*	NA	CA	11001	REPLACED SEAT BELT BUCKEL	
*	NA	GA	11001	RATTLE IN LEFT SEAT BELT	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	CA	11001	REPAIR DRIVER SEAT BELT TO LATCH	
*	NA	GA	11001	REPLACE ONE SEAT BELT BUCKLE CKLE	
*	NA	KY	11001	INSTALLED SOP FOR AIR BAG LIGHT 16 W TECH 599, VERIFIED CONCERN, R I DR SEAT TO GAIN ACCESS TO RR BAD SEAT BELT BUCKLE, RETEST, SEAT BELT LATCHS AND UNLATCHES AT THIS TIME QUALITY INSPECTED BY #599,16	
*	NA	FL	11001		
*	NA	CA	11001	SEAT BELT JAMMED	REPLACED DRIVERS SEAT BELT
*	NA	OH	11001	10180 CC B4 WARRANTY REPLACED DRIVER SIDE SEAT BELT BUCKLE AND SEATBELT WARNING PIGTAIL	

NA	TX	11001	1902 DRIVERS SIDE SEAT BELT BUCKLE SHORTED TO GROUND VERIFIED CONCERN. PERFORMED B C E SELF TEST. RECEIVED DRIVERS SIDE SEAT BELT BUCKLE CONCERN DTC. PERFORMED B C E PINPOINT TEST, FOUND DRIVE RS
NA	FL	11001	COMING APART SEAT BELT ASSEMBLY REAR
NA	NC	11001	RIGHT OR LEFT REPLACE
NA	AL	11001	REPLACED LEFT FRONT SEAT BELT ASSY
NA	GA	11001	REPLACED BUCKLE ASSEMBLY
NA	AL	11001	SEAT BELTS WILL NOT RETRACT
NA	CA	11001	5071 REPLCE SEAT BELT BELT WAS BROKEN CODE 01 PART NO 1L7Z 7881203 BAB CK LFT FT SEAT BELT OPER, FOUND FAULTY LFT FT SEAT BELT BUCKLE, REPLACED, RETEST, OK. NO OP CODE MT 61203 .7
NA	TN	11001	INSTALLED SEATBELT REPLACED SEATBELT
NA	TX	11001	2382 ELECTRICAL DIAG PIN POINT TEST RESTRAINT SYSTEM, FOUND DRIVERS SEAT BELT BUCKLE TO HAVE AN OPEN. R+R DRIVERS SEAT + REPALCE SEAT BELT BUCKLE. *** QUALITY CONTROL BY JOHN MEDROW ***
NA	CA	11001	REMOVED & REPLACED LEFT FRONT SEAT BELT BUCKLE.
NA	PA	11001	REPLACE DRIVER SEAT BELT
NA	WA	11001	2077 WARR TESTED DR SEAT BELT BUCKLE ROAD TESTED 10 MILES LAMP WONT COME ON INSPECTED WIRE HARNESS AND NGS TESTED GEM NO CODES WORKS PROPERLY AT THIS TIME POSS INTERMITTLY SHORTING IN BUCKLE ORDER

NA	VA	11001	INSTALL SOP SEAT BUCKLE LEFT FRT SEAT WARR 42
NA	TX	11001	REPLACE DRIVERS SEAT BELT BUCKLE.
NA	FL	11001	FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT
NA	CA	11001	REPLACE SEAT BELT LIGHT COMES ON SEATBELT ASSEMBLY
NA	FL	11001	FRONT REPLACE
NA	CA	11001	1 INSPECT SEATBELTS REMOVE AND REPLACE RIGHT REAR SEATBELT
NA	CA	11001	CUST STATE THAT FRONT PASSENGER SIDE SEAT BELT BUCKLE IS INOP PART IS HERE..CAUSE: SEAT BELT BUCKLE..CORRE: REPALCED DEFECTED SEAT BELT BUCKLE ..APROX TIME: 0.4 HRS JOB STARTED 12.012.3 ON 02 28 02
NA	FL	11001	BROKEN LATCH. R & R PASSENGER FRONT SEATBELT LATCH.
NA	CA	11001	REPLACED CENTER BUCKLE.MISMATCHED.
NA	FL	12001	REPLACE BOTH FRONT SEATBELT BUCKLES
NA	CA	11001	REPLACE BOTH FRONT SEAT BELT BUCKLES FOUND STICKING.
NA	OK	12001	INSTALLED REVISED SEAT BELT BUCKLES
NA	AZ	12001	1 REPLACE SEAT BELT BUCKLES
NA	IL	12001	1 INSTALL SOP SEAT BELT ENDS IN NEW CAR
NA	ON	11001	DIAG & REPLACE RIGHT FRT SEAT BUCKLE
NA	NM	11001	SEAT BELT BUCKLE VISIBLY BROKEN INTERNALLY. R&R SEAT BELT BUCKLE. 81172A 0.4
NA	GA	11001	CK OUT INSP.TEST REPLACE FAULTY BELT
NA	CA	11001	FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT HOLD.REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE
NA	CA	12001	WF 0821D PERFORMED SEAT BELT RECALL RIGHT FRONT SEAT.

*	NA	CA	11001	RIGHT SEATBELT WONT LATCH SEATBELT BUCKLE	REPLACED RIGHT SEATBELT BUCKLE
*	NA	CA	11001	RIGHT SEATBELT WONT BUCKLE SEATBELT BUCKLE	REPLACED RIGHT SEATBELT BUCKLE
*	NA	LA	11001	INOP	SEATBELT ASSEMBLY FRONT REPLACE
*	NA	MI	11001	CC 42 A85 7861203	REMOVED DRIVERS SIDE SEAT AND REMOVED BUCKLE AND INSTALLED NEW AND RETESTED OK
*	NA	TX	11001	BINDING BUCKLE	REPLACED LEFT SIDE SEAT BELT BUCKLE
*	NA	TX	12001		REPLACE RT HAND SEATBELT.
*	NA	TX	11001	CKED OUT AND REPLACE SEAT BELT BUCKLE	INOP WILL NOT LATCH
*	NA	TX	11001		REPLACED SEAT BELT BUCKLE
*	NA	FL	11001	20506 INOP W 42 REMOVE DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE ASY. INOP	
*	NA	CA	11001	CCG28 CHECKED OUT	REPLACED DRIVERS SEAT BELT BUCKLE.
*	NA	TX	11001	CC,01 BROKEN BASIC#61203	REPLACE L F SEAT BELT
*	NA	CA	11001		REPLACE SEATBELTS WILL NOT LATCH
*	NA	TX	11001	6997 SEAT BELT LATCH INOP 81172A .4	REPLACED SEAT BELT LATCH
*	NA	VA	12001	PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED PASSENGER FRONT SEAT TO ACCESS SEATBELT BUCKLE, REPLACED SEATBELT BUCKLE, NO LABOR OPS, USE M TIME	
*	NA	FL	11001	11 SEAT BELT NOT LATCHING .4 DR SEAT BELT BUCKLE NOT LATCHING. ORDERED NEW BUCKLE.INSTALLED PROBLEM FIXED	
*	NA	GA	12001	SEAT BELT BUCKLE INOP	R&R PASS FRONT SEAT TO REPLACE SEAT BELT BUCKLE

*	NA	CA	11001	LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH. REPLACED SEAT BELT BUCKLE NOW OKAY. 04 03 08.21 08.49.
*	NA	NC	11001	REPLACED BUCKLE
*	NA	TX	12001	REPLACE RIGHT SEAT BELT.
*	NA	TX	11001	FAULTY SEATBELT (81203) DIAGNOSIS AND REPLACED LF SET BELT BUCKLE
*	NA	AZ	11001	R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT LATCH.
*	NA	CA	11001	RIGHT FRONT SEAT BELT BUCKLE INOPSEATBELT ASSEMBLY FRONT REPLACE
*	NA	SC	11001	CK AND REPLACED LEFT FRT SEAT BELT BUCKLE ASSY.
*	NA	CA	11001	INSPECT PASS SIDE SEAT BELT REPLACE DEFECTIVE SEAT BELT
*	NA	TX	12001	4826 FAULTY RT SIDE BUCKLE NEC TO REPLACE RT SIDE BUCKLE
*	NA	FL	11001	REPLACED SEAT BELT 01S21 RECALL
*	NA	TX	12001	7450 42 INOPERATIVE VERIFY RT SEATBELT NOT FASTENING REPLACE RT SEATBELT BUCKLE
*	NA	MS	11001	12182 W CHECKED DRIVERS SEAT BEALT OPERATION TO FIND FAULTY SEAT BELT BUCKLE ASY R&R BUCKLE ASY TO FIX CONCERN RETEST.
*	NA	TN	11001	REPLACED LEFT FRONT SEATBELT
*	NA	WA	12001	FAULTY RECEIVER INSPECT AND REPLACE RECIEVER.
*	NA	TX	12001	REPLACE RT HAND SEAT BELT.
*	NA	TX	12001	REPLACE RT HAND SEAT BELT.
*	NA	IL	11001	9687 DEFECTIVE SEAT BELT BUCKLE DRIVERS SEATBELT BUCKLE INTERMITTENTLY INOP. REMOVED AND REPLACED SEATBELT BUCKLE.

*	NA	TX	12001	REPLACE RT HAND SEAT BELT.
*	NA	MS	11001	INOPERATIVE REPLACE LEFT SEAT BELT BUCKLE
*	NA	NV	11001	BUCKLE SEATBELT ASSEMBLY FRONT
*	NA	TX	11001	REPLACE INSTALLED NEW SEATBELT BUCKLES
*	NA	VA	11001	5735 SOMETHING STICKY IN LATCH WARR REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	GA	11001	DRIVERS SIDE SEAT BELT BUCKLE WILL NOT LOCK. REMOVED AND REPLACED. RECHECKED OPERATION. OK. USED MTIME DUE TO NO LABOR OPERATION BEING FOUND.
*	NA	MS	12001	9088 61202 42 W R&I PASS SIDE SEAT AND REMOVED OLD SEAT BELT BUCKEL AND INSTALLED NEW ONE Y
*	NA	CA	11001	DRIVERS SEAT BUCKLE STUCK REMOVE AND REPLACED BUCKLE
*	NA	FL	11001	REPLACR DRIVERS SEAT BELT BUCKLE
*	NA	OK	12001	6 TESTED SEAT BELTS AND INSTALLED BOTH LEFT AND RIGHT SIDE SEAT BELT LATCHES R.L.B
*	NA	FL	11001	REPLACE LEFT SEAT BELT BUCKLE NO TIME LISTED
*	NA	ON	11001	REPLACE LF SEAT BELT BUCKLE 61172A (.4 HRS) LF SEAT BELT BUCKLE NOTHOLDING 61203 42
*	NA	FL	11001	BINDING TRACK ASSEMBLY FRONT SEAT REPLACE
*	NA	TX	12001	1 REPL BOTH FRONT SEAT BELT BUCKLES
*	NA	IL	11001	REPL DRIVERS SEAT BELT BUCKLE WPI ADD ON AUTHO BY AS
*	NA	CA	11001	NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	OH	12001	BUCKLE COMES LOOSE, REPLACE
*	NA	OK	12001	60 REPLACED PASSENGER FRONT SEATBELT THAT WAS BROK EN VERIFIED REPAIR CM

*	NA	CA	12001	BUCKLE FAILED REPLACED SEAT BELT
*	NA	LA	12001	372 RECALL 82 TESTED AND REPLACED BOTH FRONT SEATBELTS
*	NA	NV	11001	BUCKLE SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	11001	VOLUNTARY FACTORY SAFETY RECALL. INSPECT AND REPLACE ONE SEAT BELT BUCKLE RIGHT
*	NA	CA	11001	RECALL 01S21 01S21 REPLACED PASS. SEAT BELT
*	NA	CA	11001	01S21 E BOTH BELT BUCKLES FAILED RPL BOTH BELT BUCKLES
*	NA	CA	11001	01S21 D DRIVER SIDE FAILED RPL DRIVER SIDE BUCKLE
*	NA	CA	11001	01S21 D DRIVER SIDE FAILED RPL DRIVER SIDE BELT BUCKLE
*	NA	CA	12001	01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE
*	NA	CA	12001	PERFORM RECALL 01S21D REPLACE PASSENGER SEAT BELT BUCKLE
*	NA	CA	12001	01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE
*	NA	TX	11001	36 01S21D 0.8 INSP AND REPL L FRONT SEAT BELT
*	NA	CA	12001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	TX	11001	10 RECALL 01S21D 0.8 PERFORM RECALL, INSPECT SEAT BELT BUCKLES AND REPLACE LEFT BUCKLE.
*	NA	TX	11001	30 01S21D 0.8 INSP AND REPL SEAT BELT
*	NA	TX	11001	31 INSTALL SEAT BELT LEFT SIDE 01S21D 0.8 INSTALL SEAT BELT
*	NA	FL	12001	1 INSPECT AND REPLACE R FRT SEAT BELT BUCKLE
*	NA	LA	12001	14 INSPECTED SEAT BELTS, FAULTY PREFORMED RECALL, REPLACED SEAT BELT
*	NA	NV	11001	RECALL 01S21
*	NA	CA	12001	RECALL PERFORMED RECALL. REPLACED SEAT BELT BUCKLE AT RIGHT FRONT

*	NA	TN	11001	M TIME IS LBR TO REPLACE SEAT BELT BUCKLE ON DRIVERS SIDE PER 01S21. NOTE VEHICLE NOT LISTED IN OASIS AS INVOLVED IN 01S21 RECALL, BUT OPTED TO GO AHEAD AND REPLACE BUCKLE SINCE SAFETY ISSUE ON A NEW
*	NA	CA	12001	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL.
*	NA	CA	12001	REPLACED RIGHT SIDE BUCKLE PER RECALL
*	NA	NY	11001	REPLACE BOTH BELT BUCKELS BINDING
*	NA	KS	11001	VERIFY CUSTOMER CONCERN SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NM	11001	SEAT BELT IS BINDING DUE TO TWISTING REPAIR UNBIND LEFT FRONT SEAT BELT REEL
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE ASSY
*	NA	CA	11001	INSPECT.REPLACED R BUCKLE.L BUCKLE OK.
*	NA	TX	11001	REPLACE BOTRH FRONT SEAT BELT BUCKLES
*	NA	TX	11001	SEAT BELTS INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	SEAT BELT BUCKLE PASSENGER SIDE INOPERATIVE REPLACE PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE
*	NA	TX	11001	SEAT BELT BCKLE WRONG WAY. 07 61203 VERIFY CUSTOMERS CONCERN SEAT BELT BUCKLE TURN THE WRONG WAY,STRAIGHTEN OUT SEAT BELT BUCKLE.
*	NA	FL	11001	REPLACE SEAT BELT BUCKLE
*	NA	FL	11001	INOP REPLACED BOTH FRONT SEAT BELT BUCKLES
*	NA	CA	11001	CUST STATE THE DRIVER SIDE SEAT BELT BUCKLE IS INOP CAUSE: SEAT BELT CORE: REPLACE SEAT BELT BUCKLE
*	NA	NC	11001	UNTWISTED SEATBELT AND REPLACED BUCKLE
*	NA	TX	11001	GM REPLACE 2 BELTS

*	NA	CA	12001	BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	CA	12001	REPLACE SEATBELTS WILL NOT LATCH PROPERLY
*	NA	TX	12001	5667 LOOSE REPLACE LOOSE RF SEAT BELT BUCKEL *****QUALITY CONTROL BY JAMES PENNOCK*****
*	NA	CA	11001	SEAT BELT BUCKLE INOP LIGHT ON BODY CHASSIS ELECTRIAL (BCE) TEST REPLACED SEAT BELT BUCKL
*	NA	NC	11001	SEAT BELT ASSEMBLY REPLACED DRIVERS SEAT BELT
*	NA	CA	11001	CCF12 REPLACE SEATBELT BUCKLES
*	NA	SC	11001	REPLACED LEFT AND RIGHT SEATBELTS.
*	NA	CA	12001	SEAT BELTS WONT LATCH REPLACE BUCKLES
*	NA	VA	12001	REPLACE BROKEN SEAT BELT
*	NA	FL	12001	REPLACED SEAT BELT
*	NA	GA	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AZ	11001	1 REPLACE BELT BUCKLE
*	NA	NC	12001	REPLACE SEAT BELT
*	NA	CA	11001	PERFORMED RECALL: REPLACED AND RETEST LEFT HAND SEATBELT
*	NA	GA	11001	LFT FRT SEAT BELT BINDS SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	12001	RECALL REPLACE RT FT BUCKLE
*	NA	TX	12001	REPLACE RT SIDE BELT. 1216 7861203 28 WTY RAN BODY CHASSIS ELECTRICAL TEST AND PINPOINT TEST AND DIAGNOSE AND REPLACED
*	NA	LA	11001	DRIVERS SEAT END RELEASE SEAT BELT BUCKLE ASSY,FOUND THAT IT HAD INTERMITTENT INOP SWITCH INTERNALL
*	NA	FL	11001	SEAT BELT WONT HOLD REPLACED DRIVERS SEAT BELT

*	NA	FL	12001	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE
*	NA	TX	11001	SEATBELT MAKES NOISE SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	12001	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE
*	NA	CA	12001	CC140 REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSY
*	NA	FL	12001	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE
*	NA	FL	11001	REPLACE BUCKLE
*	NA	TN	11001	REPLACED SEAT BELT
*	NA	LA	12001	REPLACE SEAT BELT
*	NA	NH	12001	CONFIRMED CUSTOMER CONCERN, REPLACED SEATBELT ASSEMBLY
*	NA	GA	12001	NEC TO REPLACE SEAT BELT
*	NA	VA	11001	4170 R R PASSENGER FRONT SEAT R R FEMALE SEAT BELT B UCKLE REPLACED & REINSTALLED SEAT
*	NA	MA	12001	REMOVED SEAT AND REPLACED SEAT BELT LATCH
*	NA	CA	11001	REPLACED BUCKLE ASSY WIRES WERE PINCHED CUTTING INTO SEAT TRACK
*	NA	AZ	11001	1 REPLACED SEAT BELT BUCKLE PER RECALL
*	NA	NC	12001	REPLACED RIGHT SIDE SEAT BELT
*	NA	NJ	11001	CHECK AND REPLACE SEAT BELT LEFT SIDE SEAT BELT BUCKLE
*	NA	IL	11001	REPLACED LEFT FRONT SEAT BELT
*	NA	NY	11001	REPLACED DRIVERS SIDE SEAT BELT
*	NA	CA	11001	CC487 PERFORMED RECALL 01S21D
*	NA	IA	12001	REPLACE SEAT BLET BUCKLE, PASSENGER SIDE.
*	NA	TX	11001	REPLACED THE BUCKLE
*	NA	CA	11001	DIAG INSP VERIFIED CONCERN AND REPLACED BOTH SEAT BELT BUCKLES

*	NA	NM	11001	REPLACED SEAT BELT
*	NA	CA	11001	REPLACE SEATBELT WILL NOT LATCH PROPERLY
*	NA	CA	12001	CCQ09/121 REPLACE RT SIDE SEAT BELT BUCKLE
*	NA	MB	11001	R&R THE LEFT FRONT SEAT BELT BUCKLE.
*	NA	ON	11001	DIAGNOSE AND REPLACE L/F SEAT BELT
*	NA	CA	11001	PASS FRT SEAT BELT WONT LATCH REPL BUCKLE AND TEST
*	NA	AZ	11001	REPLACED THE BUCKLE
*	NA	IA	11001	INSPECT. RELEASE BUTTON IS STUCK. REPLACE BUCKLE
*	NA	NY	11001	FOUND SEAT BELT DIF RR BUCKLE SEAT BELT
*	NA	MO	11001	INTERNLA FALT IN BUCKLE INSTALLED NEW BUCKEL ASSY
*	NA	AL	11001	REPLACED SEAT BELT BUCKLE
*	NA	AZ	11001	REPLACED THE BUCKLE
*	NA	NY	11001	PER SEAT BELT BUCKLE NOT LATCHING.
*	NA	OH	11001	REPLACE BELT WONT LATCH
*	NA	IA	11001	L RIGHT FRONT SEAT BELT BUCKLE
*	NA	MO	11001	DIAG. CODE B2434.B2292.B2295. DIAG. AIR BAG SYSTEM. REPLACED LEFT SEATBELT. RETEST.
*	NA	PA	11001	TECH 147 VERIFY CONCERN PERFORM AIR BAG DIAG REPLACE SEAT BELT RECHECK OK
*	NA	ON	11001	DUPLICATE FAULT,NGS,RETRIEVE DTC,RETEST,RE/RE OBSTRUCTIONS,PIN TEST, RE/REPLACE RF SEAT BELT BUCKLE ASSY OPEN CIRUCIT.
*	NA	PQ	11001	TEST PIN POINT TEST SHORT TO GROUND REPLACE BUCKLE
*	NA	PQ	11001	6886 VERIFIER BOUCLE DE CEINTURE AVANT GAUCHE NE CLENCHE PAS RAPPORT PRENDRE BOUCLE SUR AUTRE AUTO VEUVE ET REMPLACER VERIFIER OK
*	NA	ON	11001	DIAF FOR AIR BAG LIGHT ON, CODE B2432, MT81203 .8 HR TO TRACE OPEN CIRCUIT, DRIVERS SIDE BUCKLE SWITCH OPEN, REPLACED DRIVERS SEATBELT BUCKLE

*	NA	NY	11001	5241 PERFORMED AIR BAG DIAG RETRIEVED CODE B2432
*	NA	MI	11001	PERFORMED DCL MONITOR TEST PERFORMED PINPOINT TEST ACCESS CARPET R&R SEAT TRACED WIRING FROM RCM TO SEAT BUCKLE NO PROBLEM FOUND R&R SEAT BE LT BUC
*	NA	ND	11001	HOOKE UP NGS AND FOUND CODE B2436 WENT THROUGH PINPOINT TEST DEACTVATED AIR BAG LITE SYSTEM AND STARTING TO CK CONNECTIONS UNDER PASSENGER SEAT FOUND SEAT BELT BUCKLE CONNECTOR TO BE BROKEN NEEDS NE
*	NA	MI	11001	INSTALLED SEAT BELT BUCKLE
*	NA	NC	11001	R AND R DRIVERS SEAT BELT ASSEMBLY
*	NA	CA	11001	SEATBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT
*	NA	NY	11001	REPLACED SEAT BELT
*	NA	RI	11001	5275 .5 REPLACED BOTTOM BUCKLE
*	NA	FL	11001	14279 164...CK AIR BAG SYSTEM.PERFORM AIRBAG DIAGNOSTICS.PERFORM PIN POINT TESTS FOR CODE B2492.REPLACE DRIVER SEAT BUCKLE AND REPAIR PINCHED AND CUT WIRES UNDER DRIVER SEAT. HARNESS MADE CONTACT
*	NA	IL	11001	AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	HI	11001	R R RF SEAT BELT BUCKLE ASSY
*	NA	CO	11001	PERFORM DIAG FOR SEAT BELT LIGHT COMING ON UNWARRANTED WITH NGS MONITORED PIDS. REPLACED INOP SEAT BELT. 1
*	NA	OH	11001	REPLACED DRIVERS SEATBELT BUCKLE
*	NA	FL	11001	REPALCED SEAT BUCKLE
*	NA	NC	11001	AIR BAG DIAGNOSIS, CODE 1233, REMOVED AIR BAG MODULE, AND DRIVERS SEAT ASSEMBLY TO PIN POINT TEST DRIVERS SEAT
*	NA	NC	11001	OPEN CKT. CLEAR CODE
*	NA	CA	11001	OPEN CIRCUIT IN LF SEATBELT BUCK BODY CHASSIS ELECTRIAL (BCE) TEST

*	NA	OH	11001	REPLACED LT FRORNT SEAT BELT
*	NA	HI	11001	R AND R BUCKLE WITH NEW
*	NA	WI	11001	TEST AIR BAG SYSTEM, PINPOINT AND FOUND PASS SIDE SEAT BELT REQUIRES REPLACEMENT. ORDER PART, REPLACE AS NEC.
*	NA	AZ	11001	REPLACED THE SEAT BELT BUCKLE
*	NA	HI	11001	REMOVED LF SEAT BELT TO TAKE CARE OF CUST GUERRERO VIN # 1BB18750 RO # 258829 INSTALLED NEW SEAT BELT BUCKLE TEST OPERATION , O.K.
*	NA	OH	11001	5106 ECC TEST NO LITE CODE B2292 PINPOINT REPLACE LEFT SIDE BELT PRETENSIONER
*	NA	WI	11001	TESTED TO FIND CODE B2358. REPLACED RIGHT SIDE FRONT SEATBELT ASSY. TESTED.OKAY
*	NA	MD	11001	NGS AIR BAG TESTS CODE B2292,PINPOINT TESTS,REPLACED PASS BUCKLE AND PRETENTIONER
*	NA	MD	11001	NGS AIR BAG DIAG.CODE B2292,TEST PASS PRETENTIONER CIRCUITS, REPLACED PASS.BUCKLE AND PRETENTIONER,RETEST
*	NA	NJ	11001	SEAT BELT PERFORMED AIR BAG DIAGNOSTICS CODE B2292 PERFORMED PINPOINT TEST TRACED TO AND REPLACED PASSENGER SEAT BELT RETRACTOR
*	NA	AB	11001	AIRBAG DIAG.MONITOR PIDS.REPLACED RIGHT FRONT SEAT BELT BUCKLE HIGH RESISTANCE.TIGHTENED TERMINALS IN CONNECTOR.RETEST
*	NA	PA	11001	EEC TEST,MONITOR PIDS,PINPOINT TEST,REPLACE L S SEAT BELT BUCKLE.CLEAR CODE AND RERUN SELF TEST
*	NA	AB	11001	13832 1H VERIFY. NEEDS LATCH ASSEM. REMOVE FROM NEW VEHICLE AND INSTALL ON UNIT. ORDER NEW ONE FOR UNIT THAT PARTS WAS ROBBED FROM. INSTALL NEW SEAT BELT LATCH ON NEW UNIT THAT PART WAS ROBBED FRO
*	NA	ON	11001	INSPECT AND REPLACE RIGHT FRONT SEAT BELT BUCKLE.
*	NA	NJ	11001	REPLACE SEAT BELT ASSY RF WONT LATCH
*	NA	CO	11001	REPLACE BOTH SEAT BELT FOR INTER. OPER.

NA	HI	11001	8854 REMOVE AND REPLACE LT FRT BUCKLE,QUALITY CHECK OK
NA	AR	11001	REPLACE SEAT BELT BUCKLE ASSEMBLY
NA	NY	11001	VERIFIED CONCERN FOUND BUCKLE PART NO GOOD JAMMED DRIVERS SEAT REPLACE SEAT BELT RETESTED OPERATION ALL OK
NA	NJ	11001	REPLACE LEFT FRONT SEAT BELT BUCKLE
NA	IL	11001	INOPERATIVE SEATBELT ASSEMBLY FRONT
NA	NV	11001	REPLACE BUCKLE
NA	TX	11001	REPLACED SEATBELT BUCKLE CC42 DOES NOT OPERATE PROPERLY MILES IN 9328 MILES OUT 9330 TESTED DRIVERS SEATBELT BUCKLE FOUND BUCKLE WOULD NOT LATCH REPLACED BUCKLE AND RETESTED NOW BUCKLE WORKS PROPERLY CHECKED OUT PASS. FRT SEATBELT WON,T STAY LOCKED IN R&R NEW SEATBELT.CLIP.
NA	ON	11001	COMPLETE RECALL
NA	OH	11001	R&R SEAT FOR ACCESS BECAUSE OF CONVERSION. REPLACED SEAT BELT BUCKLE. REPLACED SHOULDER ADJUSTER FOR SAME SEAT. BROKEN.
NA	ME	11001	
NA	AB	11001	
NA	ON	11001	NGS TESTED RCM. CODE B2548. DIAG AND REPLACE RIGHT FRT SEATBELT BUCKLE. RETEST & CLEAR CODES
NA	MB	11001	TESTED SEAT BELT LATCH FEMALE END FOUND VERY HARD TO UNLATCH. INTERNAL PROBLEMS IN LATCH.REPLACED FEMALE LATCH ASSEMBLY.RETESTED OK NOW.
NA	AB	11001	CODE CHECK B2438 REPLACE RT SIDE SEAT BELT BUCKLE
NA	BC	11001	1120 NGS TEST B2438 PINPOINT TEST PASS SEAT BELT BUC KLE SWITCH CKT OK RE AND RE PASS FRONT SEAT AND REPLACED SUSPECT BUCKLE CLEAR CODE RD TEST WITH SEAT BELT LATCHED UNLATCHED RETEST SYSTEM PASS

*	NA	PQ	11001	154 VERIFIER PAS LA BONNE PIECE RECOMMANDER BUCKLE DRIVER SEAT . 153 CHANGER SEAT BELT ET VERIFIER OK.
*	NA	PQ	11001	REPLACE SEAT BELT GAUCHE NE RETRACTE PAS
*	NA	ON	11001	REPLACE BUCKLE ASSY
*	NA	MB	11001	DID BCE TEST, PIN POINT TEST,REPLACED DRIVER'S SEAT BUCKLE AND DID FINAL QUICK TEST
*	NA	PQ	11001	REINSTALLER LE TRIM DE BOUCLE
*	NA	PQ	11001	TEST AND REPLACE DRIVER SEAT BELT BUCKLE DOING LIGHT SRS WARNING LIGHT
*	NA	PQ	11001	REPLACER CEINTURE AVANT GAUCHE
*	NA	PQ	11001	CHANGE LES 2 CEINTURES AVANT DEFECTUEUSE
*	NA	PQ	11001	REPLACE CEINTURE AVANT GAUCHE
*	NA	ON	11001	DIAG CODE B2432 PINPOINTEST RE RE SEAT REPLACED SEAT BELT BUCKLE(42)
*	NA	ON	11001	DIAG, REPLACE LEFT FRONT SEAT BELT BUCKLE
*	NA	SK	11001	AIR BAG SYSTEM DIAG REPLACE DRIVERS FRONT SEATBELT BUCKLE(42)
*	NA	OH	11001	REPLACED DRIVERS SIDE SEAT BELT CHECKED FOR PROPER OPERATION OK
*	NA	MI	11001	DIAG, REPALCE OPEN CIRCUIT IN DRIVER SEAT BELT
*	NA	MN	11001	5147 HAVE TO ORDER PARTS
*	NA	CT	11001	DIAGNOSE AND REPLACE LOCK PAWL
*	NA	NY	11001	OPEN CIRCUIT IN BUCKLE, AFTER PINPOINT TEST, REPLACED BUCKLE AND CLEARED AND RETESTED.
*	NA	NY	11001	3848 BUCKLE STICKS SEAT BELT BUCKLE ON DRIVERS SEAT STICKS AND HARD TO GET BELT OUT. REPLACED SEAT BELT BUCKLE 6 WAY POWER SEAT.
*	NA	MD	11001	DIAGNOSIS REMOVED AND REPLACED DRIVERS SEATBELT

*	NA	WI	11001	STRIP CAME OFF REPLACED NEW BELT
*	NA	NE	11001	REPLACED THE BUCKLE
*	NA	NJ	11001	TEST SYSTEM CODES B2436 REMOVE RT FRONT SEAT TO ACCES AND CHECK CIRCUIT FOR PINPOINT TEST RT FRONT BUCKLE OPEN CIRCUIT IN ALL SEAT BELT BUCKLE CLEAR CODES
*	NA	PA	11001	61203 S36 28 CHECKED OVER & REPLACED CONNECTOR AT R FRONT SEAT BELT BUCKLE
*	NA	NJ	11001	REPLACED SWITCH IN BUCKLE ASSEMBLY JAMMED
*	NA	TX	11001	4815 PASS. SIDE SEAT BELT BUCKLE SHORTED 14056D .5 HRS. 998A 2 HRS. .7 HRS. SOP
*	NA	TX	11001	6432 A BAG LIGHT FLASHES CODE 52 14056D 61171A A BAG D.G. REPLACE PASS SEAT BELT
*	NA	CA	11001	CODE 51 RUN DIAG TEST DRIVERS SEAT BELT RECEIVER SWITCH OPERATION. REPLACE
*	NA	IN	11001	6734 PASSENGER SEAT BELT SWITCH INOP VERIFIED CONCERN RESTRAINT DIAGNOSIS RETRIEVED B2436 PINPOINT TEST P REPLACED PASSENGER FRONT SEAT BUCKLE ASSEMBLY AND RETESTED
*	NA	TX	11001	NGS TEST, RETRIEVE CODES FROM AIR BAG SYSTEM, CODE B2432, WENT TO PINPOINT TEST FOUND OPEN CIRCUIT ON DRIVERSIDE SEATBELT BUCKLE, REMOVE SEAT AND REPLACE BUCKLE
*	NA	TX	11001	1 REPLACE LEFT FRT SEAT BELT BUCKLE
*	NA	VA	11001	5689 EEC TEST DRIVERS SEAT SHORT TO GROUND R R DRIVER S POWER SEAT. R R TRIM PANNEL ON SIDE OF SEAT TO GET ACCESS TO FEMALE END OF SEAT BELT BUCKLE. FOUND SHORTED WIRE. R R SEAT BELT BUCKLE. REPLACED
*	NA	AL	11001	GET SEAT BELT LATCH OUT OF SEAT ON 3RD ROW 1
*	NA	OR	11001	VERIFIED, NEEDS SEAT BELT BUCKLE, REPLACE BUCKLE L OK AT THIS TIME
*	NA	CT	11001	CHECK FOR CAUSE OF AIR BAG LAMP, RAN SYSTEM SELF TEST CODE B2432 FOLLOWED PINPOINT TEST AND REPLACED THE LF SEAT BELT BUCKLE.
*	NA	SC	11001	REPLACED SEAT BELT BUCKLE. TESTED SAT.

*	NA	AR	11001	TEST FOR CODES REPLACE SEAT BELT BUCKLE
*	NA	CO	11001	REPLACED THE BELTS
*	NA	MA	11001	RUN AIR BAG DIAG, RUN PIN POINT TEST L., TEST ANDREPLACE DRIVERS SEAT BUCKLE, CLEARED CODES RETEST ED OK
*	NA	NE	11001	VERIFY, SCAN CHECK, CODE B 2432, DRIVERS SEAT BELT BUCKLE SWOTCH OPEN, REPLACE DRIVERS SEAT BELT BUCKLE, CLEAR CODES, TEST DRIVE. OK.
*	NA	MI	11001	ROAD TESTED VEH. VERIFIED CONCERN, PERFORMED NGS DIAG MONITORED PIDS, FOUND DRIVERS SEAT BELT BUCKLE SHOWING REMOVED DRIVER SEAT, REPLACED SEAT BELT BUCKLE, RETEST OPS AS DESIGNED, CP 1661203
*	NA	NY	11001	DRVR SEAT BELYT BCKT SW OPEN CKT. REPL
*	NA	PA	11001	MT TIME TO CHECK OUT REMOVE AND REPLACE BUCKLE
*	NA	IA	11001	REPLACED THE DRIVERS BUCKLE
*	NA	FL	11001	OPEN RESISTOR. REPL BELT AND BUCKEL
*	NA	TN	11001	1661203 41 REMOVE DR1VER SEAT TO REPLACE DR1VER SEATBELT BUCKLE HAS BUCKLE HAS HARNESS
*	NA	PA	11001	NOT WORKING PROPERLY BODY CHASSIS ELECTRIAL (BCE) TEST
*	NA	NC	11001	DIAGNOSE AIRBAG SYSTEM PINPOINT FOUND BAD SENSOR IN BUCKLE ASSEMBLY OF SEAT BELT REPLACED BUCKLE LATCH ASSEMBLY RETEST
*	NA	IL	11001	FAULTY LFT.FRT.SEAT BELT BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	SC	11001	BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	MA	11001	PUT ON WDS RUN TEST CODE B2432 PINPOINT TEST FO UND LEFT FRONT BUCKLE MISSING INSTALLED NEW BUC KLE RERUN TEST PASS
*	NA	CT	11001	COND CODE 42 TEST AIR BAG SYSTEM CODE FOR SEAT BELT SYSTEM PINPOINT TO RT FRONT SEAT BELT BUCKLE AND REPLACE
*	NA	MO	11001	761 BUCKLE CK STUFF GONE INSIDE BUCKLE GET CODES O P #23 R&R LEFT FRONT SEAT BELT BUCKLE ASSEMBLY WPI

*	NA	IA	11001	POOR CONNECTION AT SEATBELT PERFORM SELFTTEST, PINPOINT TEST, REPAIR CONNECTION AT SEATBELT
*	NA	AR	11001	BINDING REPLACED DRIVERS SEAT BELT
*	NA	FL	11001	REPLACE SEATBELT BUCKLE
*	NA	NS	11001	REPL RH FT SEAT BELT CUCKLE
*	NA	NY	11001	SEAT BELTS NOT WORKING MILEAGE ENTERED IN ERROR
*	NA	NJ	11001	REPLACED RIGHT BU CKLE
*	NA	ME	11001	15032 VERIFIED CONCERN REMOVED 2 BOLTS THAT HOLD DOWN LEFT SIDE OF DRIVERS SIDE SEAT BASE, TIPPED SEAT BASE TO UNPLUG WIRING TO SEAT BELT LATCH, AND REMOVED WIRING, REMOVED 1 BOLT THAT HOLDS LATCH
*	NA	MN	11001	8347 INSPECTED ALL SEAT BELTS AND BUCKLES FOR PROPER OPERATION COLD NOT VERIFY CONCERN ALL BELTS ADM BUCKLES ARE OPERATING PROPERLY AT THIS TIME NO PROBLEM FOUND REPLACED RIGHT FRONT BUCKLE ASSY AS
*	NA	OH	11001	7777 INSPECTED LH FRONT SEAT ACTIVE RESTRAINT FOR ERRATIC BUCKLE OPERATION INTERMITTENT CONCERN VERIFIED AND APPROVED SVC DIR. FOR RECEIVER REPLACEMENT. S.O.P. RH 60 40 SEAT BELT BUCKLE. INSTAL
*	NA	AB	11001	INTERM WONT LATCH 41 REPLACED LF SEAT BUCKLE WITH PRETENSIONER QC407
*	NA	ND	11001	DIAGNOSE INPSECT AND FOUND LEFT FRONT SEAT BELT BUCKLE WILL NOT CLIP AND LOCK, INSPECT FOR FOREIGN OBJECTS , NONE PRESENT, REMOVE LEFT F SEAT TO GAIN ACCESS TO REPLACE LEFT FRONT SEAT BELT BUCKLE AND

*	NA	IL	11001	8202 LF SEAT BELT WILL NOT LATCH, CHECKED, FOUND BAD BUCKLE. ORDERED NEW BUCKLE. DEACTIVATED AIR BAG SYSTEM. REMOVED LF SEAT, R R SEAT BELT BUCKLE LF, REINSTALLED SEAT, REACTIVATED AIRBAG SYSTEM, C
*	NA	IN	11001	1258 CC42 REPLACED RIGHT FRONT PRETENSIONER SEAT BELT BUCKLE, OPERATES PROPERLY
*	NA	MA	11001	REPLACED SEAT BELT, WONT LATCH
*	NA	UT	11001	1 FOUND DRIVERS SIDE SEATBELT BUCKLE JAMMED, REMOVED DRIVERS SIDE SEAT FROM VEHICLE AND REMOVED AND REPLACED SEATBELT
*	NA	IL	11001	REPLACED LEFT FRONT SEAT BELT BUCKLE. WILL NOT ALWAYS LATCH
*	NA	ON	11001	REPLACE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH
*	NA	MS	11001	1155 W95 INSP VEHICLE FOUND R H SEAT BELT NOT LATCHING, REMOVED SEAT REPLACED SEAT BELT LATCH.
*	NA	KY	11001	FOUND PART OF THE LATCHES MISSING PART FAILURE DUE TO PART FATIGUE REPLA
*	NA	GA	11001	CK & FOUND SEATBELT BAD REPLACED & RECHECKED OK
*	NA	MI	11001	2633 42 W PERFORM NGS AIR BAG DIAG, ON DEMAND, PID DATA MONITOR TESTS, NO CODES. PERFORM PINPOINT TESTS FOUND LT FRT SEAT BELT WITH PRETENSIONER INOP. REMOVE LT FRT SEAT ASSEMBLY TO ACCESS AND REPLACE
*	NA	CA	11001	DRIVERS BUCKLE INOP BROKENM REMOVED DRIVERS SEAT T REMOVED OLD BUCKLE INSTALL NEW BUCKLE AND SEAT AND TEST
*	NA	AZ	11001	INSTALLED THE NEW SEAT BELT BUCKLE
*	NA	MI	11001	9739 INSTALL NEW SEATBELT TESTED NEW SEATBELT DONE 9654
*	NA	NE	11001	REPLACED DRIVERS SIDE LATCH
*	NA	OH	11001	41 STICKING REPLACED SEAT BELT BUCKLE

NA	WA	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
NA	TN	11001	2897 DRIVERS SEAT BELT LATCH CKED THE SEAT BELT SYSTEM, R AND R THE DRIVERS SEAT AND REPLACED THE SEAT BELT LATCH.
NA	TX	11001	3099 C.C 61202 RR RIGHT FRONT SEAT REPLACE RIGHT SEAT BELT BU CKLE FOR BEING INOP
NA	AZ	11001	REPLACE BROKEN DRIVER SIDE SEAT BELT BUCKLE
NA	OH	11001	9153 42 REMOVED THE PASSENGER SEAT TO REPLASE THE SEAT BELT LATCH 6881
NA	NV	11001	SEAT BELT BUCKLE INOP REPLACE RIGHT FRT SEAT BELT BUCKLE
NA	TX	11001	RAN DAIG ON SEAT BELTS. R&R RIGHT FRONT SEAT. REPLACED SEAT BELT BUCKEL ASSY. TECH 561
NA	OH	11001	REPLACED SEATBELT ASSY
NA	NY	11001	INSTALLED PS STAT BUCKE
NA	TX	11001	1 REPLACED RIGHT SEAT BELT BUCKLE
NA	AZ	11001	STICKS BINDS OR GRABS MECHANISM INSIDE OF BELT BUCKLE IS BROKEN REPLACED SEAT BELT WORKS GOOD
NA	WI	11001	INSPECT AND REPLACE PASS. SEAT BELT BUCKLE RECH ECK OK
NA	CA	11001	VERIFY CONCERN M TIME ID TO REPLACE DRIVER SEAT BELT BUCKLE REMOVE SEAT TO REPLACE REASSEMBLE AND VERIFY REPAIRS
NA	KS	11001	42 REP PRETENSIONER
NA	TX	11001	SEATBELT WONT LATCH TRACK ASSEMBLY FRONT SEAT REPLACE
NA	TX	11001	VERIFIED CONCERN. BELT BUCKLE WONT STAY LATCHED ALL THE TIME. REPLACED BUCKLE.
NA	MD	11001	RR SEAT COVER TO REPL SEATBELT AND BUCKLE ASSY
NA	TX	11001	1 REMOVE REPLACE LEFT FRONT SEATBELT ASSEMBLY
NA	TX	11001	1 REMOVE REPLACE RIGHT SEATBELT BUCKLE ASSEMBLY LEFT SEATBELT REPLACED PREVIOUSLY

*	NA	OK	11001	DRIVE SEAT BELT WILL NOT STAY BUCKLED CC 42 REMOVE DRIVE SEAT AND REPLACE BUCKLE ASSEMBLY PARTS TURNED INTO T.L. QUALITY CHECKED BY GARY H.
*	NA	CA	11001	REPL FRT SEAT BELT
*	NA	AZ	11001	REPLACED SEATBELT ASSY ABD USE M TIME TO REPLACE BUCKLE RETEST OK AFTER REPAIR
*	NA	TX	11001	REPLACE LF SEAT BELT WITH RECALL BUCKLE
*	NA	NE	11001	WDS AND TEST RUN PIN POINT TEST R&R RIGHT SIDE SEAT BELT ASSEMBLY.
*	NA	OH	11001	AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	NY	11001	REPLACED PASSENGERS SIDE SEATBELT
*	NA	CO	11001	REPL SEAT RETRACTOR AND HANDLE
*	NA	MI	11001	MT TIME TO REMOVE SEAT AND REPLACE SEAT BELT PRETENSIONER.
*	NA	MI	11001	VERIFIED CONCERN. PERFORMED RESTRAINT CONTROL MODULE DIAG AND MONITORD PIDS AND PERFORMED PINPOINT TEST, FOUND LEFT FRONT BUCKLE ASSEMBLY NEEDED. REMOVED LEFT FRONT SEAT ASSEMBLY, DISASSEMBLED AND REP
*	NA	MB	11001	REPLACED PASSENGER SIDE SEAT BELT BUCKLE.
*	NA	OH	11001	REPLACE BELT BUCKLE ASSEMBLY WIRE CIRCUIT OPEN
*	NA	ON	11001	REPLACED DRIVERS SEAT HANDLE TO CORRECT PROBLEM
*	NA	NY	11001	0 CHECK PASS. SEAT BELT BUCKLE INOP., CHECK OPERATION OF PASS. SEAT BELT BUCKLE, VERIFIED COMPLAINT. BUCKLE IS BROKEN, REMOVED PASS. FRONT SEAT AND REPLACED SEAT BELT BUCKLE. ASSEMBLE AND CHECK OP
*	NA	MN	11001	SEAT BELT BUCKLE BAD EEC (QUICK TEST) DIAGNOSIS

*	NA	NS	11001	ROAD TESTED CONFIRMED PROBLEM PERFORMED ELECTRICAL SELF TEST ON RESTRAINT SYSTEM AND SYSTEM PASSED CHECKED OASIS FOUND NOTHING CALLED HOTLINE CHECK
*	NA	PA	11001	
*	NA	NY	11001	SEATBELT PAGER DRVR PRTEN OPEN ARAM CHCK AND TEST FUSE BOTH SEAT BELT
*	NA	VA	11001	INTERNAL SHORT OF CIRCUIT 85 IN DRIVERS SEATBELT BUCKLE ASSEMBLY VERIFIED CONCERN. CHECKED FOR STORED CONTINUOUS CODES, NONE PRESENT. MONITORED SEATBELT BUCKLE SWITCH PID TO GEM NOT RESP TO BUCKLE LATC
*	NA	CO	11001	OPEN CIRCUIT CHEKC OUT IN FOUND OPEN IN PRETENSIONER REPALCE DRIVER
*	NA	OH	11001	667 D AND L SEALERS REMOVE AND REPOSITION LEFT DOOR SEAL
*	NA	MI	11001	W P INOP 42 1061203 REPLACE DRIVERS FRONT SEAT BELT BUCKEL PRETENTIONER
*	NA	NJ	11001	R&R RIGHT FRONT SEAT AND REPLACE BUCKLE, AND CLEAR CODE. 1
*	NA	WA	11001	REPLACE PRETENSIONER ASSY WPI
*	NA	HI	11001	8436 CUSTOMER STATES AIR BAG LIGHT COMES ON. PERFORM AIR BAG SYSTEM DIAGNOSIS, DTC B1877 DRIVERS SEATBELT PRETENSIONER CIRCUIT OPEN. CHECK WIRING AND CONNECTIONS TO PRETENSIONER, OKAY. REMOVE DRIVE
*	NA	NC	12001	AIR BAG DIAGNOIS CODE B1877. PINPOINT TEST. REPAITLOOSE WIRE AT PRETENSIONER CONNECTOR

*	NA	TX	11001	983 DRIVERS PRE TENSIONER VERIFIED CUSTOMER CONCERN, HOOKED UP NGS TO PULL CODES FROM RCM, FOUND CODE B1877, PERFORMED PASSIVE RESTRAINT PINPOINT TEST T FROM SERVICE MANUAL, FOUND PRE TENSIONER DE
*	NA	HI	11001	NO AIRBAG LIGHT ON, TESTED AIRBAG SYSTEM WITH NGS, PULLED CODE B1877, CHECKED FAILURE CLEAR CODE, RETESTED ON DEMAND ALL PASS, MONITORED PID ALL WITHIN SPECS, ROAD TESTED AIRBAG LIGHT CAME ON, PULLED
*	NA	FL	11001	RR SEAT BELT BUCKLE ASSY
*	NA	NC	11001	100 PASS FRONT SEAT BELT INOP REPLACED PASS FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY 42 #61202
*	NA	OH	11001	CHECK OUT PROBLEM CODE B1885 PROBLEM IN DRIVER SEAT BUCKEL CHECK PIN POINT TEST REPLACE
*	NA	CA	11001	INSPECTED DRIVERS SIDE SEAT IT WAS LOOSE AND THE SEAT BELT BUCKLE WAS MISSING. NEEDED TO INSTALL A SEAT BELT BUCKLE AND PUT THE SEAT BACK
*	NA	FL	11001	SERP BELT INTERNAL FAILURE. REPL
*	NA	TX	11001	RF SEAT BELT INOP. LATCH INOP, REPLACED BUCKLE
*	NA	TX	11001	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	LA	11001	7003 28 WARR. VERIFIED CONCERN AIRBAG LIGHT ON.NGS TEST AND RETREVED CODE B1881 PASSENGER SEATBELT PRETENSIONER OPEN.R R RIGHT FRONT SEAT AND REPLACED SEATBELT BUCKLE.CLEARED CODE.ALL OK.
*	NA	FL	11001	PRETENSIONER VERIFIED CONCERN, DIAG & TEST, NEC TO REPLACE SEATBELT PRETENSIONER, RETEST O.K.
*	NA	VA	11001	VERIFY CONCERN, EEC TEST CODE FOR OPEN IN SEAT BELT TENSIONER. MONITORED PIDS FOUND RESISTANCE AT 3.3OHMS. REMOVED DRIVERS SEAT BENCH. REPLACED SEAT BELT PRETENSIONER . NO LABOR OPS TO R AND R DRIVE
*	NA	FL	11001	AIRBAG LIGHT STAY ON SUSPECT PASS SEAT BELT INTERNAL FAILURE REPLACED BELT

NA	MI	11001	REPLACE RT FT BUCKLE WITH PRETENSIONER
NA	CA	11001	PERFORMED DIAGNOSIS AND REPLACED SEATBELT
NA	FL	11001	TRACED PROB TO AN INTERMITANT FUALT INDRIVER
NA	FL	11001	PRETNTIONER REPALCE PRETNSINER
NA	NC	11001	FAULTY PAS PRETENSIONER. REPL BUCKLE
NA	FL	11001	REPLACED SEAT BELT
NA	IN	12001	PERFORM DIAGNOSTIC TESTING CODE B1877 REPLACE DR SIDE PRETENSIONER AND RETEST VERIFIED CUST CONCERN OF AIR BAG LIGHT BEING ON, FOUND PROBLEM IN THE ELT PRETENSIONER; SEAT BELT HAD OPEN CIRCUIT, REATTACHED WIRING IN PRETENSIONER, AIR BAG LIGHT OUT NOW.
NA	FL	11001	INSTALLED NEW SEAT BELT BUCKLE; ENTERED AT WPI
NA	TX	11001	SEAT BELT BUCKLE NOT OPERATING PROPERLY M TIME TO REPLACE
NA	NC	11001	AIRBAG SYSTEM DIAGNOSTICS PINPOINT TEST CK REPLACED DRIVERS SIDE SEATBELT PRE TENSIONER, TEST DROVE RETEST, OK
NA	FL	11001	15 CK AND VERIFY NECESSARY TO REPLACED BUCKLE
NA	TX	11001	INTERNAL PROBLEM. REPL BUCKLE
NA	TN	11001	TEST AIR BAG SYSTEM WITH PINPOINT TEST ON PASS SIDE PRETENSIONERS CIRCUITS REPLACE TENSIONER AND AIRBAG MODULE REMOVE CARPET TO TEST HARNESS FOR SHORTTO GROUND FOUND ONE SPOT THAT MAY HAVE OVERLAY RET
NA	FL	11001	OPEN CKT. REPL
NA	GA	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
NA	FL	11001	RESISTNACE HIGH PERFORMED TO ADEFFECTIVE RF BUCKLE ASY
NA	OH	11001	INSTALL NGS R&R LS SEAT OPEN #57 R&R SEAT, SEAT BELT, PRETENSIONER, REINSTALL SEAT RETEST

*	NA	TX	11001	8 OPEN 28 TIME TO DIAGNOSE RUN CODES ON GEM MOD WITH WDS (NO CODES) TIME TO MONITPR PIDS WITH WDS WHILE OPERATING BELT LATCH. TIME TO RUN PINPOINT ON BELT TIME T TO RUN CONTINUITY AND CHECK FOR SHO
*	NA	TX	11001	AIR BAG DIAG DRIVER SEAT OPEN CRKT IN PRETENSIONER REPLACED PRETENSIONER SEAT BELT BUCKLE CLEARED CODE NOW OPERATING PROPERLY
*	NA	TX	11001	ROAD TEST KOEO FOUND CODE FOR PASS BUCKLE WDS PID MONITOR FOR ALL INPUT OUTPUT MONITOR ALL PASS RESET LIGHT RETEST
*	NA	OR	11001	1 DIAG CODES,B1885,B1878,PINPOINT DEACTIVATED AIR BAGS,REPLACE DRIVERS PRETENSIONER ASSY,MT. R&R MODULE AND RETESTED OK.
*	NA	OR	11001	AIR BAG DIAGNOSIS MT PINPONT TEST CODE B1877 & DRILL & REMOVE SEIZED SEAT PRETENSIONER BOLT. R&I DRIVE SEAT TO ACCESS & REPALCE PRETENSIONER. CLEAR CODE & RETEST.
*	NA	HI	11001	4847 PERFORM AIR BAG SYSTEM DIAGNOSIS, DTC B1877 OPEN IN DRIVERS SEAT BELT PRETENSIONER CIRCUIT. CHECK WIRING AND CONNECTIONS TO PRETENSIONER, OKAY. REMOVE LEFT FRONT SEAT AND REPLACE SEAT BELT BU
*	NA	TX	11001	OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS, WDS, PIN POINT TEST, R & I DRI
*	NA	LA	11001	5153 AIR BAG DIAG CODE B1877, PERFORMED PIN POINT TEST REMOVED DRIVERS SEAT TO REPLACED PRETENSIONER SEAT BELT BUCKEL RETEST ROADTEST OK CC 28
*	NA	MI	11001	3083 CP61203 CC42 INSPECTED DRIVERS SEAT BELT. FOUND BUCKLE INOP. REMOVED AND REPLACED BUCKLE AND PRETENSIONER. NECESSARY TO DISABLE SUPPLEMENTAL RESTRAINT SYSTEM TO REMOVE PRETENSIONER. NECESSARY T

*	NA	CA	11001	CCM01 NGS TEST, PINPOINT TEST FOUND AND REPLACED INOP RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY. NECESSARY TO REMOVE SEAT FOR ACCESS. REASSEMBLED AND RETESTED OK.
*	NA	TX	11001	PERFORMED BCE DIAGNOSIS, PINPOINT TEST AND AIRBAG DIAG CODE B1877. REMOVED LF SEAT TO REPLACE LEFT FRONT SEAT BELT PRETENSIONER. RETESTED OK.
*	NA	NC	11001	R AND I SEAT REMOVE FROM FRAME REPLACE SEAT BELT TRACK AND AMD REINSTALL
*	NA	CA	11001	REPLACED THE LEFT FRONT SEATBELT THAT HAD FAILED CAUSING CHIME TO STAY ON
*	NA	TX	11001	CC28 SHORTED OUT CIRCUIT. BASIC # 81203 VERIFIED CONCERN, NOTE CUST HAS RIGHT AIR BAG IN OFF MODE NGS DIAGNOSIS, BCE TEST. AIR BAG DIAGNOSIS, COMPLETED PIN POINT TEST. DTC 1877 CHECKED WIRING CIRCUITS.
*	NA	LA	11001	DIAGNOSIS AIR BAG RESTRAINT SYSTEM M TIME TO REPLACE DRIVER SEAT BELT PRETENSION
*	NA	TX	11001	9800 L F SEAT BELT BUCKLE STICKING WARR INSPECTED L F SEAT BELT, FOUND L F SEAT BELT BUCKLE WAS STICKING, DEACTIVATED AIR BAG SYSTEM DUE TO PRETENSIONER, R&R L F SEAT BELT BUCKLE & PRETENSIONER, R&
*	NA	CA	11001	REMOVED & REPLACED PRETENSIONER
*	NA	FL	11001	INSTALL SEAT BELT PRETENSIONERS BOTH SIDES
*	NA	FL	11001	1081203 28 M O 19818 AIR BAG LIGHT LFC 46 WDS START UP BCE SELF TEST C1877 PID MONITOR RECORD HIGH DRIVER RETRACT CIRCUIT OHMS HIGH 470HMS ,PINPOINT TEST
*	NA	TN	11001	B1881 PASSAGER SIDE SEAT BELT BUTTOM SHOWS OPEN FOUND PASSAG SIDE BROKEN SHORT R&R SEAT AND REPLACED SELIDT PROBLEM COMPLETED

*	NA	TX	11001	SEATBELT PRETENSIONER PERFORMED AIRBAD DIANGOSIS,INSTALLED SEATBELT PRETENSIONER
*	NA	TX	11001	AIRBAG LIGHT DRIVER SEAT BELT BUCKLE ASSY HAS HIGH RESISTANCE REPLACED BUCKLE AS NEEDED
*	NA	OH	11001	CAUS 1061202 CCC AB5 CC 42 VERIFY, PERFORM RCM SELF TEST. RECEIVED CODE B1881. PERFORM PINPOINT TESTS B1881. DEACTIVATE SYSTEM AND REPLACED
*	NA	FL	11001	REPLACE PRETENS.
*	NA	CA	11001	BAD PRETENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	SC	11001	ELECTRIC TEST B1877 IN MEMORY ON DEMAND PASSED INTERMITTEN PROBLEM PINPOINT TEST,S1 S5 REMOVED DRIVERS SEAT AND REPLACED PRETENSIONER AND RETEST OK
*	NA	TX	11001	1061203 DRIVERS PRE TENSIONER F C 28 AIR BAG DIAG.,LFC 48, DTC B 1877,PINPOINT TEST,FOUND DRIVERS PRE TENSIONER CKT OPEN,REPLACE PRE TENSIONER,CLEAR DTC,
*	NA	TX	11001	PERFORMED AIRBAG DIAGNOSTICS REPLACED PASSENGERS PRE TENSIONER..
*	NA	HI	11001	2002 1 PERFORMED A SRS SYSTEM TEST. 1877 2 CHECKED OASIS. 3 PERFORMED A SRS SYSTEM PIN POINT TEST. 4 DEACTIVATE SRS SYSTEM. 5 REMOVED DRIVER SEAT. 6 TEST DRIVER SRS PRE TENSIONER. 7 FOUND PRE TENS!
*	NA	HI	11001	3317 1 PERFORMED A SRS SYSTEM TEST. 1881 1877 2 DEACTIVATE SRS SYSTEM. 3 PERFORMED A SRS SYSTEM PIN POINT TEST. DRIVER 8.9OHMS RESISTANCE. PASSENGER 7.8 OHMS RESISTANCE. 4 REMOVED DRIVER AND PASSE

*	NA	CA	11001	INSPECTED AND INSTALLED NGS TO CHECK FOR ANY CODES IN SYSTEM AND RETRIEVED CODE 1877,TESTED AND FOUND INTERMITTENT PRETENSIONER CODE FOR DRIVERS SIDE,INSTALLED NEW DRIVERS SIDE PRETENS CLEARED CODE
*	NA	TX	11001	6 SEAT BELT LIGHT STAYS ON ALL THE TIME. 12851D,D2,DX1,MT 61203AAA 1.0 1.8 PERFORMED NGS TEST, PINPOINT TEST, REPEAT QUICK TEST, R&I DRIVER SEAT, R&I CARPET TO CHECK WIRING, REPLACED SEAT BELT BUCK
*	NA	FL	11001	INOP
*	NA	WI	11001	EEC (QUICK TEST) DIAGNOSIS FND SEAT BELT BAD RPLCD OK
*	NA	KY	11001	4083 42 W RR LF SEAT, REPLACE LF SEAT BELT BUCKLE 2847
*	NA	WV	11001	REPLACE TENSIONER
*	NA	IA	12001	EEC TEST PINPOINT TEST WIGGLE TEST UNABLE TO DUPLICATE CONCERN
*	NA	CA	11001	LF SEAT BELT BUCKEL JAMMED REPLACED LF SEAT BELT BUCKLE
*	NA	SC	11001	RESTRAINT DIAGNOSIS CODE B1881,FAULTY PASS. PRE TENSIONER,REPLACE,CLEAR CODES AND RETEST.
*	NA	FL	11001	INSPECT REPLACE SEAT BELT
*	NA	KY	11001	TEST AIR BAG SYSTEM REPLACE LEFT PRETENSIONER
*	NA	WI	11001	INSPECT AND REPLACE DRIVERS SEAT BELT BUCKLE RECHECK OK
*	NA	CA	12001	CK FOR CODE GOT CODE 1877 PP LED TO DR BUCKLE FOUNT IT NOT MATED, RECONNECT
*	NA	TX	11001	REPLACEDDRIVERS SIDE PRE TENSIONER FOR SEATBELT ROAD TESTED TO VERIFY CONCERN, FOUND AIR BAG LIGHTON, PERFORMED BCE DIAG, FOUND LOOSE GROUND TO AIR BAG AND SEAT BELT LIGHT, REMOVED AND REPLACED SEATBELT, RETESTED OK
*	NA	MN	11001	X SEATBELT ASSEMBLY FRONT REPLACE

*	NA	TX	11001	42 DRIVERS SIDE SEAT BELT INOPERABLE FOUND AT TIME OF PDI
*	NA	AL	11001	MT61203, TIME TO REPLACE 1 SEAT BELT BUCKLE THAT DOES NOT FASTEN CORRECTLY.
*	NA	MI	11001	8869 41 61203 1.3 CK SEAT BUCKLE NISS TO R R SEAT AND REPLACE BUCKLE ASSY 60 40 WITH PRETENS THIS IS BUCKLE END NOT SEAT BELT ASSY
*	NA	FL	11001	DRIVER SEAT BELT BUCKLE WONT LOCK DUE TO INTERNAL MECHANISM FAILURE R AND R THE LF SEAT BELT BUCKLE ASSY
*	NA	AL	11001	DIAG AND REPLACED DRIVER SEAT BELT. PULLED SEATBELT FROM PDI
*	NA	IN	11001	INSPECTION OF DRIVERS SEAT BELT FOUND BUCKLE WOULD NOT LATCH.CHECKED OASIS FOR ACTIVE RECALL,FOUND NONE.REMOVED DRIVERS SEAT AND REPLACED DAMAGED BUCKLE.UPON REINSTALLING SEAT FOUND SEAT RAIL ASSY W
*	NA	VA	11001	SEAT BELT WOULD NOT LATCH, REPLACED WITH NEW SEAT BELT, WORKS PROPERLY
*	NA	DE	11001	SEAT BELT BUCKLE JAMMED SEATBELT ASSEMBLY FRONT REPLACE
*	NA	OH	11001	SOP SEAT BELT
*	NA	AR	11001	REPLACED DRIVERS SIDE SEAT BELT
*	NA	NC	11001	R&R SEATBELT ON DRIVER SIDE
*	NA	OH	11001	REPLACED RIGHT FRONT SEAT BELT WITH TENSIONER RETRACTOR.
*	NA	CA	11001	REPLACED SEATBELT AND NOW OK.
*	NA	OH	11001	INSTALLED DRIVERS SIDE SEAT BELT BUCKLE
*	NA	MN	11001	CHECK OUT RIGHT SEAT BELT BUCKLE WILL NOT LATCH, CHECK OUT NOT INVOLVED IN RECALL 01S21, REMOVE AND REPLACE SEAT BELT LATCH ASSEMBLY
*	NA	MO	11001	REPLACE SEAT BELT BUCKLES
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS

*	NA	TX	11001	REPLACE RIGHT SEAT BELT, 42
*	NA	FL	11001	DEACTIVATE AIR BAG SYSTEM DISCONNECT BATTERY RR DRIVERS SEAT REPLACE SEAT BELT BUCKLE ASSEMBLY GAS CHARGED RETEST
*	NA	CA	11001	SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELTS
*	NA	IL	11001	FOUND BAD SEAT BELT RECEPICAL REMOVE AND REPLACE SEAT BELT RECEPICAL
*	NA	OR	11001	1 REPLACE BUCKLE, DOES NOT LATCH.
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	TX	11001	SEAT BELT BUCKLE NOT CATCHING ALL THE TIME NEC TO REPLACE FRONT BUCKLE
*	NA	AZ	11001	REPLD DEFECTIVE LF SEATBELT BUCKLE PRETENSIONER THAT WOULD NOT LATCH.
*	NA	CO	11001	REPL RF SEAT PRETENSIONER
*	NA	CA	11001	VERIFY CONCERN LH SEAT BELT BUCKLES BINDING R&R L F SEAT BELT BUCKLES VERIFY REPAIRS L F SEAT BELT BUCKLES NORMAL
*	NA	CA	11001	RECALL REPAIRED AS PER RECALL
*	NA	WI	11001	MT EQUALS TIME TO REPLACE SEATBELT BUCKLE DRIVERS SIDE
*	NA	OR	11001	
*	NA	LA	11001	R R L SEAT REPLACED L SEAT BELT BUCKLE TENSIONER INOP
*	NA	CA	11001	TEST SEAT BELT FOUNT WILL NOT LATCH REPLACED SEAT BELT.
*	NA	TX	11001	VERIFY CUSTOMER CONCERN REMOVE DRIVER SIDE SEAT AND REPLACE SEAT BELT BUCKLE
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEATBELTS
*	NA	NM	11001	INOP. SEAT BELT BUCKLE REMOVE LEFT FRONT SEAT FROM VEHICLE, REPLACE SEAT BELT BUCKL E ASSEMBLY

*	NA	AB	11001	10914 DIAGNOSED AND REPLACED DRIVERS SEAT BELT BUCKLE AND PRETENSIONER QUALITY CHECKED RETESTED
*	NA	TX	11001	WONT LATCH VERIFY CONCERN REPLACED DRIVER SIDE BUCKLE OK THIS TIME
*	NA	KS	11001	8711 REPLACE DIRVERS SEAT BELT BUCKLE, WILL NOT LATCH, 80.40 SEAT, WITH PRETENDIONER.
*	NA	MO	11001	5660 81202 BUCKLE, 42 DNOP VERIFIED CONCERN OF PASS FRONT SEAT BELT NOT LATCHING PROPERLY. REMOVED PASS FRONT BUCKET SEAT AND REPLACED PRETENSIONED SEAT BELT BUCKLE REASSEMBLED VEHICLE AND VERIFIED
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELT
*	NA	NM	11001	LH FRONT BUCKLE JAMMED. DISABLE AIR BAG SYSTEM, REPLACED BUCKLE. RE ACTIVATE AIR BAG SYSTEM.
*	NA	TX	11001	1 REMOVED D S SEAT FROM VEH. SEAT BELT BUCKLE BOLT STUCK IN SEAT TRACK. R R SEAT TRACK. INSTALLED NEW BUCKLE.
*	NA	TX	11001	DRIVERS SEAT BELT BUCKLE INOP INSPECT BUCKLE WOULD NOT LATCH R.R. DRIVER SEAT ASSY REPLCAE BINDING SEAT BELT BUCKLE
*	NA	MO	11001	REPLACE LEFT FRONT SEAT BELT
*	NA	CA	11001	SEATBELT BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE
*	NA	MI	11001	1GS DIAG AIR BAG SYS PINPOINT TEST R&R LEFT SEAT TO
*	NA	CA	11001	REPLACE BELT PRETENSIONER
*	NA	CA	11001	CC262 CHECKED OUT REMOVED DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE
*	NA	AZ	11001	VERIFY L FRONT BUCKLE BINDING REPLACE RETEST OK
*	NA	WI	11001	LATCH STICKS, PULLED SEAT, REPLACED BUCKLE & REINSTALLED SEAT
*	NA	CA	11001	BUCKLE INOP HOUSING MATTER WILL NOT BUCKLE. R&R BUCKLE ASSY

*	NA	MN	11001	REPLACE SEAT BELT BUCKLE
*	NA	CA	11001	REMOVE & REPL RT FRT SEAT & REPL BUCKLE ASSY.
*	NA	TX	11001	REPLACED SEAT BELT BUCKLE
*	NA	CA	11001	VERIFIED CUST CONCERN REPLACED L F SEAT BELT BUCKLE REINSPECTED ALL OK. 3.
*	NA	TX	11001	REPLACE DRIVERS SIDE SEAT BELT ASSY
*	NA	FL	11001	R&R LH SEAT BELT BUCKLE
*	NA	OK	11001	INSPECTED SEATBELT BUCKLE, REPLACED R/F SEATBELT BUCKLE
*	NA	TX	11001	NEG TO REPLACED SEAT BELT BUCKLE WONT LATCH
*	NA	NV	11001	SEATBELT INOP REPLACED BUCKLE
*	NA	NE	11001	REPLACED SEAT BELT
*	NA	TX	11001	REPLACE RT FRT SEATBELT BUCKLE (WILL NOT STAY LATCHED AT TIMES PER CUST)
*	NA	CA	11001	VERIFY CONCERN. REPLACED LEFT SEATBELT BUCKLE.
*	NA	IL	11001	TEST AND REPLACE SEAT BELT TEST O.K.
*	NA	MN	11001	CONFIRMED CONCERN.INSPECTED AND FOUND THE PRETENSIONER BOUND UP.ORDERED PARTS. REMOVE DRIVER SEAT AND REPLACE SEAT BELT BUCKLE.
*	NA	TN	11001	CKED SEAT BELT OPERATION FD SEAT BELT WOULD NOT STAY BUCKLED REM FRT SEA R&R ASSY REASSEMBLE & RECKED OK
*	NA	IN	11001	748 DUPLICATE CUST CONCERN. PROBLEM DETERMINED TO BE IN BUCKLE ASSY. ORDER REPLACEMENT. REMOVE SEAT ASSY. REMOVE AND REPLACE SEAT BLET BUCKLE ASSY. RETEST. ALL OKAY. NGS TEST SYSTEM DUE TO BUCKLE BE
*	NA	CA	11001	BUCKLE INOP M TIME TO RT BUCKLE

*	NA	CA	11001	BROKEN BUCLE	M TIME TO REPLACE LEFT SEAT BELT
*	NA	MI	11001	REPLACERTFT SEAT BELT	
*	NA	MO	11001	REPLACED DRIVERS BUCKLE	
*	NA	MO	11001	REPLACED DRIVERS BUCKLE	
*	NA	MO	11001	REPLACED DRIVERS BUCKLE	
*	NA	MO	11001	REPLACED DRIVERS BUCKLE	
*	NA	OH	11001	1 INSPECTED BOTH FRONT SEAT BELTS ONE FAILED REPLACED ONE	
*	NA	FL	11001	5 RECALL W TECH 599,PERFORMED RECALL 01S21,RR PASS FRONT SEAT BELT(FAILED),ALL OK AT THIS TIME	
*	NA	OH	11001	01S21 COMPLETED	
*	NA	FL	11001	INSPECT AND REPLACE PASSENGER SEAT BELT	
*	NA	AZ	11001	REPLACE SEAT BELT. RT SIDE	
*	NA	MN	11001	10 REPLACE PASSENGER FRONT SEAT BELT	
*	NA	TN	11001	BOTH FRT SEATBELT BUCKLE ASSYS FAILED RECALL 01S21 SEATBELT INSPECTION. OASIS DOESNT SHOW THIS VEHICLE AS BTING INVOLVED IN RECALL 01S21. REPLACED BOTH FRT SEATBELT BUCKLE ASSYS AS SAFETY LIABILITY IS	
*	NA	TN	11001	DRIVERS SEATBELT BUCKLE FAILED 01S21 INSPECTION. OASIS NOT INVOLVED IN RECALL. RPL BUCKLE FOR SAFETY LIABILITY CONCERN. M TIME IS LBR TO REPLACE DRIVERS SEATBELT LBUCKLE. NO OP# PUBL.	
*	NA	TN	11001	BOTH FRT SEATBELT BUCKLES FAILED RECALL INSPECTION. OASIS DOESNT SHOW VEHICLE INVOLVED IN RECALL. RPL BUCKLES DUE TO SAFETY LIABILITY ISSUES. LISTED AS M TIME. NO OP# PUBL.	
*	NA	ID	11001	RECALL	WE REPLACED THE RIGHT SEAT BELT

*	NA	MO	11001	REPLACED DRIVERS BUCKLE
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	AZ	11001	01S21Q PERFORM RECALL SEAT BELTS AS PER RECALL
*	NA	NE	11001	17 PULLED THE PASSAGER SEAT OUT TURNED IT UP SIDE DOWN PULLED THE SEAT COVER BACK TOOK OLD BELT BUCKEL OUT REPLACE IT WITH A KNEW ONE
*	NA	FL	11001	CHECK AND REPLACE BOTH FRONT SEAT BELTS
*	NA	TX	11001	SEAT BUCKLES NOT LATCHING CORRECTLY NEC TO REPLACE BUKLES AND BUSHINGS
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	CA	11001	PERFORM REALL 01S21
*	NA	NE	11001	31 REPLACED THE RIGHT SIDE SEAT BELT BUCKLE. CUSTOMER STATES IT WAS NOT WORKING. FAILED TESTER FOR 01S21.
*	NA	TX	11001	28 RECALL 01S21. WR PERFORM RECALL 01S21. PERFORM INSPECTION ON SEAT BELT BUCKLES. PASS OK.
*	NA	AZ	11001	RECALL REPLACED SEAT BELT TENSIONER BUCKLE AS PER RECALL
*	NA	CO	11001	1 REPLACED SEAT BELT AS PER RECALL.
*	NA	CA	11001	REPLACE LEFT AND RIGHT SEAT BELT BUCKLES
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	CA	11001	REPLACED BOTH SEAT BELT BUCKLES WOULD NOT HOLD
*	NA	NC	11001	RR LEFT FRONT SEAT MAKE A SIMULATOR FOR SEAT BELT BUCKLE. 20 OHS REPLACE FRONT SEAT BELT BUCKLE AND PRETENSIONER

*	NA	FL	11001	NGS TEST B1877 DRIVERS SIDE PRETENTIONERS FAULT CLEAR CODES RETEST FAULTS INTERMITTEN NGS PIDS PINPOINT TEST REMOVE DRIVERS SEAT DISCONNECT HARNES CHECK CIRCUITS 1080 AND 1079 FOR SHORTS O
*	NA	NY	11001	AIRBAG LIGHT ON AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	MS	11001	AIR BAD DIAG REPLACE PRE TENSIONER
*	NA	ME	11001	I CHECKED FRONT SEATBELTS AND FOUND RIGHT FRONT BAD, RR SEATBELT WITH PRENESIONER FOR SPLIT BENCH SEAT. ALL OKAY NOW.
*	NA	FL	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	OH	11001	VERIFY CONCERN AIR BAG DIAG SELF TEST B1877 PINPOINT TEST ELFC TEST T PRETENSIONER HIGH RESISTANCE DISCONNECT AIR
*	NA	FL	11001	NGS TEST DTC B1877 PINPOINT TEST REPLACE SEAT BELTBUCKLE PRETENSIONER RETEST OK
*	NA	MA	11001	REPLACED SEAT BELT
*	NA	NC	11001	TESTED & TRACED TO BAD PRETENSIONER. REPLACED TO CORRECT.
*	NA	NC	11001	OPEN CIRCUIT REPL TENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	NH	11001	VARIFIED LIGHT ON, PERFORMED AIRBAG DIAG, RETRIEVED CODE 48. PERFORMED PINPOINT TEST, SOP PRETENSIONER
*	NA	NJ	11001	
*	NA	AL	11001	DATE WAS ENTERED WRONG. CORRECT DATE NOW ENTERED.
*	NA	NB	11001	TEST AIR BAG SYSTEM, ACCESS AND PERFORM PPTS ON SEAT BELT PRETENSIONERWHICH READ OPEN CIRCUIT.

*	NA	OH	11001	8651 CODE 42. BAD DRIVERS SEAT BELT PRETENSIONER. LIGHT WAS NOT ON. INSTALLED NGS AND CHECKED FOR CONT. AND ON DEMAND CODES. ONLY STORED 1844 CONT. PERFORMED PINPOINT TESTS FOR CODE 1844. WITH NGS W
*	NA	NY	11001	8000 HIGH RESISTANCE CHECKED AIR BAG LIGHT INTERMITTENTLY FLASHING. PERFORMED RCM SYSTEM SELF TESTS. RETRIEVED CODE B1877. PERFORMED PINPOINT TESTS. MONITORED DRIVERS & PASSENGERS SIDE PRETENSION
*	NA	AL	11001	TEST SYSTEM REPLACED SEAT BELT ASSEMBLY
*	NA	FL	11001	REPLACED SEAT BELT
*	NA	ME	11001	Q REMOVED PASSENGERS BUCKET SEAT RR SOP SEATBELT ASSEMBLED TOGETHER, WORKS FINE NOW.
*	NA	VA	11001	5418 CHECKED THE AIR BAG LT BEING ON, GOT CODE B1877, DRIVER SEAT BELT PRETENSIONER CRT. BAD, REPLACED THE SEAT BELT PRETENSIONER ASSEMBLY. CLEARED THE CODE AND RETESTED GOOD.
*	NA	OH	11001	AIR BAG DIAG REPLACE BUCKLE
*	NA	OR	11001	TEST AIR BAG SYSTEM CODE B1881 RAN PIN POINT TESTS FOUND FAULTY RF PRETENSIONER R&R PRETENSIONER RETEST OK
*	NA	MI	11001	REPALCED LF BUCKEL ASY
*	NA	MD	11001	DIAGNOSIS,TESTED SYSTEM,REMOVED AND REPLACED
*	NA	NC	11001	DRIVERS SIDE PRETENSIONER,RETESTED
*	NA	MI	11001	REPLACED DRIVERS SIDE SEAT BELT...
*	NA	MI	11001	DIAGNOSIS AND REPLACED SEAT BELT

*	NA	KY	11001	DIAG AIR BAG LIGHT ON DIAGNOSIS	AIR BAG RESTRAINT SYSTEM
*	NA	TN	11001	INSTALL BUCKLE	
*	NA	FL	11001	HIGH RESISTANCE DIAGNOSIS	AIR BAG RESTRAINT SYSTEM
*	NA	NY	11001	DIAGNOSE AIR BAG LIGHT ON.RAN SELF TEST B1877.PINPOINT TEST T1.CHECK WIRING TO RETRACTOR.OK.REPLACE RETRACTOR HAS INTERMITTENT OPEN.RECHECK OK	
*	NA	FL	11001	8731 81203 42 14056D 0.6 81172A 0.4 PERFORMED SRS DIAG REMOVED SEAT ON DRIVERS SIDE REPLACED SEAT BELT PRETENIONER RETEST OK	
*	NA	ON	11001	REPLACE L.F SEAT BELT	
*	NA	TX	11001	AIRBAG LIGHT IS ON	EEC (QUICK TEST) DIAGNOSIS
*	NA	NY	11001	CONFIRMED.FOUND FEMALE RECEPICAL NOT WORKING PROPERLY REMOVED AND REPLACED TO CORRECT	
*	NA	FL	11001	11487MO 42 BUCKEL ELECT AIR BAG CK OUT HAD TO DRIVE TO GET TO ACT UP HAD CODE 47 B1881 REPL PASS SEAT BELT PRETENSHER AN RECK	
*	NA	TX	11001	1 STEERING COLUMN DIAG, AIR BAG DIAG, PINPOINT TEST, EEC. FOUND BOTH PASSENGER AND DRIVER PRETENSIONERS TO BE BAD.	
*	NA	MI	11001	INSTALL NGS AND TEST SYS REMOVE PASS SEAT AND REPLACE BUCKLE ASSY AND RETEST	
*	NA	CA	11001	DR BUCKLE DIAGNOSIS	AIR BAG RESTRAINT SYSTEM
*	NA	CA	11001	9920 OPEN PASS. SEATBELT PRETENSIONER 1.5 14056D.6,81704A.6,PRETENSIONER .3 AIR BAG SYSEM DIAGNOSIS FOUND OPEN PRETENSIONER R&R PASS. SEAT TRACK TO GAIN ACCESS, REPLACED PASSENGER SIDE SEATBELT PRETEN	

*	NA	TX	11001	7088 DRIVER SIDE SEAT BELT BUCKLE 28 W CK AIR BAG LIGHT STARTS BLINKING AND THENS STAYS ON PERFORM QUICK TEST WITH NGS P1036 OPEN ON SEAT BELT BUCKLE R&R SEAT BELT BUCKLE RECHECK AND ROAD TESTED OK
*	NA	CA	11001	INSEPECTED AND REPLACE LEFT FRT SEAT BELT
*	NA	OR	11001	SEAT BELT BUCKLE REPLACE NOT WORKING CORRECTLY
*	NA	WI	11001	ROAD TEST FLASH CODE 46.NGS TEST DTC 1877.PINPOINT TEST REPAIRED HIGH RESISTANCE IN CIRCUIT 1079 LG RD UNDER SEAT REPLACED DRIVER PRETENSIONER CLEARED CODES AND ROAD TEST AFTER REPAIRS OK .
*	NA	WA	11001	REPLACED PASS SEAT BELT
*	NA	WI	11001	9643 R R RIGHT FRONT SEAT REPLACE SEAT BELT ASSY.
*	NA	TX	11001	TEST RCM CODE B1877 PIN POINT TEST REPLACED LEFT FRONT SEAT BELT BBUCKLE AND RETEST PASS
*	NA	TX	11001	6082 VERIFY CUSTOMERS CONCERN CONNECTED NGS FOUND CODES B1871 DRIVER SIDE PRETENSIONER OPEN CIRCUIT AND B1881 DRIVER SIDE PRETENSIONER OPEN CIRCUIT.USED MULTIMETER TO PERFORM PINPOINT TEST M FOR B187
*	NA	TX	11001	REPLACE L SEAT BELT INOP
*	NA	IL	11001	1 REPLACED DRIVERS PERTENSIONER HIGH RESISTANCE.
*	NA	HI	11001	REPLACE LF SEAT BELT BUCKLE.
*	NA	HI	11001	M TIME TO REPLACE FRT SEAT BELT BUCKLES.
*	NA	WI	11001	FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	MN	11001	REPLACED PASSENGER SIDE SEAT BELT
*	NA	TX	11001	REPLACED ONE SEAT BELT BUCKLE

*	NA	AR	11001	EXTENSIVE DIAG. BELT RETRACT,BAD AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	AZ	11001	REPLACED SEAT BELT BUCKLE
				18335 SEAT BELT BUCKLE 28 CHECK AIR BAG LIGHT FLASH ON,PERFOMED NGS AND DIAGNOSTIC RCM MODULE
*	NA	FL	11001	MEMORY CODE B1877 SEAT BELT DRIVE PRETENSIONER OPEN CKT,CLEAN CODE AND PERFOMED ON DEMAND SELF TEST SA
*	NA	FL	11001	REPLACED BOTH DRIVERS AND PASSENGER BUCKLES
*	NA	TX	11001	23179 W F USE NGS TO RUN QUICK TEST B1877, RUN DCL TO CHECK SYSTEM, INTERMITTENT IN DRIVERS SIDE PRETENSIONER, REPLACE DRIVER SIDE PRETENSIONER
*	NA	CA	11001	RETEST PASS
*	NA	CA	11001	REPLACE SEATBELTS WILL NOT LATCH PROPERLY
*	NA	OR	11001	INOP WIRING ASSEMBLY REPAIR
*	NA	FL	11001	AIR BAG DIAG, INSPECT SEAT BELT, REPLACE DRIVERS SIDE SEAT BELT BUCKLE
*	NA	TX	11001	REPLACE BELTS
*	NA	AL	11001	R R DRIVER FRONT SEAT AND REPLACED SEAT BELT BUCKLE WITH PRETESIONER CAUSING AIRBAG LIGHT TO COME ON
*	NA	CA	11001	AIR BAG IGH T CONCERN QUICK TEST TRACED TO INTERM OPEN IN RIGHT SEAT BELT BUCKLE
*	NA	NE	11001	TEST DRIVE TO VERIFY AIR BAG LIGHT FLASHES.EEC TEST RCM.PINPOINT TEST.MONITOR REPLACE DRIVERS SIDE SEAT BELT PRETENSIONER.CLEAR CODES TEST DRIVE.
*	NA	OR	11001	REPAIR AND REPLACE THE SEAT BELT BUCKLE

*	NA	MI	11001	WDS TEST AND RECIEVED CODE B 1877. PERFORM PINPOINT TEST AND FOUND DRIVERS SEAT BELT BUCKLE PRE TENSIONER FAULTY. REMOVE DRIVERS SEAT AND REPLACE BUCKLE ASSEMBLY. CLEAR CODES AND RETEST.
*	NA	CA	11001	DIAGNOIS FOR AIR BAG HAD DTC B1877. REPLACE DRIVER SEAT BELT PRETENSIONER THAT HAS AN OPEN CIRCUIT. 1 VERIFIED CONCERN. HOOKED UP NGS AND PERFORMED BODY CHASSIS ELECTRICAL TEST. PERFORMED PINPOINT TEST AND DCL DISPLAY. REPLACED OPEN DRIVER S SIDE PRETENSIONER. CLEARED CODES AND
*	NA	TX	11001	1 SUPPLEMENTAL RESTRAINT SYSTEM DIAGNOSTICS CODE B1881 PINPOINT TEST REPLACE RIGHT SEATBELT PRETENSIONER RETEST
*	NA	CA	11001	REPLACE SEAT BELT
*	NA	CA	11001	REPLACE SEAT BELTS
*	NA	NV	11001	REPLACE SEAT BELT
*	NA	CA	11001	PIN POINT TEST MOINTOR PIDS OHMS ON LEFT PRETENSIONER GOOD SYATES LIGHT ONLY COMES ON AT TIMES REPLACED L/ SEST BELT BUCKLE PRETENSIONER RETEST OK
*	NA	CA	11001	REPLACED 2 SEAT BELT BUCKLES
*	NA	AR	11001	BROKEN LATCH REPLACE SEAT BELT
*	NA	ID	11001	REPLACED BOTH FRONT SEAT BELTS
*	NA	FL	11001	VERIFY CONCERN,NGS DIAG CODE B1877,PINPOINT TEST HIGH RESISTANCE,REPLACED DRIVERS SEATBELT BUCKLE
*	NA	CA	11001	RETEIVE CODES PINPOINT TEST TEST CIRCUITS TO HIGH PRETENSIONER REPIAR LOOSE CONN RETEST CODE STILL PRESS REPL RIGHT FRONT PRETENSIONER PERFORMED SRS SYSTEM DIAGNOSIS AND FAULT CODE RETRIEVAL, FAULT LFC 46,DRIVERS SIDE SEATBELT PRETENSIONER FAULT. REMOVED AND REPLACED DRIVERS SIDE SEATBELT PRETENSIONER ASSY ROAD TESTED,ALL SYSTEMS ARE

*	NA	FL	11001	VERIFY CONCERN PERFORM DIAGNOSTICS CODE 48 PRESENT PERFORM PINPOINT TESTS
*	NA	FL	11001	PERFORM PINPOINT TEST R I SEAT REMOVE AND REPALCE
*	NA	TX	11001	11379 28 PRETENSIONER 12651D .2, DX1 .1, D2 .3, M1 .7 1.3 WDS TO BCE. PINPOINT P1877. R&R SEAT REPLACE DRIVERS PRETENSIONER
*	NA	CA	11001	LATCHES INTERMITTENTLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	11001	REPLACE BOTH SEAT BELTS
*	NA	CA	11001	ROAD TEST LIGHT DID NOT COME ON, HOOKED NGS HAS CODE P1877 IN MEMORY. PASS ON DEMAND PINPOINT TEST T1 THROUGH T5 HAD REMOVED DRIVERS SEAT TO ACCESS PRETENSIONER, REPLACED PRETENSIONER, ROAD TEST, RECH
*	NA	TX	11001	REMOVE AND INSTALL DRIVERS SEAT BELT ASSEMBLY
*	NA	OH	11001	41 STICKING REPLACED BELT
*	NA	BC	11001	35223 538 28 WDS START UP SELF TEST, MONITOR SENSOR INPUTS DTC 1877 OPEN CIRCUIT DRIVER SIDE PRE TENSIONER REMOVE SEAT, REPLACE PRETENSIONER, CLEAR CODE RE TEST 12650D.2 14058D.6 81172A.4
*	NA	WI	11001	INOP REMOVED SEAT AND RELPACED BELT BUCKLE ASSEMBLY
*	NA	CA	11001	REPLACE SEAT BELT
*	NA	OK	11001	RUN AIR BAG DIAG, CODE B1877, PIN POINT TEST OPEN CIRCUIT PRETENSIONERS, REPLACE DRIVER AND PASS SEAT BELT ASSY
*	NA	CA	11001	1 TESTED AIR BAG SYS CODE B1877 MT81203 AIR BAG SYS PPT FOUN INT INOP DRIVERS SEATBELT PRETENSIONER R R SEAT TO REPLACE
*	NA	TX	11001	9273 C.C 81203 AIR BAG DIAG RETRIVE CODE B1877 DRIVER PRETENSIONER OPEN REPLACE DRIVER PRETENSIONER BUCKLE RE TEST OK
*	NA	TX	11001	OPEN CIRCUIT VERIFY CUSTOMER CONCERN. RD TEST ABS TEST CODE B1881 R&I RS SEAT TO REPLACE PRETENTIONER, OPEN CIRCUIT

*	NA	AZ	11001	SEATBELT BUCKLE INOP REPLACED BUCKLE
*	NA	MN	11001	REPLACE LATCH DOESN,T WORK
*	NA	LA	11001	7 REPLACED DRIVERS SEAT BELT BU CKLE WITH PRETENSION ER
*	NA	CA	11001	REPLACE ONE SEAT BELT FAULTY DR SIDE SEATBELT PRETENSIONER.CC42 CK AIRBAG LIGHT OPER,PERFORMED AIRBAG DIAGNOSED HOOK NGS TO RERIVE CODES.PULLED CODE B1877 OPEN CIRCUIT AT PRETENSIONER.
*	NA	CA	11001	REPLACED PASS SIDE SEAT BELT BUCKLE M TIME TO REPLACE NO LABOR OPS
*	NA	IL	11001	1623 TEST PASSIVE RESTRAINTS SYSTEMS FIND DTC 1881. PINPOINT PASSENGER SEAT BELT PRETENSIONER BAD. REPLACE RETEST OK CC 42
*	NA	TX	11001	RAN NGS DIAG, RPL SEATBELT TENSIONGS TEST AND DIAG CODES B1881 PINPOINT TEST DIAG REMOVE RH
*	NA	CO	11001	1 REPLACED PASS SEAT BELT
*	NA	CO	11001	1 REPLACED PASS SEAT BELT.
*	NA	CO	11001	1 REPLACED BOTH SEAT BELTS.
*	NA	CA	11001	REPLACE ONE SEAT BELT
*	NA	MN	11001	13 FOUND UNIT APART AIR BAG LIGHT ON, CONNECT NGS RETEIVE CODE B1831 , INSTALL SEAT BELT TENSIONER AND CLEAR GEM CODES .
*	NA	CO	11001	REPL SEATBELTS
*	NA	MN	11001	CC 01 NEW SEATBELT BUCKEL INSTALLED
*	NA	WI	11001	REPALCED SEAT BELT BUCKEL
*	NA	CA	11001	11348 CC 42 CP 81203 MT61203 2.0 2.0 FLAG 112 TEST DROVE TO VERIFY AIR BAG LIGHT CONCERN. UNABLE TO VERIFY, HOOKED UP NGS TO PULL CODES. PULLED CODE 1877 DRIVERS TENSIONER CIRCUIT OPEN . HOOKED UP

NA	CA	11001	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS INOPERATIVE BODY CHASSIS ELECTRICAL (BCE)
NA	MS	11001	TEST PERFORMED AIR BAG DIAG DTC 48 PRESENT, R AN R SEAT BELT BUCKLES, RETEST OK
NA	OR	11001	INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS
NA	FL	11001	AIRBAG LIGHT ON NGS TESTS, CODES B1881, REPLACED PASS BUCKLE, RETEST
NA	TX	11001	23815 42 W DIAG USE NGS NGS START UP PULLED CODES DO PIN POINT TEST PULLED PASS SEAT REPLACED PRETENSIONER ER RETESRT CLEAR CODES ALL OK AFTER REPAIR
NA	CA	11001	LEFT SEAT BELT REPLACED DEFECTIVE LEFT SIDE SEAT BELT BUCKLE
NA	OK	11001	DRIVERS SEAT BELT BUCKEL VERIFIED AIR BAG LITE ON, HOOK UP NGS AND PERFORMED BCE DIAG RETRIEVED CODE B1877 FROM RCM. PERFORMED PPT TO DRIVERS SEA
NA	TX	11001	REMOVE DRIVERS SEAT REPLACE BUCKLE PRETENSIONER ASSEMBLY
NA	FL	11001	46 SHORTED 6731 AIR BAG DIAG REMOVE DRVR SEAT REPLACE AIR BAG PRETENSIONER RETEST OK
NA	OR	11001	INSPECTED AND VERIFIED , REPLACED RIGHT SIDE FR ONT SEAT BELT
NA	MI	11001	5830 R&R LEFT FRONT SEAT ASSY, REPLACE PRETENSIONER SEAT BELT END. SEAT BELT WORKING NOW. CC 42 CP 1061203
NA	FL	11001	4426 42 W 7655 AIRBAG LIGHT FLASHING RETRIEVE CODE WITH NGS CODE 1881 IRCUIT IN RT PRETENSIONER PINPOINT TEST REPLACE RT PRETENSIONER
NA	TX	11001	POOR CONTACT EEC TESTED KOEO B1877, B1869, B1877 PINPOINT TESTED REMOVED

*	NA	TX	11001	CHECKED AIR BAG.B1877.FOLLOW PINPOINT TEST TO CHECK RESIST. AT DRIVERS SIDE SEAT BELT.2.1 4.0 OHMS.REPLACED DRIVERS SIDE OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM
*	NA	HI	11001	DIAGNOSIS MT TO PIN POINT TEST S1 S2 3 7 REPL FRONT SEAT BELT PRETENSIONER FAILED VERIFIED CONCERN PIN POINT TEST TO PRETENSIONER REPRGM PCM AND REINSTALLED NEW TENSIONER
*	NA	TX	11001	1 VERIFIED CVONCERN PERF SRS SYSTEM TEST RETEST CODE FOR DRIVE SEAT BELT HIGHR RESISTOR PERF PINPOINT TEST PID MONITOR FOUN
*	NA	FL	11001	PERFORM DIAG WDS DCL PPT FAILED SEAT BELT TENSIONER TO BE INSTALLED AT B SHOP
*	NA	NE	11001	1124 DRIVERS SEATBELT BUCKEL HAS INTURNAL SHORT WARRANTY R&I DRIVERS SEAT REPLACED SEAT BELT LATCH
*	NA	AR	12001	AIR BAG LIGHT ON DIAG CODE B2292 LFC 33 SEAT BELT UNPLUG
*	NA	MO	11001	515 SET UP WDS PERFORM RCM SELF TEST 1811 HARD FAULT .HIGH RESISTANCE IN RF PRETENSIONER PERFORM RCM DCL CAN GET RF TO FAIL BY MOVING SEAT FORWARD AND BACK WIGGLE LOOM TAP ON PRETENSIONER NOW IT WIL
*	NA	HI	11001	DOES NOT OPERATE PROPER SEATBELT ASSEMBLY FRONT REPLACE DR SIDE
*	NA	TX	11001	OPEN PRETENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	GA	11001	INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS REPLACE LEFT SIDE AIR BAG PRETENTIONER

*	NA	TX	11001	1 PERFORMED AIR BAG DIAG. PID MONTIOR, TEST. PINPOINT TEST AND REPLACED DRIVER SEAT BELT PRESTENSIONER
*	NA	TX	12001	11542 28 1061202 HOOK UP N.G.S., RETRIEVE CONT. DTCS, B1881 PRESENT, PASS SEATBELT PRETENTIONER OPEN CKT. PERFORMED DAIG. & PINPOINT TEST, R&I PASS SEAT AND INSPT 60 40 SEATING. PRETENTIONER BUCKL
*	NA	NJ	11001	REPL LF SEAT BELT.
*	NA	NJ	11001	REPL BELT ASSY.
*	NA	SC	11001	REPLACE LEFT FRT SEAT BELT BUCKLE
*	NA	MD	11001	1223 LATCH ON SEAT BELT BROKEN INSIDE REMOVE DRIVES FRONT SEAT REPLACE SEAT BELT LATCH
*	NA	MI	11001	21 41 WARR FOUND THAT THE LEFT FRONT SEAT BELT BUCKLE BOUND UP, R & R LEFT FRONT SEAT BELT BUCKLE ASSY. CHECKED FOR OPERATION OK AT THIS TIME. 5574
*	NA	NJ	11001	REPLACE BUCKLE
*	NA	AL	11001	REPLACED BUCKLE ASSY
*	NA	WI	11001	INSPECTED AND REPLACED SEAT BELT BUCKLE
*	NA	FL	11001	61202 42 REPLACED PASSENGER BELT BUCKLE AND RE TEST OK TJK
*	NA	CA	11001	VERIFIED CONCERN,SEAT BELT BUCKLE LATCH BROKEN INTERNALLY REMOVED AND REPLACED BUCKLE
*	NA	CA	11001	PASS FRT SEAT SHOULDER BELT TRACK ASSEMBLY FRONT SEAT REPLACE
*	NA	AL	11001	BUCKLE NOT LATCHING REPLACED DRIVERS BUCKLE
*	NA	GA	11001	TRACK ASSSEMBLY FRONT SEAT REPLACE
*	NA	NC	11001	PASS FRONT SEATBELT WONT LATCH, REPALCED PASS FRONT SEATBELT BUCKLE AND RETESTED. OK
*	NA	CA	11001	REPLACED RIVER SEAT BELT BUCKLE WILL NOT LATCH NECC R R SEAT

*	NA	KY	11001	REPLACED DRIVER SEAT THAT WOULD NOT LATCH.
*	NA	CA	11001	9 PASS. FRONT SEAT BELT BUCKLE WILL NOT LATCH R&I SEAT TO REPLACE BUCKLE ASSY.
*	NA	OK	11001	13 CAUSE: AIR BAG LIGHT FLASHING CORR: VERFIED CONCERN , BCE DIAG B2296, B2436, CONT , B2436 HARD FAULT, PID DATA MONITOR, PPT P1 P8, REPLACED PASSENGER SEAT BUCKLE , CLEARED CODES, RETEST OK BPN 5
*	NA	IL	11001	FOUND SEATBELT BUCKLE IS BINDING. RR SEAT AND REPL RS SEATBELT BUCKLE. CLOSED AT WPI.
*	NA	MI	11001	XXXXXXXXXXXXXXXXXXXXX
*	NA	MI	11001	REPLACED SEAT BELT LATCH
*	NA	CA	11001	. REPLACED A FAULTY SEAT BELT BUCKLE ASSEMBLY TO CORRECT CONCERN
*	NA	NY	11001	REPLACE DRIVER SIDE SEAT BELT ASSY
*	NA	CA	11001	REMOVED BUCKLES FOR CUSTOMER CAR. REPLACED BOTH FRONT SEAT BUCKLES.QC3
*	NA	AL	11001	
*	NA	NJ	11001	FOUND SEAT BELT BUCKLE SWITCH DEFECTIVE REPLACE DRIVER SEAT BEELT BUCKLE AND RETEST S39 42
*	NA	FL	11001	2108 42 W AIR BAG DIAGNOSTICS CODE B2432 DEACTIVATE AIR BAG SYSTEM PINPOINT TEST 2432 1 RESULT OPEN CIRCUIT TO SEAT SWITCH REPLACE SEATBUCKLE REACTIVATE SYSTEM RERUN TEST GA
*	NA	TN	11001	REPLACE R SIDE SEAT BELT BUCKEL
*	NA	KY	11001	REPLACED D SIDE SEAT BELT BUCKLE M TIME FOR NO LABOR OPS
*	NA	FL	11001	2555 W ROAD TEST PERFORMED AIR BAG DIAG NO CODES CALLED HOT LINE CONTAC# 2EGKG007 WAS TOLD POSS SEAT BELT SWITCH HAS INTERMETTING OPEN TO REPLACED SEAT BELT BUCK AND SWITCH ASY REMOVED D SEAT TO R
*	NA	FL	11001	PASS. PRETENSIONER FAILURE. REPL BUCKLE

*	NA	FL	11001	LF SEAT BELT BUCKLE INOP, FOUND LF SEAT BUCKLE JAMMED, REPLACED
*	NA	VA	11001	5845 CHECK SEAT BELT OPERATION FOUND SEAT BELT BUCKLE LOCK UP RR BOTH FRONT SEAT TO REPLACE BOTH BUCKLES AND REASSEMBLE
*	NA	IA	11001	CHECKED AIR BAG LIGHT ON TEST WITH NGS TESTER FOUND FAULT IN DRIVERS SEAT BELT SHOWS OPEN REMOVED SEAT FOUND WIRE TO SEAT BELT SENSOR BAD REPAIRED RETEST OK
*	NA	FL	11001	REPALCE BUCKLE ASSY
*	NA	OK	11001	LF SEAT LATCH NOT WORKING REMOVE LEFT SEAT ASY AND REPLACE SEAT LATCH
*	NA	NJ	11001	1 PERFORM WDS DIAGS PERFORM AIR BAG DIAGS PERFORM PIN POINT TEST REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY
*	NA	VA	11001	3 28 WDS START. SELF TEST AIR BAG. CODE B2434. PINPOINT TEST. DISSABLE AIR BAG SYSTEM AND PERFORM AIR BAG DIAG. R+R DRIVER SEAT. ATTEMPT TO LOCATE INTER SHORT TO DRIVER SEATBELT BUCKLE. REPLACE BUC
*	NA	TX	11001	LEFT FRONT SEAT BELT WOULD NOT MOVE WAS BINDING REPLACED LEFT SEAT BELT
*	NA	FL	11001	STICKS REPLACED SEAT BELT BUCKLE ON DRIVERS FRONT
*	NA	FL	11001	OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	TN	11001	REPLACED SEAT BELT ASSY
*	NA	CA	11001	PERFORM AIR BAG RESTRAINT SYSTEM DIAGNOSIS, PIN POINT TEST FOUND FAULTY DRIVER SIDE SEAT BELT BUCKLE ASSEMBLY OPEN. REMOVE AND REPLACE DRIVER SEAT BELT BUCKLE (M TIME TO REPLACE). ROAD TEST, OKAY
*	NA	IL	11001	VERIFY CONCERNAND REPLACE RIGHT FRONT SEAT BELT RECEPTACLE RECHECK OK
*	NA	NY	11001	
*	NA	NY	11001	

*	NA	MD	11001	CAP ON BUCKLE END LOOSE RESECURED EEC TESTED FOUND CODE B2432.PERFORMED PINPOINT
*	NA	VA	11001	TEST PER SHOP MANUAL.R&R BOTH AIR BAGS TO INSTALL SHORTING BARS.PERFORMED. SOP INSTALLED EEC TESTED AND FOUND CODE B2432. PERFORMED
*	NA	VA	11001	PINPOINT TEST, R AND R DRIVERS SEAT TO TEST WIRE TO SAFETY BELT PRETENSIONER ALL OK. DEACTIVATED RESTRAINT SYSTEM TO R AND R AIR BAGS TO INSTALL DIAG TOO CHECK FOR CODES AIR BAG LIGHT ON B2432 PERFORM
*	NA	NJ	11001	DIAGNOSIS CHECK AND DIAG REMOVED DRIVER SEAT AND REPLACED DRIVER SEAT BELT ASSEMBLY RECHECK AND REASSEMBLE RECHECK ALL PASS
*	NA	GA	11001	R AND R SEAT BELT AND REPLACED TO CORRECT
*	NA	CA	11001	DRIVE SIDE SEAT BELT BUCKLE STUCK LOCK SPRING INSIDE. INTERNAL BUCKLE. REPL NEW BUCKLE
*	NA	MI	11001	3647 EXAMINE CONCERN, TESTED PASSENGER SEAT BELT FOR OPERATION, AT THIS TIME CAN NOT VERIFIED ANY PROBLEM WITH PASSENGER FRONT SEAT BELT. TESTED DRIVER FRONT SEAT BELT BUCKLE, FOUND THAT THE SEAT
*	NA	FL	11001	BURNT OUT AIR BAG RESTRAINT SYSTEM DIAGNOSIS, REPLACE LEFT FRONT SEAT BELT BUCKLE PRETENSIONER 11053 PERFORM AIR BAG SYSTEM DIAG, CODE 51, TRACE AND REPAIR DAMAGED CONNECTOR AND RETEST, REPLACE ONE FUSE AND RETEST, R AND R DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE AND RETEST OK
*	NA	LA	11001	BELT BUCKLE INOP REMOVED RF PASS SEAT TO GAIN ACCESS TO BUCKLE REPLACED BELT BUCKLE
*	NA	NM	11001	INSPECT & REPLACE RT FRT SEAT BELT BUCKELS WONT LATCH,BUCKEL BIND

*	NA	KS	11001	
*	NA	GA	11001	A REPLACED SEAT BELT BUCKLE
*	NA	NY	11001	REPLACE TAILGATE LOCK ASSEMBLY.
*	NA	FL	11001	INOP ADDITIONAL MISC. REPAIRS
*	NA	FL	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	1 REPLACE SEAT BELT BUCKLE
*	NA	TX	12001	R&R SEAT BELT BUCKLE
*	NA	LA	12001	PASS FRT SEAT BELT DOESNT LATCH. REPLACED SEAT BELT BUCKLE ASSY. FSA 01S21 CHECKED REQUIRED SEAT BELT BUCKLES WITH TOOL
*	NA	AB	11001	15737 LEFT FRONT SEAT BELT BUCKLE NOT LATCHING CODE 42 CHECK SEAT BELT BUCKLES FOUND LEFT FRONT NOT LATCHING REMOVE LEFT FRONT SEAT REMOVE RT SIDE SEAT TRACK REMOVE BUCKLE REINSTALL NEW BUCKLE REI
*	NA	AB	12001	INSTALLED PASS SIDE SEAT BELT BUCKLE.
*	NA	BC	12001	DIAG FOR RIGHT SEAT BELT WILL NOT LATCH.R&R FAULTY LATCH ASSY.TST PASS
*	NA	BC	12001	R/H FRONTSEAT BELT BUCKEL WON'TR LATCH ,R/R SEAT AND REPLACE BUCKEL.
*	NA	TX	11001	REPLACED THE L F SEAT BELT BUCKLE
*	NA	TX	11001	REPLACE LEFT FRT SEATBELT ASSY,WOULD NOT LATCH
*	NA	NC	11001	R & R LEFT FRONT SEAT & TRACK ASSEMBLY & REPAIR SEAT BELT ANCHOR REPLACE SEAT BELT BUCKLE ASSEMBLY
*	NA	TX	11001	REPLACE LEFT SEAT BELT BUCKLE ASSEMBLY
*	NA	UT	11001	REPLACE DRIVERS SEAT BELT INSTALLED DRIVER SIDE FRONT SEAT BELT, IT WAS MISSING.
*	NA	AZ	11001	INSTALL SPO PART INSTALLED SEATBELT BUCKLE

*	NA	NC	11001	102 SEAT BELT BUCKLE, CODE 42 REPLACED DRIVERS SEAT BELT BUCKLE DUE TO ERRATIC OPERATION NEC TO LOOSEN SEAT CUSHION TO THREAD SEAT BELT WIRING THRU FRAME
*	NA	CO	11001	SEATBELT WILL NOT LATCH PROPERLY REPLACED LEFT FRONT SEATBELT RETEST, CHECKS GOOD (R)
*	NA	AZ	11001	STICKS BINDS OR GRABS REPLACED SEAT BELT 40 20 40
*	NA	AZ	11001	DRIVERS SIDE BELT FAILED
*	NA	TX	11001	TEST DRIVERS SIDE BUCKLE OPERATION BUCKLE WILL NOT LATCH BELT INTERNAL DAMAGE TOBUCKLE R'R SEAT AND REPLACE SEATBELT BUCKLE ASSY RETEST OK
*	NA	CA	11001	LATCH DOES NOT HOLD SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AB	12001	REMOVE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH REINSTALL NEW BUCKLE ASSY CHECK OPERATION OK MT NO PUBLISHED LABOUR OPERATION FOR THIS REPAIR
*	NA	PQ	12001	REPLACER CEINTURE DEFECT
*	NA	AB	12001	REMOVE SEAT BELT AND REINSTALL NEW ONE
*	NA	AB	12001	INSPECT AND REPLACE DRIVERS SIDE SEATBELT BUCKLE ASSY, WILL NOT HOLD BELT IN PLACE. MT TIME NO LAB OP IN SLTS TO REPLACE BUCKLE ASSY
*	NA	AB	12001	VERIFIED FOUND DRS SIDE SEATBELT LATCH NOT LATCHING, NO DEBRIS IN BUCKLE ORDERED AND REPLACED OK NOW
*	NA	MN	11001	FEMALE END OF SEAT BELT BAD SEATBELT ASSEMBLY FRONT REPLACE
*	NA	WA	11001	REPLACED DRIVERS SEATBELT ASSEMBLY. HAD TO REMOVE DRIVERS SEAT FOR ACCESS. REASSEMBLED AND RECHECKED OPERATION, OK.
*	NA	MO	11001	REPLACE SEAT BELT BUCKLE
*	NA	OR	11001	REPLACE DRIVERS SEAT BELT BUCKLE MT USED NO LABOR OPP

*	NA	OK	12001	VERIFIED CONCERN FOUND RIGHT FRONT SEAT BELT LATCH BROKEN REPLACED SEAT BELT LATCH
*	NA	PA	12001	1 REPL D R F SEAT BELT BUCKLE
*	NA	TX	12001	4375 RIGHT SEAT BELT WILL NOT BUCKLE DIAGNOSE AND TESTED SEAT BELT BUCKLE. FAILURE TO OPERATE REPLACE SEAT BELT BUCKLE,PART # REPLACE RIGHT SIDE SEATBELT BUCKLE AND LEFT SIDE PAST TEST. Q.C. BY BEN
*	NA	MO	12001	1925 DEFECTIVE PASS SIDE SEAT BELT LATCH ASSM. 160.ORDERED PASS SIDE SEAT BELT LATCH ASSEMBLY. R+R PASS SIDE SEAT LATCH ASSEMBLY.160.
*	NA	TX	12001	INSPECT AND TEST SEATBELT BUCKLES DRIVER AND PASSENGERS HAD TO REPLACE PASSENGERS SIDE BUCKLE
*	NA	TX	12001	REPLACE RH SEAT BELT ASSY
*	NA	TX	12001	
*	NA	AZ	12001	CC01 REPLACED RIGHT FRONT SEAT BELT BUCKLE INT TRIM 3E BUCKET SEATS GRAY
*	NA	WA	12001	10198 PASSENGER SIDE SEAT BELT WILL NOT LATCH. REPLACED WORKS NOW.
*	NA	CA	12001	REPL PASS SIDE FRONT SEAT BELT BUCKLE NOT LATCHING AT TIMES
*	NA	UT	12001	1 VERIFY CONCERN. CHECK BUCKLE FOR OBSTRUCTIONS. NONE RREMOVE SEAT AND REPLACED BUCKLE AND REINSTALL SEAT
*	NA	PA	12001	TECH 151 VERIFIED CONDITION.REPLACED RIGHT FRONT SEAT BELT BUCKLE AND RETESTED,SEAT BELT OPERATING PROPERLY AT THIS TIME
*	NA	IN	12001	CP7881202 S28 42 REPLACED RF SEATBELT
*	NA	CO	12001	1 REPLACED BUCKLE.
*	NA	PA	12001	INOP REPLACE R S SEAT BUCKLE
*	NA	CA	12001	REMOVE AND REPL RIGHT FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY AT THIS TIME

NA	WI	12001	ACCESS AND REPLACE SEATBELT ASSY SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE ORDERED AND INSTALLED NEW PASS FRONT SEAT BELT BUCKLE
NA	CA	12001	REPL SEAT BELT.
NA	CA	12001	INOP SEATBELT ASSEMBLY FRONT REPLACE
NA	CA	12001	42 REPLACE RF SEATBELT BUCKLE
NA	TX	12001	RATTLING INTERNALLY RETEST REPLACE R H SEAT BELT BUCKLE BINDING INTERNALLY AND NOT LATCHING
NA	TX	12001	REPLACE RT FRONT SEAT BELT.
NA	OH	12001	1 REPLACED RIGHT FRT SEAT BELT BUCKEL DONE
NA	TX	12001	RH SEAT BELT BUCKLE DEFECTIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
NA	TX	12001	REMOVED AND REPLACED PASSENGER SIDE SEAT BELT BUCKLE
NA	CO	12001	CK SEAT BELT FOR BEING BROKE REM AND REPLACED
NA	TX	12001	RIGHT SIDE LOWER SEAT BELT INSPECT AND ORDERED NEW BUCKLE REPLACED SEAT BELT BUCKLE RECHECKS GOOD
NA	GA	12001	WILL NOT LATCH REPLACE FRONT PASSENGER SEAT BELT
NA	NJ	12001	CHECK AND REPLACE RIGHT FRONT SEAT BELT BUCKLE
NA	IL	12001	3 38 WARRANTY SEATBELT ASSEMBLY FRONT REPLACE
NA	IL	12001	1 REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE
NA	TX	11001	ORDERED SEAT BELT LATCH. REPLACED DRIVERS SIDE SEAT BELT LATCH AND VERIFIED REPAIR.
NA	MO	11001	DEF BUCKLE REPLACED DRS SEAT BELT BUCKLE
NA	PA	12001	REMOVED SEAT AND SEAT TRACK AND REPLACED SEAT BELT BUCKLE
NA	GA	12001	

NA	WA	12001	35 HAD TO ORDER LF SEAT BELT STOCK
NA	IA	12001	REPLACED SEATBELT ASSY
NA	WA	12001	INOP REPLACED DRIVERS SEATBELT BUCKLE
NA	UT	12001	VERIFIED CONCERN. FOUND BUCKLE INOP. REMOVED SEAT TO ACCESS AND REPLACED ORDERED BELT BUCKLE. VERIFIED REPAIR.
NA	TX	12001	10060 DRIVER SEAT BELT WILL NOT LATCH REPLACE DRIVER SIDE SEAT BELT BUCKLE AND RETEST OK
NA	CA	11001	REPLACED SEAT BELT RECEPICAL
NA	CA	12001	REPLACED SEATBELT AND NOW OPERATION OK.
NA	NC	11001	TECH VERIFIED CONCERN, ACCESS DRIVERS SEAT, REMOVEAND REPLACE SEAT BELT. OK AT THIS TIME
NA	CA	12001	INSTALL DEFECTIVE SEAT BELT BUCKLE
NA	MT	12001	VERIFIED THAT DRIVERS SEAT BELT BUCKLE WOULD NOT LATCH. REMOVED DRIVERS SEAT AND REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. REINSTALLED DRIVERS SEAT AND CHECKED OPERATION OF NEW BUCKLE.
NA	SD	12001	NECESSARY TO REPLACE RIGHT SIDE SEAT BELT BUCKLE
NA	NH	11001	CHECKED OPERATION. REMOVED THE SEAT TO ACCESS & REPLACED A BINDING SEATBELT.
NA	TX	12001	BUCKLE INOP WONT LATCH REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSY.
NA	MO	12001	REPLACE SEAT BELTS
NA	CA	12001	INOP INSPECTED DRIVERS SEAT BELT. DOES NOT SECURE PROPERLY. REPLACED SEATBELT AND VERIFIED REPAIRS.
NA	CA	12001	REPLACED DRIVER SEAT BELT BUCKLE END
NA	MT	11001	REPLACED DRIVERS SIDE SEAT BELT.

*	NA	MN	12001	INSPECT AND VERIFY LEFT FRONT SEAT BELT WONT LATCH, BUCKLE BROKEN, REPLACE LEFT FRONT SEAT BELT AND RECHECK OPERATION
*	NA	IN	12001	REPLACE LEFT SEAT BUCKLE LATCH
*	NA	OR	11001	MT REPLACED SEAT BELT BUCKLE.
*	NA	TX	11001	REPLACED DRIVERS BUCKLE MM
*	NA	CA	12001	REPLACED SEAT BELT BUCKLE
*	NA	OH	11001	REPLACED DRIVER SEAT BELT END
*	NA	MO	11001	BUCKLE FAULTY REPLACED LF BUCKLE AND RECHECKED OKAY
*	NA	TX	12001	SEAT BELT BUCKEL MALFUNCTIONING R&R DR SEAT REPLACED SEAT BELT BUCKEL MO 3320
*	NA	IA	12001	REPLACED DRIVERS SEATBELT
*	NA	SC	12001	NOT LATCHING SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	12001	300 42 WAR DRIVER SIDE SEAT BELT BUCKEL WOULD NOT LATCH, REPLACED SEAT BELT BUCKEL.
*	NA	TX	12001	CC 42 CP 81203 REPLACED DRIVER FRONT SEAT BELT BUCKLE,SPECIAL ORDERED RIGHT REAR SEAT BELT BUCKLE,TESTED,FIXED VEHICLE.
*	NA	MN	12001	REMOVED DRIVERS SEAT, REPLACED LEFT FRONT BUCKLE.
*	NA	AZ	11001	INSPECT SYS.FOUND BLOWN FUSE,ALSO FOUND INTERIOR LIGHTS INOP AS WELL AS KEY CHIME,WINDOWS AND GAUGES.FUSE NUMBERS F2,35 10 AMP FUSE IN CENTRAL JUNCTION BOX,ACCESSED HEADLINR TO START TRACING SHORT TO

*	NA	IL	12001	INSPECTED VEHICLE FOR CUSTOMER CONCERN, FOUND LEFTFRONT SEAT BELT BUCKLE BROKEN AND NOT OPERATING P ROPERLY. REMOVED AND REPLACED LEFT FRONT SEAT BELT BUCKLE ASSEMBLY.
*	NA	NC	12001	VERIFIED, INSTALL MISSING BELT AND BUCKLE ASSY
*	NA	TN	12001	REPLACED SEAT BELT DRIVER SIDE CAPTION CHAIR MISSING BELT COMPLETED
*	NA	AZ	12001	CONCERN VERIFIED ON DRIVE BY JEREMY R&R SEAT FOR ACCESS TO SEATBELT, R&R SEATBELT BUCKLE WORKING TO SPECS
*	NA	CA	12001	REPLACE BOTH FRT BUCKLE ASSEMBLES,THEY RELEASED ON WHILE DRIVING AT TIMES
*	NA	CT	12001	42 SEATBELT ASSEMBLY FRONT REPLACE
*	NA	ID	12001	RECALL PREFORM RECALL
*	NA	TX	12001	NOT LATCHING PROPERLY. REPLACE BOTH FRONT BELT BUCKLES. M TIME FOR REPAIR NO OPERATIONS AVAILABLE
*	NA	TX	11001	REPAIRED SEATBELT
*	NA	PQ	11001	NGS TEST B1881 CLEAR CODE B1881 CHECK PRETENSIONNER CONNECTOR ECRASER SOUS BRACKET SIEGE REMOVE CONNECTOR REPLACE PRETENSIONNER ALL O.K
*	NA	PQ	11001	DEMONTER ET REMPLACER CEINTURE AVANT DROITE BLOQUE
*	NA	ON	11001	REMOVE SEAT FOR ACCESS TO REPLACE PRETENSION BELT
*	NA	ON	11001	PERFORMED DIAGNOSIS AND REPLACED PASSENGER SIDE PRETENSIONER
*	NA	ON	11001	REPLACE RIGHT FRONT SEAT BELT BUCKLE WONT INTERMITANTLY LATCH (42)
*	NA	TX	12001	7330 ACCESS THE REAR SEAT AND REPLACED THE REAR C PI LLAR. R&R FORNT PASS SIDE SEAT AND REPLACED THE DEFECTIVE SEAT BELT BUCKLE.
*	NA	BC	11001	CHECK AND REPLACE SEATBELT ASSY, RETEST , OK

*	NA	SK	11001	DTC 46 FLASH. NGS BODY TEST. DTC B1885. R&R D/S SEAT DEACTIVATED AND REPLACED THE D/S SEAT PRETENSIONER. CLEARED THE CODES AND RE TESTED SYSTEM PAS
*	NA	AB	11001	CHECK FOR FEMALE END OF DR SEAT BELT NOT HOLDING SEATBELT, YES, REMOVE SEAT AND SEATBELT LATCH, REPLACE LATCH WITH UPDATED VERSION, REINSTALL SEAT, CHECK OPERATION, GOOD NOW.
*	NA	GA	12001	TORN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	FL	11001	BUCKLE REPLACE RIGHT SIDE SEAT BELT BUCKLE
*	NA	TX	11001	TEST BOTH FRONT SEAT BUCKLES WONT DRIVERS SIDE OK PASSENGER SIDE WONT STAY BUCKLED REPLACED PASSENGER SIDE SEAT BELT BUCKLE
*	NA	MO	11001	REPLACE BELT REMOVE SEAT FOR ACCESS
*	NA	NC	11001	CHK AND FIND RF SEAT BUCKLE OPEN REPLACE BUCKLE AND RECHECK OK
*	NA	IN	11001	RUN AIRBAG SYSTEM DIAG. REPLACE SEATBELT PRETENSIONER.
*	NA	NJ	11001	REPLACE PASSENGER SIDE SEAT BELT HAD TO REMOVE SEAT TO GAIN ACCESS TO BUCKLE
*	NA	MT	11001	REPLACE LATCH, RI SEAT TO ACCESS. OK.
*	NA	MD	11001	148 R&R R FRONT SEAT ASSEMBLY, REPLACE SEAT BELT LATCH ASSEMBLY. CUST COULD GET SEAT BELT TO POP APART
*	NA	AL	11001	TESTED AIRBAG LIGHT ON, TEST CODE B1886, PIN POINT TESTED AND REPLACED RT FRT SEAT BELT RETRACTOR AND PRETENSIONER....
*	NA	VA	11001	REPLACED BAD SEAT BELT TENSIONER
*	NA	CO	11001	6127 RI RF SEAT AND REPLACED INOP SEAT BELT BUCKLE
*	NA	AL	11001	REPLACE PASSENGER REAR SEAT BELT RECEPTACLE. INOP
*	NA	TX	11001	
*	NA	VA	11001	REPLACED PASS SEATBELT

*	NA	VT	11001	FOUND SEAT BELT NOT LATCHING REMOVED AND REPLACED RIGHT PASSENGER FRONT BUCKLE
*	NA	MO	11001	TENSION OHM SHORTED DIAG BODY ELEC R&R DRIVERS SEAT AND REPLACED SEAT BELT BUCKL ASSY ON 40 20 40 SUPER CAB
*	NA	TN	11001	AIRBAG TESTS. REPLACED LEFT SEAT BELT BUCKLE
*	NA	OR	11001	MT REPLACED DRIVER SIDE SEAT BUCKLE
*	NA	WY	11001	SEAT BELT INOP REPLACED SEAT BELT BUCKLE
*	NA	CO	11001	DRIVERS FRONT BUCKLE WAS NOT ACCEPTING THE BUCKLE REMOVED NAD REPLACED THE BUCKLE
*	NA	ID	11001	STICKING DRIVERS SEATBELT BUCKLE.REPLACED DRIVERS SEATBELT BUCKLE TO REPAIR.
*	NA	PA	11001	REPLACE DRIVERS SIDE SEAT BELT
*	NA	CA	11001	DEFECTIVE SEAT BELT BUCKLE M TIME TO REPLACE BUCKLE
*	NA	PA	11001	REPLACED LEFT SEAT BELT BUCKLE
*	NA	NC	11001	75 DRIVERS SIDE PRETENSIONER LOW RESISTANCE AIR BAG DIAG AND REPLACED PRETENSIONER
*	NA	TX	11001	INTERNAL REPLACED BUCKLE ASSY
*	NA	TX	11001	INSPECT SEAT BELT WILL NOT WORK PROPERLY DISARM AIRBAG SYSTEM REMOVED AND REPLACED DRIVERS SIDE PERTENOME SEATBELT CK GOOD
*	NA	NC	12001	CAUSAL PART 1861202 PERFORMED AIR BAG DIAG., CKED AND REPLACED SEAT BELT AND BUCKLE ASSY. CONDITION CODE 82
*	NA	ID	11001	DIAGNOSE,REPLACE BELT AND BUCKLE
*	NA	NY	12001	BUCKLE WONT ACCEPT BELT REPLACED SEAT BELT BUCKLE NO LOPS
*	NA	IL	11001	REPLACE BOTH FRONT SEAT BELT BUCKLES
*	NA	OK	11001	REPLACED BOTH SEAT BELT BUCKLES ON PASS FORNT SEATWERE NOT RELEASING PROPERLY
*	NA	UT	12001	WARRANTY, I RAN OASIS, I THEN RAN SEAT BELT DIAG I FOUND THE PASSENGERS FRONT SEAT BELT RETRACTOR IS BRAKEN ALSO

*	NA	OR	12001	6227 WARRANTY RIGHT FRONT SEATBELT WOUL DNOT LATCH AT TIMES. REMOVED PASSENGER SIDE SEAT ASSEMBLY TO ENABLE REPLACEMENT OF RECIEVER BUCKLE ASSEMBLY. R&R RECIEVER BUCKLE ASSEMBLY. REINSTALLED SEAT CH
*	NA	TX	11001	VERIFIED CONCERN, LF SEAT BELT WILL NOT LATCH. REPLACED BUCKLE ASSY
*	NA	TX	11001	BUCKLE WONT SNAP TOGETHER, REPL BUCKLE ASY
*	NA	FL	11001	REPLACE BUCKLE
*	NA	TX	11001	1 VERIFIED CONCERN;R&R PASSENGER SEAT REPLACED BUCKLE NOT LATCHING; VERIFIED REPAIR;OK
*	NA	MI	11001	5461202 FAILED INSPECT REPLACE DRIVERS SEAT BELT
*	NA	TX	11001	VERIFY. PINPOINT TEST; BUCKLE BROKEN. R&R SEAT TO ACCESS. REPLACE BUCKLE. RETEST; O.K.
*	NA	IL	11001	REPLACED RIGHT FRONT SEAT BELT BUCKLE.
*	NA	ON	11001	L/F SEAT BELT DOESN'T LOCK RE RE BELT AND REPL BUCKLE
*	NA	VA	11001	1488 REPLACE RIGHT FRONT SEAT BELT,COMP
*	NA	FL	11001	REPLACE RF SEATBELT BUCKLE
*	NA	MI	11001	24787 41 W VERIFIED CONCERN. INSPECTIONF OUND RT FRT SEAT BELT BUCKLE INTERNALLY BINDING, REPL ACED BUCKLE AND RETST, OK
*	NA	ID	11001	X REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	CO	11001	BUCKEL WONT SNAP THE SEAT BELT. REPL NEW BUCKLE
*	NA	TX	11001	TESTED AND REPLACED BOTH SEAT BELTS AND BUCKLES
*	NA	TX	11001	VERIFY CONCERN REPLACED RIGHT FRONT SEATBELT WEAK AND NOT HOLDING
*	NA	MD	11001	4530 REPLACED SEAT BUCKLES AS PER RECALL 01S21
*	NA	OH	11001	REPLACED LEFT AND RIGHT SEAT BELT BUCKLES WERE INOP
*	NA	WV	11001	FOUND BUCKLE ON DRIVERS SIDE BROKEN. REPLACED DRIVERS SIDE SEAT BELT
*	NA	TX	11001	REPLACE SEAT BELT BUCKLES
*	NA	MD	11001	APPROVAL F27PZ

*	NA	TX	11001	1296 61203, 41 MT61203 0.8 REPLACE RIGHT FRONT SEATBELT BUCKLE, BINDING
*	NA	LA	11001	REPLACE LEFT FRONT SEAT BELT BUCKLE DEACTIVATE SRS REMOVE LEFT FRONT SEAT REPLACE BUCKLE REACTIVATE SRS
*	NA	FL	11001	REPLACE BELT
*	NA	VA	11001	14 RECALL 01S21N REPLACED BOTH FRONT SEAT BELTS RECALL 01S21 WITH SIDE AIR BAGS.
*	NA	CA	11001	REPL BUCKLE ASSY
*	NA	KY	11001	REPOSITIONED SEAT BELT LATCH DUE TO NOT POSITIONED CORRECTLEY
*	NA	NY	11001	TEST DIAG AND REPL SEAT BELT BUCKLE ASSEMBLY INCL REMOVAL OF SEAT TRACE AND REPAIR HARNESS
*	NA	PA	11001	DIGNOSE BOTH FRONT SEATBELTS WILL NOT LATCH PROPERLY, REMOVED AND REPLACED BOTH FRONT SEATBELT BUCKLES
*	NA	TX	11001	REPLACE BUCKLE
*	NA	FL	11001	REPLACE DRIVERS SEAT BELT
*	NA	TX	11001	REPLACED BELT BUCKLE
*	NA	FL	11001	REPLACE DRIERS SEAT BELT BUCKLE
*	NA	PQ	11001	DIAG AIR BAG SYSTEM B2436 PIN POINT P1 P2 TRY TO FIND PCM, SUPOSE TOBE IN RIGHT KICK PAD CHECK ALL OVER NOT THERE, CHECK OTHER E.V.T.M. THE SAMECHECK IN DASH AND AT LEFT KICK PAD NOT THERE LOCATE MO
*	NA	TX	11001	REPLACED RF SEAT BELT BUCKLE
*	NA	BC	11001	CHECK AND REPLACE SEAT BELT
*	NA	MA	11001	6042 REPLACED SEAT BELT.

*	NA	OK	11001	10698 42 HOOKED UP NGS AND GOT CODE B2438 PIN POINT TEST R1 TO R6 SAID TO REPLACE RCM ,CHECKED HISTORY RCM HAD BEEN REPLACED ,CALLED HOT LINE AND TALKED TO MIKE ,SAID TO CHECK WIRING AND CONNTECTO
*	NA	OK	11001	7547 42 VERIFY CONCERN AIR BAG LIGHT COMES ON WHILE DRIVING, CHECK CODES B2438 (PASSAGER SAFETY BELT BUCKLE SHORT TO GROUND), PERFORMED PIN POINT TEST R1: CHECK FOR A HARD OR INTERMITTENT DTC (COD
*	NA	MS	11001	8452 PEROFMRED ELEC DIAG FOUND AIR BAG LIGHT BLINKIN G ON AND OFF TESTED RESTRAINT CONTROL MODULE HAVING CODE B2295 RCM HAVING INTERNAL SHORT REPLACED MODULE AND RETESTED NEW CODE WAS FOUND B2434
*	NA	FL	11001	HOOK UP NGS, RUN SELF TEST, RUN DCL DISPLAY, RUN PINPOINT TEST ON PASSENGER SIDE SEAT BELT BUCKLE, FOUND BUCKLE BAD, R AND R PASSENGER SIDE SEAT, REPLACE BUCKLE, CLEAR CODES, RETEST.
*	NA	OK	11001	TECH INSTALLED DRIVERS FRONT SEATBELT BUCKLE DUE TO NOT LOCKING INTO PLACE PROPERLY
*	NA	NY	11001	REPLACED SEAT BELT BUCKLE
*	NA	LA	11001	1395 REPLACE DRIVERS SEAT BELT BUCKEL
*	NA	VA	11001	REPL RF SEAT BELT BUCKLE
*	NA	CA	11001	TESTED BOTH FRONT SEAT BELT BUCKLES DRIVER SEAT FAILED REPLACED SEAT BELT RECEIVER
*	NA	AK	11001	

*	NA	UT	11001	R & R RIGHT SEAT BELT BUCKLE LOCKS UP, R & R LEFT FORNT SEAT RETRACTRO
*	NA	WA	12001	10521 REPLACED PASS SIDE SEAT BELT BUCKLE RECIEVER NOTE VEHICLE HAS 40 20 40 SPLIT BENCH AND IS A CREWCAB
*	NA	CA	12001	INSPECT AND REPLCE BOTH FRONT SEAT BELT BUCKLES W O SIR BUCKETS
*	NA	CA	12001	REPLACED RIGHT FRONT BUCKLE
*	NA	IN	12001	MT; TIME TO PERFORM REPAIR ON SEATBELT BUCKLES ON BOTH FRONT SEATS.
*	NA	CA	11001	VERIFIED CONCERN REPLACED THE SEAT BELT LATCH
*	NA	MO	12001	REPLACED RIGHT FRONT
*	NA	UT	11001	REPL DR SIDE SEAT BELT LATCH ASSY
*	NA	NC	12001	LATCH SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	CA	12001	BELT NOT SECURED. REPLACED BELT ASSEMBLY
*	NA	MO	12001	REPLACED RIGHT FRONT SEAT BELT BUCKLE
*	NA	MI	11001	286 BCE TEST B1885 PPT REPLACE DRIVER SIDE PRETENSI ONER CLEAR CODES RETEST OK
*	NA	GA	11001	SEAT BELT & CLOCK SPRING FAILED AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	KS	11001	
*	NA	NE	12001	DIAG AND REPLACED BELT ASSY
*	NA	AZ	11001	REPLACED LT SEATBELT.
*	NA	CA	11001	CHECKED & VERIFIED SEAT BELT ON PASSENGER SIDE INOP REPLACED BUCKLE & RECHECKED & OK
*	NA	SD	12001	WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	12001	NOTE NO RECALL BUT FAILED TEST PASS BUCKLE RPL PASS SIDE BELT BUCKLE NO RECALL OPERATION REG WARRANTY
*	NA	TX	11001	REPLACED LOWER DRIVER SEAT BELT

*	NA	PA	12001	REPLACED LEFT SEAT BELT
*	NA	WA	12001	REPLACED BUCKLE VERIFIED CONCERN. DIAG. FOUND DRIVER SEAT BUCKLE INOP. R&R DRIVER SEAT BELT BUCKLE. RETESTED OK. VERIFIED REPAIR. CCC S40
*	NA	AZ	12001	INTERNAL DEFECTIVE REPLACED RT SEAT BELT BUCKLE VERIFIED CONCERN,REPLACED BOTH SEAT BELT BUCKLE ASSY RECHECKED ALL GOOD AT THIS TIME.
*	NA	CO	12001	INSTALL NEW SEAT BELT
*	NA	TX	12001	IMPROPER SEAT BELT BUCKLE FUNCTION REPLACED BUCKLE ASSY DRIVERSIDE TEST AND REPLACED DRIVESIDE BELT
*	NA	ND	12001	REPLACE RIGHT AND LEFT SEAT BELT BUCKLES PERRECALL
*	NA	CA	12001	VEHICLE MISSING DRIVERS SIDE SEAT BELT LATCH. REPLACED LATCH
*	NA	CA	11001	REPLACE RIGHT FRONT SEAT BELT ASSY
*	NA	CO	12001	REPLACE LEFT FRT SEATBELT WONT LATCH
*	NA	TX	11001	REPLACE L/F BELT
*	NA	TX	12001	VCC REPLACED DRIVERS SEAT BELT BUCKLE. R AND R SEAT FOR ACCESS 40 20 40 NO SIR
*	NA	TX	11001	BELTS FAILED INSPECT AND REPLACE BOTH FRONT SEAT BELT BUCKLES
*	NA	NV	12001	PASSENGER SIDE SEAT BELT BUCKLE WEAK, BINDS CHECKED SEAT BELTS, REPLACED PASSENGER SIDE SEAT BELT BUCKLE, RETESTED TO VERIFY, PASSED 8 REMOVED SEAT FROM TRUCK CHANGED SEAT BELT THEN BOLTED SEAT BACK IN TRUCK
*	NA	IA	12001	2814 VERIFIED CONDITION FOUND BOTH FRONT SEATBELT WILL NOT HOLD THE SEAT BELT IN PLACE WITH MINIMAL FORCE APPLIED. REPLACED BOTH FRONT SEAT BELT BUCKLES. THIS VEHICLE DOES NOT SHOW TO HAVE THE RECAL
*	NA	OH	12001	
*	NA	LA	11001	

*	NA	OH	12001	REPLACE BOTH FRT SEAT BELTS
*	NA	CA	12001	REPLACE SEATBELT WILL NOT LATCH PROPERLY
*	NA	TX	12001	INSTALLED NEW SEAT BELTS
*	NA	MO	12001	REMOVE FROM STOCK UNIT AND REPLACE ON CUSTOMERS VEHICLE
*	NA	TX	12001	VERIFIED CONCERN, REMOVED AND REPLACED SEAT BELT BUCKLE.
*	NA	AZ	12001	REPLACED BUCKLES
*	NA	TX	11001	1 REPLACE BOTH FRONT SEAT BELTS.
*	NA	CA	12001	INSTALL SOP SEAT BELT ASSEMBLY
*	NA	MO	12001	1 REPLACE DRIVER SEAT BELT BUCKLE. NORMAL AFTER REPAIRS.
*	NA	TX	11001	REPALED PASS SIDE SEAT BELT BUCKLE WONT LATCH
*	NA	TX	11001	36640 PASSENGER PRETENSIONER ASSEMBLY VERIFIED CUSTOMER CONCERN, PERFORMED AIR BAG DIAGNOSTICS, HOOKED UP NGS TO PULL CODES FROM ECS, FOUND CODE B1886, PERFORMED PASSIVE RESTRAINT PINPOINT TEST H
*	NA	WA	11001	
*	NA	NC	11001	CHECK & REPLACED SEAT BELT BUCKLE
*	NA	NM	12001	RECALL INSTALLED PASS. SIDE BELT AS PER RECALL 01S21
*	NA	FL	12001	FAILED BELT CHECK, REPLACE SEAT BELT
*	NA	LA	12001	35093 REPLACE PASS SIDE SEAT BELT BUCKLE
*	NA	FL	12001	SEAT BELTS WILL COME UNLATCHED. REPLACED BOTH SEAT BELT BUCKLES.
*	NA	TN	12001	REPLACED PASS FRONT SEAT BELT BUCKLE, FOUND WHEN INSPECTING STOCK UNITS FOR RECALL 01S21,RECALL NOT OPEN ON THIS VEH

*	NA	CA	12001	NEC TO REPLACE BOTH
*	NA	CA	12001	
*	NA	PA	11001	REPLACE SEATBELT ASSY AS PER RECALL 01S21
*	NA	PA	12001	15 INSTALL BELT#1L7Z 7861202 AAB #1C3Z 2581203 CAC DUE TO SEAT BUCKLES FAILURE OF THE SEAT BELT TEST USING THE TESTER REPLACE THE BUCKLES THE VEHICLE IS OK
*	NA	SC	12001	INSPECTED.REPLACED DRIVERS SIDE SEAT BELT & BUCKLE.TEST & RETEST.
*	NA	BC	11001	CONFIRM & REPLACED RIGHT SEATBELT ASSEMBLY
*	NA	TX	11001	SEATBELT SURROUND FALL OFF SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NY	11001	VERIFIED, RR FRONT LR SEAT BELT BUCKLES, NOW OPS NORM
*	NA	FL	11001	REPLACE SEATBELT, FAILED CHECK DONE SAME AS FOR RECALL
*	NA	VA	11001	TECH INSPECTED AND REPLACED DRIVER SIDE SEATBELT DUE TO DEFECT WAS INOPERATIVE
*	NA	AK	11001	TESTED BOTH FRONT SEAT BELTS DRIVERS SEAT RECEIVER FAILED R&R SEAT BELT RECEIVER
*	NA	CA	11001	REPLACE SEATBELT WILL NOT LATCH PROPERLY
*	NA	CA	12001	INSPECT AND REPLACED R BUCKLE.FAILED. L BUCKLE OK PASSED.
*	NA	MN	12001	X REPLACED BUCKLE ASY WOULD NOT LATCH
*	NA	AB	12001	INSPECT FRONT SEAT BELT BUCKLES HARD TO CLIP & HOLD REPLACE BOTH BUCKLES
*	NA	MI	12001	FAILED BUCKLE ASSY PASS FRT REPLACED FAILED PASS FRT SEAT BELT BUCKLE ASSEMBLY, RETEST OK NOW
*	NA	MN	12001	28663 REMOVE L F POWER SEAT TO GAIN ACCESS REPLACE S O BUCKLE AS NEEDED REINSTALL SEAT
*	NA	NC	12001	REPLCED SEAT BELT PER ED KARAZIN

*	NA	AK	12001	RF SEATBELT BUCKLE STICKS FOUND DEBRIS POSSIBLE BUR IN BUCKLE REMOVE RF SEAT TO GAIN ACCESS TO RF SEAT BELT BUCKLE REPLACE BUCKLE RETEST NORMAL LATCH OPERATION
*	NA	FL	12001	08 SEAT BELT RECALL 1.1 INSPECTED BOTH SEAT BELTS PASS FAILED. REPLACED PASS SEAT BELT.
*	NA	PA	12001	REMOVED PASSENGER SIDE SEAT AND REPLACED BUCKLE,RECHECK OPERATION
*	NA	AB	12001	HAD TO INSTALL SEAT BELT ASSEMBLIES. MT TIME TO CHECK SEAT BELT OPERATION AND TO REPLACE BOTH BELTS
*	NA	WA	12001	DIAG. R&R RIGHT FRONT SEAT BELT TO REPAIR.
*	NA	CA	11001	CC118 REPLACE RIGHT SEAT BELT BUCKLE
*	NA	CA	12001	REPLAE LEFT AND RIGHT SEAT BELT BUCKLES STICKS BINDS OR GRABS TESTED SEAT BELT BUCKLE AND
*	NA	AZ	12001	FOUND THAT PASSENGER SIDE IS BINDING INTERNALLY R AND R PASSENGER SIDE SEAT BELT.
*	NA	CO	12001	1 REPLACED BOTH SEAT BELTS, WORKING GREAT
*	NA	FL	12001	TESTED THE SEAT BELTS, REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE SIDE,
*	NA	NC	12001	INOP REPLACE BELT PASS SIDE SEAT BELT DOESNT HOLD
*	NA	TN	11001	REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	AZ	12001	RECALL 01S21 REPLACE L AND R BUCKLES AS PER RECALL
*	NA	CA	11001	BAD BUCKLE TENSIONER MT TO R R DRIVERS SEAT BELT BUCKLE
*	NA	NY	11001	13025 HARNESS OPEN AND BELT NOT HOLDING CHECKED AND FOUND SEAT BELT WOULD NOT HOLD IN THE BUCKLE R+R BUCKLE ASSEMBLY AND LIGHT STILL STAYED ON AND CHIMING CHECKED GEM MODULE AND IT PASSED CHECKED W

*	NA	PA	11001	INSPECTED AND REPLACED BOTH BUCKLES
*	NA	WI	11001	REPLACED THE LEFT SEATBELT BUCKLE THAT DOES NOT HOLD
*	NA	OH	11001	REPLACE SEATBELT
*	NA	WI	11001	REPLACED THE LEFT SIDE SEATBELT BUCKLE
*	NA	WI	11001	REPLACED THE SEATBELT BUCKLES THAT DID NOT HOLD.
*	NA	IA	12001	TEST BUCKLE REMOVE AND REPAIR INSTALL.
*	NA	NJ	11001	REPLACE SEAT BELT
*	NA	CA	11001	DIAG INSP VERIFIED CONCERN MT TIME TO REPLACE SEAT BELT BUCKLE
*	NA	CO	11001	1 REPLACED SEAT BELT
*	NA	WA	11001	REPLACED BOTH SEAT BELTS
*	NA	FL	12001	TEST AND REPLACE BOTH SEAT BELT ASSEMBLIES
*	NA	NC	11001	REPLACE SEAT BELT BUCKLE, LEFT FRONT
*	NA	NC	11001	REPLACE SEAT BELT BUCKLE ASSY
*	NA	AB	11001	TEST THE AIR BAG SYSTEM. FOUND AND REPLACED THE FAULTY DRIVERS SEAT BELT BUCKLE ASSEMBLY.
*	NA	SD	11001	REPL SEAT BELT ASSY
*	NA	NC	11001	BELT INOP SEATBELT DOESNT HOLD
*	NA	NC	12001	REPLACED RIGHT SIDE SEAT BELT
*	NA	MO	11001	CCC S39 TESTED SYSTEM RAN PIN POINT TEST CC 42 REPLACED DRIVER SEAT BELT
*	NA	OH	11001	REPLACED THE FAULTY SEAT BELT.
*	NA	AB	11001	SEATBELTS CHECKED UNDER 01S21 IN ERROR BUT FOUND THAT P/S SEATBELT FAILED. REPLACED BELT
*	NA	SD	11001	PULLED WIRE AND BUCKLE INSTALLED NEW AND REASSEMBLED CHECK OK
*	NA	OH	12001	PERFORMED RECALL FOR SEATBELTS
*	NA	TX	11001	OBSERVE SEAT BELT INOP WILL NOT LATCH REPLACE SEAT BELT BUCKLE
*	NA	TX	11001	REPLACE LT SEAT BELT.

*	NA	TX	11001	AIRBAG LIGHT IS ON DIAGNOSIS	AIR BAG RESTRAINT SYSTEM
*	NA	TX	11001	AIRBAG LIGHT FLASHES DIAGNOSIS	AIR BAG RESTRAINT SYSTEM
*	NA	TX	11001	REPLACE PASS SEAT BELT BUCKEL WONT NOT STAY LATCH	
*	NA	AL	11001	R R DRIVERS FRT SEAT BUCKLE INSTALL DRIVERS SEAT BELT BUCKLE MISSING WHEN DEALER TRANSFER HAS TENSIONER	
*	NA	TX	12001	CKED OUT TWIST LEFT SEAT BELT BUCKLE OPERATE PROPERLY IMPROPERLY INSTALLED	ON STRAP TO
*	NA	CO	11001	REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY	
*	NA	CA	12001	REPLACED SEIZED SEAT BELT BUCKLES	
*	NA	IN	12001	MT; TIME TO REPAIR SEAT BELT BUCKLES.	
*	NA	TX	12001	SEAT BELT BUCKLE BINDING DIAG INSP VERIFIED CONCERN AND REPLACED PASS SIDE SEAT BELT INOP	REPLACED BUCKLE
*	NA	CA	12001		
*	NA	TX	11001	FOUND PASSENGER SEAT BELT BUCKLE WOULD NOT LATCH PERFORMED RECALL 01S21 ON DATE 7 20 01 CHECK SEAT BELTS AND THEY PASSED REPLACED SEAT BELT BUCKLE	
*	NA	CA	12001	SEAT BELT RECALL	R&R LEFT BUCKLE
*	NA	GA	12001	SEAT BELT BUCKLE FAILED FRONT REPLACE	SEATBELT ASSEMBLY
*	NA	CA	12001	REPLACED AS PER FORD	
*	NA	ND	12001	TEST NESS TO REPLACE SEAT BELT	
*	NA	AZ	12001	FR81 LF SEAT BELT BUCKLE FROM STOCK 11689 NEC TO REPLACE FRONT SEAT BELT BUCKLES NOT WORKING ALL THE TIME	
*	NA	TX	11001		
*	NA	MT	12001	REPLACED RT FRONT SEAT BELT BUCKLE. 4827	
*	NA	ND	12001	INSPECT AND REPLACED WITH NEW	
*	NA	GA	11001	REPL SEATBELT ASSY REPLACE	SEATBELT ASSEMBLY FRONT

*	NA	CA	12001	BINDING REPLACE	SEATBELT ASSEMBLY FRONT
*	NA	PA	12001	INSPECT AND REPLACED STICKING SEAT BELT	
*	NA	AZ	12001		
*	NA	PQ	12001	DIAG REMPLACER BOUCLE DE CEINTURE AVANT LH BRISSE	
*	NA	FL	11001	DOES NOT OPERATE PROPERLY FRONT REPLACE	SEATBELT ASSEMBLY
*	NA	NY	12001	VERIFIED CONCERN FOUND AND TRACED BUCKLE ASSY FAULTY REMOVED AND REPLACED BUCKLE ASSY RETESTED ALL OK	
*	NA	HI	12001	LEFT SEAT BELT BUCKLE SEIZED. REPLACE LEFT SEAT BELT BUCKLE.	
*	NA	CA	12001	REPLACED SEIZED SEATBELT BUCKLE	
*	NA	CA	12001	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL	
*	NA	TX	12001	CHECKED SEAT BELT FUNCTION NECESSARY TO REPLACE DRIVERSIDE SEATBELT BUCKLE	
*	NA	TX	12001	LEFT FRONT SEATBELT BUCKLE NOT FUNCTIONING PROPERLY, R AND R BUCKLE	
*	NA	TN	12001	REPLACED SEATBELTS	
*	NA	ND	12001	CHECK AND REPLACED WITH NEW ONE RETEST	
*	NA	CA	11001	REPLACED LEFT AND RIGHT SEAT BELT BUCKLE PER 01S21.	
*	NA	CA	11001	BUCKLE NOT HOLDING RIGHT OR LEFT REPLACE	SEAT BELT ASSEMBLY REAR
*	NA	TX	12001	8416 SEAT BELT BUCKLE INOP MT61203 1.0 TEST AND DIAG SEAT BELT BUCKLE. ACCESS LEFT FRONT SEAT AND REPLACE SEAT BELT BUCKLE, INOP. RETEST. CODE 42 CAUSAL PART 61203	
*	NA	LA	12001	NEC TO REPL DRIVERS FRT SEAT BELT ASY	
*	NA	NV	12001	PASS SEAT BELT BUCKLE UNBUCKLES INSPECT & REPLACE PASS SEATBELT BUCKLE	

*	NA	TX	12001	FOUND INTERNAL FAILURE OF RT SEAT BELT BUCKLE 40 20 40 FT SEAT ASSY REMOVED AND REPLACED RT FT SEAT BELT BUCKLE
*	NA	GA	12001	NEC TO REPLACE SEAT BELT
*	NA	GA	12001	DIAG AND RR SEAT BELT
*	NA	TX	12001	CHECK BELT OPERATION WILL NOT LATCH REMOVE DRIVERS SEAT INSTALL NEW BUCKLE AND REINSTALL SEAT RETEST OK
*	NA	TX	12001	REPLACED SEATBELT
*	NA	GA	12001	BUCKLE FAILED SEATBELT ASSEMBLY DRIVERS FRONT REPLACE
*	NA	TX	12001	REPLACE SEAT BELTS DO NOT LATCH
*	NA	VA	12001	REPLACED SEAT BELT
*	NA	IL	12001	WPI R&I LF SEAT & TRACK ASSY REPLACE RCEIVER
*	NA	IL	12001	12 REPLACED SEAT BELT
*	NA	MI	12001	REPLACED FAULTY RT SIDE SEATBELT (REGULAR CAB)
*	NA	VA	12001	REPLACE SEAT BELT
*	NA	AZ	11001	FOUND BUCKLE STICKS SOME REPALCE AND RETESTED
*	NA	IL	12001	REPLACE LEFT FRONT SEAT BELT BUCKLE
*	NA	OH	11001	REPLACED SEAT BELT
*	NA	CO	12001	REPLACED SEAT BELT
*	NA	AB	12001	INSPECTED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE.RETESTED OK MT NO LABOUR OPERATIONS CODE IN SLTS FOR REPAIRS
*	NA	OH	11001	DIASSM TRIM AND WEATHERSTRIP TO GET TO RETRACTOR.REMOVED AND REROUTED BELT BACK IN AND OUT TO MAKE SURE IT WORKED.
*	NA	OH	0110XX	REMOVED PANELS JAMMED BAD. UNSTUCK AND RECHECK OK
*	NA	ON	11000	REPAIR WHITE WIRE AT PASS BELT CONNECTOR
*	NA	SC	11000	PCM BODY CHASSIS ELECTRICAL (BCE) TEST

*	NA	IL	11000	DIAGNOSED AND REMOVED RIGHT FRONT SEAT BELT COVER AND UNTWISTED SEAT BELT. RETESTED AND VERIFIED SEAT BELT NOW RETRACTING.
*	NA	TN	01XXXX	REPAIRED AND REPLACED SCREW.
*	NA	IN	0110XX	TRIM PIECE THAT IS AROUND BELT ON PASS SIDE IS NOT ON DRIVERS SIDE THAT IS NORMAL CHECKED OTHER VEHICLES
*	NA	CO	01XXXX	
*	NA	CA	11000	REMOVE SEAT BELTS FROM THIS STOCK UNIT TO USE TO REPAIR A CUSTOMERS VEHICLE AND REINSTALL BACK IN THIS UNIT
*	NA	TX	11000	FOUND SEATBELT TWISTED FROM FACTORY REINSTALLED CORRECTLY
*	NA	TX	11000	3870 REPLACE RT SIDE SEAT BELT ANCHOR BOLT BEZEL WAS MISSING
*	NA	GA	0110XX	7168 33 SECURED SEAT BELT TO FLOOR MOUNT
*	NA	OK	0110XX	DIAG AND REPOSITION SEAT BELT BUCKLE LATCH
*	NA	FL	12000	BELT TWISTED
*	NA	ID	01XXXX	R&I BUCKLE
*	NA	GA	0110XX	USED STOCK UNIT PART DUE TO HANDICAP CUSTOMER REPLACED SEATBELT BACK
*	NA	MB	11001	AS PER LAST ROOBELT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT.
*	NA	SC	12001	WIRE PINCHED & BROKEN REPL DR SIDE SEAT BELT BUCKLE
*	NA	ON	01XXXX	INSTALL SPO BELT BUCKLE DRIVER'S SIDE
*	NA	VA	11001	NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT REPLACED RIGHT
*	NA	AZ	11001	USED M TIME TO REPLACE RH FNT BUCKLE. RETEST OK AFTER REPAIR
*	NA	FL	11001	STICKING SEAT BELT BUCKLE REPLACE

•	NA	CA	11001	CUST STATES THE RIGHT FRONT SEAT BELT WONT HOLD OR LOCK SEE JC.....CORRE:REPLACED RIGHT FRONT SEAT BELT BUCKLE .4 ON 06 01 02
•	NA	TN	11001	SEAT BELT BUCKLE RETENTION REPLACE ONE SEAT BELT BUCKLE
•	NA	IL	11001	REPLACE SEAT BELT ASSY
•	NA	AB	11001	8628 REPLACED SEAT BELT BUCKLE DRIVERS FRONT.ALL GOOD. 7861203
•	NA	AB	11001	REPLACE THE DRIVERS SIDE SEATBELT BUCKLE
•	NA	AB	11001	20342 REPLACED DRIVERS SEAT BELT BUCKLE QUALITY CHECKED RETESTED
•	NA	IN	11001	FOUND L FRT SEAT BELT PRETENSIONER REPLACED BUCKLE
•	NA	FL	11001	VEHICLE IN FRONT LH SEAT BELT IS INOP, FOUND FAULTY BUCKLE ASSY DUE TO INTERNAL MALF, REPLACED
•	NA	TX	11001	RECEIVER JAMMED REPALCED BUCKEL
•	NA	TX	01XXXX	1010 SHORTED CHECK WITH MIKE Z FOR M TIME TEST SYSTEM R&R GEM TO TEST WIRES R&R SEATS R&R CARPET TO ACCESS WIRES FOUND SHORT WHERE CUSTOMER HAD A SPEAKER BOX WIRED IN DIRECT TO THE SEAT BELT HARNES
•	NA	AR	11000	DONE DIAG FOUND SEAT BELT WONT LATCH REPLACED BUCKLE FIXED PROBLEM
•	NA	NM	01XXXX	REPLACED DRIVERS SEAT BELT ASSEMBLY.
•	NA	TX	11000	3367 SEAT BELT CHIME STAYS ON 12651D .2 D2 .3 DX1 .1 61203 M TIME .5 1.1 HRS NGS BODY & ELECTRICAL DIAGNOIS REPLACE LT SEAT BELT BUCKLE & RETEST CODE 42 CP 61203 SWITCH IN BUCKLE NOT WORKING PROPER
•	NA	OH	11001	REPLACED THE SEAT BELT
•	NA	AL	11001	M TIME TO REPLACE DRIVER SEATBELT BUCKLE NO OPP#
•	NA	TN	11001	REPLACED THE SEAT BELT BUCKLE ASSY.

*	NA	FL	11001	1572 41 WARR 7855 L SEAT BELT WONT STAY FASYENED BUCKLE RELEASE BINDING REPLACE L BUCKLE & TEST
*	NA	FL	11001	6513 W 5121 REPLACE DRIVERS SEAT BELT CLASP OK
*	NA	NY	11000	CHECK AND REPLACE BELT STICKING
*	NA	FL	01XXXX	INSTALLED NEW SEAT BELT BUCKLE AND RE TEST. OK. AE
*	NA	NC	01XXXX	11405 INSTALL DRIVER SEAT BELT BUCKELY RETEST VERIFY REPAIR
*	NA	TX	11001	REPL SEAT BELT BUCKLE
*	NA	VA	11000	CHECKED SEATBELT R&R RT SEAT AND REPLACED SEATBELT BUCKLE
*	NA	TX	11001	REPLACED THE L F SEAT BELT BUCKLE
*	NA	TX	11000	CAME APART SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AZ	11001	M TIME TO REPLACE DRIVERS SEAT BELT BUCKLE DUE TO NOT LATCH ING AT TIMES. 1
*	NA	PA	01XXXX	1 REPLACE SEATBELT BUCKLE
*	NA	TX	11001	TEST AND REPLACE DRIVERS SEAT BELT BUCKLE, BROKEN
*	NA	KY	11001	REPLACE DRIVER SIDE SEAT BELT BUCKLE
*	NA	TX	11001	REMOVED AND INSPECT DRIVERS SEAT AND BUCKLE INSTALLED NEW BUCKLE NON SIR
*	NA	AR	11001	REPL LEFT SEAT BELT
*	NA	KY	11001	DIAG SEATBELT REPLACE RECEIVER
*	NA	CA	11001	SEAT BELT BUCKLE RELEASES ON ITS OWN AT TIMES
*	NA	TX	11001	THE L F SEATBELT BUCKLE WOULD COME LOOSE REPLACE THE BUCKLE TO CORRECT

*	NA	WI	01XXXX	CHECK OUT AND REPLACE LEFT FRONT RIGHT SIDE SEAT BELT WOULD NOT LATCH
*	NA	TX	11001	REPLACED LEFT FRONT SEAT BELT BUCKLE ASSEMBLY,
*	NA	NH	01XXXX	REPLACED DRIVERS SEAT BELT
*	NA	OH	11001	REPLACE PASSENGER SIDE FRONT SEATBELT
*	NA	WA	11000	RR BELT ASSYTESTED
*	NA	OK	12001	1641 REMOVED PASSENGER SEAT AND INSTALLED MISSING SEAT BELT. REINSTALLED SEAT AND TESTED ALL OK. CMD TECH 54
*	NA	CO	11001	5886 4496 F1 61172A .3 12651D .2 DX1 .1 D2 .3 GEM SYSTEM TESTS, KOEC B1426, B1450, KOEO B1428 DCL DISPLAY, RECORD & MONITOR PIDS, PERFORM PINPOINT TESTS & ACTIVE COMMAND TESTS, REPLACED DRIVERS SID
*	NA	ND	11001	M TIME TO REPLACE BUCKLE ASSY
*	NA	MI	11001	2 INSTALLED SEAT BELT WILL NOT STAY BUCKLED
*	NA	MN	11001	CC01 REPLACE SEAT BELT BUCKLE WAS BROKEN WORKS OK
*	NA	OK	11001	2729 REPLACED DRIVERS SEATBELT PER FSA LABOR OP 00S21B 0.6 HRS
*	NA	AZ	11001	
*	NA	IN	11001	CCN 640 CC 42 BPN#7861203 DIAG REPLACED SEATBELT BUCKLE ASSL
*	NA	GA	11001	SEAT BELT WILL NOT FASTEN, REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	GA	11001	NECC TO REPLACED DRIVER SEAT BELT BUCKLE DUE TO IT BROKE.
*	NA	PA	11001	REPLACED BUCKLE ASSEMBLY
*	NA	FL	11001	BINDING REPLACE SEAT BELT
*	NA	MO	11001	REMOVE SEAT AND REPLACE BUCKLE, REINSTALL SEAT AND RETEST, OK.
*	NA	MT	11001	RUN CHECK ON WDS, GOT CODE ON SEATBELT SHORT. R@R SEATBELT BUCKLE

*	NA	SD	11001	REPLACE SEAT BELT BUCKLE.
*	NA	MI	11001	REPLACE LF SEAT BELT BUCKLE
*	NA	TX	11001	INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	GA	11001	SEAT BELT BUCKLE FAILED SEATBELT ASSEMBLY DRIVERS FRONT REPLACE
*	NA	CA	11001	SEAT BELT BUCKLE INOP REPLACE DRIVERS SIDE BUCKLE
*	NA	CA	11001	
*	NA	AZ	11001	5 VERIFIED CONCERN,BCE TEST,BCE PIN POINT TEST SHOWED FAULTY SEAT BELT RECEIVER, REPLACED RECEIVER (40 60) BCE RETEST,ALL FUNCTIONS NORMAL. DOES NOT OPEATE PROERLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	LA	11001	6371 VERIFY CONCERN HAD TO REPLACE REMOVE SEAT TO REPLACE SEAT BELT BUCKLE. FOUND SEAT BUCKLE NOT WORKING SEAT BELT IS WORKING NORMAL.
*	NA	TX	11001	SEATBELT BUCKLE INOP, WILL NOT LATCH, REPLACE WITH NEW, RECHECK OK
*	NA	FL	11001	CONFIRM DRIVERS SEATBELT DOSENT STAY LATCHED REPLACE DEFECTIVE LATCH MT81203 NO SLTS
*	NA	CA	11001	
*	NA	TN	11001	REPLACE BUCKLE
*	NA	TX	11001	FOUND DRIVERS SIDE SEAT BUCKLE WOULD NO LATCH REPLACE SEAT BELT BUCKLE LATCHES OK
*	NA	CA	11001	VERIFIED SEAT BELT WARNING LIGHT & CHIME STAYS ON WITH SEAT BELTS BUCKLED. REMOVED DRIVERS SEAT TO INSPECT WIRING,OK. DISCONNECTED SEAT BELT SENSOR TO TEST. FOUND SENSOR HAS CLOSED SHORT CIRCUIT CAUSI
*	NA	AL	11001	7763 (CODE 42) REMOVED D SIDE FRONT SEAT TO ACCESS. REMOVED AND REPLACED D SIDE FRONT SEATBELT RETRACTOR AND REASSEMBLED. RETESTED OK.

*	NA	CA	11001	433 SEAT BELT NOT STAYING ATTACHED FOUND DRIVERS SEAT BELT NOT STAYING ATTACHED FOUND SEAT BELT BUCKLE NOT WORKING REMOVE SEAT TO ACCESS THE BUCKLE REMOVE OLD BUCKLE INSTALL NEW BUCKLE REINSTALL SEAT Q
*	NA	TX	11001	. D S BUCKLE COMES UNLATCHED WHILE DRIVING. INSPECT & REPLACE BUCKLE. WEAK LATCH SPRING.
*	NA	CA	11001	M TIME TO TEST & REPLACE DRIVERS SEAT BELT BUCKLE FOR WILL NOT LATCH CONCERN
*	NA	IA	11001	5031 WARR REMOVED AND INSTALLED DRIVERS FRONT SEAT BELT ASSEMBLY RECALL 01S21
*	NA	OH	11001	1779 INSTALLED DRIVER SIDE FRONT SEAT BELT BUCKLE
*	NA	FL	11001	10318 AIR BAG LIGHT FLASHING W REPLACE DRS SIDE SEAT BELT LATCH SOP PRETENSIONER FOR DRS SIDE C1878 CODE PRETENSIONER SHORTED TO BATTERY POWER
*	NA	TX	11001	4015 R&R DRIVERS SEAT. INSTALLED NEW SEAT BELT BUCKLE. TESTED. WORKS FINE AT THIS TIME
*	NA	TX	11001	R R FRONT CAPTAIN S CHAIR. REPLACED LEFT BUCKLE.
*	NA	TX	11001	REPLACED JAMMED BUCKLE
*	NA	CA	11001	NA CHECK OPERATION REMOVE & REPLACE SEATBELT BUCKLE.
*	NA	TX	11001	REPLACE DRIVER SIDE SEAT BELT AND LATCH ASSYMBLY
*	NA	TX	11001	5119 NGS TEST CK PID TEST RR DR SEAT AND REPLACE SEAT BELT BUCKLE WAS INOP
*	NA	TX	11001	2587 61203 C.C. 42 RESTRAINT SYS. DIAG. ACCESS DRIVER SEAT REPLACED DRIVER SEAT BELT BUCKLE
*	NA	AR	11001	BINDING REPLACED SEAT BELT ON DRIVER SIDE
*	NA	MO	11001	REPLACE SEAT BUCKLE USED IN CUST REPAIR
*	NA	TX	11001	9717 PERFORMED SEAT BELT DIAG; BUCKLE BROKEN; R&R SEAT BELT BUCKLE; ADJUSTED PASS REAR DOOR STRIKER; RETESTED DOOR AND BUCKLE OK

*	NA	NM	11000	NESS TO RR CENTER AND PASS BUCKLE ASSY
*	NA	MS	11001	REPLACE FRONT CENTER SEAT BELT.
*	NA	TX	11000	1 REPLACED SEATBELT
*	NA	TX	11000	REPLACED RIGHT SIDE SEATBELT BUCKLE
*	NA	OH	11001	REPLACED SEAT BELT T
*	NA	TX	11001	3229 42 M1 .3 .3 REPLACE CENTER BUCKLE ASSY.
*	NA	MO	11001	SEATBELT ASSEMBLY FRONT REPLACE (811A72 811A73)
*	NA	CA	11001	R&R RIGHT FRONT BUCKLE ASSEMBLY
*	NA	CA	11001	
*	NA	CA	11001	
*	NA	GA	11000	FLAWED BUCKLE REPLACED RIGHT REAR SEAT BELT
*	NA	OH	11000	REPLACE PASS SEAT BELT BUCKEL ASS FOR WILL NOT LATCH
*	NA	TX	11000	INOPERATIVE TRACK ASSEMBLY FRONT SEAT REPLACE
*	NA	OK	11001	FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11000	REPLACED SEAT BELT BUCKLE
*	NA	NC	11001	CHECK AND REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	TX	11000	
*	NA	IL	11001	REPLACED LEFT FRONT DRIVER'S SEAT BELT BUCKLE THAT KEEPS THE BELT MINDER LIGHT ON
*	NA	IL	11001	REMOVED DRIVERS SIDE SEAT BELT BUCKLE AND REPLACED WITH NEW ONE. RECHECKED OK.
*	NA	PA	11001	SEAT BELT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

*	NA	AB	11000	INSPECT,CENTER SEATBELT WILL NOT LATCH CORRECTLY,REPALCE SEATBELT ASSY AND RE TEST OPERATION OK.MT TIME NO LAB OP IN SLTS TO REPLCENTER BELT ASSY
*	NA	ON	12000	REPLACE RIGHT SEAT BELT BUCKLE (42)VERIFY CUSTOMER CONCERN REMOVE OLD BELT BUCKLE AND INSTALLED NEW ONE AND CK OPERATION GOOD
*	NA	AB	12000	BUCKLE JAMMED WONT BUCKLE TO BELT DEFECTIVE SEAT BELT BUCKLE REPLACED PAA SIDE BUCKLE VERIFIED CONCERN TESTED SEAT BELT WIRING FOUND SEAT BELT BUCKLE INTERNALLY OPEN R&R BUCKLE AND TESTED OPERATION NORMAL MTIME REQUESTED FOR ALL THE MENTIONED REPAIRS DONE DUE TO NO LABOR OPPTS FOUND
*	NA	WI	12000	
*	NA	AZ	01XXXX	
*	NA	TX	11000	8256 LOOSE PULL BENCH SEAT TO REPLACE DRIVERS SEAT BUCKLE TEST OK ***QUALITY CONTROL BY TIM HUDSON***
*	NA	LA	11000	16698 DR.SEATBELT LOCK BROKEN DIAG.SEATBELT BUCKLE INOP,REPL DRIVER SEATBELT LOCK ASSY.,RETESTED O.K.
*	NA	TX	11000	LFT FRT SEATBELT BINDING REPLACED SEATBELT ASSY.
*	NA	CA	11000	CENTER SEAT BELT ADDITIONAL MISC. REPAIRS
*	NA	FL	11000	RENEW DRIVERS SEAT BELT
*	NA	OH	11000	94 REPLACED SEAT BELT SPECIAL ORDERED
*	NA	MD	11000	59 SEAT BELT ASS WARR REMOVED AND REPLACED LEFT SIDE BUCKLE ASS.
*	NA	MD	11000	REPLACE DRIVER SEAT BELT BUCKLE WILL NOT LATCH
*	NA	TX	12000	1945 49 M1 .2 .2 REPLACE BUCKLE
*	NA	CA	12000	VERIVY CONCERN REPALCE PASSEMNGER SEAT BELT BUCKLE VERIFYREPAIR

*	NA	AR	12000	P.O.O.3 18 02 SEAT BELT ASSEMBLY
*	NA	TX	12000	8283 CC41 RIGHT FRONT BUCKLE WILL NOT LATCH. REMOVE AND REPLACE BUCKLE.
*	NA	TX	12000	REPLACED SEAT BELT BUCKLE PASSENGER SIDE
*	NA	CA	12000	RT FRONT SEAT BELT WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CT	12001	REMOVED LF SEAT AND REPLACED LF SEAT BELT BUCKLE,WOULD NOT LATCH.
*	NA	GA	11001	NEC TO REPLACE SEAT BELTS
*	NA	FL	11000	INSTALLED LEFT & RIGHT SIDE SEAT BUCKLE ASSEMBLIES,TESTED ALL FUNCTIONS AFTER THE REPAIR,ALL TO SPEC AT THIS TIME
*	NA	TX	11001	3310 TESTED BOTH FRT SEAT BELT BUCKLES,VERIFIED CONC ERN,ACCESS BOTH FRT SEAT & REPLACED BOTH FRT SE AT BELT BUCKLES.
*	NA	AB	11000	
*	NA	CT	11001	TEST OPERATION OF SEAT BELTS REMOVE AND REPLACE SEAT BELTS
*	NA	FL	11000	. INSTALLED SEAT BELTS BUCKLES
*	NA	CA	11000	REPLACE MISSING LAP BELT AND BUCKLE
*	NA	TN	11001	REPLACE SEAT BELT BUCKLE AND LAP STRAP.
*	NA	CA	12000	BOTH SEAT BELTS INOP REPLACE BOTH SEAT BOLTS
*	NA	IL	12000	SEAT BELT BUCKLE LATCHES BROKEN
*	NA	NJ	11000	SEATBELT LOCKS UP WHEN TRAVELING, REPLACED SEATBELT

*	NA	AZ	11001	INSPECTED DRIVERS SEAT BELT. CONNECTOR IS BROKEN. REPLACED SEAT BELT AND BUCKLE ASSEMBLIES. RE TESTED, OK MY78611B08 TIME TO REPLACED DRIVERS SEAT BELT AND BUCKLE ASSY. NO LABOR OPS AVAIL.
*	NA	FL	11000	BINDING COMPLETED INSTALL OF SEAT BELT PASSENGER SIDE
*	NA	KY	11001	11076 42 W 14B321, 7861203 VARIFIED AIR BAG MI FLASHING. NGS RETRIEVED B1821, B1878, B1869 CMDTC. ON DEMAND SELF TEST RCM MODULE B1821, B1878, B1869. PINPOINT TESTS AS1, AS2 DEACTIVATE BRACKET GRO
*	NA	CA	11000	DIAG INSP M TIME TO REPLACE BOTH SEAT BELT BUCKLES
*	NA	CA	11000	REPLACED LEFT SEAT BELT BUCKLE PER RECALL.
*	NA	FL	11000	1 INSPECT AND REPLACE BOTH FRONT SEATBELT BUCKLES
*	NA	MO	11000	REPLACED DRIVERS BUCKLE
*	NA	MO	11000	REPLACED BOTH FRONT BUCKLES
*	NA	CA	11000	REPLACED BOTH SEAT BELT BUCKLES PER RECALL
*	NA	AZ	11000	REPLACE DRIVERS LEFT FRONT SEAT BELT
*	NA	MO	11000	REPLACED RIGHT FRONT SEAT BELT BUCKLE
*	NA	TX	11000	580 W REPLACEDDRIVER SIDE SEAT BELT RETESTED ALL OK
*	NA	CA	11000	RECALL 01821

*	NA	MO	01XXXX	ASSEMBLY AS NEEDED
*	NA	CA	11000	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS
*	NA	OH	11000	COMPLETE RECALL
*	NA	CA	11000	RECALL 01S21
*	NA	NS	11001	TRACE CODE HAD CODE 46 B1877 INSTALL PRETENSIONER NEC TO R&R BACK OF SEAT DRIVERS SIDE & REPLACE BUCKLE
*	NA	OH	11000	01S21 SEAT BELT RECALL 01S21 SEAT BELT RECALL
*	NA	GA	11000	547174 5323 MILES REPLACED SEAT BELT BUCKLE
*	NA	CA	11000	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	CA	11000	01S21 G PASS BUCKLE RPL PASS BELT BUCKLE
*	NA	OH	11000	COMPLETE RECALL
*	NA	MD	11000	SEATBELT BUCKLE IS BINDING. REPLACED SEAT BELT ASSEMBLY.
*	NA	ON	11000	REPLACE SEAT BELT BUCKLE
*	NA	TX	11000	10159 LEFT SIDE SEAT BELT RECIEVER IN OP INSPECT FOUND SEAT BELT RECEIVER IN OP REPLACE RECEIVER ASSEMBLY OK AFTER REPAIR. CC 42
*	NA	TN	11000	LF SEATBELT BUCKLE FAILED TEST. OASIS SAYS NOT INVOLVED IN 01S21 RECALL. REPLACED LF SEAT BUCKLE AS SAFETY LIABILITY ISSUE. LISTED LABOR AS M TIME. NO OP# PUBLISHED.
*	NA	NJ	11000	SEAT BELT LITE ON AT TIMES BODY CHASSIS ELECTRIAL (BCE) TEST
*	NA	OH	11000	COMPLETE RTECALL PER FORD
*	NA	IN	11000	LEFT SIDE SEAT BELT BUCKLE STICKING REPLACED LEFT SIDE BELT BUCKLE
*	NA	OH	11000	COMPLETE RECALL
*	NA	CA	11000	REPLACE SEATBELT WILL NOT LATCH PROPERLY
*	NA	OH	11000	COMPLETE RECALL
*	NA	OH	11000	RECALL COMPLETE RECALL
*	NA	OH	11000	COMPLETE RECALL PER FORD

*	NA	NY	11000	CK ORDER AND REPLACE BELT ASSY
*	NA	OH	11000	COMPLETE RECALL
*	NA	ON	11000	REPLACE PASSENGER SEATBELT.
*	NA	CA	11000	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS
*	NA	CA	11000	SEATBELT WONT LATCH REPLACE SEAT BELT
*	NA	GA	11000	SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	11000	RECALL 01S21
*	NA	CA	11000	CC348 CLIAM 598495 SHOULD BE A SPW
*	NA	CA	11000	CCD30 DIAG, REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	CA	11000	RECALL 01S21
*	NA	CA	11000	RECALL 01S21
*	NA	CA	11000	RECALL 01S21
*	NA	AB	11000	FAULTY BUCKLE. CHK OPER OF DR SEATBELT BUCKLE.REPLACED BUCKLE ASSY. VERFIY REPAIR BY FUNCTIONALITY
*	NA	AZ	12000	M TIME TO REPLACE SEATBELT BUCKLE, NO TIME IN LTS
*	NA	CA	11000	RECALL 01S21
*	NA	NS	11000	TECH REPLACED BELT BUCKLE PASS SEAT, WAS STUCK DOWN
*	NA	PQ	01XXXX	VERIFIER FONCTIONNEMENT DES BOUCLES DE CEINTURE AVEC OUTIL DU RAPPEL 01S21... CEINTURE DEFECTUEUSE , REMPLACER CEINTURE GAUCHE
*	NA	KY	01XXXX	CHECKED AND REPLACED LEFT SEAT BELT BUCKLE
*	NA	SK	11001	LEFT FRONT SEAT BUCKLE DOES NOT BUCKLE PROPERLY. REPLACE LEFT FROTN SEAT BELT BUCKLE.

*	NA	CA	11000	SEAT BELT FAULTY REPLACE	SEATBELT ASSEMBLY FRONT
*	NA	TX	11000	REPLACED DRIVERS SEAT BELT BUCKLE	
*	NA	OH	11000	25 REPLACE BOTH FRONT SEAT BELTS AS PER RO	
*	NA	MI	11000	851 BELT BUCKLE BROKEN AND MOUNT BOLT HEAD IS STRIPPED TIME AS NESSY. TO REMOVE BOLT AND REPLACE RF BUCKLE MT .6 HRS	
*	NA	IN	01XXXX	TECH INSPECTED VEHICLE , CHECKED OPERATION AND SEAT BELT BUCKLE INOP WILL NOT LATCH. ORDERED NEW S.O.P TECH REMOVED DRIVER SEAT REMOVED AND REPLACED SEAT BELT BUCKLE CHECKED OPERATION OKAY. REINSTALLE	
*	NA	MO	11000	DEFECTIVE SEATBELT RECEIVER. DIAGNOSIS CHECKED AND REPLACED DRIVERS SEATBELT RECEIVER.	
*	NA	VA	11000	VERIFIED CONCERN AND FOUND THAT RIGHT SEAT BELT LATCH WILL NOT LATCH REMOVED RIGHT SEAT REMOVED CENTER SEAT BELT UNIT	
*	NA	ON	11001	CHECK FOR CONCERN & CHECK & REPLACE SESATBELT LATCH ASSEMBLY, RECHECK ALL OK.	
*	NA	PQ	11000	REPLACER CEINTURE AV DROITE	
*	NA	ON	11000	REPLACE P/S SEAT BELT BUCKLE	
*	NA	TX	11000	4811 SEAT BELT BUCKLE INOP DIAGNOSE REPLACE LR FRONT SEAT BELT BUCKLE ASY CC42 407	
*	NA	VA	11000	SWAPPED SEATBELTS	
*	NA	WV	0110XX	FOUND SEAT BELT LATCH CONNECTPOORRECONNECTED CONNECTION	
*	NA	WV	11001	R&R DRIVERS SEAT, REPLACE SEATBELT BUCKLE BROKEN	
*	NA	MO	01XXXX	REPLACE FRONT SEAT BELT AND BUCKLE CHECK OUT CHECK OVER SEAT BELT BUCKLE BOTH ARE BROKEN ON PASSENGER SIDE NEED TO REPLACE REPLACED SEAT BELT BUCKLE	
*	NA	AR	11000	MISSING BUCKLE ASSY. REPLACED DRIVERS SEAT SEAT BELT BUCKLE ASSY MISSING PART BASIC 62103 CODE 39	
*	NA	OH	01XXXX	THIS VEHICLE WAS DEALER TRADE FROM ANOTHER DEAL. WASN'T CORRECTED AT THERE DEALERSHIP	

*	NA	TX	11000	REPLACE RIGHT FRONT SEAT BELT BUCKLE
*	NA	IL	12001	REPLACE SEATBELT
*	NA	CA	11001	REPLACED L.F. SEAT BELT LATCH. DE
*	NA	TX	11001	RECALL INSPECT AND REPLACE SEAT BELTS BUCKLE
*	NA	OK	11001	INSTALL SEAT BELT
*	NA	CA	11001	FAILED DRIVERS SEAT BELT BUCKLE TEST REPLACE DRIVER SIDE BELT BUCKLE NO RECALL OP CODE REG WARRANTY
*	NA	SC	12001	CK AND REMOVED DRIVERS SEAT BELT BUCKLE ASSY AND REPLACED RECHECKS FINE
*	NA	CA	11001	
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	CA	12001	NO SEAT BELT IN VEHICLE. EXCHANGED PART FROM STOCK UNIT. PARTS ARRIVED AND A NEW SEAT BELT BUCKLE WAS INSTALLED.
*	NA	SC	11001	WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE
*	NA	CO	11001	REPLACE SEATBELT BUCKLE BINDING
*	NA	FL	11001	09 SEAT BELT RECALL .4 INSPECTED BOTH SEAT BELTS DRIVER FAILED. REPLAC ED DRIVERS SEAT BELT
*	NA	WI	11001	CHECK AND REPLACE RF SEATBELT BUCKLE PER RECALL
*	NA	GA	12001	SEAT BELT FAILED BODY CHASSIS ELECTRICAL (BCE) TEST
*	NA	LA	11001	3895 RR FRONT PASS. SEAT BELT BUCKLE, ORDERED REAR PASS. SEAT BELT BUCKLE
*	NA	NC	11001	REPLACED LEFT SIDE SEAT BELT
*	NA	CA	11001	RECALL 01S21
*	NA	TX	12000	1 CHECK FRONT PASS SIDE SEAT BELT BUCKLE IS VERY HARD RO RELEASE.REMOVE AND REPLACE RIGHT FRONT SEATBELT BUCKLE.
*	NA	CA	11001	REPLACED BOTH SEAT BELT BUCKLES
*	NA	CA	11001	REPLACED SEAT BELT
*	NA	TX	11001	78812B18 ANCHOR REPLACE SEAT BELT BUCKLE RIGHT FRONT

*	NA	CA	11001	11 INSPECT AND REPLACE 2 SEATBELT BUCKLES. 80 40 SPLIT BENCH WITH NO POWER OR SIR.
*	NA	SC	11001	WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AZ	11001	REPLCE COMPLETE
*	NA	SD	11001	VERIFIED CONCERN CHIME WENT ON WITH BUCKLE HOOKED CIRCUR TEST SEAT BELT WARNING SYSTEM REPLACE DRIVERSEAT BELT BUCKLE OPEN CIRCUIT IN BUCKLE WIRING
*	NA	CO	11001	989A TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	TX	11001	INSPECTED AND REPLACED FAILED RF SEAT BELT BUCKLE.
*	NA	CA	11001	RECALL INSPECT AND REPLACED TWO SEAT BELT BUCKLES.
*	NA	FL	11001	RR RIGHT SEAT AND REPLACE BUCKLE ASSY
*	NA	CA	11001	DIAG INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT BUCKLE
*	NA	FL	11001	SEAT BELT INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	MO	11001	REPLACE ONE SEAT BELT
*	NA	TX	11001	R I SEAT TRACK TO REPLACE SEAT BELT
*	NA	CA	11001	21 CHECK AND INSPECT PERFORMED RECALL 01S21 RMOVE AND REPLACE FAIL BOTH FRONT SEAT BELT BUCKLE END RELEASE ASSY. 21
*	NA	TX	11001	SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	11001	PERFORMED RECALL 01S21 REPLACED BOTH FRONT SEAT BELT BUCKLES OUT MILEAGE 5404
*	NA	OH	11000	COMPLETE RECALL
*	NA	CA	12000	REPLACE REAR BELT BUCKLE. PASSENGER SIDE.

*	NA	WI	11001	CHECK OUT, CONFIRMED SEAT BELT INOP, REPLACE AND RETEST
*	NA	TX	11001	SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	11001	3911 WARR VERIFY CONCERN NGS DIAG TO MONITOR PIDS FOUND DRIVER SEAT BELT NOT SHOWING SEAT BELT NOT BUCKLED. PERFORMED PPT. FOUND SEAT BELT BUCKLE INOP RR BUCKLE RETEST AND QUALITY INSPECTED BY #711
*	NA	FL	12001	VEYFY AND TEST NECESSARY TO REPLACED BUCKLE
*	NA	TX	12000	VERIFY CONCERN CENTER BUCKLE WOULD NOT LATCH AND RT REAR REPLACED CENTER BUCKLE AND RIGHT REAR SEATBELT BUCKLES
*	NA	FL	11001	REPLACE SEAT BELT.
*	NA	FL	11001	09 SEAT BELT RECALL .4 INSPECTED BOTH SEAT BELTS PASS FAILED.REPLACED PASS SEAT BELT.
*	NA	WI	12001	CHECKED BUCKLES DID GEM TEST NEEDS DRIVERS FRONT SEAT BUCKLEREPLACED THE BUCKLE OK NOW
*	NA	MD	12001	189 CHIMEING SEAT BELT WARR REPLACED SEAT BELT BUCKEL CHIMES WHEN SEAT BELT NOT BUCHELED DOES NOT CHIME WHEN SEAT BELT IS BUCKLED
*	NA	OK	12000	BINDS SEATBELT ASSEMBLY FRONT REPLACE
*	NA	OK	11001	SEATBELT INOP CENTER SEAT BELT ASSEMBLY
*	NA	NC	11001	BELT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	REPLACE RIGHT HAND SEAT BELT BUCKLE, 42.
*	NA	LA	11001	CK AND FOUND SEAT BELT BUCKLE BAD AND REPLACE SEAT BELT BUCKLE AND RECHECK
*	NA	CA	11001	11 INSPECT AND REPLACE 2 SEATBELT BUCKLES. POWER BUCKET, SLIDING BUCKET. NO SIR.

*	NA	TX	11001	SEAT BELT NOT OPERATING PROPERLY VERIFIED AND R AND R SEAT BELT ANCHOR RETESTED AND CHECKED OK AT THIS TIME
*	NA	CA	11001	FOUND INOP SEAT BELT HAD TO REMOVE DRIVERS SEAT TO REPLACE BELT BUCKLE
*	NA	CA	11001	RECALL 01S21
*	NA	ON	12001	REPLACED DRIVERS SIDE SEATBELT BUCKLE
*	NA	CA	11001	REPLACED BOTH FRONT SEAT BELT BUCKLES PER RECALL.
*	NA	CA	11001	
*	NA	CO	11001	INTERNAL FAILURE IN BUCKLE REPLACED RT AND LT SEAT BELT BUCKLES
*	NA	AZ	11001	REPLACED SEAT BELT
*	NA	LA	11001	REPLACED SEATBELT ALL OK
*	NA	CA	11001	RECALL 01S21
*	NA	TX	11000	NOT LATCHING REPLACED PASSENGER SIDE BUCKLE
*	NA	TX	11001	REPLACE SUPER CREW BUCKET SEAT BUCKLE INOP
*	NA	CA	11001	INOP REPLACE ONE SEAT BELT
*	NA	TX	11001	CC42 DOES NOT OPERATE PROPERLY MILES IN 1765 MILES OUT 1767 TEST FRONT CENTER SEATBELT BUCKLE OPERATION FOUND BUCKLE WOULD NOT EXCEPT THE SEATBELT INSERT INSPECTED BUCKLE FOR
*	NA	TX	11001	REPLACED SEAT BELT BUCKLES
*	NA	CO	11001	REPLACED FRONT SEATBELT ASSY
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE
*	NA	IA	11001	REPLACE PASSENGER BUCKLE, MT NO PUBLISHED LABOR OP
*	NA	LA	11001	9 INSPECTED SEAT BELTS, FAUILTY PREFORMED
*	NA	CA	11001	RECALL,REPLACED SEAT BELT
*	NA	LA	11001	CONFIRMED NEC TO REPLACE OT CORRECT
*	NA	LA	11001	8 INSPECTED SEAT BELTS , FAUILTY PREFORMED RECALL, REPLACED SEAT BELT

*	NA	FL	11000	BROKEN	REPLACE LEFT SEAT BELT BUCKLE
*	NA	TX	11001	REPLACED SEAT BELT WITH NEW	
*	NA	AZ	11001	20393 VERIFIED PASS FRONT SEAT BELT RECEIVER IS INOP,REPLACED PASS SEAT BELT RECEIVER (40 60)ALL FUNCTIONS NORMAL. REPAIR SUBMISSION DELAYED DUE TOPARTS NOT AVL. REPAIR COMPLETED 6 13 02 AT 20393 MI	
*	NA	WI	12000	RIGHT SIDE BUCKLE NOT LOCKING	M TIME TO REPLCE RIGHT SIDE BUCKLE ASSY
*	NA	AZ	11001	1	REPLACED DRV.BUCKLE.
*	NA	WI	11001	R & R R & LF SEATBELT BUCKLES.	WPI.
*	NA	CA	11001		
*	NA	FL	11000	REPLACED SEATBELT BUCKLE	
*	NA	TX	11001	VERIFY FAULTY SEAT BELT BUCKLE REPLACED RIGHT SIDE SEAT BELT NOW OPERATING PROPERLY	
*	NA	MO	11001	SEAT BELT RECEPTACLE PASSENGER BELT WONT STAYED LATCHED CC 42 REPLACED PASSENGER SEAT BELT	
*	NA	OH	11000	COMPLETE RECALL	
*	NA	IN	11001	MT; TIME TO REPAIR SEAT BELT BUCKLES ON SEATS.	
*	NA	SC	11001	01S21B	01S21B
*	NA	OH	11000	COMPLETE RECALL	
*	NA	MN	12000	11110 ORDERED SEAT BELT BUCKLE REMOVED OLD SEAT BELT AND INSTALLED NEW. TESRED AND FOUND GOOD.	
*	NA	IL	12001	SAFTEY BELT CHIMES INTERMITTENT REPLACED DRIVERS SIDE SAFETY BELT BUCKLE ASSEMBLY	
*	NA	KY	11001	TEST W NGS REPLACED SEAT BELT BUCKLE	
*	NA	OH	11001	01S21 COMPLETED	
*	NA	OK	11001	REPLACED RIGHT FRONT SEATBELT BUCKLE	
*	NA	MN	12001	4892 REPLACED SEAT BELT BUCKEL (NOT A RECALL)	

NA	AL	12000	REPLACE RT FRONT SAFTY BVELT BUCKLE ASSY. INOP
NA	TX	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
NA	CA	11001	CC348.. PERFORMED 01S21 SEATBELT RECALL
NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
NA	TX	11001	REPLACED SEAT BELT WITH NEW
NA	NM	11001	BUCKLE JAMMED, WILL NOT ACCEPT BUCKLE TONGUE.
NA	CA	11001	REPLACE BELT ASSY.
NA	WI	11001	SEAT BELTS WILL NOT LATCH REPLACE SEAT BELTS
NA	VA	11001	REPLACED THE RIGHT SIDE SEATBELT BUCKLE THAT DOES
NA	AZ	12001	NOT LATCH.
NA	CA	11000	REPLACED SEATBELT. 1
NA	CA	11001	BELT R & R BINDING PANSSENGER FRONT
NA	CA	11001	BELT BUCKLE DEFECTIVE VERIFY CONCERN. INSTALL SPECIAL
NA	TX	11001	ORDERED SEAT BELT BUCKLE AND BOLT
NA	TX	11001	14340 RF SEAT BELT BUCKLE BAD WARR VERIFIED
NA	CA	11001	CONCERN. FOUND RF SEAT BELT WOULD NOT LATCH.
NA	CA	11001	TESTED AND FOUND SEAT BELT BUCKLE BAD. REPLACED RF
NA	TX	11001	SEAT BELT BUCKLE ASSY. RETESTED. ALL OK AT THIS TIME
NA	TX	11001	RIGHT SEATBELT WILL NOT LATCH SEATBELT ASSEMBLY
NA	TX	11001	FRONT REPLACE
NA	TX	11001	WOULD NOT LATCH SEATBELT ASSEMBLY FRONT
NA	TX	11001	REPLACE SEAT BELT BUCKLE
NA	CA	11001	BAD SEAT BELT BUCKLE ROADTEST, PERFORMED
NA	FL	11001	ELECTRICAL TEST R & R BUCKLE, RETEST.
NA	TX	12000	INOP REPLACED SEAT BELT BUCKLE
NA	TX	11000	SEAT BELT BUCKLE WONT LATCH REPLACED THE PASS SIDE
NA	SC	11000	FT SEAT BELT BUCKLE
			DIAG AND REPAIRED OPEN CIRCUIT TO CONECTOR AT SEAT
			BELT

*	NA	FL	12001	OPEN SEATBELT ASSEMBLY FRONT REPLACE FRONT REPLACE
*	NA	AR	12000	10187 ***** G.P REPLACE PASS FRONT SEAT BELT BUCKLE ASY WOULD NOT BUCKLE
*	NA	CA	11001	NEC TO RPELACE BOTH TO CORRECT
*	NA	CA	11001	REPLACED RIGHT SIDE SEAT BELT BUCKLE PER 01S21.
*	NA	TX	12001	DAMAGED WIRE ON SEAT BELT BUCKLE REPLACED SEAT BELT BUCKLE ON DRIVER SIDE SEAT
*	NA	CA	11001	NEC TO RPLACE BOTH TO CORRECT
*	NA	ND	12000	CK OUT REPLACE BUCKLE
*	NA	ND	12000	CK OUT REPLACE BAD LATCH ASSY
*	NA	ND	11000	CK OUT REPLACE BAD SEAT BELT
*	NA	NJ	11001	REPLACED DRIVERS SEAT BELT
*	NA	FL	11001	14 VERIFIE FOUND PASS SEAT BELT INOP REPLACED
*	NA	TX	11001	REPLACED SIDE BUCKEL WITH NEW
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	CA	12001	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELT
*	NA	TX	11001	
*	NA	CA	12000	INSTALLED SOP SEAT BELT BUCKLE
*	NA	CA	11000	REP BUCKLE ASSEY
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	TX	11000	8051 REPLACED PASSENGER SEAT BELT LATCH + TEST. *** QUALITY CONTROL BY JOHN MEDROW ***
*	NA	GA	12001	CHECKED AND REPLACED LEFT FRONT SEATBELT BUCKLE TO CORRECT CONCERN.
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	AR	12000	CENTER BELT BUCKLE WONT LATCH TIME IN TO R&R NEW CENTER SEAT BELT BUCKLE ASSY.
*	NA	NC	11000	MT TO REINSTALL CLIP
*	NA	FL	11001	REPLACED DRIVER SIDE SEATBELT
*	NA	MO	12000	REPLACE PASSENGER FRONT SEAT BELT BUCKLE

*	NA	CA	11001	REMOVE NAD REPLACE FAIL R.F SEAT BELT BUCKLE END RELEASE ASSY.
*	NA	CA	11001	REPLACE SEATBELTS WILL NOT LATCH PROPERLY
*	NA	CA	11001	REPLACE SEAT BELT BUCKLE. WILL NOT LATCH
*	NA	CA	12001	REMOVE RIGHT SEAT TO REPLACE RIGHT BUCKLE PER RECALL
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	AR	12001	ADDITIONAL MISC REPAIRS DO NOT USE WITH ANY OTHER LABOR OPERATIO N
*	NA	LA	11001	BUCKLE WILL NOT LATCH REPALCED CENTER SEAT BELT BUCKLE
*	NA	MO	12001	REMOVED DIRVERS SIDE SEAT REPLACED SEAT BELT LATCH FOR HARD TO UNLATCH
*	NA	LA	11001	REPLACE DR SEATBELT
*	NA	WI	11001	CHECK AND REPLACE SEATBELT BUCKLE PER RECALL
*	NA	CA	11001	DIAG INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT BUCKLE
*	NA	TX	11001	CHECK SEAT BELT OPERATION WILL NOT LATCH NEC TO REPLACE SEAT BELT LATCH
*	NA	MN	12001	REPLACE LEFT FRT SEAT BELT WILL NOT LATCH
*	NA	TX	11001	1 REMOVED AND REPLACED LEFT FRONT SEAT BELT BUCKLE,RECHECKED OK
*	NA	AL	11001	REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	CA	11001	REPLACED DRIVERS SEAT BELT BUCKLE
*	NA	TX	11001	SEAT BELT BUCKLE WILL NOT LATCH
*	NA	OH	11000	INSPECTED AND DOES NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE AND RETESTED OK.
*	NA	OH	12000	BUCKLE WILL NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE.
*	NA	IA	11001	REPLACED DR SIDE SEAT BELT DUE TO INSIDES COMING OUT AT TIMES
*	NA	CA	11001	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
*	NA	CA	11001	REPLACE LEFT SEATBELT BUCKLE D
*	NA	TX	12000	BUCKLE WILL NOT LATCH R&R FRONT RIGHT BUCKLE ASSY

*	NA	WI	11001	CHECK AND REPLACE LEFT FRONT SEATBELT
*	NA	GA	11001	REPLACED D SIDE SEAT BUCKLE
*	NA	TX	11001	BCE DIAG,PINPOINT,REPLACED BUCKLE ASSY AND RETEST
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE
*	NA	GA	11001	RECALL 01S21 RECALL REPLACE SEAT BELT BUCKLE
*	NA	TX	11000	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	FL	11000	BROKEN REPLACE SEATBELT BUCKLE
*	NA	TN	12001	REPLACE SEATBELT SENSOR REPLACE SEATBELT SENSOR
*	NA	CA	11001	10824 M TIME .6 M TIME NO OPS FOR SUPER CREW TO REPLACE DRIVERS SEAT BELT BUCKLE. BUCKLE IS INTERNALLY JAMMED QC BY TECH
*	NA	NE	11001	2276 BASIC 7861203 CONDITION 41 REPLACED THE INTERMITANTLY STICKING L F SEATBELT BUCKLE
*	NA	GA	11001	31802 C K R&R LT FT SEAT TO REPLACE SEAT BELT VCC INSPECTED SEAT BELT FOUND THAT THE BUCKET WAS JAMED. REMOVED FRONT SEAT AND REMOVED AND REPLACED LEFT FRONT SEAT BELT. CHECEKED TO VERIFY REPAIR
*	NA	TX	12001	
*	NA	TX	11001	REPLACED SEAT BELT WITH NEW
*	NA	CA	11001	51 REPLACE BUCKLE
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11001	
*	NA	TX	11001	1 REPLACE RIGHT FRONT SEAT BELT.
*	NA	TX	11001	33 01S21 O 0.4 INSP AND ERPL P SIDE SEAT BELT
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11001	VERIFY CONCERN FOR SEAT BELT RELEASE BUTTON SITCKS. REMOVED & REPLACED SEAT BELT BUCKLE.

*	NA	TX	12001	1127 RAN NGS TO CHECK FOR CODE NO CODE. RAN ON DEMAND TEST PASSED. RAN PINPOINT CHECK SEAT BELT BUCKLE SWITCH AND FOUND ITS STICKING INTERMITTENTL Y. REMOVE DRIVER SEAT. REPLACE DRIVER SEAT BELT BUC
*	NA	AZ	11001	NGS BCE TEST NO CODES MONITORED PIDS FOUND DRIVERS BELT BUCKLE STUCK OPEN AND NOT WORKING PROPERLY R&R BUCKLE TESTED OPERATION GOOD
*	NA	ON	12001	R & I LEFT FRONT SEAT & REPLACE BELT BUCKLE. RUN WDS, PID MONITOR, DRIVERS SEATBELT NOT CORRESPONDING WITH ACTION GIVEN. REMOVE DRIVERS SEAT TO CHECK CONNECTIONS, GOOD. WDS TO CHECK SEATBELT MODULE ACTION, GOOD. COMPONENT TEST SEATBELT FAILED. R
*	NA	NM	11001	RAN TESTS ON SYSTEM AND FOUND THE BUCKLE BAD ORDERED A NEW BUCKLE WE WILL CALL WHEN THE PART COMES IN REPLACED THE SEAT BELT BUCKLE OK NOW
*	NA	WI	12001	TESTED AND VERIFIED.REPLACED FAILED BUCKLE.
*	NA	OR	12000	5717 FEMALE END BROKEN W INSPECTED SEAT BELT AND FOUND IT BROKEN. PARTS ON ORDER FROM FORD. STILL WAITING ON RIGHT PARTS. PARTS CAME IN. R&R MIDDLE BELT FEMALE END. TESTED OK. CHECKED ALL OTHER BEL
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11001	SEAT BELT BINDING. CK. OP OF SEAT BELT INTERMITTEN BINDING. REPLACE SEAT BELT ASSY.
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11001	
*	NA	TX	12001	VERIFIED CONCERN, SEAT BELT BUCKLE INOP, REPLACED LEFT FRONT SEAT BELT BUCKLE, FIXED VEHICLE

*	NA	PA	11001	SEAT BELT BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE
*	NA	MO	11001	13588 253 CHECK FOR CODES WITH WDS FOUND NO CODES PERFORMED ON DEMAND TEST FOR SEAT BELT FOR SENSER INTERMITTING IN SEAT BELT ORDERED SEAT BELT PART DID NOT HAVE PER MARK C 253 253 REMOVED SEAT AND
*	NA	ON	11001	INSTALL REAR SEATBELT.
*	NA	OH	12000	REPLACE SEAT BELT BUCKEL
*	NA	AR	11001	SEAT BELT RELEASE BINDING SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	INOPERATIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	TX	11000	CENTER SEAT BELT NOT BOLTED TOP FLOOR 42 INSTALL CENTER SEAT BELT S40
*	NA	TX	11001	LIGHT STAY ON REPLACED SEAT BELT BUCKLE DRIVER SIDE
*	NA	LA	0110XX	POOR CONNECTION AT SEAT BELT CONN CLEAN AND RECONNECT SEAT BELT CONNECTOR DRIVERS SIDE
*	NA	TX	12000	INSP RECIEVERS, PASS. SIDE DEFECTIVE. REPLACED BUCKLE, CHECKED OPERATION, MIDDLE LAP BELT HAD INCORRECT BELT. REPLACE BELT AND RETEST BELT OPERATION
*	NA	SC	11001	REPLACED DRIVERS SIDE SEATBELT BUCKLE
*	NA	TN	11001	SEAT BELT ALARM WAS GOING OFF WHEN SEAT BELT WAS PLUGGED IN. REPLACED DRIVERS SIDE SEAT BELT LATCH.
*	NA	MO	12000	3798 612B18 BUCKLE, 42 DNOP CONFIMRED CONCERN OF PASSENGER SIDE SEAT BELT BUCKLE INOP ON 80 40 SPLIT SEAT. REPLACED PASSENGER SIDE BUCKLE ASY. CUST CONCERN NO LONGER PRESENT.

*	NA	TX	11000	VERIFIED CONCERN, FOUND ALL THREE SEAT BELT BUCKLES IN REGULAR CAB FAILED SEAT BELT BUCKLE TESTS. REPLACED DRIVER SIDE, PASSENGER, AND CENTER SEAT BELT BUCKLE ASSEMBLIES. RETESTED NORMAL AFTER REPAIRS
*	NA	AR	11000	OUT OF ADJUSTMENT ADDITIONAL MISC. REPAIRS
*	NA	TX	11001	1961 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL *****QUALITY CONTROL BY JAMES PENNOCK*****
*	NA	TX	11001	832 NOT STAYING LATCHED REPLACED BOTH FRONT SEAT BELT BUCKLES DUE TO NOT STAYING LATCHED. *****QUALITY TESTED BY LOUIS TREVINO*****
*	NA	AZ	12000	42 TEST SEAT BELT BUCKLE INTERMITTENTLY NOT LOCKING CHANGED SEAT BELT OUT
*	NA	AZ	12000	62 SPW R&R SEAT BELT BUCKLE
*	NA	AZ	11000	BROKEN CC 01 REPLACED CENTER SEAT BELT
*	NA	TX	11001	REPLACED SEAT BELT BUCKLE REMOVED PASSENGER BELT ONTO VEHICLE 274087 TO FINISH DRIVERS FAILED ISNTALLED DRIVER BELT INSTALLED BELT ON PASSENGER SIDE THAT WAS ORDERED TECH 614 0211
*	NA	OH	11001	REPLACED DRIVER SIDE SEAT BELT BUCKLE
*	NA	WI	11001	46 SEAT BELT BUCKLE REMOVED RIGHT FRONT SEAT BELT BUCKLE FROM STOCK UNIT # 121115 AND INSTALLED IN VEHICLE. HAD TO ORDER SEAT BELT BUCKLE FOR # 121115
*	NA	CA	11001	01S21 O SEAT BELT BUCKLE REPLACE PASS. SEAT BELT BUCKLE
*	NA	TX	11001	CC 01 BPN 78612B18 PASSENGER SEAT BELT BUCKLE WOULD NOT STAY LATCH. REPLACED BUCKLE AND RETEST PROVED OK.

*	NA	AZ	12001	OPEN CIRCUIT IN DRIVERS SEAT BELT ASSEMBLY NGS TEST PID MONITOR AND RECORD REMOVED DRIVER SEAT AND SEAT BELT ASSEMBLY INSTALLED NEW ONE CHECKED CODES, NONE IN RESTRAINT SYSTEM. LIGHT FLASHES WITH BELT BUCKLED. CHECKED PIDS, ORDERED LEFT SEAT BELT LATCH ASST. REPLACED LATCH ASSY WHEN PARTS CAME IN.
*	NA	IA	12001	DIAGNOSE SEAT BELT LIGHT ON OPEN IN SESAT BELT BUCKLE ASSY R & I SEAT ASSY TO ACCESS AND REPLACED SEAT BELT BUCKLE ASSY CODE 28
*	NA	NM	11001	SEAT BELTS WILL NOT LATCH PROPERLY REPLACE SEATBELT
*	NA	CA	11001	REPLACE BELT AND BUCKLE ASSY
*	NA	TX	11001	BUCKLE INOP R R L H BUCKLE
*	NA	NM	11000	CHECK AND R AND R THE LF SEAT BELT BUCKLE ASSY
*	NA	PA	11001	CHECK AND DIAG CONCERN REPL L F SEATBELT ASSY. RECHECK OK NOW
*	NA	PA	12001	NEC TO REPLACE BOTH TO CORRECT
*	NA	CA	11001	1 CHECK DRIVERS SEATBELT BUCKLE IS INTERMITTING INOP. REPLACE DRVIERS SEAT BELT BUCKLE.
*	NA	TX	11001	RECALL REPLACE FEMALE END OF SEATBELT
*	NA	FL	11001	DIAG GEM MODULE PINPOINT SYSTEM PASS (NO CODES)
*	NA	AZ	11001	MONITOR BUCKLE PIN IS NOT SWITCHING REPLACE L F SEAT BELT BUCKLE INOP
*	NA	CO	11001	WARNING SWITCH FAILURE TEST SYSTEM AND REPLACE DRIVERS SIDE SEATBELT BUCKLE
*	NA	WA	12001	114 CHECK LEFT FROM BELT BUCKLE HAS BRAKEN LATCH ME CHANISM REPLACE LATCH ASSEMBLY
*	NA	NC	11001	AIR BAG RESTRAINT SYSTEM DIAGNOSIS DO NOT USE WITH OPERATION 12651D
*	NA	NC	11001	PINCHED DAMAGED WIRE BODY CHASSIS ELECTRIAL (BCE) TEST REPLACE SEAT BELT ASY

*	NA	NY	12000	VERIFIED CUSTOMERS COMPLAINT, FOUND RIGHT SIDE SEAT BELT BUCKLE NOT CATCHING. REPLACED SEAT BELT BUCKLE, VERIFIED REPAIR.
*	NA	CA	11001	FRT BELT BUCKLE DOES NOT LOCK SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	12001	BUCKLE WAS SHORTED OUT. ABNORMAL DIAG. NGS TEST, PIN POINT TEST, TRACE THE WIRING FROM THE SEAT AREA TO THE GEM MODULE. ALL OF THE WIRING WAS
*	NA	GA	11001	PINPT TEST PER MANUAL FOUND BUCKLE BAD R&R BUCKLEAND REPLACE
*	NA	VA	11001	INSPECT TEST AND MONITOR AND REPLACE BUCKLE ASSY AND RETST
*	NA	TX	11001	1188 REPLACE PASS SIDE SEAT BELT BUCKLE
*	NA	NM	11001	R AND I LEFT SEAT BELT BUCKEL AND REPLACE
*	NA	NY	12000	0 CUSTOEMR STATES SEAT BELT WILL NOT ENGAGE CONFIRMED CUSTOMERS COMPLAINT SEAT BELT WILL NOT ENGAGE DUE TO SEAT BELT RETAINER IS JAMMED REPLACED RETAINER AND CHECKED OPPERATION O.K. INSTALLED ORDE
*	NA	FL	11001	10368 VERIFY CUSTOMER COMPLAINT.INSPECT RT FT SEAT BELT BUCKLE,FOUND LATCH IN BUCKLE BAD.REMOVE AND REPLACE RT FT SEAT BELT BUCKLE.CC 42
*	NA	TX	12000	PASS. SEATBELT INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	CHECK FOR RECALLS, NO RECALLS, SAFETY BELT LATCH SWITCH NOT WORKING PROPERLY, REPLACE SEAT BELT
*	NA	ON	11001	REPLACE SEAT BELT RELEASE ON RIGHT SIDE
*	NA	TX	11001	7976 STICKING 81172AB .4 .40 REPLACED R F SEATBELT BUCKLE
*	NA	TX	11001	PASSENGER SIDE SEAT BELT FAILED, REPLACED SEAT BELT

*	NA	MN	12000	1 REPLACED RIGHT FRONT SEAT BELT BUCKLE.
*	NA	MO	12000	SEATBELT INOP. REPLACED RIGHT FRONT SEAT BELT BUCKLE.
*	NA	MO	11001	FRONT CENTER SEATBELT INOP. REPLACED FRONT CENTER SEATBELT AND BUCKLE.
*	NA	TN	11001	CKD AND FOUND SEATBELT WARNING CHIME STAY ON TESTED AND FOUND SEAT BELT BUCKLE SWITCH INOP R AND R BUCKLE AND RETEST OK
*	NA	GA	12000	C SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	CA	11000	REPLACE SEAT BELT BUCKLE
*	NA	CA	12001	NEC OT REPLACE SEAT BELT
*	NA	CA	11000	SEAT BELT WONT LATCH REPLACE SEATBELT
*	NA	TX	11001	R&R SEAT TO REPLACE SEAT BELT ASSY INTERNAL FAILURE
*	NA	CA	11001	12 RECALL 01S210 0.4 HRS TECH 5170 INSPECT & REPLACE DRIVERS SEAT BELT
*	NA	OK	11001	REPLACE BELT BUCKLE ASSY ON DRIVERS SIDE
*	NA	CA	12000	INSPECT RIGHT FRONT SEAT BELT FOR WILL NOT BUCKLE. NEED BUCKLE SPRING IS JAM . REMOVE AND REPLACE SEAT BELT BUCKLE. DONE
*	NA	CA	12001	CHECKED FOR CODES PP TEST LEAD TO OPEN CIRCUIT AT DR SIDE BELT BUCKLE
*	NA	CA	11001	CHECK AND REPLACE BUCKLE
*	NA	NM	11001	NOT WORKING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	CA	11001	VERIFIED CONCERN,REMOVED DRIVERS SEAT FOR ACCESS,INSPECTED WIRING FRM BUCKLE UNDER CARPET,FD WIRING INSULATION CUT SHORTED OUT BUCKLE,ORDERED NEW BUCKLE,VECHICLE SAFE TO DRIVE INSTALLED NEW BUC
*	NA	AZ	11001	RIGHT FRONT SEAT BELT BUCKLE BINDING. REPLACE. RETEST. OK

*	NA	GA	11001	SEAT BELT CHIME STAYS ON ALL THE TIME WARR CC 28 TECH 195212 MILEAGE OUT 11358 TEST WITH NGS KOEO NO CODES MONITOR PIDS FOUND DRIVERS SEAT BELT ON SHOWING LATCHED REPLACE DRIVERS SEAT BELT BUCKLE RETE
*	NA	TX	11001	28 RPL DRIVERS SEATBELT BUCKLE FOR OPEN RETEST
*	NA	MO	12001	13 REPLACED SO SEAT BELT BUCKLE. QC SMC
*	NA	NM	11001	28 OPEN CIRCUIT. DIAGNOSIS TESING WITH WDS ONSEAT BELTS AND CIRCUIT. SEFT TESTS. DTC ON DRIVER SIDE BELT CIRCUITR, OPEN AT TIMES.
*	NA	AZ	11001	REPLACE RIGHT FRONT SEAT BELT BUCKLE
*	NA	CA	11001	DIAG WHY RIGHT SEAT BELT WONT UNLATCH BUCKLE IS BROKEN REPLACE RIGHT FRONT SEAT BELT ASSEMBLY
*	NA	CA	11001	REPLACED THE SEAT BELT BUCKLE
*	NA	CA	11001	SEAT BELT CHIME REPLACE DRIVER BELT ASSY
*	NA	CA	11001	SEAT BELT REPLACED SEAT BELT BUCKLE
*	NA	TN	11001	10163 BELL RINGS RNR SEAT BELT BUCKLE ON DRIVERS SEAT SS 4811
*	NA	MO	11000	INSTALL SEAT BELT
*	NA	CA	11001	NGS TEST NO CODE PINPOINT TEST, REPLACED SEAT BELT BUCKLE WIRING SHORTED TO SEAT TRACK M TIME IS FOR REPLACING BUCKLE
*	NA	MO	11001	SEAT BELT PRETENSIONER BAD MT TIME NGS TEST PID MONITOR R & R DRIVERS SEAT BELT BUCKLE
*	NA	TX	12001	4486 61202.01 BROKEN R R PASS FRONT SEAT REPLACED PASS SEAT BELT BUCKLE TEST, OK
*	NA	GA	11001	SEATBELT SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NY	11001	SEAT BELT ALRM INTERMITTENT AIR BAG RESTRAINT SYSTEM DIAGNOSIS

*	NA	AB	12000	REPLACE PASS SIDE SEAT BELT BUCKLE HAD TO SWITCH CENTRE BUCKLE OVER TO WORK IN NEW BUCKLE ASSEMBLY CHECK OPERATION AFTER REPAIR ALL O.K.
*	NA	FL	12001	10454 MO B4 BUCKEL ELECT CK AND REPL DRIVERS SEAT BELT BUCKEL AND RECK
*	NA	TX	12000	3341 SEZAT BELT BUCKLE BROKEN 01 WRT PERFROMED VERIFIED OCNCENR AND PERFROMED REMOVED AND REPLACE SEAT BELT BUCKLE ADMP PART ORDERED
*	NA	TX	11001	215 CC42 MT .8 .80 REPLACED L F SEATBELT BUCKLE. RETEST OK
*	NA	CA	11001	5424 SEAT BELT LAMP FLASHING CHECKED AND VERIFIED SEAT BELT LAMP FLASHING WHEN SEAT BELT WAS LATCHED. PERFORMED NGS HOOKUP. ACCESSED RESTRAINT MODULE AND PERFORMED SELF TESTS. ACCESSED GEM MODULE AN
*	NA	LA	11001	REPLACE FRT SEAT BELT BUCKLE
*	NA	KS	11001	42 REPL PASS SIDE SEATBELT BUCKLE
*	NA	MI	12000	BROKEN LATCH RT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NC	12001	REPALCED SEAT BELT BUCKLE
*	NA	TX	12000	VERIFIED CONCERN R R SEAT BELT BUCKET TO FIX CONCERN
*	NA	AZ	11001	RR SEATBELT INOP
*	NA	ND	12001	3922 REMOVE REAR SEAT, REPLACE THE SEAT BELT BUCKLES REMOVE FRONT SEATS AND TURN TO THE SIDE, REPLAC E BOTH FRONT SEAT BELT BUCKLES. RIGHT REAR BUCKLE WAS BROKE AND THE REST WERE STICKY
*	NA	ME	11001	10808 REM AND REP SEAT BELT BUCKLE
*	NA	TX	11001	BINDING BUCKLES. R&I BOTH FRONT SEATS TO REPL BOTH SEAT BELT BUCKLES.
*	NA	TX	11001	REPLACE SEAT BELT BODY CHASSIS ELECTRIAL (BCE) TEST

*	NA	IL	11000	REPLACE DRIVER SEAT BELT BUCKLE WPI
*	NA	TN	11001	INSPECTED AND REPLACED DRIVERS SIDE SEATBELT BUCKLE AND RETESTED OK
*	NA	TX	11001	23641 VERIFY CUSTOMER CONCERN, TIME TO REMOVE PASSENGER SEAT TO GAIN ACCESS. TIME TO REPLACE PASSENGER SIDE SEAT BELT BUCKLE
*	NA	AZ	11001	CCC S28 RIGHT FRONT SEAT BELT WONT LATCH, REMOVED SEAT REPLACED BUCKLE FOR BEING BROKEN, WORKING PROPERLY AFTER REPAIRS.
*	NA	TN	11001	FOUND DRIVERS SEATBELT BUCKLE INTERMITTENTLY OPEN AND R&R BUCKLE TO CORRECT, RETEST OK
*	NA	MN	11001	15359 REMOVED CENTER CONSOLE REMOVED DRIVER SIDE BUCKLE PART THAT ON ORDER WAS D99. INSTALLED RECALL BUCKLE WE HAD IN STOCK WIRE ON RECALL UPDATED BUCKLE WAS 1IN LONGER. SHORTENED WIRE AND RETEST
*	NA	AL	11001	R & R BOTH FRONT SEAT BELT BUCKLES
*	NA	TX	11001	VERIFY CONCERN PASSENGER SIDE BUCKLE WONT LATCH REPLACED BUCKLE BUCKET SEAT TYPE WITH SIR VERIFY REPAIR OK THIS TIME
*	NA	AZ	12000	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NJ	11001	11124 CHECK AND CONFIRM. ORDER SEAT BELT ASSY. INSTALLED NEW SEAT BELT BUCKLE, TESTED ALL OK
*	NA	NJ	12000	8744 REPLACE PASS SIDE SEAT BELT AREA REMOVE SEAT TO ACCESS ANCHOR BOLT INSTALL AND TEST OK
*	NA	LA	11001	1 REPLACED DRIVERS SEATBELT INOP CHIMING BUCKLE SEATBELT ASSEMBLY FRONT
*	NA	GA	11001	REPLACE SEAT BELT BUCKLE
*	NA	TX	12000	REPLACED SEATBELT BUCKLE
*	NA	TX	11001	REPLACED BROKEN RIGHT FRONT SEAT BELT BUCKLE ASSY
*	NA	KY	11001	REPL RIGHT FRT SEAT BELT BUCKLE

*	NA	MO	11000	RT SEAT BELT PRETENS. NOT CONNECTDIAG,CONNECT RT SEAT BELT PRETENSION NOT CONNECTED,CONNECT & CLEAN
*	NA	TX	11001	REPLACE SEAT BELT BUCKLE.
*	NA	CA	11000	RECALL 01S21
*	NA	GA	11001	REMOVED SEAT BELTS REINSTALLED SEAT BELTS
*	NA	AR	11000	1 1 REPLACED BOTH FRONT SEATBELTS.
*	NA	FL	11000	27 TECH 22 REPLACED PASSENGER SIDE FRONT SEAT BELT
*	NA	TN	11000	
*	NA	IN	11000	REPLACED RIGHT FRT SEAT BELT BUCKLE, BUCKLE WOULD NOT LATCH
*	NA	MD	11000	24 REPLACE PASS SIDE BELT REMOVED SEATS AND REPLACED SEAT BELT BUCKLES THAT WERE TAKEN OUT OF STOCK UNIT REPLACED BUCKLES IN STOCK UNIT
*	NA	TN	11000	
*	NA	SC	11000	01S21D 01S21D
*	NA	CA	11000	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL.
*	NA	OH	11000	SEAT BELT BUCKLE WOULD NOT LATCH REPLACED RIGHT FRONT SEAT BELT BUCKLE
*	NA	NJ	11000	VERIFY CONCERN REMOVE AND REPLACE INOP ASY
*	NA	FL	01XXXX	VERIFY CONCERN. R&R DRIVERS SEAT, REPLACE BUCKLE.
*	NA	OH	11000	COMPLETE RECALL
*	NA	CA	11000	SEAT BELT RECALL REPLACED LEFT SEAT BELT BUCKLE
*	NA	CA	11000	INSPECTED AND TESTED SEAT BELT BUCKLES PER RECALL. REPLACED LEFT SEAT BELT BUCKLE PER RECALL.
*	NA	FL	11000	REPLACE BUCKLE
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11001	REPLACED SEAT BELT

*	NA	IL	11001	VERIFIED CONCERN REPLACED BUCKLE CHECKS GOOD.
*	NA	MI	12000	HAD TO REPLACE BOTH FRT SEAT BELTS TO FIX 42
*	NA	TX	11001	RR SEAT BELT ASSY AND REPAIR
*	NA	OH	11000	CHECK CONCERN AND FOUND DRIVERS SEAT BELT RECEPTACLE BAD.ORDER PART.INSTALL NEW SEATBELT RECEPTACLE AND VERIFY OPERATION.
*	NA	GA	01XXXX	BUCKLE WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
*	NA	AR	11000	R R PASSENGER FRONT SEAT BELT. LATCH WAS BAD.
*	NA	CA	11001	
*	NA	AZ	11000	TT .8 61704AB REPLACED PASSENGER SIDE SEAT BELT PERFORMED TESTING FOUND PRE TENSIONERS BAD
*	NA	NY	11001	REMOVED FROM ANOTHER STOCK UNIT AND INSTALLED NEW SEAT BELT BUCKLES OK NOW
*	NA	PA	11000	TECH 146 VERIFIED AND REPLACED SEAT BELT RECHECKED OPERATION
*	NA	OH	11000	COMPLETE RECALL
*	NA	TX	11000	
*	NA	CA	11000	4434 41 61172A 0.7 9267 REPLACED RT. SEATBELT BUCKLE ASSY; QC CHECK BY TECH
*	NA	OH	11000	RECALL 01S21 COMPLETED
*	NA	OK	01XXXX	REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE
*	NA	AZ	11000	REPLACED SEAT BELT RETENTIONER
*	NA	MA	11000	INSPECT AND REPLACE BOTH SEAT BELT BUCKLES
*	NA	IN	11000	FAULTY SEAT BELT BUCKLE REPLACED PASSENGER SIDE SEAT BELT BUCKLE
*	NA	LA	11000	REPLACED LEFT SIDE LAP BELT WOOD NOT LATCH PARTS NUMBER 612B19 AAD
*	NA	NM	11000	REMOVED DRIVER SIDE BELT FOR COMPLETION. INSTALLE NEW PASSENGER SIDE SEAT BELT. INSTALLED DRIVER SIDE SEAT BELT THAT WAS BROKEN

*	NA	AL	11000	FOUND BUCKLE NOT CATCHING. R AND R PASS SIDE BUCKLE TO CORRECT.READY.
*	NA	AL	11000	. COMPLETED INSTALLATION OF SPECIAL ORDERED PART AS REQUESTED.
*	NA	WV	01XXXX	INSTALL AND REPLACED DRIVER SIDE SEAT BELT
*	NA	TX	11001	DRIVERS SIDE SEAT BELT DOES NOT RECOIL IT HAD TO BE REPLACED
*	NA	IL	11000	REPLACE MIDDLE SEAT BELT BUCKLE
*	NA	NC	11000	REPLACE LEFT SEAT BELT WOULD NOT RELEASE ONCE IT WAS BUCKLED WITHOUT EXTREME DIFFICULTY
*	NA	MD	11000	28379 WARR CHECK FOR LEFT SEAT BUCKLE WON T LOCK R&R AND REPLACE LEFT SEAT BELT BUCKLE RECHECK OK
*	NA	NC	11000	PERFORM TEST REPLACE BUCKLE AND SEAT BELT
*	NA	TX	11001	SEAT BELT LATCH REPLACE LATCH
*	NA	MO	12001	SEAT BELT LATCH BROKEN. REPLACE RIGHT FRONT SEAT BELT BUCKLE
*	NA	OK	11001	SEAT BELT BUCKLE LATCH BINDING REPLACED LF SEAT BELT BUCKLE LATCH.CK OPER,OK.QC..DD
*	NA	ID	11001	SEAT BELT BUCKLE REPLACED DRIVER SIDE SEAT BELT BUCKLE
*	NA	CA	11001	
*	NA	CA	11001	SEATBELT BUCKLE JAMMED REPLACE BELT BUCKLE
*	NA	CA	11001	SEAT BELT BUCKLE WILL NOT LATCH. VERIFIED CONCERN REPLACED SEAT BELT LATCH RECHECKED OK.
*	NA	TX	12001	REPLACED SEAT BELT BUCKLE
*	NA	CA	12001	51 SEATBELT ASSEMBLY FRONT REPLACE
*	NA	TX	11001	REPLACED DRIVERS SIDE BUCKLE
*	NA	CA	12001	SEAT BELT DEFECTIVE REP PASS BELT BUCKLE

*	NA	NV	11001	VERIFY CONCERN. REMOVE SEAT TO ACCESS BUCKLE. REPLACE BUCKLE AND REINSTALL SEAT. QC CHECK, OPERATES PROPERLY.
*	NA	TX	12001	1 REPLACED LEFT FRONT BUCKLE
*	NA	MD	11001	DRIVER SEAT BELT WILL NOT LATCH PROPERLY REPLACE DRIVER SEAT BELT BUCKLE
*	NA	TX	11001	469 DRIVER SIDE FRONT SEAT BELT BUCKLE NOT LATCHING REPLACE DRIVER FRONT SEAT BELT BUCKLE AND TEST OK.
*	NA	CA	11001	CCG26 REPLACED DRIVERS SEAT BELT
*	NA	TX	12001	CHECK FOR LATCH OPERATION FOUND SEATBELT LATCH WITH FAULTY LATCH NEC TO REPLACE SEAT BELT LATCH ON PASSENGER SIDE
*	NA	OR	11001	REPLACED BELT ASSY
*	NA	FL	11001	REPLACED DRIVER SEAT BELT BUCKLE
*	NA	TX	11001	REPLACE LEFT FRONT SEAT BELT
*	NA	NY	11001	6921 REPALACED SEAT BELT BUCKLE
*	NA	CA	11001	SEATBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT
*	NA	CA	11001	SEAT BELT DEFECTIVE INSTALLED SEAT BELT
*	NA	PA	11001	INOP REPAIR HARNESS PINCHED BETWEEN HEATER BOX AND INSTRUMENT PANEL REMOVE AND INSTALL RADIO ACCESS INSTRUMENT PANEL PULL WIRE OUT REMOVE GLOVE BOX AND GEM 107 HOOKED UP NGS AND GOT CODE B1888 FROM RCM MODULE PERFORMED PINPOINT TESTS AND FOUND PASS SEATBELT PRETENSIONER BAD REMOVED B PILLAR MOULDING AND REPLACED PRETENSIONER ASSEMBLY RETESTED AND COD
*	NA	NJ	12001	
*	NA	NC	11001	REPLACE BOTH FORNT SEAT BELT BUCKLES
*	NA	CA	11001	OPEN IN SEAT BELT SWITCH REMOVE AND REPLACED SEAT BELT BUCKLE.

*	NA	NC	11001	FOR BUCKLE JAMMED REPLACE BUCKLE ASSEMBLY
*	NA	CO	11001	1 NO TIME LISTED NGS PULLED RCM CODES, B1877, RUN ELEC PP TEST E, TRACED TO DRIVER SEAT BELT PRETENSIONER, REMOVED DRIVER POWER SEAT
*	NA	TX	11001	VERIFIED CONCERN. R&R PASSENGER SEAT. REPLACED BUCKLE.
*	NA	VA	11001	11549 FOUND LEFT FRT BUCKLE TO BE BROKEN AND SEAT BELT WOULD NOT INSERT. R&R FRT SEAT AND REPLACE BELT BUCKLE. POWER SEATS, LEATHER TRIM
*	NA	FL	11001	DRIVER SEAT BELT WONT LATCH, BUCKLE DEFECTIVE, REPLACED BUCKLE
*	NA	FL	11001	BUCKLE DEFECTIVE RR BELT ASSEMBLY
*	NA	MA	11001	1 1 REPLACE THE DEFECTIVE SEAT BELT BUCKLE
*	NA	FL	11001	PASS SEATBELT BUCKLE WONT LATCH, BUCKLE DEFECTIVE, RR BELT BUCKLE
*	NA	MI	11001	6319 81202,CC 42 VERIFIED DRIVERS SIDR FRONT SEAT BELT BUCKLE INOP,REPLACED LEFT FRONT SEAT BELT BUCKLE,OK NO W
*	NA	AZ	11001	REPLACED THE SEATBELT BUCKLE
*	NA	FL	11001	DEFECTIVE BUCKLE. RR BUCKLE
*	NA	AZ	11001	INTERNAL FAILURE WILL NOT LOCK. REPL DS BUCKLE
*	NA	FL	11001	BUCKEL DEFECTIVE RR BELT ASSEMBLY
*	NA	FL	11001	REPLACED D SIDE BUCKLE
*	NA	FL	11001	DRIVER SEAT BELT WONT LATCH BUCKLE WONT LATCH REPLACED BUCKLE
*	NA	TX	11001	8710 81202, 41 MT81202 0.9 CHECK AND R I RIGHT FRONT SEAT AND REPLACE SEATBELT BUCKLE
*	NA	TN	11001	REPLACED SEATBELT BUCKLE
*	NA	KY	11001	BUCKLE FAILURE INTERNALLY. REPL
*	NA	NV	11001	REPLACE THE BUCKLE
*	NA	FL	11001	2651 DOES NOT OPERATE PROPERLY 42 NONE REPL DRIVERS SEATBELT LATCH ASSY 81202
*	NA	MO	11001	CHECKED DRIVERS SEAT BELT WONT LATCH,BUCKLE WONT HOLD REPLACED DRIVERS SEAT BELT BUCKLE ASM,WORKS OK NOW.
*	NA	NJ	11001	REPLACED SEAT BELT MODULE

*	NA	IL	11001	REPLACE DRIVERS SEAT BELT LATCH
*	NA	NY	11001	INOP M TIME TO REPLACE SEAT BLET CLASP
*	NA	OH	11001	FOUND INTERNAL FAULT IN SEATBELT ASSEMBLY REPLACED DRIVERS SEAT BELT
*	NA	MS	11001	REPLACE LEFT FRT BELT BUCKLE. (IMPROPER OPERATION)
*	NA	PA	11001	REPL SEATBELT BUCKLE MT TIME
*	NA	FL	11001	RT FRT SEAT BELT WONT LATCH REPLACE SEAT BELT BUCKEL
*	NA	NS	11001	SEAT BELT BUCKLE WILL NOT FASTEN REPLACED LEFT FRT BELT
*	NA	MS	11001	LATCH BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	ON	11001	REPLACE LF SEAT BELT 61172A (2.7 HRS) LF SEAT BELT BUCKLE INOP TO CONNECT 61202 42
*	NA	OH	11001	REPLACED SEAT BELT BUCKLE BECAUSE OLD ONE WOULD OT LATCH
*	NA	GA	11001	REMOVE INSPECT AND REPLACE D S SEAT BELT BUCKLE
*	NA	IL	11001	REPLACE FAULTY DRIVERS SIDE SEAT BELT BUCKLE
*	NA	IL	11001	1 REMOVED PASSENGER SEAT AND REPLACED SEAT BELT RECEPTICLE. TECH 32189.
*	NA	FL	11001	REPLACED LEFT FRONT SEATBELT BUCKLE ASSY
*	NA	VA	11001	CHECKED SEAT BELT BUCKLE, REPLACED SEAT BELT BUCKLE
*	NA	NC	11001	LOOSE CHECK AND REPLACE DRIVERS SEATBELT BUCKLE
*	NA	CA	11001	BUCKLE M TIME REPLACE RIGHT FRT BELT BUCKLE
*	NA	SC	11001	CK AND REPLACED FRT SEATBELT ASSY. RECHECKED

*	NA	FL	11001	5964 01 5461202 WF TESTED DRIVERS SIDE SEAT BELT BUCKLE. LATCH WOULD NOT HOLD. R&R DRIVERS SEAT TO REPLACE SEAT BUCKLE. NOTE: THIS VEHICLE IS A POLICE CAR AND HAD A PETITION BEHIND DRIVERS SEAT.
*	NA	FL	11001	42 WILL NOT CATCH REPLACED R S SEAT BELT BUCKLE
*	NA	FL	11001	INSPECT SEAT BELTS CAN NOT VERIFY CONCERN PER SER MAG BILL L. FOR CUSTM SATISFACTION REPLACED DRIVERS SEAT BELT BUCKLE 191 8041
*	NA	FL	11001	REPLACED BOTH SEAT BUCKLES
*	NA	IN	11001	SEAT BELT BUCKLE WDS TEST, REMOVE AND REPLACE SEAT BELT BUCKLE
*	NA	FL	11001	REPLACED DRIVER BUCKLE
*	NA	OH	11001	
*	NA	NC	11001	WDS TEST CHECKED RCM MODULE CODE B2432 REPLACED DRIVERS SEATBELT BUCKLE
*	NA	AZ	11001	REPLACED THE SEAT BELT
*	NA	AZ	11001	REPLACED THE BUCKLE
*	NA	MA	11001	1 TESTED AND FOUND TO BE INOP R&R LF BELT LATCH.
*	NA	TX	11001	RESECURED PIN INTO CONNECTOR
*	NA	SC	11001	CODE B2436 SEAT BELT BUCKLE LOOSE CONNECTOR TO PASS SEAT BELT TIGHTEN CONNECTOR RETEST
*	NA	AZ	11001	CHECK AIR BAG LIGHT. NGS TEST. RETREIVE DTC. B2436 & CLEAR C CODE. ON DEMAND TEST & SAME DTC & MONITOR PID & PINPOINT RECONNECT & RESECURE CONNECTION. SYSTEM PASS
*	NA	IL	11001	REPLACED THE BUCKLE
*	NA	LA	11001	REINSTLAED WIRE CONNECTOR
*	NA	GA	11001	INSPECT REPLACED FRONT SEAT BELTS
*	NA	MN	11001	CP 5461202;CC 26;CCC 939 AIR BAG RESTRAINT SYSTEM DIAGNOSIS REPLACED RIGHT FRONT SEAT BELT BUCKLE.
*	NA	NM	11001	STICKING REPLACED LEFT FRONT SEAT BELT BUCKLE THAT WAS STICKING AND WOULD NOT ALLOW BELT TO FASTEN .
*	NA	NJ	12001	INSTALLED NEW DRIVERS BELT BUCKLE
*	NA	FL	11001	R AND R BUCKLE WPI

*	NA	FL	11001	REPLAC DRIVERS SEAT BELT BUCKLE
*	NA	OH	11001	WDS CAME UP WITH CODE B2432 DRIVERS BUCKLE CHECKED WIRES REPLACED BUCKLE
*	NA	SC	11001	INSPECTED R&R RF SEAT TO READJUST SEAT BELT BUCKLE TO CORRECT POSITION. (TURNED AROUND) RECHECK.
*	NA	OH	11001	44 VERIFIED CONCERN PERFORMED AIR BAG DIAGNOSTICS FOUND DTC B2439 PERFORMED PINPOINT TESTS REPLACED DEFECTIVE PASSENGERS FRONT SEAT BUCKLE ASSY CLEAR CODES RETEST OK
*	NA	NJ	11001	1 PERFORM DIAGNOSIS ON AIR BAGS REPLACE SEAT BELT BUCKLE
*	NA	TX	11001	USE NGS CHECK CODES FIND DTC B2432 DRIVER SIDE SEAT BELT GO THROUGH MANUAL PINPOINT TEST FIND SEAT BELT BUCKLE BAD REPLACE BUCKLE. MT NO LABOR OP
*	NA	FL	11001	REPL. FRON SEAT BELT. WPI
*	NA	CA	11001	61202 RF SEATBELT BUCKLE SWITCH, NOT OPERATING PROPERLY CC42 BCE TEST DTC B2436 HARD FAULT. PERFORM AIRBAG SYSTEM DIAG NOSIS. PINPOINT TEST TO INTERNAL FAILURE IN RT FRT PASS
*	NA	OH	11001	108 VERIFIED AIR BAG LAMP ON PERFORMED AIR BAG DIAGNOSTICS FOUND HARD FAULTS B2436 AND B2432 DRIVERS AND PASSENGERS SEAT BELT CIRCUITS OPEN PERFORMED PINPOINT TESTS FOUND CIRCUIT 1558 TAN AND BLAC
*	NA	MI	11001	RIGHT FRONT SEATBELT BUCKLE BACKWARDS FROM FACTORY CC42 61202 REMOVE RIGHT FRONT BUCKLE AND REINSTALL CORRECT WAY
*	NA	LA	11001	80 PERFORMED PIN POINT TEST AND REPLACED LFT FRT SEATBELT BUCKLE CC 42
*	NA	WA	11001	CLOSED AT ALL TIMES ORDERS PART REMOVD SEAT DS R R SEAT BELT BUCKL

*	NA	GA	11001	DIAG TEST 2436 52 PIN POINT TEST TIME TO TRACE HARNESS TO RF SEAT BELT SWITCH REPLACE SWITCH OPEN 28 TIME TO
*	NA	NJ	11001	REPLACED SEATBELT BUCKLE THAT WA JAMMED
*	NA	TN	11001	SECURED HARNESS TO CONNECTOR
*	NA	MI	11001	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
*	NA	MN	11001	38 AIR BAG DIAGNOSTICS. TRACED WIRING AND FOUND DRIVERS SEAT BELT BUCKLE SWITCH FAULTY. REPLACED SEAT BELT BUCKLE AND RETESTED.
*	NA	GA	11001	INTERNAL SHORT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
*	NA	NC	11001	AIR BAG SYSTEM DIAGNOSIS, CONTINUOUS CODE B2436, NEC TO REPLACE R F SEAT BELT BUCKLE
*	NA	LA	11001	AIR BAG RESTRAINT SYSTEM DIAGNOSIS..REPLACE SEAT BELT BUCKLE
*	NA	AL	11001	
*	NA	PA	11001	DIAGNOSE LEFT FRONT SEATBELT IS PULLING AWAY FROM SEAT, REMOVED SEAT CUSHION COVER, REPOSITION BELT AND REPAD SEAT, REFIT SEAT BELT
*	NA	NJ	11001	PULLED CODES B2432,2436, & C1948 FOUND D S SEAT BELT BUCKLE UNPLUGGED, REINSTALLED PROPERLY, CLEARED CODES GOOD
*	NA	AR	11001	AB SELF TEST B2436 PINPOINT TEST REPAIRED OPEN CIRCUIT AT SEAT BELT BUCKLE SWITCH CONNECTOR
*	NA	GA	11001	PERFORM DIAG, INSPECT AND REPLACE FAULTY DRIVERS SEAT BELT BUCKLE END.
*	NA	AZ	11001	AIRBAG RESTRAINT SYS B2438 DTC RIGHT SEAT BELT BUCKLE SHORTED. R AND I SEAT TO INSPECT WIRING. REPL BUCKLE SHORTED INTERNALLY
*	NA	FL	11001	DIAG AIR BAG SYSTEM, CODE B2432. PINPOINT TEST. REPLACED DRIVERS SEAT BELT BUCKLE. OPEN CKT.
*	NA	FL	11001	AIR BAG DIAGNOIS AND REPIARED WIRING ON DRIVERS SIDE, NEC TO R&I SEATBELT AND SEAT TO REPAIR
*	NA	IL	11001	R N R DRIVER SEAT. REPLACED LEFT FRONT SEAT BUC KLE ASSY. CC01.
*	NA	ON	11001	AIR BAG DIAG REPAIR OPEN CIRCUIT

*	NA	VA	11001	11 OPEN IN DRIVERS SEAT BELT BUCKLE CODE 51 DISPLAYED,RAN NGS CODE2432 LH SEAT BELT OPEN RAN PID TEST WAS OPEN NOT CLOSING CIRCUIT REPLACED BUCKLE ASSY CLEARED CODES RETEST OK ROAD TEST OK #3
*	NA	FL	11001	7 42 SAME PERFORM AIRBAG DIAGNOSIS PINPOINT TEST CODE 51 B1253 REPLACE LT FT SEATBELT BUCKLE JH
*	NA	NY	11001	REPLACED WEATHER STRIP AROUNT DRIVERS WONDOW
*	NA	GA	11001	977 REPLACE LT FRONT SEATBELT
*	NA	NY	11001	INTENAL DEFECT PERFORM DIAGNOSIS,REMOVE AND REPLACE LEFT SIDE SEATBELT BUCKLE.RECHECK.
*	NA	GA	11001	DIAG TEST 2432 PIN POINT TEST K TIME TO TRACE HARNESS TO LF SEAT BUCKLE REPL BUCKLE OPEN 28
*	NA	NC	11001	EEC TEST,PIN POINT TEST,NGS ,REPLACE SEAT BELT BUCKLE
*	NA	IL	11001	REPLACED DRIVERS SEATBELT BUCKLE
*	NA	MI	11001	
*	NA	MI	11001	1 REPLACED THE DRIVER SIDE SEAT BELT BUCKLE.
*	NA	CA	11001	DTC B2432 AIR BAG RESTRAINT SYSTEM DIAGNOSIS
*	NA	MO	11001	BUCKLE BINDING
*	NA	MO	11001	AIR BAG DIAG, REPLACE PASSENGER FRONT SEAT BELT
*	NA	MN	11001	1 REPLACE RIGHT FRUNT SEAT BELT R&R SEAT TO REPLACE BUCKLE
*	NA	MD	11001	REPLACE SEAT BELT
*	NA	TX	11001	AIR BAG LIGHT FLASHING NGS TEST WIRING DIAG FOUND DRIVER SEA T BELT THROWING CODE ACCESS DRIVER AND PASS SEAT ACCESS CARPET CK FOR PINCHED WIRE UNDER SEAT NO WIRING DAMAGE REPL DRIVER SEAT BELT BUCKLE

*	NA	TX	11001	CHECK OUT AIR BAG LIGHT FLASHES, TEST DRIVE, NOTE AIR BAG LIGHT ON,CONNECT NGS, RUN KOED, NOTE DTC B2434, PERFORM PIN POINT TEST M, RR DRIVERS SEAT ASPER PIN POINT TEST, REPLACE DRIVERS SEAT BELT BUC
*	NA	KS	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	OK	11001	Z2 VERIFY CONCERN. AIR BAG LIGHT FLASHING CODE 52. USE WDS AND CHECK RCM FOR CODES, CODE B2436 (PASSENGER SEATBELT BUCKLE CIRCUIT OPEN). REFER TO SERVICE MANUAL FOR PPT INFO. PERFORMED PPTO1 PPT
*	NA	NJ	11001	1 REPLACE L F SEAT BELT BUCKLE AND REPAIR OPEN WIRE
*	NA	TN	11001	S39 02 61202 NGS DIAG. REMOVED DRIVER SEAT PINPOINT TEST. REPAIR WIRING CONNECTOR UNDER SEAT AND RETEST. ALL OK.
*	NA	MI	11001	WDS TEST AND RECIEVED CODE B 2436. PERFORM PINPOINT TEST AND FOUND OPEN SEATBELT BUCKLE SWITCH. REMOVE RF SEAT AND REPLACE PASS. SIDE SEAT BELT BUCKLE ASSEMBLY. CLEAR CODES AND RECHECK. OKAY.
*	NA	LA	11001	DIAGNOSIS AIR BAG RESTRAINT SYSTEM M TIME TO REPAIR OPEN CIRCUIT AT SEAT BELT BUCKLE
*	NA	TX	11001	POLICE CAR WITH CAGE BEHIND FRONT SEAT AND HAVE CONSOLE IN CENTER HAVE TO REMOVE BOTH FRONT SEATS TO REPLACE BELT LATCHES MT NO LABOR OP
*	NA	IL	11001	28 REPAIRED OPEN TO WIRING ON LEFT FT SEAT BELT AIR BAG LAMP ON
*	NA	GA	11001	AIR BAG WILL NOT OPEWRATECATVTINETRIM COVER FRONT SEAT BACK REPLACE
*	NA	IL	11001	CHECK CODES, PERFORMED PINPOINTS, RECONNECT PASSENGER SEAT BELT CONNECTOR.
*	NA	TX	11001	1114 41 INSPECTED & FOUND DRIVERS SEAT BELT LATCH CATCH BINDS & WILL NOT HOLD PROPERLY. NEC. TO REPLACE LATCH ASSEMBLY. SYSTEM OK.

*	NA	OH	11001	INSTALL NGS TESTER CODE B2292 B2434 PINPOINT TEST DATALOGGER DISPLAY CHECK PIDS FRONT SEAT BELT TENSIONER OPEN
*	NA	NE	11001	REPLACE SEAT BELT ASSY
*	NA	VA	11001	REPAIRED WIRING CIRCUIT TO PASSENGER SEAT BELT BUCKLE
*	NA	MN	11001	1 REPLACED RIGHT FRONT SEAT BELT BUCKLE
*	NA	CA	11001	CHECK AIR BAG LAMP FLASHING CODE 51 TEST NOTE CAME TO THE SEAT BELT BUCKLE NEED TO BE REPLACED REMOVED AND REPLACED SEAT BELT BUCKLE
*	NA	TN	11001	AIR BAG DIAGNOSIS NGS TEST PINPOINT TEST CK WIRINGREPAIR OPEN CIRCUIT AT DRIVERS SEAT LFC 51
*	NA	PQ	11001	ABS DIAG,REPLACER SEAT BELT ASSY
*	NA	CA	11001	PERFORM AIR BAG DIAGNOSTICS SELF TEST CODES 32438. PINPOINT TEST. REPLACED RIGHT FRONT SEAT BELT ASSEMBLY. AIR BAG LIGHT IS OUT
*	NA	TN	11001	TEST SYSTEM FOUND TERMINAL PULLED OUT OF CONNECTORREPAIRED HARNESS RETESTED OK
*	NA	TX	11001	10 01202,28 OPEN CIRCUIT AIR BAG DIAG FOUND OPEN IN SEAT BELT BUCKLE REPLACED BUCKLE TEST,OK
*	NA	TX	11001	NOT INVOLVED IN RECALL BUT WOULD NOT HOLD
*	NA	MD	11001	1773 BUCKLE INOP WARR VERIFY CONCERN REPLACED PASS FRONT SEAT BELT BUCKLE
*	NA	LA	11001	REPLACED DRIVERS SEAT BELT
*	NA	CA	11001	. SBT997240 61172A
*	NA	CA	11001	WPI FOUND BUCKLE WONT LOCK BELT REPL RT BELT
*	NA	NJ	11001	REPLACE SEATBELT BUCKLE
*	NA	WI	11001	INTERNAL FAULT IN BUCKLE INSPECT AND REPLACE RETEST OK NOW
*	NA	TX	11001	REPLACED PASSENGER SEAT BELT BUCKLES NOT LATCHING
*	NA	FL	11001	VERIFIED CONCERN REMOVED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE
*	NA	FL	11001	BUCKLE ASSEMBLY DEFECTIVE R AND R DRIVERS SEAT BELBUCKLE

*	NA	TX	11001	REPLACED LEFT FRONT SEAT BELT BUCKLE
*	NA	TX	11001	8200 RECIVER INOP REPLACE LEFT FRONT SEAT BELT RECIVER ASSEMBLY TK372 CODE 42
*	NA	TX	11001	4258 61202, 41 MT61202 0.5 REPLACE LEFT FRONT SEATBELT BUCKLE, BINDING, NPF WITH WARINING CHIME, REPAIRED WITH BUCKLE
*	NA	FL	11001	5914 SAME RECALL REPLACED DRIVER SIDE SEAT BELT BUCKLE JH 3992 CHECKED SYSTEM AND VERIFIED CONCERN, REMOVED AND INSTALLED NEW LEFT FRONT SEAT BELT BUCKLE ASSEMBLY, SYSTEM NOW WORKS CORRECTLY AT THIS TIME, ALSO CHECKED RIGHT BUCKLE AND FOUND THIS ONE TO BE
*	NA	IL	11001	RELEASE JAMMED REPLACED RT FT SEAT BELT BUCKLE
*	NA	KS	11001	LF SEATBELT WILL NOT LATCH REPLACED LEFT FRONT SEAT BELT BUCKLE DUE TO IT NOT LATCHING
*	NA	PA	11001	DIAGNOSE AND REPLACED BOTH FRONT SEATBELT BUCKLES DUE TO NOT LATCHING
*	NA	NC	11001	REPLACED PASSENGER SEAT BELT BUCKLE
*	NA	ON	11001	REPL FRT PASS SEAT BELT BUCKLE
*	NA	NH	11001	VERIFIED REPLACED SEAT BELT
*	NA	MA	11001	CHECK DRIVERS SEAT BELT FOUND SEAT BELT DEFECTIVE WILL NOT LATCH.REPLACED WITH NEW SEAT BELT ASSEMBLY.
*	NA	MA	11001	DRIVERS SEAT BELT WILL NOT LATCH.CHECK AND FOUND SEAT BELT DEFECTIVE REPLACED WITH NEW SEATBELT.
*	NA	CT	11001	INSTALL SEAT BELT
*	NA	CA	11001	OK M TIME D.C.S.
*	NA	SD	11001	REPLACE DRIVERS SIDE SEAT BUCKLE
*	NA	CA	11001	REPLACE SEAT BELT BUCKLE ON THE DRIVERS SIDE DUE TO WOULD NOT LATCH.
*	NA	TX	11001	REPLACED BOTH FT SEAT BELT BUCKLES

*	NA	TX	11001	REPLACED BOTH FRONT SEAT BELT BUCKLES.
*	NA	TX	11001	REPLACED BOTH FRONT BUCKLES.
*	NA	TX	11001	REPLACED BOTH FRONT SEAT BELT BUCKLES.
*	NA	TX	11001	REPLACED BOTH SEAT BELT BUCKLES
*	NA	WI	11001	12784 INSTALL L F SEAT BELT
*	NA	TX	11001	REPLACED BOTH FRONT BUCKLES.
*	NA	CA	11001	FRONT SEATBELTS DO NOT LATCH REPLACED INOP L F SEAT BELT. INSPECTED DRIVERS SIDE SEAT BELT BUCKLE. BROKEN. REPLACED BUCKLE ASSY. RE TESTED. OK.MT5461202 TIME TO REPLACE DRIVER SEAT BELT BUCKLE ASSY. NO LABOR OPS.
*	NA	AZ	11001	INSPECT AND REPLACE SEAT BELT LATCH INOP
*	NA	GA	11001	CHECKED RIGHT FRONT SEAT BELT BUCKLE DEFECTIVE,IT WILL NOT HOLD.NEC TOREPLACE RIGHT FRONT BUCKLE.
*	NA	NY	11001	REPLACE BUCKLE ASSY BINDS REPLACE ONE BUCKLE
*	NA	IA	11001	DIAG AND REPLACE FEMALE BELT END
*	NA	TX	11001	190 01 61202 61203 AIR BAG DIAG OF BUCKLES R R BOTH FT SEATS ACCESS REPLACED BOTH FT SEAT BELT BUCKLES INOP
*	NA	CO	11001	CHECKED REPLACED LEFT AND RIGHT FRONT SEAT BELT ASSEMBLIES
*	NA	TX	11001	REMOVE RIGHT AND LEFT SIDE SEAT TO REPLACE BOTH FRONT SEAT BELTBUCKLES
*	NA	TX	11001	124 PERFORMED RECALL 01S21 AS REQUIRED. TESTED BOTH SEAT BELTS AND BOTH FAILED. REPLACED BOTH SEAT BELTS 01S21H LABOR OP. TECH 307
*	NA	AL	11001	REINSTALLED WIRE ON PASSENGER BELT BUCKLE
*	NA	FL	11001	6 W INSTALL LEFT SEAT BELT BUCKLES 1W7Z5461202AAD
*	NA	AL	11001	AIR BAG LIGHT COMES ON. FOUND FAULTY SEAT BELT BUCKLE.
*	NA	NJ	11001	VERIFIED LEFT FRONT SEATBELT AND BUCKLE INOPERABLE REPLACED
*	NA	GA	12001	REPLACED L F SEAT BELT BUCKLE

*	NA	TX	11001	MECHANISM DONT RELEASE COMPLETELY. REPL BUCKLE
*	NA	NY	11001	REPALCE R F SEATBELT BUCKLE
*	NA	FL	11001	CHECK AND REPLACE PASSENGERS SEAT BELT
*	NA	MI	11001	
*	NA	FL	11001	REPLACE PASSENGER SIDE SEAT BELT
*	NA	FL	12001	REPLACED PASSENGER SEAT BELT BUCKLE
*	NA	NJ	11001	REPLACE BELT BUCKLE
*	NA	CA	11001	TESTED ELECT SYSTEM,FOUND WIRE IN DRIVER SEAT BELT BAD REPLACED & RETESTED GOOD ,NO CHIME MT USED AS NO OP CODE
*	NA	GA	11001	REPLACED SEATBELT LATCH
*	NA	TX	11001	REPLACED BELT BUCKLE
*	NA	ME	11001	ROAD TESTED VEHICLE TO CONFIRM AIR BAG LIGHT PR OBLEM TECH 3900 ROAD TESTED NO LIGHT NO CODES, SELF TEST CAME UP GOOD MORE TESTING?? FOUND THAT THE PROBLEM IS SOMEWHERE IN THE PASSENGERS SIDE SEAT
*	NA	AZ	11001	0894 REPLACED BOTH RIGHT AND LEFT FRT SEAT BLTS BUCKLES. INOP
*	NA	MN	11001	REPLACED THE BUCKLE
*	NA	GA	11001	
*	NA	TX	11001	REPLACED THE BUCKLE
*	NA	MD	11001	REPLACE SEALT BELT
*	NA	FL	11001	PERFORMED 01S21 RECALL,FOUND FAULTY RF SEAT BELT BUCKLE,REPLACED RF SEAT BELT BUCKLE ASY AS PER RECALL.
*	NA	TX	11001	INSPECT SEAT BELT BUCKLE. NEC TO RELACE SEAT BELT BUCKLE
*	NA	MA	11001	INSTALL BORRED SEAT BELT RECEPTICALS FOR FRFT, PARTS CHARGED OUT ON RO 159518 ON 8.30.2001
*	NA	NJ	11001	REPALCE THE BUCKLE
*	NA	FL	11001	REPLACED R F SEAT BUCKLE
*	NA	PA	11001	REPLACED SEATBELT
*	NA	TX	12001	REPLACE 2 FRT SEAT BELT BUCKLES
*	NA	FL	12001	REPLACE BOTH SEAT BELTS

*	NA	FL	11001	VEHICLE HAS NO OPEN RECALL NUMBER 01S21 BUT NEEDED SAME REPAIRS
*	NA	NY	12001	1 INSPECT AND REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES
*	NA	TX	11001	1 DIAGNOSE SEAT BELT WILL NOT LATCH INTERNALLY COMING APART REPLACE LATCH RETEST OK
*	NA	AR	11001	REPLACED SEAT BELT BUCKLE
*	NA	TX	11001	SECURE LOOSE CONNECTION TO SENSOR
*	NA	KY	11001	1 REMOVE SEATBELT FROM THIS UNIT AND PUT ON SOLD UNIT PART #5481202
*	NA	IL	11001	WPI VERIFY COMPLAINT CODE B2438 R&R FAULTY BUCKLE ASSY
*	NA	MO	11001	HOOKE UP WGS TO PERFORM RCM TESTS B2432 REMOVED DRIVERS SIDE AND PASSENGER SEATS, KICK PANEL TRIM AND PERFORMED OAM TESTS ON WIRING PER SHOP MANUAL AFTER DEACTIVATING AIRBAG SYSTEM REMOVED AIR BAGS A
*	NA	TX	11001	SEATBELT BUCKLE SWITCH OPEN PERFORMED PINPOINT TEST FOUND OPEN IN RF SEAT BELT BUCKLE SWITCH R AND R RF BUCKLE
*	NA	CA	11001	REPL DRIVER SEAT BELT BUCKLE
*	NA	FL	11001	REPLACE BELT PER RECALL 01S21
*	NA	IN	11001	REPLACE INOP RT FT SEAT BELT
*	NA	TX	11001	BOTH FRONT SEATBELTS HARD TO FASTEN REPLACE BOTH FRONT SEAT BELT BUCKLE ENDS BINDING NO LABOR OPERATION IN SLTSM
*	NA	OH	11001	DUPLICATED CONCERN RAN ON WDS CODE B2432 PERFORMED PIN POINT TEST FOUND DS SEATBELT SWITCH CONNECTOR DISCONNECTED REINSTALLED CONNECTOR RECKED OEPRATION OK RERAN SELF TEST SYSTEM PASSED.
*	NA	MA	11001	REPLACE SEAT BELT BUCKLES NOT WORKING
*	NA	FL	11001	CHECK SEAT BELT OPERATION AND REPLACE PASSENGERS SIDE SEAT BELT

NA	NJ	11001	CHECKED VEHICLE CONFIRMED CUSTOMER COMPLAINT PERFORMED PINPOINT TESTING REPLACED DEFECTIVE BUCKLE RETEST OK
NA	GA	11001	REPLACED BOTH FRONT SEAT BELT LATCHES
NA	TX	11001	PERFORMED DIAGNOSIS, BCE DIAG, PIDS MONITOR TEST, PINPOINT TEST, AND CIRCUIT TEST CODE 2432. REMOVED LF SEAT AND TRACED OUT OPEN CIRCUIT. REPLACED LEFT FRONT SEAT BELT BUCKLE. REINSTALLED SEAT. RETESTE
NA	FL	11001	CHECK FRONT DRIVER SIDE SEAT BELT BUCKLE WOULD NOT LATCH 3 OUT OF 15 TIME REPLACE BUCKLE SIDE OF DRIVER SIDE SEAT BELT.
NA	GA	11001	L F SEAT BELT BUCKLE LOOSE VERIFY CONCERN REATTACH L F SEAT BELT BUCKLE AND SECURE IN PLACE
NA	ON	11001	MT REPLCE INOP LF SEAT BELT ASSY
NA	MA	11001	REPLACE DEFECTIVE SEATBELT
NA	TX	11001	INOPERATIVE
NA	PA	11001	REPLACED BELT BUCKLES INSPECTED SEAT BELT
NA	NY	11001	RIGHT SEAT BELT BUCKLE JAMMED CHECK AND VARIFY RIGHT FRONT SEAT BELT BUCKLE JAMMED REPLACE RIGHT FRONT SEAT BELT BUCKLE RECHECK OK
NA	NY	11001	FOUND LEFT FRONT SEAT BELT BUCKLE JAMMED CHECK AND VARIFY LEFT FRONT SEAT BELT BUCKLE JAMMED REMOVE DEFECTIVE SEAT BELT AND REPLACE SEAT BELT ASSEMBLY
NA	NJ	11001	PERFORM DIAG RETRIEVED CODE B2432 FOR DRIVER SEAT BELT BUCKLE SWITCH FOLLOWED PINPOINT TEST, FOUND CONNECTOR UNDER SEAT BROKEN, REPLACED
NA	AR	11001	CHECKED AND REPLACED LEFT FRONT SEAT BELT END LINK
NA	MA	11001	REPLACED SEAT BELT LATCH
NA	OK	11001	OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS
NA	SC	11001	INSPECT BUCKLE

*	NA	OH	11001	829 CC42 BASC 5461202 CK OUT AIR BAG LIGHT ON INSTALL WDS AND CK CODES CODE B2436 REMOVE DASH PANEL TO AXSES MODUAL PREFORM PINPONT TEST REMOVE PASENGER SEAT ASSBLY REMOVE SEAT BELT RECIVER ASSBLY
*	NA	CA	11001	RECALL 01S21 SEATBELT PERFORMED 01S21 SEATBELT RECALL
*	NA	NY	11001	AIR BAG SYSTEM DIAGNOSED REPLACED DEFECTIVE FRONT SEAT (L FRONT) BELT BUCKLE.
*	NA	ON	11001	REPL SEAT BELT BUCKLE
*	NA	NM	11001	BELT LATCH R&R LEFT CENTER SEATBELT LATCHCE
*	NA	SC	11001	INSPECT BNUCKLE
*	NA	CA	11001	BUCKLE EEC (QUICK TEST) DIAGNOSIS
*	NA	MD	11001	8 PREFORM RECALL 01S21 ON DS SEATBELT
*	NA	NV	11001	BUCKLE BROKEN TESTED SEAT BELT BUCKLE
*	NA	MD	11001	WIREWAS BROKE , R&R SEAT BELT BUCKLE , INS
*	NA	NY	11001	8 REPLACE ONE SEAT BELT Y 2
*	NA	NY	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NY	11001	INOP SEATBELT ASSEMBLY FRONT REPLACE
*	NA	NY	11001	BINDING VERIFIED CONCERN DIAGNOSED AND REPLACED FAULTY SEAT BELT BUCKLE CHECKED OPERATION CONCERN CORRECTED
*	NA	OK	11001	HOOK UP NGS, RUN SELF TEST ON AIR BAG SYSTEM RUN DCL DISPLAY, RUN PIN POINTEST ON LEFT FRONT SEAT BELT BUCKLE, FOUND BUCKLE SWITCH OPEN, R AND R DRIVERS SEAT, REPLACED BUCKLE, CLEAR CODES AND RETEST.
*	NA	CA	11001	
*	NA	ID	11001	01S21 REPLACE SEAT BELT 01S21 RECALL

*	NA	NJ	11001	CONFIRMED AIR BAG LIGHT IS ON LFC 51 DIAG W NGS TEST RCM # B2438 DRIVERS SEAT BELT OPEN CIRCUIT PERFORMED AIR BAG PINPOINT TEST REPLACED SEAT BELT BUCKLE O.K.
*	NA	OK	11001	REPLACED DRIVER SIDE SEATBELT BUCKLE DUE TO INTERMITENT CONCERN 61202
*	NA	MA	11001	REPLACE SEAT BELT
*	NA	MA	11001	DRIVERS SEAT BELT SWITCH INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS,PINPOINT & REPL SEAT BELT SWC
*	NA	AZ	11001	5130 5461202 ERATIC OPERATION AIRBAG DIAGNOSIS FLASH CODE 51, DTC 2432 PINPOINT TESTS ACCESS DRIVERS SEAT TEST HARNESS REPLACE SEAT BELT BUCKLE, ERRATIC OPERATION CLEAR CODE RETEST CODE PASS
*	NA	MI	11001	78 CC 28,33,42 BPN 61202 INSPECT CUSTOMERS CONCERN OF AIR BAG LIGHT FLASHING. CHECKED AND VARFIED CONCERN. NECESSARY TO RETRIVE LFC LFC CODE RETRIVE 52 NECESSARY TO PERFORM TEST AND RETRIVE CODES
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	CA	11001	REPLACE BELT BUCKLE
*	NA	NJ	11001	TRACED CODE B2432 REPLACED L/F SEAT BELT BUCKLE
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	GA	11001	SEAT BELT BUCKLE FRONT RIGHT OR LEFT REPLACE
*	NA	CA	11001	PRODUCT MODIFICATION REPLACED SEAT BUCKLE AS PER RECALL
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	CT	11001	R AND R PASS. SEAT REPLACE SEAT BELT BUCKLE
*	NA	CT	11001	RREPLACE PASS SIDE SEAT BELT BUCKLE
*	NA	NH	11001	TEST & REPLACE SEAT BELT END
*	NA	NH	11001	TEST & REPAIR LOOM & REPLACE BELT
*	NA	MD	11001	CAUSAL 5461202 CC 42 CCC S39 TEST AIR BAG SYSTEM AND REPLACED SEAT BELT CODE 51

*	NA	CA	11001	TEST ECM USING NGS DTC B2432 GIVEN OD AND CONT ACCESS SEAT TO PINPOINT TEST BUCKLE OPEN REPLACE LF BUCKLE FINAL TEST AND CLEAR CODES
*	NA	FL	11001	FP 81202 C C 42 V.C.C. FOUND DRIVERS SEAT BELT BUCKLE WOULD NOT RELEASE ALL THE TIME. REPLACED DRIVERS SEAT BELT BUCKLE
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	WA	11001	CHECKED HARNESS AND FOUND OPEN IN DRIVERS SEAT BELT BUCKLE REPLACED BUCKLE AND RETESTED ALL OK
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	PA	11001	MANUFACTURER RECALL SEATBELT INSPECTION
*	NA	TX	11001	37 INSTALL BUCKLE REPLACEMENTS PER RECALL 01S21. LABOR:01S21H.
*	NA	NJ	11001	PERFORM RESTRAINT SYSTEM DIAGNOSIS REPAIR OPEN CIRCUIT IN DRIVERS SEAT BELT BUCKLE CIRCUIT
*	NA	MA	11001	RECALL OR OWNER NOTIFICATION
*	NA	CA	11001	
*	NA	OK	11001	182 NGS TEST CODE 51 DRIVERS SEAT BELT AND BUCKLE POSSIBLE AREA SHORT TO GROUND TRIED BELT OHM TEST SHOWED NOTHING ON OLD ONE LEFT IN BECAUSE OF DIFFERENCE R AND I SEATS FRONT R AND I GOOD PART OF D
*	NA	SD	11001	FAULTY SEAT BELT. REPLACE SEAT BELT.
*	NA	NJ	11001	REPLACED BOTH FRONT BUCKLES. RECALL 01S21
*	NA	GA	11001	1 REPLACED SEAT BELT
*	NA	NJ	11001	PERFORM AIR BAG DIAG. LOCATE AND INSPECT HARNESS REPLACE DRIVERS SEAT BELT BUCKLE
*	NA	CT	11001	REMOVED THE ADD ON PROTECTIVE SIDE SHIELD AND CONSOLE MOUNT PLATES IN ORDER TO ACCESS AND REP LACE THE DRIVERS FEMALE SEAT BELT RECEPICLE.
*	NA	PQ	11001	REMPLECE LA CEINTURE