

Noncompliance Report Guide for Equipment  
**PART 573 Defect and Noncompliance Responsibility and Reports**

On **APRIL 11, 2006**, **EAGLE EYES, SONAR [MFR]** decided that a noncompliance with Federal Motor Vehicle Safety Standard No. 108 exists in items of motor vehicle equipment listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 **Defect and Noncompliance Responsibility and Reports**.

Date this report was prepared: APRIL 12, 2006

06E-032  
(6 pgs.)

Furnish the manufacturer's identification code for this recall (if applicable): N/A

1. Identify the full corporate name of the fabricating manufacturer/brand name/trademark owner of the recalled item of equipment. If the recalled item of equipment is imported, provide the name and **mailing address** of the designated agent as prescribed by 49 U.S.C. §30164.

EAGLE EYES TRAFFIC INDUSTRIAL CO., LTD

SONAR AUTO PARTS CO., LTD

TOM MOTORSPORT INC., 168 MASON WAY UNIT B7, CITY OF INDUSTRY, CA 91746

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

TOM TRAN, PRESIDENT

Telephone Number: 626-968-4007 Fax No.: 626-968-7020

Name and Title of Person who prepared this report.

TOM TRAN, PRESIDENT

Signed: 

RECEIVED  
2006 APR 19 P 3 31

**I. Identify the Recalled Items of Equipment**

2. Identify the Items of Equipment Involved in this Recall, *for each make and model or applicable item of equipment product line (provide illustrations or photographs as necessary to describe the item of equipment), provide:*

Generic name of the item:

Make: \_\_\_\_\_ Model:

Part Number: \_\_\_\_\_ Size:

PART NUMBER	MAKE				
PHCV8891	EAGLE EYES	Headlights	Honda	Civic	88-91
PHCV9295	EAGLE EYES	Headlights	Honda	Civic	92-95
PHCV9698	SONAR	Headlights	Honda	Civic	96-98
PHCV9900	SONAR	Headlights	Honda	Civic	99-00
PHCV0105	SONAR	Headlights	Honda	Civic	2001-2005
PHAC9093	EAGLE EYES	Headlights	Honda	Accord	90-93
PHAC9497	SONAR	Headlights	Honda	Accord	94-97
PHAC9802	EAGLE EYES	Headlights	Honda	Accord	98-02
PHAC0305	EAGLE EYES	Headlights	Honda	Accord	2003-2005
PHIN9093	EAGLE EYES	Headlights	Acura	Integra	90-93
PHIN9401	EAGLE EYES	Headlights	Acura	Integra	94-01
CLCV8891	SONAR	Corner lights	Honda	Civic	88-91
CLCV9295	SONAR	Corner lights	Honda	Civic	92-95
CLAC9093	SONAR	Corner lights	Honda	Accord	90-93

CLAC9497	SONAR	Corner lights	Honda	Accord	94-97
CLIN9093	SONAR	Corner lights	Acura	Integra	90-93
CLIN9401	SONAR	Corner lights	Acura	Integra	94-01

**Function:**

**Other information which characterizes/distinguishes the items of equipment to be recalled:**

---

**Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Widgets equipped with certain items of equipment from January 1, 1996, through April 1, 1997, then what was the percentage of the recalled Widgets of all Widgets manufactured during that time period.**

**II. Identifying the Recall Population**

**3. Furnish the total number of items of equipment recalled potentially containing the noncompliance.**

<b>Model</b>	<b>Year</b>	<b>Number of Items Potentially Involved</b>				
PART NUMBER	MAKE					NUMBER ( POTENTIAL
PHCV8891	EAGLE EYES	Headlights	Honda	Civic	88-91	20
PHCV9295	EAGLE EYES	Headlights	Honda	Civic	92-95	60
PHCV9698	SONAR	Headlights	Honda	Civic	96-98	60
PHCV9900	SONAR	Headlights	Honda	Civic	99-00	70
PHCV0105	SONAR	Headlights	Honda	Civic	2001-2005	30
PHAC9093	EAGLE EYES	Headlights	Honda	Accord	90-93	15
PHAC9497	SONAR	Headlights	Honda	Accord	94-97	30
PHAC9802	EAGLE EYES	Headlights	Honda	Accord	98-02	20
PHAC0305	EAGLE EYES	Headlights	Honda	Accord	2003-2005	10
PHIN9093	EAGLE EYES	Headlights	Acura	Integra	90-93	15
PHIN9401	EAGLE EYES	Headlights	Acura	Integra	94-01	20
CLCV8891	SONAR	Corner lights	Honda	Civic	88-91	120
CLCV9295	SONAR	Corner lights	Honda	Civic	92-95	180
CLAC9093	SONAR	Corner lights	Honda	Accord	90-93	40
CLAC9497	SONAR	Corner lights	Honda	Accord	94-97	50
CLIN9093	SONAR	Corner lights	Acura	Integra	90-93	25
CLIN9401	SONAR	Corner lights	Acura	Integra	94-01	80

**Total Number Potentially Affected by the Recall:** 845

**4. Furnish the approximate percentage of the total number of items of equipment estimated to actually contain the noncompliance:** 100%

**Identify and describe how the recall population was determined--in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled items of equipment:**

BASED ON NHSTA REQUEST FOR INFORMATION, EAGLE EYES AND SONAR DETERMINED THAT THE

PART NUMBERS LISTED DID NOT MEET THE FMVSS NO.108 STANDARD FOR AMBER SIDE REFLECTORS. FROM 2004-2005 SALES

---

---

**III. Describe the Noncompliance**

**5. Describe the noncompliance. The description should address the nature and physical location of the noncompliance. Illustrations should be provided as appropriate.**

PART NUMBERS LISTED DO NOT MEET THE REQUIREMENT SET FORTH IN FMVSS NO.108, 49 CFR 571.108 PARAGRAPH S5.4 FOR AMBER SIDE REFLEX REFLECTORS ON COMBINATION LAMPS

---

**Describe the cause(s) of the noncompliance condition.**

DESIGN FLAW

---

**Describe the consequence(s) of the noncompliance condition.**

WITHOUT AMBER SIDE REFLEX REFLECTOR THEREFORE LIGHTING VISIBILITY DECREASED

---

**Identify any warning which can (a) precede or (b) occur.**

N/A

---

**If the noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.**

N/A

---

**Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:**

N/A

---

**IV. Provide the Chronology in Determining the Noncompliance**

**6. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.**

NOTIFIED OF NONCOMPLIANCE ISSUE BY NHTSA ON JANUARY 10, 2006

REVIEW AND NONCOMPLIANCE CONFIRMED ON FEBRUARY 13, 2006

NHTSA REQUEST FOR INFORMATION COMPLETED ON FEBRUARY 26, 2006

**V. Identify the Remedy**

**7. A description of the manufacturer's program for remedying the noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.**

TOM MOTORSPORT INC. (DISTRIBUTOR) ON BEHALF OF EAGLE EYES TRAFFIC INDUSTRIAL CO., LTI AND SONAR AUTO PARTS CO., LTD WILL IMPLEMENT A VOLUNTARY RECALL TO ALL CUSTOMERS WHO PURCHASED THE PARTS LISTED. RETURN OF NONCOMPLIANT PARTS WILL BE FREE OF CHARGE TO CUSTOMERS AND FULL CREDIT WILL BE ISSUED FOR EVERY PART NUMBER RETURNED

**8. Furnish a description of the manufacturer's remedy for the noncompliance. Clearly describe the difference between the recall condition and the remedy.**

ON BEHALF OF EAGLE EYES TRAFFIC INDUSTRIAL CO., LTD AND SONAR AUTO PARTS CO., LTD (MANUFACTURER) TOM MOTORSPORT INC. WILL IMPLEMENT A VOLUNTARY RECALL OF ALL PARTS SOLD LISTED

**Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.**

N/A

**Identify and describe how and when the recall condition was corrected in production. If the production remedy**

was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

N/A

---

---

**VI. Identify the Recall Schedule**

**9. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.**

NOTIFICATION TO CUSTOMERS BY CERTIFIED MAIL ON APRIL 17, 2006

---

**VII. Furnish Recall Communications**

**10. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the noncompliance condition on, not just the initial notification. *A DRAFT copy of the notification documents should be submitted to the Office of Defects Investigation by Fax (202-366-7882) for review prior to mailing.***

**Note: These documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.**

---

**A copy of the completed Part 573 report guide should be faxed to:**

**Mr. Michael Cole at (202) 366-7097**