

06E-040
(11 pgs.)

Safety Defect and Noncompliance Report Guide for Equipment
PART 573 Defect and Noncompliance Responsibility and Reports

RECEIVED

On May 10, 2006, E Speed Racing [Importer] decided that a noncompliance with Federal Motor Vehicle Safety Standard No. 108 exists in items of motor vehicle equipment listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49CFR Part 573 Defect and Noncompliance Responsibility and Reports.

2006 MAY 18 A 9:26

DEFECTS

Date this report was prepared: May 10, 2006

Furnish the manufacturer's identification code for this recall (if applicable): N/A

1. Identify the full corporate name of the fabricating manufacturer/brand/trademark owner of the recalled item of equipment. If the recalled item or equipment is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

E Speed Racing
2275 E. Locust Court
Ontario, CA 91761

Identify the corporate official, by name and title, whom the agency should contact with respect To this recall.

Stewart Lee (President)

Telephone Number: (909) 923-3636 Fax No.: (909) 923-3820

Name and Title of Person who prepared this report.

Stewart Lee (President)

Signed:

Each manufacturer must furnish a report, to the Associate Administrator for Enforcement, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Responsibility and Reports" and also outlines information currently requested. Any questions, please consult the Complete Part 573 or contact Mr. George Person at (202) 366-5210 or by FAX at (202) 366-7882.

I. Identify the Recalled Items of Equipment

2. Identify the Items of Equipment Involved in this Recall, for each make and model or applicable item of equipment product line (provide illustrations or photographs as necessary to describe the item of equipment), provide:

Generic name of the item: Combination lamps

Make: _____ **Model:** Make, Model, and Part Numbers are supplied in list attached.

Part Number: _____ **Size:**

Function: All are combination lamps designed to be mounted at or near the front of a motor vehicle.

Other information which characterizes/distinguishes the items of equipment to be recalled:

These parts do not have amber side reflex reflectors like they do in the OE combination Lamps.

Make: _____ **Model:**

Part Number: _____ **Size:**

Function:

Other information which characterizes/distinguishes the items of equipment to be recalled:

Make: _____ **Model:**

Part Number: _____ **Size:**

Function:

Other information which characterizes/distinguishes the items of equipment to be recalled:

Make: _____ **Model:**

Part Number: _____ **Size:**

Function:

Other information which characterizes/distinguishes the items of equipment to be recalled:

List of the Items of Equipment Involved in This Recall

Recall Products

Sonar

Item No.	Make	Model	Year	Designation
SK3300S-ACD94	Honda	Accord	1994-1997	Combination Lamps
SK3300S-ACD94-JM	Honda	Accord	1994-1997	Combination Lamps
SK3300S-ACD98	Honda	Accord	1998-2000	Combination Lamps
SK3300S-ACD98-JM	Honda	Accord	1998-2000	Combination Lamps
SK3300S-CV01	Honda	Civic	2001-2003	Combination Lamps
SK3300S-CV01-JM	Honda	Civic	2001-2003	Combination Lamps
SK3300S-CV92	Honda	Civic	1992-1995	Combination Lamps
SK3300S-CV92-3D	Honda	Civic	1992-1995	Combination Lamps
SK3300S-CV92-3D-JM	Honda	Civic	1992-1995	Combination Lamps
SK3300S-CV92-JM	Honda	Civic	1992-1995	Combination Lamps
SK3300S-CV96	Honda	Civic	1996-1998	Combination Lamps
SK3300S-CV96-JM	Honda	Civic	1996-1998	Combination Lamps
SK3300S-CV99	Honda	Civic	1999-2000	Combination Lamps
SK3300S-CV99-JM	Honda	Civic	1999-2000	Combination Lamps
SK3325-G1/G3	Chevy	Pick-Up	1994-1999	Combination Lamps
SK3325-G2/G4	GMC	Pick-Up	1994-1999	Combination Lamps
SK3325-CV90	Honda	Civic	1990-1991	Combination Lamps
SK3325-ACD94-N	Honda	Accord	1994-1997	Combination Lamps
SK3325-CV92-3D-NA	Honda	Civic	1992-1995	Combination Lamps
SK3325-E46-4D-NA	BMW	E46	1999-2002	Combination Lamps
SK3325-CRX90-N	BMW	E46	1990-1991	Combination Lamps
SK3325-CV90	Honda	Civic	1990-1991	Combination Lamps

Identify the approximate percentage of the production of all the recalled models manufactured [/imported] by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Widgets equipped with certain items of equipment from January 1, 1996, through April 1, 1997, then what was the percentage of the recalled Widgets of all Widgets manufactured during that time period.

100%

II. Identifying the Recall Population

3. Furnish the total number of items of equipment recalled potentially containing the defect or noncompliance.

Items Model	Year	Number of Potentially
----------------	------	--------------------------

Involved

List is attached.

Total Number Potentially Affected by the Recall: \$ 93,853.00

4. Furnish the approximate percentage of the total number of items of equipment estimated to actually contain the defect or noncompliance: 100%

Identify and describe how the recall population was determined-in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recall items of equipment:

Items were selected if they are combination lamps designed to be mount at or near front of motor vehicle that do not have amber side reflex reflectors like they do in the OE combination lamps sold from February 1, 2003 until February 9, 2006.

**List of Total Number of Items of Equipment
Recalled Potentially Containing the Defect or
Noncompliances**

Qty	Item #	Price ea.	Total Amount
48	SK3300S-C1088	\$ 68.00	\$ 3,264.00
39	SK3300S-ACD94	\$ 80.00	\$ 3,120.00
15	SK3300S-ACD98	\$ 80.00	\$ 1,200.00
39	SK3300S-CRX88	\$ 80.00	\$ 3,120.00
36	SK3300S-CRX90	\$ 80.00	\$ 2,880.00
42	SK3300S-CV01	\$ 70.00	\$ 2,940.00
75	SK3300S-CV92	\$ 80.00	\$ 6,000.00
40	SK3300S-CV96	\$ 72.50	\$ 2,900.00
40	SK3300S-CV99	\$ 70.00	\$ 2,800.00
23	SK3300S-PL92	\$ 75.00	\$ 1,725.00
54	SK3300S-ACD94	\$ 80.00	\$ 4,320.00
53	SK3300S-ACD98	\$ 80.00	\$ 4,240.00
45	SK3300S-C1088	\$ 68.00	\$ 3,060.00
24	SK3300S-CRX88	\$ 80.00	\$ 1,920.00
24	SK3300S-CRX90	\$ 80.00	\$ 1,920.00
33	SK3300S-CV01	\$ 70.00	\$ 2,310.00
70	SK3300S-CV92	\$ 80.00	\$ 5,600.00
45	SK3300S-CV96	\$ 72.50	\$ 3,262.50
41	SK3300S-CV99	\$ 70.00	\$ 2,870.00
2	SK3300S-CRX90	\$ 80.00	\$ 160.00
23	SK3300S-CV01	\$ 70.00	\$ 1,610.00
15	SK3300S-CV92	\$ 80.00	\$ 1,200.00
19	SK3300S-CV96	\$ 72.50	\$ 1,377.50
109	SK3300S-F15097	\$ 65.00	\$ 7,085.00
5	SK3300S-CRX90	\$ 80.00	\$ 400.00
30	SK3300S-ACD94	\$ 80.00	\$ 2,400.00
24	SK3300S-ACD98	\$ 80.00	\$ 1,920.00
48	SK3300S-C1088	\$ 68.00	\$ 3,264.00
26	SK3300S-CRX88	\$ 80.00	\$ 2,080.00
24	SK3300S-CRX90	\$ 80.00	\$ 1,920.00
44	SK3300S-ECPS95	\$ 90.00	\$ 3,960.00
36	SK3300S-ACD94	\$ 80.00	\$ 2,880.00
20	SK3400-F15097	\$ 95.00	\$ 1,900.00
75	SK3325-G1/G3	\$ 5.70	\$ 427.50
65	SK3325-G2/G4	\$ 5.70	\$ 370.50
40	SK3325-CV90	\$ 4.00	\$ 160.00
50	SK3325-ACD94-N	\$ 4.00	\$ 200.00
75	SK3325-CV923D-NA	\$ 4.00	\$ 300.00
37	SK3325-E464D-NA	\$ 11.00	\$ 407.00
35	SK3325-CRX90-N	\$ 4.00	\$ 140.00
60	SK3325-CV90	\$ 4.00	\$ 240.00
TOTAL			\$ 93,853.00

1,648

III. Describe the Noncompliance

5. Describe the noncompliance. The description should address the nature and physical location of the noncompliance. Illustrations should be provided as appropriate.

They do not have amber side reflex reflectors like they do in the OE combination lamps.

Describe the cause(s) of the noncompliance condition.

As we are an importer, not as a manufacturer, we have no knowledge of what would cause the noncompliance condition. We, in good faith with the manufacturer, believe that all products were compliant.

Describe the consequence(s) of the defect or noncompliance condition.

No amber side reflex reflector decreased lighting visibility.

Identify any warning which can (a) precede or (b) occur.

Not applicable.

If the noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

Purchased from Sonar Auto Parts, Co.Ltd. [No. 427, Sec. 2, Wenhua Rd. Panchiao, Taipei, Taiwan]

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

Milton Yang-General Manager.

IV. Provide the Chronology in Determining the Noncompliance

6. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

There were no test results to provide. We were informed by Mr. Sam Campells's fax on March 9, 2006 that our combination lamps may not comply with regulations, that they do not have the amber reflex reflectors. And that was when we realized these lamps may not be compliant.

V. Identify the Remedy

7. A description of the manufacturer's program for remedying the noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

We would like to recall all the customers who bought the said combination lamps from us and compensate them along with shipping and handling. In the mean time all sales and purchases have been ceased since February 9, 2006. We will also send back the said combination lamps to our manufacturer in Taiwan, if this case is applicable.

8. Furnish a description of the manufacturer's remedy for the noncompliance. Clearly describe the difference between the recall condition and the remedy.

Not applicable. Since we are an importer, not a manufacturer, the best we can do is recall the products and discontinue selling them.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

Not applicable.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

Products have been discontinued. Company has been dissolved since February 9, 2006.

VI. Identify the Recall Schedule

9. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

Recall will be done immediately.

VII. Furnish Recall Communication

10. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the noncompliance condition on, not just the initial notification. *A DRAFT copy of the notification documents should be submitted to the Office of Defects Investigation by Fax (202-366-7882) for review prior to mailing.*

Note: These documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.

Please see as attached.

**A copy of the completed Part 573 report guide should be
Faxed to:**

Mr. Michael Cole at (202) 366-7097