



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

October 2, 2006

DAVID GANNON
DIRECTOR OF SERVICE
GLOBAL ELECTRIC MOTORCARS, LLC
1301 39TH STREET NW, SUITE 2
FARGO ND 58102

NVS-215
06V-369

Subject: POWER SIGNAL DISTRIBUTION MODULE

Dear MR. GANNON:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
GEM/NEV/2006

NHTSA Campaign Number: 06V-369

Mfg's Report Date: September 7, 2006

Components: ELECTRICAL SYSTEM

Potential Number of Units Affected: 170

Summary:

ON CERTAIN LOW SPEED VEHICLES, THREE BOLTS ON THE BACK OF THE POWER SIGNAL DISTRIBUTION MODULE (PSDM) MAY NOT HAVE BEEN TIGHTENED PROPERLY WHICH COULD CAUSE A TOTAL LOSS OF POWER TO THE VEHICLE.

Consequence:

A LOSS OF POWER WILL RENDER THE CAR INOPERATIVE AND, IF IT HAPPENS WHILE DRIVING, CAN RENDER THE VEHICLE A ROAD HAZARD. ADDITIONALLY, LOSS OF HEADLAMP, TAIL LAMP OR TURN SIGNAL LAMP FUNCTIONS COULD LIMIT THE VEHICLE'S VISIBILITY TO OTHER DRIVERS, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSPECT AND REPLACE, AS NECESSARY, THE POWER SIGNAL DISTRIBUTION MODULE. THE RECALL IS EXPECTED TO BEGIN IN LATE SEPTEMBER OR EARLY OCTOBER 2006. OWNERS MAY CONTACT GLOBAL ELECTRIC AT 1-888-871-4367.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.


We have reviewed your proposed owner letter and it meets the requirements of Part 577.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during late September or early October 2006. Therefore, the first quarterly report will be due on or before January 30, 2007.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement