



Driven to Explore

Fleetwood Enterprises, Inc.
3051 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwood.com

IMPORTANT RECALL INFORMATION #61117

January 2007

TO: ALL FLEETWOOD DEALER PRINCIPALS,
SERVICE MANAGERS,
AND PARTS MANAGERS

SUBJECT: **RECALL CAMPAIGN #61117**
Gearbox Federal Certification Tags

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Pendleton, Oregon and Crawfordsville, Indiana are requesting your assistance in conducting a voluntary safety recall notification campaign in accordance with the National Highway Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., has decided that certain 2006 and 2007 model year Gearbox 385 FS2G and 395 FS3G model fifth wheel travel trailers fail to comply with the requirements of Part 567, "Certification". These fifth wheel travel trailers were manufactured at our Pendleton, Oregon and Crawfordsville, Indiana manufacturing plants from August 26, 2005 through October 24, 2006.

We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

Fleetwood Enterprises, Inc., has become aware of a tire psi rating input error. The Travel Trailer Manufacturer Federal Certification Tag was printed with an incorrect tire value of 80 pounds per square inch air pressure (psi). The correct tire pressure value is 65 psi. Please note that all other values are correct.

To correct this non-compliance, it is necessary to replace the Travel Trailer Manufacturer Federal Certification Tag and check tire pressures as described in the enclosed Recall Service Bulletin #61117.

WHAT SHOULD YOU DO?

Please check your travel trailer inventory and perform the repair procedure on affected units as outlined in the attached Service Bulletin #61117. It is imperative that this procedure be completed prior to the sale of the affected units so your customers will not be inconvenienced.

Owners of the above mentioned travel trailers have been asked to contact their Fleetwood dealer to have the described non-compliance remedied. In the event that a customer contacts

you, please verify eligibility by referring to the serial number range listed in the enclosed Recall Service Bulletin #61117 prior to beginning the inspection and repairs.

Should a customer have you perform this service, please complete the **Fleetwood Repair Order (form X-SR-042)**. Once the inspection and repairs are completed, have the customer sign the **Fleetwood Repair Order** and return it to your Regional Travel Trailer Service Center for payment. You will be reimbursed in accordance with Service Bulletin #61117. Customers will not be charged for these repairs.

If you are contacted by the owner of a travel trailer with questions concerning this topic, please ask them to contact:

**FLEETWOOD CUSTOMER SERVICE - RECALL #61117
800-455-3307**

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific fifth wheel travel trailer. Fleetwood is asking our dealers to make repairs to stock units on dealer lots prior to sale or lease.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act of 1966) requires that:

If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Safety Recall Campaign.

Thank you for helping Fleetwood with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your regional Fleetwood Service Center.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Jacy Young
Service Administrator
Travel Trailer Division

Enclosures: Recall Service Bulletin #61117
Recall Customer Letter

Recall Bulletin 61117



RECALL BULLETIN:
61117

The purpose of this Bulletin is to inform Fleetwood dealers of the need to replace the Manufacturer Federal Certification Tag and a potential adjustment to the tire air pressure on certain 2006 GearBox Fifth Wheel Travel Trailers.

YEAR(S) AFFECTED:
2006-2007

Condition:

Fleetwood Enterprises, Inc., has discovered that certain 2006 and 2007 model year GearBox Fifth Wheel Travel Trailers, have an incorrect listing on the Manufacturer Federal Certification Tag. The Tag was printed with an incorrect tire air pressure value of 80 pounds per square inch (psi). The correct tire pressure value is 65 psi. **Note: All other values on the Tag are correct.**

PRODUCT(S) AFFECTED:

GearBox Fifth Wheel Travel Trailers

Procedure:

MODEL(S) AFFECTED:
385FS2G,
395FS3G

1. Retail owners of affected fifth wheel travel trailers and dealers holding affected units in inventory will receive a letter from Fleetwood containing a new and corrected Manufacturer Federal Certification Tag. Affected serial numbers requiring a new Tag are listed in this Bulletin.

SUBJECT:

Replacing the Federal Certification Tag with Corrected Tire Air Pressure Listings

2. **Important: Be sure the correct replacement Tag is available and on-hand before proceeding. Tags are serial number specific.**

3. Locate the original Manufacturer Federal Certification Tag on the roadside forward section of the fifth wheel travel trailer.

4. Wipe off the surface of the original Manufacturer Federal Certification Tag to remove dirt and debris.

KEYWORDS:

Tires, Tire Air Pressure, Air Pressure, Tire, Tires, PSI

5. Deface the original Manufacturer Federal Certification Tag with a black permanent marker.

6. Peel the backing from the new Tag and apply over the top of the defaced original Manufacturer Federal Certification Tag. The new Tag should completely cover the original.

ISSUE DATE:
December 2006

7. Make sure the tires are cool and the fifth wheel travel trailer has been sitting for at least one hour. Check, and if necessary, adjust the tire air pressure to the correct 65 psi.

© 2006 Fleetwood Enterprises, Inc.

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade in all conceivable ways in which service might be done or of the possible hazardous consequences of such work. Accordingly, anyone who uses a service procedure or tool must first assure that neither customer safety nor vehicle safety will be jeopardized by the selected service methods."

Warranty Labor Allowance:

Use Flat Rate Codes:

Install new Manufacturer Federal Certification Tag and Adjust Tire Air Pressures

9179 - 11	.1 hr. Inspected/Not Defective
9179 - 12	.1 hr. Inspected/Defective/Repaired
9179 - 13	.1 hr. Inspected/Defective/Owner Decline
9179 - 14	.1 hr. Inspected/Defective/Missing Parts
9179 - 15	.1 hr. Inspected/Defective/Need Tools
9179 - 16	.1 hr. Unable to Notify Customer
9179 - 17	.1 hr. Customer Unreachable

Tools Required:

Black Permanent Marker

Tire Air Pressure Gage Capable of Measuring 80 psi

Air Compressor

Air Hose with Air Chuck

If you have any questions concerning this bulletin, contact Fleetwood's Travel Trailer Dealer Technical Assistance at:

1-800-617-6447

Fleetwood Service Literature can be accessed at: <http://www.fleetwoodrvdealers.com>

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that, if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. New vehicle leases receiving this recall notice must forward a copy of the notice to the lessee within 30 days.

It is impossible to know, evaluate and address the service trade of all conceivable ways in which vehicles might be done or of the possible hazardous consequences of such acts. Accordingly, beyond what can be done in service procedure or test must first assure that neither personal safety nor vehicle safety will be jeopardized by the intended service methods.

2006-2007 GearBox 385FS2G Fifth Wheel Travel Trailers

Affected Unit Serial Numbers:

4CE7F383862313737	4CE7F383762314006	4CE7F383462314111	4CE7F383162315877
4CE7F383562313968	4CE7F383X62314002	4CE7F383662314109	4CE7F383162315880
4CE7F383762313969	4CE7F383262314060	4CE7F383662314112	4CE7F383362315878
4CE7F383362313970	4CE7F383462314061	4CE7F383162314115	4CE7F383562315879
4CE7F383562313971	4CE7F383662314059	4CE7F383362314116	4CE7F383662315874
4CE7F383762313972	4CE7F383662314062	4CE7F383562314117	4CE7F383862315875
4CE7F383962313973	4CE7F383862314063	4CE7F383762314118	4CE7F383X62315876
4CE7F383062313974	4CE7F383X62314064	4CE7F383862314113	4CE7F383062315885
4CE7F383262313975	4CE7F383162314065	4CE7F383X62314114	4CE7F383262315886
4CE7F383462313976	4CE7F383362314066	4CE7F383062314123	4CE7F383362315881
4CE7F383662313977	4CE7F383562314067	4CE7F383562314120	4CE7F383462315887
4CE7F383662313980	4CE7F383562314070	4CE7F383762314121	4CE7F383562315882
4CE7F383862313978	4CE7F383762314068	4CE7F383962314122	4CE7F383762315883
4CE7F383862313981	4CE7F383762314071	4CE7F383262314124	4CE7F383962315884
4CE7F383X62313979	4CE7F383962314069	4CE7F383462314125	4CE7F383662315888
4CE7F383162313983	4CE7F383062314073	4CE7F383662314126	4CE7F383062316485
4CE7F383362313984	4CE7F383262314074	4CE7F383562314733	4CE7F383262316486
4CE7F383562313985	4CE7F383462314075	4CE7F383062314722	4CE7F383362316481
4CE7F383762313986	4CE7F383662314076	4CE7F383062314736	4CE7F383562316482
4CE7F383X62313982	4CE7F383862314077	4CE7F383262314737	4CE7F383762316483
4CE7F383062313988	4CE7F383962314072	4CE7F383762314734	4CE7F383962316484
4CE7F383062313991	4CE7F383X62314078	4CE7F383962314735	4CE7F383462316487
4CE7F383262313989	4CE7F383162314079	4CE7F383262314723	4CE7F383462316490
4CE7F383262313992	4CE7F383162314082	4CE7F383462314724	4CE7F383662316488
4CE7F383962313987	4CE7F383264284630	4CE7F383162314728	4CE7F383662316491
4CE7F383962313990	4CE7F383862314080	4CE7F383162314731	4CE7F383862316489
4CE7F383162313997	4CE7F383X62314081	4CE7F383362314729	4CE7F383862316492
4CE7F383462313993	4CE7F383162314101	4CE7F383662314725	4CE7F383862316542
4CE7F383662313994	4CE7F383362314083	4CE7F383862314726	4CE7F383162316544
4CE7F383862313995	4CE7F383562314084	4CE7F383X62314727	4CE7F383362316545
4CE7F383X62313996	4CE7F383762314085	4CE7F383X62314730	4CE7F383562316546
4CE7F383362313998	4CE7F383962314086	4CE7F383062314719	4CE7F383762316547
4CE7F383562313999	4CE7F383062314106	4CE7F383362314732	4CE7F383962316548
4CE7F383662314000	4CE7F383262314107	4CE7F383762314720	4CE7F383X62316543
4CE7F383862314001	4CE7F383362314102	4CE7F383962314718	4CE7F383162316494
4CE7F383162314003	4CE7F383562314103	4CE7F383962314721	4CE7F383362316495
4CE7F383262314057	4CE7F383762314104	4CE7F383062315871	4CE7F383562316496
4CE7F383362314004	4CE7F383962314105	4CE7F383262315872	4CE7F383762316497
4CE7F383462314058	4CE7F383262314110	4CE7F383462315873	4CE7F383962316498
4CE7F383562314005	4CE7F383462314108	4CE7F383962315870	4CE7F383X62316493

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first ensure that neither personal safety nor vehicle safety will be jeopardized by the stated service methods.

**2006-2007 GearBox 385FS2G Fifth Wheel Travel Trailers
Affected Unit Serial Numbers (continued):**

4CE7F383062316499	4CE7F383462316571	4CE7F383362317582	4CE7F383174286712
4CE7F383062316504	4CE7F383662316569	4CE7F383562317583	4CE7F383374286713
4CE7F383362316500	4CE7F383662316572	4CE7F383762317584	4CE7F383874286710
4CE7F383562316501	4CE7F383862316573	4CE7F383962317585	4CE7F383X74286711
4CE7F383762316502	4CE7F383062316776	4CE7F383162317600	4CE7F383372318748
4CE7F383962316503	4CE7F383262316777	4CE7F383362317601	4CE7F383572318749
4CE7F383262316505	4CE7F383262316780	4CE7F383562317597	4CE7F383574286714
4CE7F383462316506	4CE7F383462316778	4CE7F383562317602	4CE7F383974286716
4CE7F383662316507	4CE7F383462316781	4CE7F383762317598	4CE7F383074286717
4CE7F383662316510	4CE7F383662316779	4CE7F383762317603	4CE7F383074286720
4CE7F383862316508	4CE7F383962316775	4CE7F383962317599	4CE7F383172318750
4CE7F383X62316509	4CE7F383X62316574	4CE7F383962317604	4CE7F383274286718
4CE7F383162316513	4CE7F383662316782	4CE7F383062317605	4CE7F383372318751
4CE7F383362316514	4CE7F383862316783	4CE7F383262317606	4CE7F383474286719
4CE7F383562316515	4CE7F383X62316784	4CE7F383462317607	4CE7F383572318752
4CE7F383762316516	4CE7F383362315475	4CE7F383462317610	4CE7F383772318753
4CE7F383862316511	4CE7F383462317560	4CE7F383662317608	4CE7F383072318755
4CE7F383962316517	4CE7F383162317564	4CE7F383662317611	4CE7F383272318756
4CE7F383X62316512	4CE7F383362317565	4CE7F383862317609	4CE7F383472318757
4CE7F383062316549	4CE7F383562317566	4CE7F383862317612	4CE7F383672318758
4CE7F383062316552	4CE7F383662317561	4CE7F383X62317613	4CE7F383872318759
4CE7F383262316553	4CE7F383762317567	4CE7F383062317619	4CE7F383972318754
4CE7F383462316554	4CE7F383862317562	4CE7F383162317614	4CE7F383472318760
4CE7F383762316550	4CE7F383X62317563	4CE7F383362317615	4CE7F383672318761
4CE7F383962316551	4CE7F383062317569	4CE7F383562317616	4CE7F383872318762
4CE7F383162316558	4CE7F383062317572	4CE7F383762317617	4CE7F383X72318763
4CE7F383362316559	4CE7F383262317573	4CE7F383962317618	4CE7F383072318769
4CE7F383662316555	4CE7F383462317574	4CE7F383062317622	4CE7F383172318764
4CE7F383862316556	4CE7F383662317575	4CE7F383262317623	4CE7F383372318765
4CE7F383X62316557	4CE7F383762317570	4CE7F383462317624	4CE7F383572318766
4CE7F383X62316560	4CE7F383962317568	4CE7F383662317625	4CE7F383772318767
4CE7F383062316566	4CE7F383962317571	4CE7F383762317620	4CE7F383972318768
4CE7F383162316561	4CE7F383162317578	4CE7F383962317621	4CE7F383072318772
4CE7F383362316562	4CE7F383362317579	4CE7F383074286703	4CE7F383272318773
4CE7F383562316563	4CE7F383862317576	4CE7F383274286704	4CE7F383672318775
4CE7F383762316564	4CE7F383X62317577	4CE7F383474286669	4CE7F383772318770
4CE7F383962316565	4CE7F383X62317580	4CE7F383474286705	4CE7F383972318771
4CE7F383262316567	4CE7F383062317586	4CE7F383674286706	4CE7F383172318781
4CE7F383262316570	4CE7F383162317581	4CE7F383X74286708	4CE7F383372318779
4CE7F383462316568	4CE7F383262317587	4CE7F383174286709	4CE7F383872318776

This bulletin is supplied for technical information only and is not an authorization for repairs

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fordwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the instructions, before selling or leasing the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to make accurate and certain the scope of all applicable laws or other national safety recall. It is the responsibility of the dealer to determine the scope of the recall and to ensure that all applicable laws are followed. The dealer must first assure that neither personal safety nor vehicle safety will be jeopardized by the indicated service methods.

**2006-2007 GearBox 385FS2G Fifth Wheel Travel Trailers
Affected Unit Serial Numbers (continued):**

4CE7F383X72318777	4CE7F383772318784	4CE7F383172318795	4CE7F383372318801
4CE7F383X72318780	4CE7F383972318785	4CE7F383372318796	4CE7F383572318797
4CE7F383072318786	4CE7F383272318790	4CE7F383672318792	4CE7F383572318802
4CE7F383272318787	4CE7F383472318788	4CE7F383872318793	4CE7F383772318798
4CE7F383372318782	4CE7F383472318791	4CE7F383X72318794	4CE7F383972318799
4CE7F383572318783	4CE7F383672318789	4CE7F383172318800	

**2007 GearBox 395FS3G Fifth Wheel Travel Trailers
Affected Unit Serial Numbers:**

4CE7F393072318978	4CE7F393972319000	4CE7F393872319022	4CE7F393772319044
4CE7F393272318979	4CE7F393072319001	4CE7F393X72319023	4CE7F393972319045
4CE7F393972318980	4CE7F393272319002	4CE7F393172319024	4CE7F393874286673
4CE7F393072318981	4CE7F393472319003	4CE7F393372319025	4CE7F393874286818
4CE7F393272318982	4CE7F393672319004	4CE7F393572319026	4CE7F393X74286819
4CE7F393472318983	4CE7F393872319005	4CE7F393772319027	4CE7F393874286821
4CE7F393672318984	4CE7F393X72319006	4CE7F393972319028	4CE7F393X74286822
4CE7F393872318985	4CE7F393172319007	4CE7F393072319029	4CE7F393174286823
4CE7F393X72318986	4CE7F393372319008	4CE7F393772319030	4CE7F393374286824
4CE7F393172318987	4CE7F393572319009	4CE7F393972319031	4CE7F393574286825
4CE7F393372318988	4CE7F393172319010	4CE7F393072319032	4CE7F393774286826
4CE7F393572318989	4CE7F393372319011	4CE7F393272319033	4CE7F393974286827
4CE7F393172318990	4CE7F393572319012	4CE7F393472319034	4CE7F393074286828
4CE7F393372318991	4CE7F393772319013	4CE7F393672319035	4CE7F393274286829
4CE7F393572318992	4CE7F393972319014	4CE7F393872319036	4CE7F393974286830
4CE7F393772318993	4CE7F393072319015	4CE7F393X72319037	4CE7F393074286831
4CE7F393972318994	4CE7F393272319016	4CE7F393172319038	4CE7F393274286832
4CE7F393072318995	4CE7F393472319017	4CE7F393372319039	4CE7F393474286833
4CE7F393272318996	4CE7F393672319018	4CE7F393X72319040	4CE7F393674286834
4CE7F393472318997	4CE7F393872319019	4CE7F393172319041	4CE7F393874286835
4CE7F393672318998	4CE7F393472319020	4CE7F393372319042	
4CE7F393872318999	4CE7F393672319021	4CE7F393572319043	

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that:
If you have received a notice of recall or notice to outsize from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the instructions, before selling or leasing the vehicles. Any vehicle dealer receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."



Driven to Explore

Fleetwood Enterprises, Inc.
3051 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwood.com

IMPORTANT RECALL INFORMATION #70122

February 2007

Dear Valued Fleetwood Motor Home Customer:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing center located in Decatur, Indiana has decided that certain 2007 model year Excursion and Providence 40E model motor homes fail to comply with Section 6.2.6 "Marking of Alternate Exits" of the 2005 Edition of the ANSI/NFPA 1192 Standard on Recreational Vehicles.

WHAT IS THE PROBLEM?

On Excursion and Providence 40E model motor homes affected by this recall, the dinette alternate exit/emergency egress window is not identified by an exit label and red egress latch. This window is used to exit the motor home in an emergency situation and must be clearly identified.

WHAT SHOULD YOU DO?

Due to safety related reasons, please make certain your motor home is inspected and repaired by contacting your selling dealer, and making an appointment to have this inspection and repair performed. If they are not available, another Fleetwood motor home dealer may do this work for you.

WHAT WILL FLEEWOOD DO?

Fleetwood will inspect and replace the existing black window latch with a red egress window latch and apply the "exit" label to the dinette alternate exit/emergency egress window. The total length of time your motor home will be out of service will depend on the dealer's work schedule

If you have had this concern corrected previously, you may be eligible for reimbursement of your cost for that repair. For more information regarding this recall #70122, contact Fleetwood Owner Relations at 800-509-3418.

When you deliver your motor home for repairs, your dealer will complete a Fleetwood Repair Order. Upon completion of the repair, please sign the Fleetwood Repair Order and fill out the enclosed, self-addressed **Vehicle Information Update Card** and return it to Fleetwood.

If you have changed your address or sold the motor home, please take a moment to provide the name and address of the person or dealership you sold it to on the enclosed **Vehicle Information Update Card** and return it to Fleetwood. This will allow us to update our records and if necessary, notify the new owner using the information you provide.

For leased vehicles: Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you are unable to obtain the specified repair promptly and without charge, please contact:

Fleetwood Owner Relations - Recall #70122

P.O. Box 59933
Riverside, California 92517
(800) 509-3418

If you believe that the dealer and Fleetwood Enterprises, Inc., have failed or have been unable to remedy the defect without charge or within a reasonable period of time, you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
400 Seventh Street SW
Washington, DC 20590

Or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>

Fleetwood Enterprises, Inc., is taking these steps in the interest of your safety. We regret any inconvenience this may cause you.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Tina Inkrote
Service Administrator
Motor Home Division