

Service Bulletin SBA0268



SERVICE BULLETIN:
SBA0268

The purpose of this Bulletin is to inform all Fleetwood dealers about a Workhorse Custom Chassis Safety Recall Campaign regarding replacement of a fuel rail pulse damper retainer clip on certain motor homes built on Workhorse chassis with 8.1 liter gasoline engines.

YEAR(S) AFFECTED:
2004-2006

CONDITION:

PRODUCT(S) AFFECTED:

The attached Safety Recall Campaign Bulletin 60601-C from Workhorse Custom Chassis identifies the possibility of a defective fuel rail pulse damper retainer clip. Defective retainer clips may fracture and allow fuel to leak, possibly resulting in a vehicle fire.

Certain 2004-2007
flounder, Fiesta,
Fiesta LX, Pace
Arrow, Southwind,
Terra, Terra LX

and

Certain 2004-2006
Storm and Flair:

CORRECTION:

Affected motor homes will need to be scheduled for repair with an authorized Workhorse service center. To locate a Workhorse service center, contact Workhorse Custom Chassis at:

(877) 946-7731

Built On
Workhorse
Custom Chassis
With 8.1 Liter
Gasoline Engine

The 17-digit Vehicle Identification Number (VIN) will be required when contacting Workhorse Custom Chassis. Please reference the attached Workhorse Safety Recall Campaign #60601-C.

All repairs are to be performed by a Workhorse service center. **All parts and warranty will be handled through Workhorse Custom Chassis.**

MODEL(S) AFFECTED:
All

Warranty repair claims for this repair campaign should **not** be submitted to Fleetwood.

SUBJECT:
Workhorse Safety
Campaign
60601-C :
8.1 L Engine Fuel
Rail Pulse Damper
Retainer Clip
Replacement

*If you have any questions concerning Workhorse Safety Recall Campaign #60601-C, contact Workhorse Custom Chassis at:
(877) 946-7731*

KEYWORDS:
Workhorse, fuel,
gasoline, damper,
retainer, clip

ISSUE DATE:
September, 2006

*Fleetwood Service Literature can be accessed at:
<http://www.fleetwoodrvdealers.com>*

© 2008 Fleetwood Enterprises, Inc.

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."