

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory
Affairs

January 25, 2012

Nigel Mortimer
Head of Recalls
Defect Investigations and Recalls
Transport Canada – Road Safety
80 Noël Street
Gatineau, Quebec J8Z 0A1

**Re: Defect Information Notice – Phase 2 - Supplemental Notice No. 6
TC2011-086, (11C-1, FL-591), Sterling Car Hauler
EPA04 MBE 4000 Low Pressure Fuel Line
Representative Owner Notice**

Mr. Mortimer,

In accordance with Section 10 of the Motor Vehicle Safety Act and Section 15 of the Motor Vehicle Safety Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and a representative copy of documents distributed to owners.

Phase 2 – Owners of 42 vehicles were notified on January 23, 2011.

The correct count on Canadian vehicles affected is: 250, including 208 notified in Phase 1

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Attachment
Via E-mail nigel.mortimer@tc.gc.ca

A Daimler Company

Daimler Trucks North America LLC
4747 N. Channel Avenue
Portland OR 97217-7699
503-745-6910 Phone
503-745-5544 Fax
Nasser.Zamani@Daimler.com

Daimler Trucks North America LLC

Daimler Trucks North America LLC

Detroit Diesel Corporation
13400 Outer Drive, West
Detroit, Michigan 48239-4001
Telephone: 313-592-5000

Subject: Safety Recall 11C1
Sterling Car Hauler EPA04 MBE4000 Low Pressure Fuel Line

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This notice is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Daimler Trucks has decided that a defect which relates to motor vehicle safety exists in certain model year 2005 through 2007 Sterling L-Line vehicles configured with car hauler bodies and chassis, manufactured from September 13, 2004 through October 10, 2007 and equipped with specific MBE4000 EPA07 engines assembled with a fuel filter mounted at the rear of the engine.

Detroit Diesel Corporation has determined that some certified EPA07 MBE4000 engines were assembled with low pressure fuel lines which may develop leaks. Lower pressure fuel lines between primary fuel pump and engine mounted fuel filter, and upper low pressure fuel line between engine mounted fuel filter and engine block may develop a substantial diesel fuel leak from cracking due to undetermined causes, or from abrasion due to contact with other components. If the condition goes undetected it may result in fuel leaking on the roadway which may create a hazard increasing the risk of a motor vehicle accident.

Please contact a Detroit Diesel Authorized Repair Facility to arrange to have the Recall performed and to ensure that parts are available. To locate an authorized facility, search online at www.detroitdiesel.com/supportnetwork/. The Recall will take approximately 11 hours and will be performed at no charge to you. Also, owners may be liable for any progressive damage that results from failure to complete this recall within a reasonable time after receiving this notification.

IMPORTANT: When the Recall has been completed, please ensure that a label has been affixed to your vehicle referencing **11C1** which is located on the passenger-side door about 12 inches (30 cm) below the door latch.

If you do not own the unit that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within ten days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information on this, contact Warranty Administration at Detroit Diesel Corporation, 13400 Outer Drive West, Detroit, MI 48239 or call (313) 592-3708.

If you have questions about this Recall, please contact the **Detroit Diesel Customer Support Center**, 13400 Outer Drive West, Detroit, MI 48239, or call **(800) 445-1980** between **8:00 a.m. to 7:00 p.m. Monday through Friday and 9:00 a.m. to 3:00 p.m. on Saturday Eastern Standard Time**. If your dealer or an authorized Detroit Diesel service center fails or is unable to remedy this defect without charge and within a reasonable time you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call 888 327-4236 (TTY: 800-424-9153), or go to <http://www.safercar.gov> if remedy difficulties exist. For **Canadian** customers, **please** contact our customer service or for additional info about the recall, you can contact **Transport Canada** at **(800) 333-0510**.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.