

**Volvo Cars of North America, LLC****Adam Kopstein, Manager**

Product Safety & Compliance Office

1 Volvo Drive

PO Box 914

Rockleigh, NJ 07647

Phone: 201-767-4871

August 27, 2012

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE, Room W45-306
Washington, DC 20590

Re: DEFECT INFORMATION REPORT

Dear Ms. Lewis,

Pursuant to Part 573 of Title 49 of the Code of Federal Regulations, Volvo Cars of North America, LLC (Volvo) submits the attached information report concerning a non-compliance that Volvo Car Corporation (VCC) is voluntarily initiating.

Summary:

- Approximately 300 certain model year 2013 S80 & XC70 vehicles in the U.S. are potentially affected.
- A software deviation results in the "TPMS Service Required" message appearing after approximately 15 minutes of accumulated driving over 25 mph. This deviation results in the non-compliance of *Federal Motor Vehicle Safety Standard 138: Tire Pressure Monitoring System*.
- The vehicles concerned are required to have a software download that upgrades the Central Electronic Module (CEM) software.

An updated Defect Information Report will be provided as soon as additional information becomes available.

If you have any questions related to this matter, please feel free to contact me at my above mentioned phone number, or Larry Mihok of my staff at 201-768-7300, extension 7336.

Sincerely yours,

A handwritten signature in blue ink that reads "A. Kopstein".

Adam Kopstein
Manager, Product Safety & Compliance Office
VOLVO CARS OF NORTH AMERICA, LLC.

Attachment

49 CFR PART 573 - DEFECT INFORMATION REPORT

573.6 (c) 1: Manufacturer's Name

Vehicle Manufacturer: Volvo Car Corporation
Gothenburg, Sweden

Designated Agent: Volvo Cars of North America
Rockleigh, N.J. 07647

573.6 (c) 2: Identification of Vehicles Involved

The vehicles involved in this non-compliance are approximately 300 model year 2013 S80 and XC70 vehicles.

573.6 (c) 3: Total Number of Vehicles Potentially Containing the Defect

Approximately 300 S80 & XC70 vehicles in the U.S. are potentially affected.

573.6 (c) 5: Description of the Defect or Noncompliance

A software deviation within the Central Electronic Module (CEM) will result in the "TPMS Service Required" message appearing after approximately 15 minutes of accumulated driving over 25 mph. This deviation results in the non-compliance of *Federal Motor Vehicle Safety Standard 138: Tire Pressure Monitoring System*.

573.6 (c) 11: The Manufacturer's Campaign Number

Volvo has assigned Recall Campaign Number 256 to this activity.