



To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Bulletin: SRA-V13-05
Date: August 14, 2013
Action Required? **YES**

From: Regulatory Affairs Department

Subject: Safety Recall, RVXX1305, Driveline Undersized

Safety Recall Summary:

On Certain 2013-2014 Volvo VNL model vehicles, manufactured from April 2, 2012 through May 3, 2013 with a Meritor RPL20 driveline, a gear ratio of 2.5, and direct drive transmission, the driveline is undersized for the application and therefore may fail. Failure of the driveline can result in a disabled vehicle or debris from the driveline on the roadway, which can increase the risk of a vehicle crash.

Affected Models and Model Years: 2013-2014 Volvo VNL

The number of vehicles affected is approximately 381 vehicles (all U.S.)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle will be posted on the Trucks Dealer Portal by end of day August 14, 2013.
- Owner Notices are scheduled to be mailed on or before October 9, 2013.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.