

RECEIVED

By Recall Management Division at 2:40 pm, Nov 22, 2013



ADAM KOPSTEIN

Manager, Product Safety & Compliance

November 22, 2013

Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE, Room W45-306
Washington, DC 20590

Subject: Defect Information Report

Dear Ms. Lewis,

Pursuant to Part 573 of Title 49 of the Code of Federal Regulations, Volvo Cars of North America, LLC (Volvo) submits the attached information report concerning a non-compliance recall that Volvo Car Corporation (VCC) is voluntarily initiating.

On certain model year 2011-2012 S60 vehicles, the oil pressure sensor is not activated with the original factory downloaded software, subsequently leading to that there will be no information to the customer in Driver Information Module (DIM) regarding the oil pressure.

The corrective action is to perform a software upgrade.

An updated Defect Information Report will be provided as soon as additional information becomes available.

If you have any questions related to this matter, please feel free to contact me at my above mentioned phone number, or Larry Mihok of my staff at 201-768-7300, extension 7336.

Sincerely yours,

A handwritten signature in blue ink that reads "A. Kopstein".

Adam Kopstein
Manager, Product Safety & Compliance Office
VOLVO CARS OF NORTH AMERICA, LLC.

Volvo Cars U.S.
Customer Service

1 Volvo Drive
P.O. Box 914
Rockleigh, NJ 07647

Telephone 1-201-768-7300
www.volvocars.us



49 CFR PART 573 - DEFECT INFORMATION REPORT

573.6 (c) 1: Manufacturer's Name

Vehicle Manufacturer: Volvo Car Corporation
Gothenburg, Sweden

Designated Agent: Volvo Cars of North America
Rockleigh, N.J. 07647

573.6 (c) 2: Identification of Vehicles Involved

Certain Model Year 2011-2012 S60 vehicles equipped with 5-cylinder B5254T5 engines listed below are involved in this non-compliance recall.

The inclusive dates of manufacture and VIN ranges are listed in the chart below.

MODEL	MODEL YEAR	PRODUCTION DATES	CHASSIS RANGE
S60	2011 – 2012	06/22/2010 – 05/14/2012	001148 - 146365

573.6 (c) 5: Description of the Defect or Noncompliance

On certain Model Year 2011-2012 S60 vehicles equipped with 5-cylinder B5254T5 engines, the oil pressure sensor is not activated with the original factory downloaded software, subsequently leading to that there will be no information to the customer in the Driver Information Module (DIM) regarding the oil pressure.

573.6(c)(7): Information Used in Determination of a Non-compliance

Failure to comply with the following requirements:
FMVSS 101 Controls and displays sections S5 and S5.2.1.

573.6 (c) 8 (i): Program for Remedy of Defect

The vehicles concerned will have a software upgrade.