

GM CUSTOMER CARE AND AFTERSALES
DCS3287
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 9, 2014

Subject: 14117A – Safety Recall
Electric Power Steering Assist
Revised Service Procedure and Warranty Transaction Information Sections

Models: 2008 Chevrolet Malibu, Pontiac G6, and Saturn Aura

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The bulletin has been revised to include a labor code for vehicles that have had the steering column (torque sensor assembly) and the power steering motor controller unit replaced. Please discard all copies of bulletin 14117.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES