



REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED




FRONT VIEW

**NOTE:**  
 REMOVE TWIST IN SEAT BELT BEFORE FASTENING END.  
 \* IDENTIFIES REPAIR KIT HARDWARE.  
 TIGHTEN REPLACEMENT BOLT TO 20 FT-LB.

LEFT SIDE OF DRIVERS SEAT SHOWN  
 RIGHT SIDE PASSENGER SEAT THE SAME.

A BUSHING 16620 IS ALSO INSTALLED ON THE OPPOSITE SIDE LINK. (IF MISSING)



LH SIDE VIEW

REFERENCE NHSTA RECALL # 14E015.

**VILLA INTERNATIONAL**

ISS LINK ASSEMBLY, RECALL REPAIR

SIZE	FORM NO.	DWG NO.	REV
SCALE		03	

This drawing is the property of Villa International all rights reserved.

4

3

2

1

A

B

C

D

A

B

C

D