

**Part 573 Safety Recall Report****14V-343****Manufacturer Name :** Ford Motor Company**Submission Date :** NOV 05,2014**NHTSA Recall No. :** 14V-343**Manufacturer Recall No. :** 14B04**Manufacturer Information :**

Manufacturer Name : Ford Motor Company

Address : 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone : 1-866-436-7332

**Population :**

Number of potentially involved : 58,669

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2006-2006 FORD MUSTANG

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** Certain 2005 through 2008 model year Ford Mustang vehicles, built at the AutoAlliance Plant from August 16, 2004, to June 25, 2007, that were originally sold or are currently registered in Florida, Hawaii, Puerto Rico, or the U.S. Virgin Islands, and equipped with driver air bags incorporating Takata PSDI-4 inflators.

Production Dates : AUG 01, 2004 - JUN 30, 2007

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2005-2005 FORD GT

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

**Descriptive Information :** Certain 2005 through 2006 model year Ford GT vehicles, built at the Wixom Assembly Plant from February 11, 2005 to January 30, 2006, that were originally sold or are currently registered in Florida, Hawaii, Puerto Rico, or the U.S. Virgin Islands, and equipped with driver air bags incorporating Takata PSDI-4 inflators.

Production Dates : FEB 11, 2005 - JAN 30, 2006

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs





**Description of Defect :**

Description of the Defect : Ford Motor Company (Ford) is conducting a limited regional recall for certain model year 2005-2007 Mustang, 2005-2006 GT and 2004 Ranger vehicles originally sold or currently registered in Florida, Puerto Rico, Hawaii and the U.S. Virgin Islands, and equipped with Takata-brand air bag inflators. Upon deployment of the driver side and/or passenger side frontal air bag, excessive internal pressure may cause the inflator to rupture.

Specifically, in the following vehicles, the driver's air bag inflators are affected: 2005-2007 Mustang. In the following vehicles, the passenger's air bag inflators are affected: 2004 Ranger. In the following vehicles, both the driver's and passenger's air bag inflators are affected: 2005-2006 GT.

Description of the Safety Risk : In the event of a crash necessitating deployment of one of the affected frontal air bags, the inflator could rupture with metal fragments striking and potentially seriously injuring the vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : TK Holdings/Takata

Address : NR

NR

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Ford will notify owners, and dealers will inspect the vehicles and replace any defective air bag inflators, as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Ford at 1-800-392-3673. Ford's number for this recall is 14B04.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : SEP 29, 2014 - NR

\* NR - Not Reported