



SUZUKI MOTOR CORPORATION

Overseas Automobile Service Group
Overseas Service Department
300 Takatsuka, Minami, Hamamatsu, JAPAN 432-8611
Tel: 81-53-440-2977, Fax: 81-53-440-2318

Page 1 of 1
Date Apr, 24, 2015
Our ref. VD-150424

To : SUZUKI MOTOR OF AMERICA, INC.
Attn. : Mr. Takeshi Hayasaki, President
Mr. Takao Kudo, Executive Vice President

SUBJECT: Addition Of Affected Vehicles Of JB627/JB632W/JB424W/RW420 Safety Recall Campaign For "AIR BAG" Warning Light Illumination (B1312)

Dear Mr. Takeshi Hayasaki and Mr. Takao Kudo,

This notification is to inform you that Suzuki Motor Corporation (SMC) decide to additionally involve some vehicles in the safety recall campaign of which we previously noticed you with the letter VD-130904 issued on September 4, 2013, VD-130904-R1 issued on September 5, 2013, and VD-140424 issued on April 24, 2014.

Because Suzuki Motor of America, Inc. (SMAI) had already carried out repair works under the warranty extension which had being conducted until the recall commenced for vehicles affected by the same problem, SMC excluded the vehicles from the VIN list of affected vehicles in the recall.

However, SMC recently became aware that when SMAI provided reimbursement to owners for repairs performed prior to the start of the warranty extension, the vehicles for which reimbursement was provided may have been counted as having a countermeasure part installed under the warranty extension without actually having the countermeasure part installed. SMC has determined that this situation may involve 108 vehicles that were repaired prior to the start of the warranty extension and were not included in the recall population.

Please see attached VIN list for additional vehicle information.

Best regards,

Yasunari Suzuki
Department General Manager
Overseas Service Department
SUZUKI MOTOR CORPORATION

Attachment

ANNEX1_Revised_VIN List_JB_(U.S. MAINLAND).xlsx
ANNEX1_Revised_VIN List_RW_(U.S. MAINLAND).xlsx