

GM CUSTOMER CARE AND AFTERSALES  
DCS3661  
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 21, 2015

Subject: 12261C – Safety Recall  
Intermittent Airbag Warning Light Illuminated – Replace Steering  
Wheel Airbag Coil  
Revised Part Information Section

Models: 2012 Buick Verano; Chevrolet Camaro, Cruze, and Sonic

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

The Part Information section has been revised to include a steering wheel bolt. Please discard all copies of bulletin 12261B.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES