

## IMPORTANT SAFETY RECALL NOTICE

This notice applies to your vehicle VIN: [REDACTED]

5/1/2015

RE: 2015 Model Year – KTM 690 Enduro R

Dear KTM Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. KTM North America, Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2015 model year 690 Enduro R motorcycles. To ensure the highest level of safety, performance, reliability and customer satisfaction, it is necessary to have the alignment (position) of the crankcase ventilation hose spring clamp checked for proper positioning on all affected units by an authorized KTM dealer free of charge.

On affected models, the rear brake line from the ABS pressure modulator to the foot brake cylinder may have been damaged during the assembly process or be subject to subsequent damage caused by vibration and contact with the spring clamp of the crankcase ventilation hose which could result in the loss of rear brake function; this could lead to a crash which could cause injury or death to the rider or others.

The cause of the defect is due to the improper alignment (positioning) of the crankcase ventilation hose spring clamp. To remedy this defect, a quality check has been implemented at the manufacturer to ensure all crankcase ventilation hose spring clamps are aligned properly during the assembly process.

**It is mandatory that you discontinue riding your motorcycle until the defect has been repaired.**

Please contact your authorized KTM Dealer (log onto [www.ktmusa.com](http://www.ktmusa.com) for a complete listing) as soon as possible and make an appointment to have the position of the crankcase ventilation spring clamp checked and corrected if necessary. Any damaged brake line will be replaced. Please present a copy of this letter along with your motorcycle to your local authorized KTM dealer. There will be no charge for this service. Repairs could take approximately from 0.5 hours to verify proper alignment of the position of the crankcase ventilation spring clamp or up to 3 hours to replace any damaged brake line.

If you experience difficulties in getting the crankcase ventilation spring clamp position verified from an authorized KTM Dealer, please contact KTM North America, Inc. Customer Relations at (888) 985-6090 for assistance. Furthermore, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you have already had the crankcase ventilation hose spring clamp position checked prior to receiving this letter, you may be eligible to receive reimbursement for the cost. For reimbursement details contact KTM North America, Inc. Customer Relations at (888) 985-6090 for details.

If you have sold, traded or no longer own this motorcycle, it is important for the safety of the current owner that you inform KTM of current ownership or unknown ownership status by returning the second page of this letter in the enclosed self-addressed prepaid postage envelope.

We apologize for any inconvenience and want to assure you that our commitment together with all KTM Dealers is to provide you with the highest level of service, support and customer satisfaction.

Best Regards,

KTM Technical Services & Warranty Department

### KTM NORTH AMERICA, INC.

Technical Department

38429 Innovation Court // Murrieta, CA 92563 // T: 951-600-8007 // F: 951-600-8866  
1119 Milan Avenue // Amherst, OH 44001 // T: 440-985-3553 // F: 440-985-3060  
1375-1 Marie-Victorin // Saint-Bruno // Quebec J3V 6B7 // T: 450-441-4451 // F: 450-441-3885  
[www.ktmusa.com](http://www.ktmusa.com)

